

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 06037

Vehicle Insured : SMA3888B
Accident Date : 16-Aug-2019

Date : 19-Aug-2019

Our Ref : 219133 (AIG) / CHAN

PAGE : 1

LIM KIAN HENG
BLK 851 YISHUN STREET 81
#10-64
Singapore 760851

*Not Withstand
11 Days @ 7
Resurvey After Paint
5 days*

ESTIMATED COST OF REPAIR FOR VOLVO S60 D4 SLC557C

=====

1 pc Front n/s door
1 pc Rear n/s door
1 pc N/s rocker garnish
1 pc Rear n/s sport rim
1 pc Rear n/s door outer handle

B 2,293.30 ✓
B 2,126.50 ✓
510.00 ?
nd 2,200.00 ✓
n 413.70 x

7,543.50

Less 10% : 754.35

6,789.15

QmI body tough guard coating

(A:11) 899.00 ?

To putty and spray replaced parts

1,200.00 *900*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

1,000.00 *600*

To check and adjust wheel alignment

65.00 *60*

To transfer sport rim & tyre

50.00 *20*

Total : S\$10,003.15

=====

Singapore Dollars Ten Thousand and Three and
Cents Fifteen Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: