

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Nor Azian Binte Noordin

Date: 22 Aug 2019

Preliminary Advice

Vehicle No	: SKN2549S	Accident Date	: 14/08/2019
Make	: VOLKSWAGEN JETTA TSI	Policy No.	: 80430749AVW
Assignment Date	: 20/08/2019	Excess	: S\$500.00
Date of Inspection	: 21/08/2019	Est. Duration of Repair	: 4.00
Inspection At	: VOLKSWAGEN GROUP SINGAPORE PTE LTD (MACPHERSON) 1 KAMPONG AMPAT, SINGAPORE 368314 SINGAPORE 368314		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,897.07
Revised Amount	:S\$	4,086.64
Check Items (Estimated)	:S\$	487.22
Total	:S\$	4,573.86

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	43,000.00
COE / PARF Rebate	:S\$	37,869.00
Salvage Value	:S\$	
Margin for Repair	:S\$	5,131.00

Remarks

- (X) The vehicle is economical for repair.
- () The above survey was conducted on a 'without prejudice' basis.