



**ESTIMATE TO REPAIR**

VEHICLE NO. : SMG 9303 B  
 MAKE : HONDA  
 MODEL : SHUTTLE HYBRID 1.5 AUTO  
 YEAR : 2019  
 CHASSIS NO : GP72002306

SURVEYOR NAME :
DATE OF SURVEY :
TIME OF SURVEY :

DATE : 19-Aug-19  
 DATE OF ACCIDENT : 17-Sep-19  
 THIRD PARTY REF : GBH 8355 H / CHINA TAIPING

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper				\$ 1,150.60
2 pcs	Rear Bumper Retainer		\$ 26.50		\$ 53.00
2 pcs	Rear Bumper Reflector		\$ 45.00		\$ 90.00
2 pcs	Rear Bumper Reflector Cover		\$ 45.00		\$ 90.00
10 pcs	Rear Bumper Clips		\$ 3.50		\$ 35.00
1 pc	Rear End Panel				\$ 560.80
1 pc	Rear End Panel Top Garnish				\$ 155.50
1 pc	Rear Spare Tyre Top Cover				\$ 655.20
1 pc	Rear Tool Tray				\$ 165.20
1 pc	Tailgate				\$ 1,193.00
1 pc	Tailgate Rubber				\$ 168.50
1 pc	Tailgate Lock				\$ 157.50
1 pc	Tailgate SHUTTLE Emblem				\$ 55.10
1 pc	Tailgate HYBRID Emblem				\$ 80.50
1 pc	Tailgate Centre Emblem				\$ 38.10
1 pc	Tailgate Inner Trim				\$ 320.20
1 pc	Rear Windscreen Moulding				\$ 120.00
2 pcs	Rear Fender Inner Trim		\$ 455.20		\$ 910.40
					\$ 5,998.60
	Less 20%				\$ 1,199.72
					\$ 4,798.88
1 tube	Rear Windscreen Sealant	S.Nett			\$ 40.00
1 set	Rear Bumper Sensor	S.Nett			\$ 200.00
	To putty and spray painting				\$ 800.00
	To remove & refix rear windscreen				\$ 120.00
	To transfer tailgate fittings				\$ 80.00
	To anti-rust				\$ 80.00
	Labour charges				\$ 700.00
TG/RA-	<b>Total</b>				<b>\$ 6,818.88</b>

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127 Email: edmund@LTM.sg Website : www.LTM.sg

Co.Reg No.199307277D GST Reg No.M2-0019086-0

This document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written consent of Lim Tan Motor Pte Ltd