

REF: es/msq17014580/Evd301

Special Instructions:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person): Crystal Lee of MBIA Date/Time: 1/18/19 @ 4:31pm

Estimated Cost: _____ Bill to: _____

OD TP WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: PC 7984J Insured: SLK 2353T

at Workshop w/o: Bomb Motor Tel: 98476171

of 2 Pender Crescent

Policy No: A28881428 QMY Claim No: 603017

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 15/08/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 11:50am @ 20/1/19 Person Contacted: Thomas Vehicle IN/OUT

Date/Time	Action/Instruction
	Initial ✓
	PC7984J-X
	SLK 2353T - es/msq17014580/R15/3
	20/1/19
21/8/19	Send preli revised via meriman
3/9/19	@ 2:27pm Thomas said vehicle still under repair
21/10/19	Final fig \$28,541.40 Confirmed by email (Real 32,973.67, 5370)

ASS. REC. BY: Steve

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: PC 7984J Yr Regn: 24/01/19
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Hiace c.c. 2982
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 9283 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JTFST22P000938398
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Mod: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 195 R15C
 R: "

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 15/8/19 D.O.I. 20/8/19
 Survey held at Bouko motor
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooflop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
	MV - 78009
	PV - 25484
	NIK - 52,516
RECEIVED 21 OCT 2019	

Date/Time, File Pass to? : Prel. Report
 : Final Report
 Date/Time, File Return to?
21/10 - typist
 Report Format: merimen
 Lump Sum / R.R. / : 28,541.40

Days Of Repair: 14
 Resurvey No. of Trip: 1
 Add Fee: : Site Insp (\$) _____
 : Interview (\$) _____
 : Tech. Invs (\$) _____
 : WSA/ENK (\$) _____

Survey Fee:	<u>400</u>
Transportation:	_____
_____ S + RS. _____ \$	_____
Plinks	_____
Gilvers	<u>11</u>
TOTAL	<u>411</u>

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	16 Aug 2019		20 Aug 2019 16:07 Edit Adj Rpt		Last:IA 21 Aug 2019 10:51		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: CHANG SIEH YONG , ID: S1482594, Tel: +6597975634, Email: CSY@ISPL.COM.SG									
Main Claimant: BREAKTHROUGH MISSIONS LTD , Co. Reg. No.: 198305430G									
Vehicle Reg. No.:	PC7984J	Date of Loss:	15/08/2019 07:00 - :59 [6 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 603017	Policy/Cover Note No.:	A28881428QMY (Comprehensive) Coverage: 10/01/2019 - 09/01/2020						
Vehicle Reg. No. (Insured):	SLK2353T	Policy No. (Claimant):							
		Excess:	S\$800.00						
Repairer:	Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong - 6594 2544]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 19/09/2019]								
Driver/Custodian (Insured):	CHANG SIEH YONG (58 / Male), NRIC: S1482594, Tel: +6597975634 Email: CSY@ISPL.COM.SG								
Adj Asg. Remarks:	on WP. CAR IN. Liab: 100%. Contact: Thomas Pang @ 9847 6171 / 6631 1860. Manual assign to LKK via email on 19/08/2019.								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Crystal Lee <crystal_lee@sg.msig-asia.com>
Sent: Monday, 19 August 2019 4:31 PM
To: Admin-D (LKKAuto); assignments
Cc: Ong Zi Hui
Subject: Survey Request - Manual Assigned
Attachments: PC7984J_EFILE.PDF; PC7984J_EST INV.pdf

Importance: High

Direct Settlement (TP) - Accident involving PC7984J (MSIG) & SLK2353T DOA 15/08/2019 (URGENT)

Manual Assigned

Dear LKK,

Refer to the email and attachment, please arrange survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment

Thank you & Best regards,

Crystal Lee

Admin Officer, Claims Services (In-House Survey)

D: +65 6594 2535 | F: +65 6643 1349 | crystal_lee@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Motor Survey

Sent: Monday, 19 August, 2019 3:35 PM

To: Jasmine Lok Kheng Kwei <jasmine_lok@sg.msig-asia.com>

Cc: Suraidah B Saidi PTCBC <SuraidahB.Saidi@inchcape.com.sg>; Ashlyn.Chng@inchcape.com.sg; Crystal Lee <crystal_lee@sg.msig-asia.com>; Ong Zi Hui <zihui_ong@sg.msig-asia.com>; Helene Phua <helene_phua@sg.msig-asia.com>

Subject: FW: RE: Direct Settlement (TP) - Accident involving PC7984J (MSIG) & SLK2353T DOA 15/08/2019 (URGENT)

Importance: High

Dear Jasmine,

Please assist on liability. Tks.

Dear Ashlyn,

As spoken, the car is in.

Dear Crystal,

Please assist to arrange survey soonest. Tks.

Best Regards

Winnie Chua

Senior Admin Officer, Claims Services (In-House Survey)

Direct line +65 6594 2556 | Direct fax +65 6225 7402 | pingping_chua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Ashlyn Chng [<mailto:Ashlyn.Chng@inchcape.com.sg>]

Sent: Monday, 19 August 2019 2:48 PM

To: Motor Survey <motorsurvey@sg.msig-asia.com>

Subject: FW: RE: Direct Settlement (TP) - Accident involving PC7984J & SLK2353T DOA 15/08/2019 (URGENT)

Importance: High

Hi Sir / Mdm,

RESEND .

Regards,

Ashlyn Chng

D: 6631 1874 | F: 6872 7260 | E: Ashlyn.chng@inchcape.com.sg

Inchcape Centre

Level 4, Bodycare Centre

2 Pandan Crescent

Singapore 128462

www.borneomotors.com.sg | www.lexus.com.sg | www.toyotasingapore.com.sg | www.hino.com.sg | www.suzukicar.com.sg

From: Ashlyn Chng

Sent: Friday, 16 August 2019 9:32 AM

To: Motor Survey <motorsurvey@sg.msig-asia.com>

Cc: Suraidah B Saidi PTCBC <SuraidahB.Saidi@inchcape.com.sg>

Subject: RE: Direct Settlement (TP) - Accident involving PC7984J & SLK2353T DOA 15/08/2019

Importance: High

Hi,

Reference to the above-mentioned.

Please find attached herein a copy of our client's Accident Report, Damaged Photos, Accident Scene Video Footage & Estimate Invoice for your kind perusal.

As our client is claiming against your insured **SLK2353T** thus would appreciate if you could revert to us on the

liability urgently or we could settle the case under Direct Settlement with Car Rental of @ \$100 per day x no. of days as recommended by your appointed surveyor.

Kindly have your surveyor to contact our Motor Claim Assessor, **Thomas Pang @ 9847 6171/ 6631 1860** is located at **2 Pandan Crescent / Level 4** for an appointment to inspect our client's vehicle (currently vehicle IN workshop).

As for liability clearance, kindly revert to this email.

Your kind attention into the above is greatly appreciated.

Thank you!

Regards,

Ashlyn Chng

D: 6631 1874 | F: 6872 7260 | E: Ashlyn.chng@inchcape.com.sg

Inchcape Centre

Level 4, Bodycare Centre

2 Pandan Crescent

Singapore 128462

www.borneomotors.com.sg | www.lexus.com.sg | www.toyotasingapore.com.sg | www.hino.com.sg | www.suzukicar.com.sg

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Katherine Wong	Date: 21 Aug 2019

Preliminary Advice

Insured Vehicle No	: SLK2353T	Accident Date	: 15/08/2019
TP Vehicle No	: PC7984J	Assignment Date	: 20/08/2019
Make	: TOYOTA HIACE	Est. Duration of Repair	: 14.00
Date of Inspection	: 20/08/2019		
Inspection At	: BORNEO MOTORS (S) PTE LTD (PANDAN) 2 PANDAN CRESCENT SINGAPORE 128462		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:SS	61,500.83
Revised Amount	:SS	27,880.00
Check Items (Estimated)	:SS	13,063.19
Total	:SS	40,943.19

Lump Sum Repair :SS

Total Loss Consideration

New for Old Value	:SS	
Pre-Accident Value	:SS	
COE / PARF Rebate	:SS	
Salvage Value	:SS	
Margin for Repair	:SS	

Remarks

The vehicle is economical/not economical for repair.

The above survey was conducted on a 'without prejudice' basis.

> **Back to OneMotoring****Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	430G

Vehicle Details

Vehicle No.:	PC7984J
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Aug 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE HIGH ROOF COMMUTER TURBO AUTO
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	1KD2829758
Chassis No.:	JTFST22P000038308
Maximum Power Output:	-
Open Market Value:	\$38,308.00
Original Registration Date:	24 Jan 2019
First Registration Date:	24 Jan 2019
Transfer Count:	0
Actual ARF Paid:	\$1,916.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	23 Jan 2029
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$27,002.00
COE Rebate Amount:	\$25,484.00
Total Rebate Amount:	\$25,484.00

The information contained herein is correct as at 15 Aug 2019

OK

Post an Advertisement
Set it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Want to Sell?

High Loan & Trade In, Free Choice Of Spray!



Warranty & Free Servicing
Provided!
Monthly

KA-HUP
VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND
HOTLINE: 6741 9997 [view all ads](#)

Browse by Category

« Back [1 2 3 4 5 6 7 8] Next »

Sort by Date Posted 20 results/page

148 vehicles

TOYOTA HIACE

Advanced Search Submit

Make	Model	Price	Deprecation	Reg Cost	Eng Cap	Mileage	Veh-Type	Status
TOYOTA HIACE		Any	Any	2019	Any	Any	Any	Available



Toyota Hiace 3.0A **\$66,800** **\$7,110 /yr** **02-Jan-2019** **2,982 cc** **40 km** **Van** **Available**
Fuel Type: Diesel
 (Auto Transmission Borneo Hiace For Sales) Newly Registered! Come With 3 Years Or 100000 Km Warranty And 8 Time Free Servicing F...
 Posted: 15-Aug-2019 Tags: 2019 Toyota Hiace, 2019 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace Commuter 3.0A High Roof **\$76,800** **\$8,390 /yr** **02-Jan-2019** **2,982 cc** **142 km** **Bus** **Available**
Fuel Type: Diesel
 Vehicle Is Only 7 Months Old, Mileage At Only 142Km Done, Due To Company Relocating, Kindly Contact Us For An Appointment Or Visit...
 Posted: 02-Aug-2019 Tags: 2019 Toyota Hiace, 2019 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace 3.0M **\$64,800** **\$7,110 /yr** **02-Jan-2019** **2,982 cc** **-** **Van** **Available**
Fuel Type: Diesel
 Monthly Deprecation Of \$582 Only! 100% Financing Welcomed! We Accept Trade-Ins/Scrap Vehicles Of All Makes And Models. 2 Weeks...
 Car (S) Pte Ltd
 Posted: 22-Jul-2019 Tags: 2019 Toyota Hiace, 2019 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace 3.0M **\$69,800** **\$7,420 /yr** **07-Jan-2019** **2,982 cc** **8 km** **Van** **Available**
Fuel Type: Diesel
 Newly Registered! Totally Legit, GST (ARF/COE All In! Toyota Hiace 5 Doors Diesel. Borneo Motors 3 Years Or 100K Km Warranty! Cheap...
 ABWIN (1994) Pte Ltd
 Posted: 15-Aug-2019 Tags: 2019 Toyota Hiace, 2019 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Buy From Dealer
Labeled Special Offer, from Toyota!



Toyota Hiace 2.8A **\$60,800** **\$6,460 /yr** **09-Jan-2019** **2,754 cc** **-** **Van** **Available**
Fuel Type: Diesel
 Rear Aircon Van Monthly \$578 Only. Auto SDR. Price Inclusive Guarantee 10 Years COE Without T&C. Monthly Income \$2K Eligible For 1...
 ABWIN Bus Pte Ltd
 Posted: 14-Aug-2019 Tags: 2019 Toyota Hiace, 2019 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace 2.8A **\$70,800** **\$7,520 /yr** **10-Jan-2019** **2,754 cc** **10 km** **Van** **Available**
Fuel Type: Diesel
 Cheapest In Town! Latest Hiace Euro 6 Price Includes (ARF, Reg Fees, GST, Road Tax, COE/ETS) Free Servicing And 3 Years Warranty...
 I-Deal Auto Trading Pte Ltd
 Posted: 27-Jul-2019 Tags: 2019 Toyota Hiace, 2019 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota



Toyota Hiace Commuter 2.8A **\$73,988** **\$8,460 /yr** **16-Jan-2019** **2,754 cc** **8,698 km** **Bus** **Available**
Fuel Type: Diesel
 Cheapest In Town, Still Under 5 Years Or 100000km Warranty Whichever. Come First, High Loan And High Trade In. Can Register Excur...
 ABWIN Bus Pte Ltd
 Posted: 14-Aug-2019 Tags: 2019 Toyota Hiace, 2019 toyota hiace, Toyota Hiace, toyota hiace, Toyota, Hiace, hiace, Used Toyota

Compare

Toyota Hiace 3.0M **\$68,800** **\$7,290 /yr** **22-Jan-2019** **2,982 cc** **-** **Van** **Available**
Fuel Type: Diesel
 BRAND NEW! Borneo Motor Unit! GST Inclusive! No Hidden Cost! Ready Stock! Immediate Registration! 8x FREE SERVICING! 3 Years...



Net Link Partners Pte Ltd
 Posted: 29-Jul-2019 Tags: 2019 Toyota Hiace, 2019 Toyota Hiace, Toyota Hiace, toyota hiace, Toyota Hiace, Hiace, Used Toyota



Toyota Hiace 2.8A **\$65,000** **\$6,870 /yr** **29-Jan-2019** **2,754 cc** **-** **Van** **Available**
Fuel Type: Diesel
 High Specs Model! Automatic Transmission! (Doboh: LED/Rear Aircon/Power Doors/Etc.) Loan Up To 100% At 2.99% Per Annum! High...
 Net Link Partners Pte Ltd
 Posted: 04-Jul-2019 Tags: 2019 Toyota Hiace, 2019 Toyota Hiace, Toyota Hiace, toyota hiace, Toyota Hiace, Hiace, Used Toyota



Toyota Hiace 3.0M **\$67,800** **\$7,160 /yr** **01-Feb-2019** **2,982 cc** **-** **Van** **Available**
Fuel Type: Diesel
 Cheapest Deal In SG! GST-Inclusive All-In Price For You As 1st Owner! New 2019 Model! Ready Stock! No Gimmicks! No Admin Fees! N...
 SG Motor Link Pte Ltd
 Posted: 21-Jul-2019 Tags: 2019 Toyota Hiace, 2019 Toyota Hiace, Toyota Hiace, toyota hiace, Toyota Hiace, Hiace, Used Toyota



That's a fine looking car interior
 Customize your ride. Replace your leather seats, door panels, steering wheels and more with quality trims of your choice. List of the best workshops available. Each with merchant information, ranking and reviews to help you make the best decision.
 Find out more!



Toyota Hiace 3.0M **\$69,800** **\$7,340 /yr** **15-Feb-2019** **2,982 cc** **-** **Van** **Available**
Fuel Type: Diesel
 Free 3 x Servicing With Borneo Motors! Flash Sale! If You Are Looking For A New Commercial Vehicle For Your Business Work Horse. Th...
 Ezy-1 Pte Ltd
 Posted: 17-Aug-2019 Tags: 2019 Toyota Hiace, 2019 Toyota Hiace, Toyota Hiace, toyota hiace, Toyota Hiace, Hiace, Used Toyota



Toyota Hiace Commuter 3.0A **\$87,800** **\$9,230 /yr** **15-Feb-2019** **2,982 cc** **-** **Bus** **Available**
Fuel Type: Diesel
 14 Seater Euro 6 Mini Bus For Sale! Ready Stock, 3 Years Or 100,000 Km Warranty Whichever Come First, Include 6 Months Road Tax...
 KSL Automotive Pte Ltd
 Posted: 11-Jul-2019 Tags: 2019 Toyota Hiace, 2019 Toyota Hiace, Toyota Hiace, toyota hiace, Toyota Hiace, Hiace, Used Toyota



Toyota Hiace 2.8A **\$71,800** **\$7,540 /yr** **18-Feb-2019** **2,754 cc** **-** **Van** **Available**
Fuel Type: Diesel
 Free 3 Year Road Tax! 5 Door Auto Unit Hiace. GST Inclusive! No Hidden Cost! High Loan And High Trade In Available, Loan Up To 100...
 Ezy-1 Pte Ltd
 Posted: 12-Aug-2019 Tags: 2019 Toyota Hiace, 2019 Toyota Hiace, Toyota Hiace, toyota hiace, Toyota Hiace, Hiace, Used Toyota



Toyota Hiace Commuter 2.8A **\$90,888** **\$9,990 /yr** **18-Feb-2019** **2,754 cc** **-** **Bus** **Available**
Fuel Type: Diesel
 Please Call To Arrange For viewing, Thanks.
 Posted: 02-Jul-2019 Tags: 2019 Toyota Hiace, 2019 Toyota Hiace, Toyota Hiace, toyota hiace, Toyota Hiace, Hiace, Used Toyota



Toyota Hiace 3.0A **\$69,800** **\$7,330 /yr** **18-Feb-2019** **2,982 cc** **-** **Van** **Available**
Fuel Type: Diesel
 Newly Registered Agent Unit Auto Hiace, 3 Years Warranty And Free 2 Times Servicing From Borneo Agent. Reliable And Easy Maintain...
 I-Deal Auto Trading Pte Ltd
 Posted: 13-Jul-2019 Tags: 2019 Toyota Hiace, 2019 Toyota Hiace, Toyota Hiace, toyota hiace, Toyota Hiace, Hiace, Used Toyota



Toyota Hiace 3.0M **\$69,800** **\$7,330 /yr** **20-Feb-2019** **2,982 cc** **-** **Van** **Available**
Fuel Type: Diesel
 Newly Registered! Totally Legit. GST/ARF/CDE All In! Toyota Hiace 5 Doors Diesel. Borneo Motors 3 Years Or 100k Km Warranty! Cheap...
 ADVIN (1994) Pte Ltd
 Posted: 14-Aug-2019 Tags: 2019 Toyota Hiace, 2019 Toyota Hiace, Toyota Hiace, toyota hiace, Toyota Hiace, Hiace, Used Toyota



Toyota Hiace 2.8A DX **\$68,800** **\$7,220 /yr** **22-Feb-2019** **2,754 cc** **-** **Van** **Available**
Fuel Type: Diesel
 Newly Registered! GST Inclusive! No Hidden Costs! The Most Reliable Large Van Available! Auto/Diesel! Drive With Class 3A! Latest Euro...
 Net Link Partners Pte Ltd
 Posted: 15-Aug-2019 Tags: 2019 Toyota Hiace, 2019 Toyota Hiace, Toyota Hiace, toyota hiace, Toyota Hiace, Hiace, Used Toyota



Toyota Hiace 3.0M **\$67,800** **\$7,100 /yr** **01-Mar-2019** **2,982 cc** **-** **Van** **Available**
Fuel Type: Diesel
 Price Is For New And 1st Registration Of Owner, 100% Loan Is Available At Your Need, With Our Easy Loan Scheme We Believe That W...
 SG Motor Link Pte Ltd
 Posted: 13-Aug-2019 Tags: 2019 Toyota Hiace, 2019 Toyota Hiace, Toyota Hiace, toyota hiace, Toyota Hiace, Hiace, Used Toyota

Compare

Toyota Hiace 3.0M **\$67,800** **\$7,090 /yr** **07-Mar-2019** **2,982 cc** **-** **Van** **Available**



Fuel Type: Diesel
FREE 8 x Servicing With Borneo Motors! Hot Selling Toyota Hiace. The Best And Most Reliable Model In The Market. 100% Loan Availabl
 Ezy-1 Pte Ltd
 Posted: 14-Aug-2019 Tags: 2019 Toyota Hiace, 2019 toyota hiace, Toyota Hiace, toyota hiace, Toyota Hiace, Hiace, Used Toyota

[View Details](#)

Toyota Hiace 3.0M **\$68,800** **\$7,190 /yr** **07-Mar-2019** **2,982 cc** **--** **Van** **Available**
Fuel Type: Diesel
Get Inclusive! No Hidden Costs! No Gimicks! Cheapest In Town! 8 x Free Servicing! 3 Years Or 100,000 Km Mileage Warranty By Borneo
 Net Link Partners Pte Ltd
 Posted: 14-Aug-2019 Tags: 2019 Toyota Hiace, 2019 toyota hiace, Toyota Hiace, toyota hiace, Toyota Hiace, Hiace, Used Toyota

[View Details](#)

Save this search criteria, to get email alerts whenever a match is found.

Price Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

< Back [1 2 3 4 5 6 7 8] Next >

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for (dealer/import) cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, water cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, 10 COE cars & CPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark fees & car insurance. Find buy used TOYOTA HIACE, TOYOTA HIACE Singapore, used TOYOTA HIACE Singapore, used TOYOTA HIACE, used vehicles Singapore or even buy used TOYOTA HIACE Singapore. We have new car dealers comprising dealer/importers, authorized car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, motor, car performance parts, car discussion, forum discussion, commercial-vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow [sgCarMart.com](#)

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.



MSIG

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, # 21-01, SGX Centre 2, Singapore 068807
Tel +65 6827 7888, Fax +65 6827 7800
Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)
(REPUBLIC OF SINGAPORE)
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.Z.601
Private Omnibuses

COMMERCIAL VEHICLE
Comprehensive

Certificate No. B 29115072 MKC

Excess : SGD1,000

1. Index Mark and Registration Number of Vehicle

PC7984J

2. Name of Policyholder

Breakthrough Missions Ltd

3. Effective Date of the Commencement of Insurance for the purposes of the Act

24/01/2019

4. Date of Expiry of Insurance

23/01/2020

5. Persons or Classes of Persons entitled to drive*

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use only for the carriage of passengers or goods in connection with the Policyholder's business.

The Policy does not cover

- (1) Use for racing pace-making reliability trial or speed-testing.
- (2) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle.

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

This Certificate is not transferable to a new owner of the vehicle, if for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.
Approved Insurers


for Chief Executive Officer

TYPE OF CLAIM: OD OD/UL ODS

MCA: TP

MOTOR ACCIDENT REPORT

Date Of Report: 15/8/19 Time: 11:22am Date Of Accident: 15/8/19 Time: 7:15am
 Exact Location Of Accident: West Coast Road (Opposite BLK 512)
 Country/State of Loss: Singapore / Wilayah Persekutuan / Selangor Darul Ehsan / Negeri Sembilan / Melaka / Pahang /

OWN VEHICLE DETAILS (INSURED/POLICY HOLDER)

Vehicle Registration Number: PC 7984 J Co. Reg. No(for Co. Vehicle)/NRIC/PP/FIN No: 1983 05 4306
 Name Of Registered Owner: Breakthrough Missions
 Mobile Number: _____ Alternative No: _____ Email Address: _____

Vehicle Particulars

Manufacturer: Toyota Lexus Suzuki Hino Model: Hiace
 Exact Purpose for which vehicle was being used at time of accident: Normal Usage Other (please specify): _____
 Are you claiming under your own insurance policy for repair to your vehicle? Yes Reporting Only Third Party
 Vehicle Category: Private Car Commercial Vehicle Others

Insurance Company

Name of Insurance Company: MSIG
 Type Of Coverage: Comprehensive Third Party Third Party Fire and/or Theft
 Fleet Policy: Yes No Policy / Cover Note No: B 29115072 MLC

DRIVER DETAILS AT POINT OF ACCIDENT

Name of Driver: Yap Bee Siong NRIC/ Passport / FIN No: 568 15891 E
 Date Of Birth: 3-4-1968 Occupation: Indoor Outdoor
 Date Of Driving Pass: 13-9-2004 Gender: Male Female
 Mobile Number: 90279916 Fax No: _____ Alternative No: _____
 Address: 24, Yew Sang Road Postal Code: 521144
 Email Address: _____
 Was driver an employee of the Insured's Company? Yes No State relationship of the driver with the insured: Director
 Vehicle Registration Number of Driver's Own Vehicle (if applicable): _____
 Insurance Company of Driver's Own Vehicle (if applicable): _____

GENERAL INFORMATION OF THE ACCIDENT

Type Of Accident: Hit from the back
 Number of Passengers in the above vehicle (including Driver): 3 / If more than 2 Pax Please fill ANNEX B

PASSENGER 1

Name: Yap Xi Ci Gender: Male Female
 Weather Conditions: Clear Raining Others (if others, please state condition): _____
 Road Surface: Wet Dry Others (if others, please state condition): _____
 Was any body injured in the Accident? No Yes
 Was any injured conveyed to hospital by ambulance? No Yes
 Was any foreign vehicle involved in this accident? No Yes Vehicle No: _____ Vehicle type: _____
 Number of vehicles involved in the accident: 2
 Was there any witness? No Yes If yes, please furnish witness details column below
 Witness Name: _____ | Contact No: _____ | Email: _____
 Was there any other vehicle or property damaged? No Yes
 Was there any video captured by Car Camera? No Yes Are accident scene photos available for attachment? No Yes
 Was the accident reported to the police? No Yes (if yes, please state which Police Station): _____
 Was notice of intended Prosecution given? No Yes (if yes, please state against whom): _____
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. No Yes

DETAILS OF OTHER VEHICLE PROPERTY 1 (Please fill Annex A if more vehicles involved)

Vehicle Registration Number: SLK 2353 T Vehicle Make/Model/Colour: _____
 Details Of Properties Damage in Accident: Front badly damage
 Vehicle Category: Toyota Altis
 Name of Driver: Chang Suet Siah Yung
 NRIC/Passport/FIN Number: 5148 2594 J Contact Number: _____
 Address: 34A Lorong L Telok Kurau Postal Code: 425443
 Insurance Company Name: MSIG
 Nature Of Damage: Front Damage No. Of Passenger (including Driver): 2

PASSENGER 2

Name:

Yap chin chin

Gender: Male Female

PASSENGER 3

Name:

Gender: Male Female

PASSENGER 4

Name:

Gender: Male Female

PASSENGER 5

Name:

Gender: Male Female

PASSENGER 6

Name:

Gender: Male Female

PASSENGER 7

Name:

Gender: Male Female

PASSENGER 8

Name:

Gender: Male Female

PASSENGER 9

Name:

Gender: Male Female

PASSENGER 10

Name:

Gender: Male Female

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature

Date & Time:



Driver's Signature

(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature

Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along West Coast Road.
 Traffic light was red, I slow down my
 car. Suddenly a vehicle SLK 2353T hit
 my car from behind.

DECLARATION

I/We declare that foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Eng Bee Recovery Pte Ltd
 Reg No: 198301425D
 39, Defu Lane 12,
 Singapore 539139.
 Tel: +65 - 6272 2208 Fax: +65 - 6280 5740
 Website: www.engbee.com.sg



EBR-WO-200 224076

AGENTS
BORNEO

JOB DETAILS:	DATE: <u>15/8/19</u>	CAR DETAILS:	OPERATOR DETAILS:	
	TIME RECEIVED: <u>9:43</u>		CAR REGN NO: <u>PC7984J</u>	DRIVER'S NAME: <u>wei</u>
	TIME ARRIVED: <u>10:11</u>	MAKE & MODEL: <u>TH6</u>	TOW TRUCK #: <u>YM6882L</u>	TOTAL MILEAGE (KM): _____
	TIME COMPLETED: <u>10:35</u>	POLICE FORCE	DRIVER'S SIGNATURE: <u>wei</u>	
	ID: _____			
	ID: _____			

LOCATION FROM: <u>West Coast Road</u>	LOCATION TO: <u>Pandan</u>
---------------------------------------	----------------------------

INDICATE DAMAGED AREAS ON VEHICLES 	<input type="checkbox"/> ACCIDENT / BREAKDOWN <input type="checkbox"/> MULTI STOREY / BASEMENT / SHELTER <input checked="" type="checkbox"/> CAR CARRIER <input type="checkbox"/> CRANE UP / WINCH OUT <input type="checkbox"/> KING DOLLY <input type="checkbox"/> CHANGE TYRE	<input type="checkbox"/> REMOVAL OF AXEL <input type="checkbox"/> GO JAK <input type="checkbox"/> COLLECT KEY / LETTER <input type="checkbox"/> TRANSPORT CHARGE <input type="checkbox"/> STANDBY <input checked="" type="checkbox"/> CASHCARD: YES/NO/SS
	REMARKS:	

CUSTOMER DECLARATION

- I am entitled to the service requested. In the event of this sequently not being the case, I shall be responsible for the cost of any assistance provided.
- I accept that any roadside repairs will be a temporary nature and that advice of a franchised dealer should be sought by me as soon as possible.
- In the case of forced entry, I confirm that I specifically requested that the operator to forcefully enter the vehicle and that all damages occasioned thereby is and shall be my sole responsibility.
- All removable items of value should be removed operated separately. I declare that there is no valuable items in the vehicle.
- I accept that any removable items left in the vehicle will not be the responsibility of the emergency service or their agents.
- Conditions on the use of the recovery trucks, truck cranes, etc. Recovery of vehicles is at my own risk. Eng Bee Recovery Pte Ltd will not be responsible for any consequences which may arise due to breakage or other unforeseen circumstances.

CUSTOMERS NAME & SIGNATURE: <u>[Signature]</u>	DATE: _____	PHONE #: <u>90279916</u>
--	-------------	--------------------------

AGENT/DEALERS DECLARATION

- I hereby represent the company and verify that the abovementioned vehicle has damages as indicated by Eng Bee Recovery or their agents.
- Any damages or loss of valuable found after the acceptance of declaration will not be held against Eng Bee Recovery or their agents.

RELEASED TO NAME & SIGNATURE: <u>[Signature]</u>	DATE: _____	PHONE #: _____
--	-------------	----------------

1. White (Agent's Copy) 2. Green (Customer's Copy) 3. Red (Account's Copy) 4. Blue (Invoice Copy) 5. Yellow (File Copy)

Co Reg No : 196700086Z
 GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail		Account No	Customer Detail		
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept		S1000004 / ICCUA1	M/S Breakthrough Missions Ltd 6 Eu Tong Sen Street #10-15 The Central Singapore 059817 Work: 64797756		
		Document No			0
		Document Date			15/08/2019

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	LEPDYQ	A5	KDH223R	24/01/2019	PC7984J	0	47751 72/DS/PC7984J
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTFST22P000038308	1KD2829758	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc%	Amount
1	Z	BP-SUNDRY TP INS: MSIG INSURANCE TP VEH: SLK2353T DATE OF ACC: 15.08.2019			✓	50 100.00
2	S	BP-SUBLET SUPPLY JOINT PANEL SEALANT			✓	200 300.00
3	S	BP-SUBLET DRILL HOLE AND INSTALL REVERSE SENSOR			✓	180.00/
4	S	BP-SUBLET CHECK WIRING AND CONDUCT WATER TEST			✓	122.40/
5	S	BP-SUBLET REMOVE AND TRANSFER TAILGATE COMPONENTS ONTO NEW TAILGATE			✓	360.00/
6	S	BP-SUBLET R/I REAR REVERSE CAMERA TO FAC REPAIR			✓	180.00/
7	S	BP-SUBLET REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR			✓	360 720.00
8	S	BP-SUBLET REPLACE TAILGATE GLASS			✓	462.00/
9	S	BP-SUBLET REPLACE LH REAR QUARTER GLASS			✓	462.00/
10	S	BP-SUBLET CONDUCT COMPUTERISED CHASSIS ALIGNMENT			X photo	1710.00
11	S	BP-SUBLET REPLACE REAR UNDER CARRIAGE			X	1440.00
12	S	BP-SUBLET REPLACE REAR EXHAUST PIPE SYSTEM			✓	360.00 X
13	S	BP-SUBLET REPLACE ACC DAMAGED PARTS 77" AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS			✓	5090 7200.00
14	S	BP-SUBLET RESPRAY ACC AFFECTED AREAS 590 X 5			✓	2950 5900.00
15	S	BP-SUBLET REPLACE LH CENTRE GLASS			✓	282.00/

Borneo Motors is the recommended workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
Steve (LKK) 8322 8813	Please acknowledge receipt of vehicle W/L Pro/Adv 20/8/19 P/P 3:30pm Resing before 14 days	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4043272

TO SECURITY GUARD

4043272

 PLEASE ALLOW THE UNDERMENTIONED
 VEHICLE TO LEAVE THE COMPANY PREMISES.

 DATE 15/08/2019
 TIME 18:08

 VEHICLE NO **PC7984J**

CUSTOMER

 SIGNATURE
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors

InChcape

Co Reg No : 196700086Z
 GST Reg No : MR-8500000-9

ESTIMATE

 Online Service Booking:
www.toyota.com.sg
Toyota Bodycare Centre
 No. 2 Pandan Crescent
 Singapore 128462
 Tel no.: 6631 1188

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail		Account No	Customer Detail		
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept		S1000004 / ICCUA1	M/S Breakthrough Missions Ltd 6 Eu Tong Sen Street #10-15 The Central Singapore 059817 Work: 64797756		
		Document No			0
		Document Date			15/08/2019

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	LEPDYQ	A5	KDH223R	24/01/2019	PC7984J	0	47751 72/DS/PC7984J
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTFST22P000038308	1KD2829758	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
16	L	BP-LPO SUPPLY REGN PLATE (PO#)				80.00/
17	L	BP-LPO SUPPLY ALUMINUM BAR AND TRIM BOARD (inner metal)		00	✓ check part	2880.00/
18	L	BP-LPO SUPPLY SOLAR FILM - TAILGATE GLASS				480.00/
19	L	BP-LPO SUPPLY SOLAR FILM - LH REAR QUARTER GLASS				480.00/
20	L	BP-LPO SUPPLY SOLAR FILM - LH CENTER GLASS				350.00/
21	Z	BP-SUNDRY SUPPLY STICKER 70KM/H				50.00/
22	B	BP-MECH2 CONDUCT FULL WHEEL ALIGNMENT				180.00/
23	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				180.00/
24	Z	BP-SUNDRY SUPPLY COMPANY STICKER, WORDING, CONTACT AND ETC..		APC 150	✓ check part ?	1500.00
25	Z	TW TOWING CHARGES				120.00/
26	S	BP-SUBLET REPLACE SPARE RIM/TYRE AND BALANCING				144.00X
27	L	BP-LPO SUPPLY TYRE				580.00X
28	1	TREVSE-CLG04 FMS 4 P REVERSE KDH223	1.00	79.90	15.00	67.91 ✓
29	2	T08210-26A48 CO RUBBER FLOORMAT	1.00	231.28	15.00	196.59 X
30	3	T08826-08115 PANEL BONDING AD	1.00	267.20	15.00	227.12 ✓
31	4	T58651-22H91 REAR FLOOR SHEET,	1.00	207.30	15.00	176.20 X
32	5	T42110-26541 HOUSING ASSY, RR	1.00	2668.80	15.00	2268.48 X
33	6	T42181-60120 GASKET, DIFFERENTIAL	1.00	18.00	15.00	15.30 X

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4043273

TO SECURITY GUARD

4043273

 PLEASE ALLOW THE UNDERMENTIONED
 VEHICLE TO LEAVE THE COMPANY PREMISES.

 DATE 15/08/2019
 TIME 18:08

 VEHICLE NO **PC7984J**

CUSTOMER

 SIGNATURE
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors

Incharge

26 007 40

Co Reg No : 196700086Z
 GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail		Account No	Customer Detail	
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept		S1000004 / ICCUA1	M/S Breakthrough Missions Ltd 6 Eu Tong Sen Street #10-15 The Central Singapore 059817 Work: 64797756	
		Document No		
		0		
		Document Date		
		15/08/2019		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	LEPDYQ	A5	KDH223R	24/01/2019	PC7984J	0	47751 72/DS/PC7984J
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTFST22P000038308	1KD2829758	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc%	Amount
34	7	T12157-10010 GASKET, PLUG X	2.00	2.00	15.00	3.40
35	8	T04412-26270 GASKET KIT, X	1.00	126.50	15.00	107.52
36	9	T41110-26432 CARRIER ASSY, X	1.00	4676.10	15.00	3974.68
37	0	T42311-26320 SHAFT, RR AXLE X	2.00	889.90	15.00	1512.82
38	1	T90363-40071 BEARING, RADIAL X	2.00	191.50	15.00	325.54
39	2	T42421-26030 CASE, RR AXLE X	2.00	159.00	15.00	270.30
40	3	T42444-60020 GASKET, BRAKE DRUM X	2.00	6.00	15.00	10.20
41	4	T42443-55020 DEFLECTOR GASKET, X	2.00	3.50	15.00	5.94
42	5	T90942-02079 BOLT, HUB X	6.00	12.60	15.00	64.26
43	6	T90301-92002 RING, 'O' X	2.00	10.20	15.00	17.34
44	7	T90310-50006 SEAL X	2.00	25.80	15.00	43.86
45	8	T42611-26152 WHEEL, DISC X	1.00	440.90	15.00	374.76
46	9	T48531-80736 ABSORBER ASSY, RR X	2.00	127.50	15.00	216.74
47	0	T48046-26130 SEAT SUB-ASSY, RR X	2.00	143.80	15.00	244.46
48	1	T90117-14177 BOLT X	4.00	54.90	15.00	186.64
49	2	T94151-21401 NUT, FLANGE X	4.00	3.40	15.00	11.56
50	3	T90105-14170 BOLT, FLANGE X	4.00	12.00	15.00	40.80
51	4	T48341-26240 BUMPER, RR SPRING X	2.00	127.90	15.00	217.42
52	5	T04483-26150 SHACKLE KIT, RR X	2.00	214.50	15.00	364.64
53	6	T90385-18008 BUSH X	4.00	8.20	15.00	27.88

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

4043274

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

4043274

 PLEASE ALLOW THE UNDERMENTIONED
 VEHICLE TO LEAVE THE COMPANY PREMISES.

 DATE 15/08/2019
 TIME 18:08

 VEHICLE NO **PC7984J**

CUSTOMER

 SIGNATURE
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors

Co Reg No : 196700086Z
 GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail		Account No	Customer Detail	
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept		S1000004 / ICCUA1	M/S Breakthrough Missions Ltd 6 Eu Tong Sen Street #10-15 The Central Singapore 059817 Work: 64797756	
		Document No		
		0		
		Document Date		
		15/08/2019		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	LEPDYQ	A5	KDH223R	24/01/2019	PC7984J	0	47751 72/DS/PC7984J
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTFST22P000038308	1KD2829758	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc%	Amount
54	7	T90105-14169 BOLT, FLANGE X NH	4.00	13.90	15.00	47.24
55	8	T48375-26080 DAMPER, LEAF SPRING X NH	2.00	116.90	15.00	198.72
56	9	T48210-26F20 SPRING ASSY, RR X NH	1.00	1140.70	15.00	1939.18 X
57	0	T51903-26661 CARRIER SUB-ASSY MIS	1.00	293.30	15.00	249.30 ✓
58	1	T90119-12261 BOLT, W/WASHER MIS	1.00	17.70	15.00	15.04 ✓
59	2	T90202-13066 WASHER, PLATE MIS	4.00	4.70	15.00	15.96 ✓
60	3	T51907-26030 STOPPER SUB-ASSY, MIS	1.00	35.00	15.00	29.75 ✓
61	4	T51938-44010 LOCK, SPARE WHEEL MIS	1.00	24.80	15.00	21.08 ✓
62	5	T51915-26030 BASE, SPARE WHEEL MIS	2.00	26.00	15.00	44.20 ✓
63	6	T90467-08056 CO CLIP APC	10.00	2.90	15.00	24.60 ✓
64	7	T52159-26530 COVER, RR BUMPER MIS	1.00	430.90	15.00	366.26 ✓
65	8	T90159-60497 SCREW, W/WASHER APC	4.00	2.20	15.00	7.48 ✓
66	9	T90189-06228 GROMMET, APC 21-36 (12pc) ✓	4.00	2.10	15.00	7.12 ✓
67	0	T90467-09185 CLIP APC	10.00	2.80	15.00	23.80 ✓
68	1	T52157-26010 R/R SIDE BPR RETAINER, DR	1.00	23.40	15.00	19.89 ✓
69	2	T52158-26010 L/R SIDE BPR RETAINER, DR	1.00	23.40	15.00	19.89 ✓
70	3	T58385-26070 REAR BUMPER BRACKET, DO	4.00	26.00	15.00	88.40 ✓
71	4	T52165-26040 AO R/REAR TOP BUMPER COVER NH MIS	1.00	93.90	15.00	79.81 ✓
72	5	T52155-26150 R/RR BUMPER SUPPORT, NH MIS	1.00	40.40	15.00	34.34 ✓
73	6	T52166-26040 AO L/REAR TOP BUMPER COVER NH MIS	1.00	93.90	15.00	79.81 X

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE SIGN ALONG PERFORMED LINE

4043275

TO SECURITY GUARD

4043275

 PLEASE ALLOW THE UNDERMENTIONED
 VEHICLE TO LEAVE THE COMPANY PREMISES.

 DATE 15/08/2019
 TIME 18:08

 VEHICLE NO **PC7984J**

CUSTOMER

 SIGNATURE
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors

Co Reg No : 196700086Z
 GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail		Account No	Customer Detail	
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept		S1000004 / ICCUA1	M/S Breakthrough Missions Ltd 6 Eu Tong Sen Street #10-15 The Central Singapore 059817 Work: 64797756	
		Document No		
		0		
		Document Date		
		15/08/2019		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	LEPDYQ	A5	KDH223R	24/01/2019	PC7984J	0	47751 72/DS/PC7984J
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTFST22P000038308	1KD2829758	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc%	Amount
74	7	T52156-26010 L/RR BUMPER SUPPORT, X <i>MTT NAI</i>	1.00	40.40	15.00	34.34
75	8	T57069-26180 REAR OUTER FLR MEMBER, <i>OO</i>	1.00	459.90	15.00	390.91 ✓
76	9	T57068-26360 MEMBER SUB-ASSY, RH <i>OO</i>	1.00	1206.20	15.00	1025.27 ✓
77	0	T58312-26212 PANEL, RR FLOOR, RR <i>X</i>	1.00	1851.10	15.00	1573.43 ✓
78	1	T57048-26200 RAIL SUB-ASSY FLOOR <i>X</i>	1.00	238.30	15.00	202.55 ✓
79	2	T57067-26271 MEMBER SUB-ASSY, RR <i>X NAI</i>	1.00	859.90	15.00	730.91 X
80	3	T57024-26690 MEMBER SUB-ASSY, RR <i>X NAI</i>	1.00	960.50	15.00	816.42 X
81	4	T58152-26040 INSULATOR, FLOOR <i>X</i>	1.00	45.40	15.00	38.59
82	5	T58151-26101 INSULATOR, FLOOR <i>X</i>	1.00	119.50	15.00	101.57
83	6	T67935-26200 PLATE, BACK DOOR <i>X</i>	1.00	110.00	15.00	93.50 ✓
84	7	T67936-26040 B1 COVER, BACK DOOR <i>X</i>	1.00	11.90	15.00	10.11 X
85	8	T67937-26040 B1 COVER, BACK DOOR <i>X</i>	1.00	11.90	15.00	10.11 X
86	9	T58517-26A91 B2 MAT, RR FLOOR <i>X</i>	1.00	1651.40	15.00	1403.69 X
87	0	T58033-26230 BOARD SUB-ASSY, RR <i>X</i>	1.00	1678.00	15.00	1426.30 X
88	1	T90189-06057 GROMMET <i>X NAI</i>	10.00	2.60	15.00	22.10 X
89	2	T90467-07198 C0 CLIP <i>X NAI</i>	10.00	2.20	15.00	18.70 X
90	3	T64726-26010 B1 CLIP, LUGGAGE TRIM, <i>X NAI</i>	10.00	3.20	15.00	27.20 X
91	4	T61612-26560 PANEL, QUARTER <i>OO</i> (<i>odv</i>)	1.00	1517.30	15.00	1289.70 ✓
92	5	T61614-26C80 PANEL, QUARTER, <i>OO</i> (<i>inv</i>)	1.00	1427.10	15.00	1213.03 ✓
93	6	T61604-26020 PANEL SUB-ASSY, <i>X NAI</i>	1.00	390.60	15.00	332.01 X

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4043276

TO SECURITY GUARD

4043276

 PLEASE ALLOW THE UNDERMENTIONED
 VEHICLE TO LEAVE THE COMPANY PREMISES.

 DATE **15/08/2019**
 TIME **18:08**

 VEHICLE NO **PC7984J**

CUSTOMER

 SIGNATURE
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors

Co Reg No : 196700086Z
 GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail		Account No	Customer Detail	
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept		S1000004 / ICCUAI	M/S Breakthrough Missions Ltd 6 Eu Tong Sen Street #10-15 The Central Singapore 059817 Work: 64797756	
		Document No		
		0		
		Document Date		
		15/08/2019		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	LEPDYQ	A5	KDH223R	24/01/2019	PC7984J	0	47751 72/DS/PC7984J
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTFST22P000038308	1KD2829758	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc%	Amount
94	7	T61620-26200 FENDER ASSY, RR LH <i>DD X NAI</i>	1.00	343.40	15.00	291.89 <i>X</i>
95	8	T61072-26140 REINFORCEMENT S/A, <i>DD</i>	1.00	126.10	15.00	107.18 <i>✓</i>
96	9	T61746-26040 REINFORCEMENT, BACK <i>DD (CALL ME)</i>	1.00	289.10	15.00	245.73 <i>✓</i>
97	0	T61706-26280 FRAME SUB-ASSY, BACK <i>DD C1</i>	1.00	722.60	15.00	614.21 <i>✓</i>
98	1	T61636-26030 REINFORCEMENT, <i>X NAI</i>	1.00	161.30	15.00	137.10 <i>X</i>
99	2	T61802-26010 BRACKET SUB-ASSY, <i>X NAI</i>	1.00	72.40	15.00	61.54 <i>X</i>
100	3	T62206-26031 GLASS SUB-ASSY, RR <i>APC (Coda)</i>	1.00	550.00	15.00	467.50 <i>✓</i>
101	4	T21000-20 SIKA 182010 SIKA TACK GO! (BLA <i>APC</i>	1.00	108.00	15.00	91.80 <i>✓</i>
102	5	T21000-22 SIKA 207. G+P ADHESIVE PRIMER <i>APC</i>	1.00	200.00	15.00	170.00 <i>✓</i>
103	6	T62074-26013 GLASS SUB-ASSY, SIDE <i>(R) APC</i>	1.00	824.10	15.00	700.48 <i>✓</i>
104	7	T21000-20 SIKA 182010 SIKA TACK GO! (BLA <i>APC</i>	2.00	108.00	15.00	183.60 <i>✓</i>
105	8	T21000-22 SIKA 207. G+P ADHESIVE PRIMER <i>APC</i>	1.00	200.00	15.00	170.00 <i>✓</i>
106	9	T62930-52030 REAR AIR-DUCT ASSY, <i>MIS</i>	1.00	34.80	15.00	59.16 <i>✓</i>
107	0	T62632-26490 B1 BOARD, QUARTER TRIM, <i>X NAI</i>	1.00	165.50	15.00	140.67 <i>X</i>
108	1	L75867-33030 TRIM BOARD CLIPS, <i>X NAI</i>	10.00	10.80	15.00	91.80 <i>X</i>
109	2	T67005-26980 PANEL SUB-ASSY, BACK <i>DD (Tah4)</i>	1.00	2375.30	15.00	2019.00 <i>✓</i>
110	3	T67881-26103 RR BACK DOOR W/STRIP, <i>CR4</i>	1.00	474.90	15.00	403.66 <i>✓</i>
111	4	T68105-26091 REAR BACK DOOR GLASS, (W/WIPER) <i>APC</i>	1.00	1397.30	15.00	1187.70 <i>✓</i>
112	5	T21000-20 SIKA 182010 SIKA TACK GO! (BLA <i>APC</i>	2.00	108.00	15.00	183.60 <i>✓</i>
113	6	T21000-22 SIKA 207. G+P ADHESIVE PRIMER <i>APC</i>	1.00	200.00	15.00	170.00 <i>✓</i>

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4043277

TO SECURITY GUARD

4043277

 PLEASE ALLOW THE UNDERMENTIONED
 VEHICLE TO LEAVE THE COMPANY PREMISES.

 DATE 15/08/2019
 TIME 18:08

 VEHICLE NO **PC7984J**

CUSTOMER

 SIGNATURE
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors

Co Reg No : 196700086Z
 GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail		Account No	Customer Detail		
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept		S1000004 / ICCUAL	M/S Breakthrough Missions Ltd 6 Eu Tong Sen Street #10-15 The Central Singapore 059817 Work: 64797756		
		Document No			0
		Document Date			15/08/2019

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	LEPDYQ A5	KDH223R	24/01/2019	PC7984J	0	47751	72/DS/PC7984J
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTFST22P000038308	1KD2829758	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc%	Amount
114	7	T76881-26010 PROTECTOR, BACK DOOR X	1.00	11.60	15.00	9.86
115	8	T76882-26010 PROTECTOR, BACK DOOR X	1.00	11.60	15.00	9.86
116	9	T67837-26040 SEAL, DOOR DUST X	2.00	11.70	15.00	19.88
117	0	T76811-26160 BACK DOOR GARNISH X	1.00	142.80	15.00	121.38
118	1	T76825-26120 BACK DOOR PROTECTOR X	1.00	13.20	15.00	11.22
119	2	T76819-26020 SEAL, BACK DOOR X	2.00	3.90	15.00	6.62
120	3	T67751-26210 BACK DOOR BOARD TRIM X	1.00	180.40	15.00	153.34 X
121	4	T67771-26230 EO RETAINER, DOOR TRIM X	10.00	5.30	15.00	45.00 X
122	5	T69350-26122 REAR BACK DOOR LOCK ASSY, X	1.00	276.60	15.00	235.11 X
123	6	T69430-95J00 BACK DOOR LOCK STRIKER, X	1.00	98.60	15.00	83.81 X
124	7	T68950-26067 STAY ASSY, BACK DR RH X	1.00	338.60	15.00	287.81
125	8	T68960-26067 STAY ASSY, BACK DR LH X	1.00	338.60	15.00	287.81
126	9	T68810-26011 HINGE ASSY, BACK X	1.00	68.20	15.00	57.97
127	0	T68820-26011 HINGE ASSY, BACK X	1.00	68.20	15.00	57.97
128	1	T90975-02086 TOYOTA SYMBOL EMBLEM, X	1.00	72.20	15.00	61.37 X
129	2	T75441-26281 "TOYOTA HIACE" EMBLEM, X	1.00	48.60	15.00	41.31 X
130	3	T76626-26050 CO MUDGUARD, QUARTER X	1.00	110.50	15.00	93.92
131	4	T81551-26202 R/R COMBINATION LENS, X	1.00	367.60	15.00	312.46
132	5	T81561-26201 L/R COMBINATION LENS, X	1.00	306.40	15.00	260.44 X

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

61,515.07

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	61,500.83
	Please acknowledge receipt of vehicle	Parts 34,698.43 Labour 2,130.00 Materials 24,672.40 Lubrication/Fluid 0.00 Others 0.00	GST 7.00%	4,305.06
			Less	0.00
			Amount Due	65,805.89

PLEASE TEAR ALONG PERFORATED LINE

4043278

TO SECURITY GUARD

4043278

 PLEASE ALLOW THE UNDERMENTIONED
 VEHICLE TO LEAVE THE COMPANY PREMISES.

 DATE 15/08/2019
 TIME 18:08

 VEHICLE NO **PC7984J**

CUSTOMER

 SIGNATURE
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors

Inchope



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
 www.toyota.com.sg
 Toyota Bodycare Centre
 No. 2 Pandan Crescent
 Singapore 128462
 Tel no.: 6631 1188

Co Reg No : 196700086Z
 GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail		Account No	Customer Detail	
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept		S1000004 / ICCUA1	M/S Breakthrough Missions Ltd 6 Bu Tong Sen Street #10-15 The Central Singapore 059017	
		Document No	0	
		Document Date	19/10/2019	
		Work: 64797756		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	LEPDYQ	A5	KDH223R	24/01/2019	PC7984J	0	47751 72/DS/PC7984J
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTFST22P000038308	1KD2829758	60	Thomas Pang W T	20/08/2019	8.00	25/09/2019	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc%	Amount
1	Z	BP-SUNDRY TP INS: MSIG INSURANCE TP VEH: SLK2353T DATE OF ACC: 15.08.2019 BY:LKK-STEVE @ 20.08.2019 14 WORKING DAYS				50.00
2	S	BP-SUBLET SUPPLY JOINT PANEL SEALANT A45				200.00
3	S	BP-SUBLET DRILL HOLE AND INSTALL REVERSE SENSOR PO A45 :24102				180.00
4	S	BP-SUBLET CHECK WIRING AND CONDUCT WATER TEST PO: A45 24102				122.40
5	S	BP-SUBLET REMOVE AND TRANSFER TAILGATE COMPONENTS A45 ONTO NEW TAILGATE				360.00
6	S	BP-SUBLET R/I REAR REVERSE CAMERA TO FAC REPAIR A45				180.00
7	S	BP-SUBLET REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR A45				360.00
8	S	BP-SUBLET REPLACE TAILGATE GLASS A45				462.00
9	S	BP-SUBLET REPLACE LH REAR QUARTER GLASS A45				462.00
10	S	BP-SUBLET REPLACE ACC DAMAGED PARTS A45				5040.00
		AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS				
11	S	BP-SUBLET RESPRAY ACC AFFECTED AREAS A45				2950.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

4116189

PLEASE TEAR ALONG PERFORATED LINE

4116189

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 19/10/2019
TIME 09:25

VEHICLE NO PC7984J

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

inccape



Co Reg No : 196700086Z
 GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
 www.toyota.com.sg
 Toyota Bodycare Centre
 No. 2 Pandan Crescent
 Singapore 128462
 Tel no.: 6631 1188

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail		Account No	Customer Detail	
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept		S1000004 / ICCUA1	M/S Breakthrough Missions Ltd 6 Eu Tong Sen Street #10-15 The Central Singapore 059817	
		Document No		
		Document Date	19/10/2019	Work: 64797756

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	LEPDYQ	A5	KDH223R	24/01/2019	PC7984J	0	47751 72/DS/PC7984J
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTFST22P000038308	1KD2829758	60	Thomas Pang W T	20/08/2019	8.00	25/09/2019	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
12	S	BP-SUBLET REPLACE LH CENTRE GLASS				282.00
13	L	BP-LPO SUPPLY REGN PLATE (PO#24020)				80.00
14	L	BP-LPO SUPPLY ALUMINUM BAR AND TRIM BOARD PO:24 A25				2880.00
		133				
15	L	BP-LPO SUPPLY SOLAR FILM - TAILGATE GLASS				480.00
16	L	BP-LPO SUPPLY SOLAR FILM - LH REAR QUARTER GLA				480.00
		SS				
17	L	BP-LPO SUPPLY SOLAR FILM - LH CENTER GLASS				350.00
18	Z	BP-SUNDRY SUPPLY STICKER 70KM/H				50.00
19	B	BP-MECH2 CONDUCT FULL WHEEL ALIGNMENT	18			180.00
20	B	BP-ECU2 TO RESET ECU AND REPROGRAMME	18			180.00
21	Z	BP-SUNDRY SUPPLY COMPANY STICKER, WORDING, CONTACT				150.00
		AND ETC..				
22	Z	TW TOWING CHARGES				120.00
23	1	TREVESE-CLG04 FMS 4 POINT REVERSE SENSOR	1.00	79.90	15.00	67.91
24	2	T08826-08115 PANEL BONDING AD	1.00	267.20	15.00	227.12
25	3	T51903-26661 CARRIER SUB-ASSY	1.00	293.30	15.00	249.30
26	4	T90119-12261 BOLT, W/WASHER	1.00	17.70	15.00	15.04
27	5	T51907-26030 STOPPER SUB-ASSY,	1.00	35.00	15.00	29.75
28	6	T51938-44010 LOCK, SPARE WHEEL	1.00	24.80	15.00	21.08

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

4116190

PLEASE TEAR ALONG PERFORATED LINE

4116190

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
 VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 19/10/2019
 TIME 09:25

VEHICLE NO PC7984J


CUSTOMER

SIGNATURE
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

incscope



Co Reg No : 196700086Z
 GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd Page 2 of 5

Online Service Booking :
 www.toyota.com.sg
 Toyota Bodycare Centre
 No. 2 Pandan Crescent
 Singapore 128462
 Tel no.: 6631 1188

Account Detail	Account No S1000004 / ICCU1	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	Document No 0	M/S Breakthrough Missions Ltd 6 Eu Tong Sen Street #10-15 The Central Singapore 059817
	Document Date 19/10/2019	Work: 64797756

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	LEPDYQ	A5	KDH223R	24/01/2019	PC7984J	0	47751 72/DS/PC7984J
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTF8T22P000038308	1KD2829758	60	Thomas Pang W T	20/08/2019	8.00	25/09/2019	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
29	7	T51915-26030	BASE, SPARE WHEEL	1.00	26.00	15.00	22.10
30	8	T90467-08056 CO	CLIP	10.00	2.90	15.00	24.60
31	9	T52159-26530	COVER, RR BUMPER	1.00	430.90	15.00	366.26
32	0	T90159-60497	SCREW, W/WASHER	1.00	2.20	15.00	1.87
33	1	T90189-06228	GROMMET SCREW	4.00	2.10	15.00	7.12
34	2	T90467-09185	CLIP	10.00	2.80	15.00	23.80
35	3	T52157-26010	SUPPORT, RR BUMPER	1.00	23.40	15.00	19.89
36	4	T52158-26010	SUPPORT, RR BUMPER	1.00	23.40	15.00	19.89
37	5	T58385-26070	BRACKET, RR BUMPER	4.00	26.00	15.00	88.40
38	6	T52166-26040 AO	L/REAR TOP BUMPER COVER	1.00	93.90	15.00	79.81
39	7	T52156-26010	SUPPORT, RR BUMPER LH	1.00	40.40	15.00	34.34
40	8	T57069-26180	MEMBER SUB-ASSY, LH	1.00	459.90	15.00	390.91
41	9	T57068-26360	MEMBER SUB-ASSY, RH	1.00	1206.20	15.00	1025.27
42	0	T57048-26200	RAIL SUB-ASSY FLOOR	1.00	238.30	15.00	202.55
43	1	T61612-26560	PANEL, QUARTER	1.00	1517.30	15.00	1289.70
44	2	T61614-26C80	PANEL, QUARTER,	1.00	1427.10	15.00	1213.03
45	3	T61072-26140	REINFORCEMENT S/A,	1.00	126.10	15.00	107.18
46	4	T61746-26040	REINFORCEMENT, BACK	1.00	289.10	15.00	245.73
47	5	T61706-26280	FRAME SUB-ASSY, BACK	1.00	722.60	15.00	614.21
48	6	T62206-26031	GLASS SUB-ASSY, RR	1.00	550.00	15.00	467.50

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 5 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature Please acknowledge receipt of vehicle	Change Summary Parts Labour Materials Lubrication/Fluid Others	Total
			Less
			Amount Due

4116191

PLEASE TEAR ALONG PERFORATED LINE

4116191

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
 VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 19/10/2019
 TIME 09:25

VEHICLE NO PC7984J

CUSTOMER

SIGNATURE
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

incape



Co Reg No : 196700086Z
 GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd Page 2 of 5

Online Service Booking:
www.toyota.com.sg
 Toyota Bodycare Centre
 No. 2 Pandan Crescent
 Singapore 128462
 Tel no.: 6631 1188

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail		Account No S1000004 / ICCUA1	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept		Document No 0	M/S BREAKTHROUGH MISSIONS LTD 6 Eu Tong Sen Street #10-15 The Central Singapore 059817 Work: 64797756
		Document Date 19/10/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	LEPDYQ	A5	KDH223R	24/01/2019	PC7984J	0	47751 72/DS/PC7984J

Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On
JTFST22P000038308	1KD2829758	60	Thomas Pang W T	20/08/2019	8.00 25/09/2019 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
49	7	T21000-20 SIKA 210002-0 TACK GOI (BLACK) SG	1.00	108.00	15.00	91.80
50	8	T21000-22 SIKA 210002-2 G+P 207 ADHESIVE PRIM	1.00	200.00	15.00	170.00
51	9	T62074-26013 GLASS SUB-ASSY, SIDE	1.00	824.10	15.00	700.48
52	0	T21000-20 SIKA 210002-0 TACK GOI (BLACK) SG	2.00	108.00	15.00	183.60
53	1	T21000-22 SIKA 210002-2 G+P 207 ADHESIVE PRIM	1.00	200.00	15.00	170.00
54	2	T62930-52030 DUCT ASSY, QUARTER	2.00	34.80	15.00	59.16
55	3	T67005-26880 PANEL SUB-ASSY, BACK	1.00	2375.30	15.00	2019.00
56	4	T68105-26091 GLASS, BACK DOOR	1.00	1397.30	15.00	1187.70
57	5	T21000-20 SIKA 210002-0 TACK GOI (BLACK) SG	2.00	108.00	15.00	183.60
58	6	T21000-22 SIKA 210002-2 G+P 207 ADHESIVE PRIM	1.00	200.00	15.00	170.00
59	7	T69350-26122 LOCK ASSY, BACK DOOR	1.00	276.60	15.00	235.11
60	8	T90975-02086 EMBLEM, SYMBOL	1.00	72.20	15.00	61.37
61	9	T75441-26281 PLATE, LUGGAGE	1.00	48.60	15.00	41.31
62	0	T81561-26201 LENS, RR COMB LH	1.00	306.40	15.00	260.44
63	1	T90202-13066 WASHER, PLATE	1.00	4.70	15.00	3.99
64	2	T90202-13066 WASHER, PLATE	1.00	4.70	15.00	3.99
65	3	T67935-26200 PLATE, BACK DOOR	1.00	110.00	15.00	93.50
66	4	T90159-60497 SCREW, W/WASHER	1.00	2.20	15.00	1.87
67	5	T90202-13066 WASHER, PLATE	1.00	4.70	15.00	3.99
68	6	T51915-26030 BASE, SPARE WHEEL	1.00	26.00	15.00	22.10

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

4116192

PLEASE TEAR ALONG PERFORATED LINE

4116192

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 19/10/2019
 TIME 09:25

VEHICLE NO PC7984J

CUSTOMER

SIGNATURE
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
 GST Reg No : MR-8500000-9

ESTIMATE

Online Service Booking :
 www.toyota.com.sg
 Toyota Bodycare Centre
 No. 2 Pandan Crescent
 Singapore 128462
 Tel no.: 6631 1198

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No S1000004 / ICCUA1	Customer Detail
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SQX Centre 2 Singapore 068807 Attn: Motor Claims Dept.	Document No 0	M/S Breakthrough Missions Ltd 6 Eu Tong Sen Street #10-15 The Central Singapore 059817
	Document Date 19/10/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	LEPDYQ	A5	KDH223R	24/01/2019	PC7984J	0	47751 72/DS/PC7984J

Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On
JTFST22P000038308	1KD2829758	60	Thomas Pang W T	20/08/2019 8.00	25/09/2019 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
69	7	T90159-60497 SCREW, W/WASHER	1.00	2.20	15.00	1.87
70	8	T90202-13066 WASHER, PLATE	1.00	4.70	15.00	3.99
71	9	T90159-60497 SCREW, W/WASHER	1.00	2.20	15.00	1.87
72	0	T67881-26103 RR BACK DOOR W/STRIP,	1.00	474.90	15.00	403.66
73	1	T90189-06228 GROMMET SCREW	8.00	2.10	15.00	14.24

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature Please acknowledge receipt of vehicle	Change Summary	Total	28,541.40
		Parts 12,943.00	GST 7.00%	1,997.90
		Labour 730.00	Less	0.00
		Materials 14,868.40		
		Lubrication/Fluid 0.00		
		Others 0.00	Amount Due	30,539.30

4116193

PLEASE TEAR ALONG PERFORATED LINE

4116193

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 19/10/2019
 TIME 09:25

VEHICLE NO PC7984J

CUSTOMER

SIGNATURE
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 21 October 2019 10:46 AM
To: Thomas Pang PTCBC; Steve; SUR
Subject: RE: Finalize Report for PC7984J

Dear Thomas,

WITHOUT PREJUDICE

Confirmed amount \$28,541.40 before GST @ 14 working days.

Kindly send Final invoice and all supporting documents directly to MSIG INSURANCE

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Thomas Pang PTCBC <Thomas.Pang@borneomotors.com.sg>
Sent: Saturday, 19 October 2019 9:40 AM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Steve <steve@blomteq.com>; SUR <sur@lkkauto.com>
Subject: Finalize Report for PC7984J

Hi,

Attach finalize report for your perusal. 14 working days.

Thank you

Regards

Thomas

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Aug 2019		20 Aug 2019 16:07 Edit Adj Rpt	S\$28,541.40 Edit Estimates	S\$28,541.40 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	CHANG SIEH YONG , ID: S1482594J, Tel: +6597975634, Email: CSY@ISPL.COM.SG								
Main Claimant:	BREAKTHROUGH MISSIONS LTD , Co. Reg. No.: 198305430G								
Vehicle Reg. No.:	PC7984J	Date of Loss:	15/08/2019 07:00 - :59 [6 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 603017	Policy/Cover Note No.:	A28881428QMY (Comprehensive) Coverage: 10/01/2019 - 09/01/2020						
Vehicle Reg. No. (Insured):	SLK2353T	Policy No. (Claimant):							
		Excess:	S\$800.00						
Repairer:	Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong - 6594 2544]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 19/09/2019]								
Driver/Custodian (Insured):	CHANG SIEH YONG (58 / Male), NRIC: S1482594J, Tel: +6597975634 Email: CSY@ISPL.COM.SG								
Adj Ass. Remarks:	on WP. CAR IN. Liab: 100%. Contact: Thomas Pang @ 9847 6171 / 6631 1860, Manual assign to LKK via email on 19/08/2019.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*PC7984J (603017)
[SLK2353T]
TP
BREAKTHROUGH MISSIONS LTD
Aug 15 2019 7:00AM
[CHANG SIEH YONG]
Borneo Motors (S) Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser v
Assessment Reports				1 per page v <input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail Print
1	20/08/19 15:06	Accident Statement <small>From: 00 - Reg. No: SLK2353T, Claimant: CHANG SIEH YONG</small>		Load HTML
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	21/08/19 10:51	Adjuster Immediate Advice		Load HTML
Photos/Images				3 per page v <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	20/08/19 18:43	General View		Load JPG <input checked="" type="checkbox"/>
2	20/08/19 18:43	General View		Load JPG <input checked="" type="checkbox"/>
3	20/08/19 18:43	General View		Load JPG <input checked="" type="checkbox"/>
4	20/08/19 18:43	General View		Load JPG <input checked="" type="checkbox"/>
5	20/08/19 18:43	General View		Load JPG <input checked="" type="checkbox"/>
6	20/08/19 18:43	General View		Load JPG <input checked="" type="checkbox"/>
7	20/08/19 18:43	General View		Load JPG <input checked="" type="checkbox"/>
8	20/08/19 18:43	General View		Load JPG <input checked="" type="checkbox"/>
9	20/08/19 18:43	General View		Load JPG <input checked="" type="checkbox"/>
10	20/08/19 18:43	General View		Load JPG <input checked="" type="checkbox"/>
11	20/08/19 18:43	General View		Load JPG <input checked="" type="checkbox"/>
12	20/08/19 18:43	General View		Load JPG <input checked="" type="checkbox"/>
13	20/08/19 18:43	General View		Load JPG <input checked="" type="checkbox"/>
14	20/08/19 18:43	General View		Load JPG <input checked="" type="checkbox"/>
15	20/08/19 18:43	Odometer Reading		Load JPG <input checked="" type="checkbox"/>
16	20/08/19 18:43	Chassis Number		Load JPG <input checked="" type="checkbox"/>
17	20/08/19 18:43	General View		Load JPG <input checked="" type="checkbox"/>
18	20/08/19 18:43	General View		Load JPG <input checked="" type="checkbox"/>
19	20/08/19 18:43	General View		Load JPG <input checked="" type="checkbox"/>
20	20/08/19 18:43	General View		Load JPG <input checked="" type="checkbox"/>
21	20/08/19 18:43	General View		Load JPG <input checked="" type="checkbox"/>
22	20/08/19 18:43	General View		Load JPG <input checked="" type="checkbox"/>
23	20/08/19 18:43	General View		Load JPG <input checked="" type="checkbox"/>
24	20/08/19 18:43	General View		Load JPG <input checked="" type="checkbox"/>
25	20/08/19 18:43	General View		Load JPG <input checked="" type="checkbox"/>
26	20/08/19 18:43	General View		Load JPG <input checked="" type="checkbox"/>
27	20/08/19 18:43	General View		Load JPG <input checked="" type="checkbox"/>
28	20/08/19 18:43	General View		Load JPG <input checked="" type="checkbox"/>
29	20/08/19 18:43	General View		Load JPG <input checked="" type="checkbox"/>
30	20/08/19 18:43	General View		Load JPG <input checked="" type="checkbox"/>
31	20/08/19 18:43	General View		Load JPG <input checked="" type="checkbox"/>
32	20/08/19 18:43	General View		Load JPG <input checked="" type="checkbox"/>
33	20/08/19 18:43	General View		Load JPG <input checked="" type="checkbox"/>
34	20/08/19 18:43	General View		Load JPG <input checked="" type="checkbox"/>
35	20/08/19 18:43	General View		Load JPG <input checked="" type="checkbox"/>
36	20/08/19 18:43	General View		Load JPG <input checked="" type="checkbox"/>
37	20/08/19 18:43	General View		Load JPG <input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
38	20/08/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
39	20/08/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
40	20/08/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
41	20/08/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
42	20/08/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
43	20/08/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
44	20/08/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
45	20/08/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
46	20/08/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
47	20/08/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
48	20/08/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
49	20/08/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
50	20/08/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
51	20/08/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
52	20/08/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
53	20/08/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
54	20/08/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
55	20/08/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
56	20/08/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
57	20/08/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
58	20/08/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
59	20/08/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
60	20/08/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
61	20/08/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
62	20/08/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
63	20/08/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
64	20/08/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
65	20/08/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
66	20/08/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
67	20/08/19 18:43	General View	Load JPG	<input checked="" type="checkbox"/>
68	21/10/19 09:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
69	21/10/19 09:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
70	21/10/19 09:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
71	21/10/19 09:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
72	21/10/19 09:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
73	21/10/19 09:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
74	21/10/19 09:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
75	21/10/19 09:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
76	21/10/19 09:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
77	21/10/19 09:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
78	21/10/19 09:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
79	21/10/19 09:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	20/08/19 15:06	TP GIA Report - PC7984J <small>From: OD - Reg. No: SLK2353T, Claimant: CHANG STEH YONG</small>	Load PDF	
2	20/08/19 15:15	Estimate	Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	20/08/19 16:03	Survey Request - Manual Assigned	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19014580/EVD3E2
Date: 29/10/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A28881428QMY
Claimant		
Vehicle No : PC7984J	Insured Vehicle No :	SLK2353T
Date of Loss: 15/08/2019	Nature of Claim:	TP
		Claim No: 603017

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC7984J		
Make & Model:	TOYOTA HIACE, 2.5 (M)	Engine No:	1KD2829758
Reg. Date:	24/01/2019 (Man. Year: 2018)	Chassis No:	JTFST22P000038308
Colour:	White	Odometer:	9283 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	37,992.67	16,073.00	21,919.67	57.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	23,522.40	12,468.40	11,054.00	46.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	61,515.07	28,541.40	32,973.67	53.60
+ GST 7.00/7.00% (S\$)	4,306.05	1,997.90	2,308.15	53.60
Nett Amount (S\$)	65,821.12	30,539.30	35,281.82	53.60

INSPECTION

Date of Assignment:	20/08/2019	
Date Inspected:	20/08/2019	Inspected At:
		Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent Singapore 128462
Estimated Period of Repair:	14.0 days	

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 29 Oct 2019)	
Parts:	N/A	TOYOTA HIACE 2.5 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC7984J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*JOINT PANEL SEALANT	Necessary	300.00 FS	*200.00 FS
2	1		*ALUMINUM BAR AND TRIM BOARD	Dented	2,880.00 FS	*2,880.00 FS
3	1		*4 P REVERSE KDH223	Broken	67.91 FS	*67.91 FS
4	1		*RUBBER FLOORMAT	Not Necessary	196.59 FS	*- FS
5	1		*PANEL BONDING AD	Necessary	227.12 FS	*227.12 FS
6	1		*REAR FLOOR SHEET	Not Necessary	176.20 FS	*- FS
7	1		*HOUSING ASSY, RR	Not Necessary	2,268.48 FS	*- FS
8	1		*GASKET, DIFFERENTIAL	Not Necessary	15.30 FS	*- FS
9	2		*GASKET, PLUG	Not Necessary	3.40 FS	*- FS
10	1		*GASKET KIT	Not Necessary	107.52 FS	*- FS
11	1		*CARRIER ASSY	Not Necessary	3,974.68 FS	*- FS
12	2		*SHAFT, RR AXLE	Not Necessary	1,512.82 FS	*- FS
13	2		*BEARING, RADIAL	Not Necessary	325.54 FS	*- FS
14	2		*CASE, RR AXLE	Not Necessary	270.30 FS	*- FS
15	2		*GASKET, BRAKE DRUM	Not Necessary	10.20 FS	*- FS
16	2		*DEFLECTOR GASKET	Not Necessary	5.94 FS	*- FS
17	6		*BOLT, HUB	Not Necessary	64.26 FS	*- FS
18	2		*RING, O	Not Necessary	17.34 FS	*- FS
19	2		*SEAL	Not Necessary	43.86 FS	*- FS
20	1		*WHEEL, DISC	Not Necessary	374.76 FS	*- FS
21	2		*ABSORBER ASSY, RR	Not Necessary	216.74 FS	*- FS
22	2		*SEAT SUB-ASSY, RR	Not Necessary	244.46 FS	*- FS
23	4		*BOLT	Not Necessary	186.64 FS	*- FS
24	4		*NUT, FLANGE	Not Necessary	11.56 FS	*- FS
25	4		*BOLT, FLANGE	Not Necessary	40.80 FS	*- FS
26	2		*BUMPER, RR SPRING	Not Necessary	217.42 FS	*- FS
27	2		*SHACKLE KIT, RR	Not Necessary	364.64 FS	*- FS
28	4		*BUSH	Not Necessary	27.88 FS	*- FS
29	4		*BOLT, FLANGE	Not Necessary	47.24 FS	*- FS
30	2		*DAMPER, LEAF SPRING	Not Necessary	198.72 FS	*- FS
31	2		*SPRING ASSY, RR	Not Necessary	1,939.18 FS	*- FS
32	1		*CARRIER SUB-ASSY	Missing	249.30 FS	*249.30 FS
33	1		*BOLT, W/WASHER	Missing	15.04 FS	*15.04 FS
34	4		*WASHER, PLATE	Missing	15.96 FS	*15.96 FS
35	1		*STOPPER SUB-ASSY	Missing	29.75 FS	*29.75 FS
36	1		*LOCK, SPARE WHEEL	Missing	21.08 FS	*21.08 FS
37	2		*BASE, SPARE WHEEL	Missing	44.20 FS	*44.20 FS
38	10		*CLIP	Necessary	24.60 FS	*24.60 FS
39	1		*COVER, RR BUMPER	Missing	366.26 FS	*366.26 FS
40	4		*SCREW, W/WASHER	Necessary	7.48 FS	*7.48 FS
41	12		*GROMMET	Necessary	21.36 FS	*21.36 FS
42	10		*CLIP	Necessary	23.80 FS	*23.80 FS
43	1		*R/R SIDE BPR RETAINER	Broken	19.89 FS	*19.89 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*L/R SIDE BPR RETAINER	Broken	19.89 FS	*19.89 FS
45	4		*REAR BUMPER BRACKET	Dented	88.40 FS	*88.40 FS
46	1		*R/REAR TOP BUMPER COVER	Missing	79.81 FS	*79.81 FS
47	1		*R/RR BUMPER SUPPORT	Missing	34.34 FS	*34.34 FS
48	1		*L/REAR TOP BUMPER COVER	Not Necessary	79.81 FS	*- FS
49	1		*L/RR BUMPER SUPPORT	Not Necessary	34.34 FS	*- FS
50	1		*MEMBER SUB-ASSY, RH	Dented	1,025.27 FS	*1,025.27 FS
51	1		*PANEL, RR FLOOR, RR	Repair	1,573.43 FS	*- FS
52	1		*RAIL SUB-ASSY FLOOR	Dented	202.55 FS	*202.55 FS
53	1		*MEMBER SUB-ASSY, RR	Not Necessary	730.91 FS	*- FS
54	1		*MEMBER SUB-ASSY, RR	Not Necessary	816.42 FS	*- FS
55	1		*INSULATOR, FLOOR	Not Necessary	38.59 FS	*- FS
56	1		*INSULATOR, FLOOR	Not Necessary	101.57 FS	*- FS
57	1		*PLATE, BACK DOOR	Dented	93.50 FS	*93.50 FS
58	1		*COVER, BACK DOOR	Not Necessary	10.11 FS	*- FS
59	1		*COVER, BACK DOOR	Not Necessary	10.11 FS	*- FS
60	1		*MAT, RR FLOOR	Not Necessary	1,403.69 FS	*- FS
61	1		*BOARD SUB-ASSY RR	Not Necessary	1,426.30 FS	*- FS
62	10		*GROMMET	Not Necessary	22.10 FS	*- FS
63	10		*CLIP	Not Necessary	18.70 FS	*- FS
64	10		*CLIP, LUGGAGE TRIM	Not Necessary	27.20 FS	*- FS
65	1		*PANEL, QUARTER (OUTER)	Dented	1,289.70 FS	*1,289.70 FS
66	1		*PANEL, QUARTER (INNER)	Dented	1,213.03 FS	*1,213.03 FS
67	1		*PANEL SUB-ASSY	Not Necessary	332.01 FS	*- FS
68	1		*FENDER ASSY, RR LH	Not Necessary	291.89 FS	*- FS
69	1		*REINFORCEMENT S/A	Dented	107.18 FS	*107.18 FS
70	1		*REINFORCEMENT, BACK	Dented	245.73 FS	*245.73 FS
71	1		*FRAME SUB-ASSY, BACK	Dented	614.21 FS	*614.21 FS
72	1		*REINFORCEMENT	Not Necessary	137.10 FS	*- FS
73	1		*BRACKET SUB-ASSY	Not Necessary	61.54 FS	*- FS
74	1		*GLASS SUB-ASSY, RR	Necessary	467.50 FS	*467.50 FS
75	1		*SIKA 182010 SIKA TACK GO! (BLA	Necessary	91.80 FS	*91.80 FS
76	1		*SIKA 207. G+P ADHESIVE PRIMER	Necessary	170.00 FS	*170.00 FS
77	1		*GLASS SUB-ASSY, SIDE	Necessary	700.48 FS	*700.48 FS
78	2		*SIKA 182010 SIKA TACK GO! (BLA	Necessary	183.60 FS	*183.60 FS
79	1		*SIKA 207. G+P ADHESIVE PRIMER	Necessary	170.00 FS	*170.00 FS
80	2		*REAR AIR-DUCT ASSY	Missing	59.16 FS	*59.16 FS
81	1		*BOARD, QUARTER TRIM	Not Necessary	140.67 FS	*- FS
82	10		*TRIM BOARD CLIPS	Not Necessary	91.80 FS	*- FS
83	1		*PANEL SUB-ASSY, BACK	Dented	2,019.00 FS	*2,019.00 FS
84	1		*RR BACK DOOR W/STRIP	Crushed	403.66 FS	*403.66 FS
85	1		*REAR BACK DOOR GLASS, (W/WIPER)	Necessary	1,187.70 FS	*1,187.70 FS
86	2		*SIKA 182010 SIKA TACK GO! (BLA	Necessary	183.60 FS	*183.60 FS
87	1		*SIKA 207. G+P ADHESIVE PRIMER	Necessary	170.00 FS	*170.00 FS
88	1		*PROTECTOR, BACK DOOR	Not Necessary	9.86 FS	*- FS
89	1		*PROTECTOR, BACK DOOR	Not Necessary	9.86 FS	*- FS
90	2		*SEAL, DOOR DUST	Not Necessary	19.88 FS	*- FS
91	1		*BACK DOOR GARNISH	Not Necessary	121.38 FS	*- FS
92	1		*BACK DOOR PROTECTOR	Not Necessary	11.22 FS	*- FS
93	2		*SEAL, BACK DOOR	Not Necessary	6.62 FS	*- FS
94	1		*BACK DOOR BOARD TRIM	Not Necessary	153.34 FS	*- FS
95	10		*RETAINER, DOOR TRIM	Not Necessary	45.00 FS	*- FS
96	1		*REAR BACK DOOR LOCK ASSY	Dented	235.11 FS	*235.11 FS
97	1		*BACK DOOR LOCK STRIKER	Not Necessary	83.81 FS	*- FS
98	1		*STAY ASSY, BACK DR RH	Not Necessary	287.81 FS	*- FS
99	1		*STAY ASSY, BACK DR LH	Not Necessary	287.81 FS	*- FS
100	1		*HINGE ASSY, BACK	Not Necessary	57.97 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
101	1		*HINGE ASSY, BACK	Not Necessary	57.97 FS	*- FS
102	1		*TOYOTA SYMBOL EMBLEM	Necessary	61.37 FS	*61.37 FS
103	1		*TOYOTA HIACE EMBLEM	Necessary	41.31 FS	*41.31 FS
104	1		*MUDGUARD, QUARTER	Not Necessary	93.92 FS	*- FS
105	1		*R/R COMBINATION LENS	Not Necessary	312.46 FS	*- FS
106	1		*L/R COMBINATION LENS	Cut	260.44 FS	*260.44 FS
107	1		*SUNDRY	Necessary	100.00 FS	*50.00 FS
108	1		*REAR OUTER FLR MEMBER	Dented	390.91 FS	*390.91 FS
Total Parts (S\$)					37,992.67	16,073.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DRILL HOLE AND INSTALL REVERSE SENSOR	New	180.00	180.00
2	CHECK WIRING AND CONDUCT WATER TEST	New	122.40	122.40
3	REMOVE AND TRANSFER TAILGATE COMPONENTS ONTO NEW TAILGATE	New	360.00	360.00
4	R/I REAR REVERSE CAMERA TO FAC REPAIR	New	180.00	180.00
5	REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR	New	720.00	360.00
6	REPLACE TAILGATE GLASS	New	462.00	462.00
7	REPLACE LH REAR QUARTER GLASS	New	462.00	462.00
8	CONDUCT COMPUTERISED CHASSIS ALIGNMENT	New	1,710.00	0.00
9	REPLACE REAR UNDER CARRIAGE	New	1,440.00	0.00
10	REPLACE REAR EXHAUST PIPE SYSTEM	New	360.00	0.00
11	REPLACE ACC DAMAGED PARTS AND STRAIGHTEN / REALIGN ACC AFFECTED AREAS	New	7,200.00	5,040.00
12	RESPRAY ACC AFFECTED AREAS	New	5,900.00	2,950.00
13	REPLACE LH CENTRE GLASS	New	282.00	282.00
14	SUPPLY REGN PLATE (PO#)	New	80.00	80.00
15	SUPPLY SOLAR FILM - TAILGATE GLASS	New	480.00	480.00
16	SUPPLY SOLAR FILM - LH REAR QUARTER GLASS	New	480.00	480.00
17	SUPPLY SOLAR FILM - LH CENTER GLASS	New	350.00	350.00
18	SUPPLY STICKER 70KM/H	New	50.00	50.00
19	CONDUCT FULL WHEEL ALIGNMENT	New	180.00	180.00
20	TO RESET ECU AND REPROGRAMME	New	180.00	180.00
21	SUPPLY COMPANY STICKER, WORDING, CONTACT AND ETC...	New	1,500.00	150.00
22	TOWING CHARGES	New	120.00	120.00
23	REPLACE SPARE RIM / TYRE AND BALANCING	New	144.00	0.00
24	SUPPLY TYRE	New	580.00	0.00
Gross Labour Cost (S\$)			23,522.40	12,468.40

Report was unsubmitted during this print-out.

< END OF ESTIMATES >