

LIAN HENG PAINTER COMPANY

160 Sin Ming Drive #06-10
Sin Ming AutoCity (S) 575722
Tel: 6453 5779

Vehicle No: E9A

Model: Lexus LX570

Chassis No: JTJHY00W104174472

Claim Type: OD

Date: 19.08.2019

1	Front bumper	1	\$	420.00
2	Front bumper number plate base	1	\$	62.00
3	Front bumper centre grille	1	\$	180.00
4	Front bumper retainer LH/RH	2	\$	29.00
5	Front bumper centre beam	1	\$	60.00
6	Front bumper absorber	1	\$	60.00
7	Front bumper reinforcement	1	\$	280.00
8	Radiator grille	1	\$	480.00
9	Radiator grille base	1	\$	40.00
10	Radiator emblem	1	\$	504.00
11	Radiator grille seal	1	\$	14.00
12	Bonnet	1	\$	780.00
13	Bonnet hook	1	\$	47.00
14	Bonnet lock	1	\$	47.00
15	Headlamp LH/RH	2	\$	1,885.00
16	Radiator support panel	1	\$	800.00
17	Radiator deflector LH/RH	2	\$	77.00
18	Brace panel	1	\$	154.00
19	Oil cooler	1	\$	48.00
20	Aircon condenser	1	\$	585.00
21	Aircon fan assy	1	\$	740.00
22	Radiator	1	\$	497.00
23	Radiator fan shroud	1	\$	1,380.00
24	Radiator fan blade	1	\$	106.00
25	Radiator fan motor	1	\$	123.00
				\$ 380.00
Total:				\$ 11,615.00
Plus 20%				\$ 2,323.00
List total:				\$ 13,938.00
				\$ 50.00
				\$ 50.00
				\$ 50.00
				\$ 30.00
				\$ 40.00
				\$ 975.66
S.Nett total:				\$ 1,195.66

Parts Total: \$ 15,133.66

- 1 Rust proofing on affected area. \$ 60.00
- 2 To check lightings & wirings. Reset fault codes & programme all related. \$ 80.00

- 3 Renew aircon condenser, refill gas R134.
- 4 Renew intercooler & radiator. Depressurise & conduct cooling test.
- 5 To remove and renew damaged parts. Re-align all affected area.
- 6 To putty and respray all damaged parts. Touch up all affected area.

\$	200.00
\$	150.00
\$	1,500.00
\$	1,800.00

Labour Total: \$ 3,790.00

Grand Total: \$ 18,923.66

Remarks

This is only an estimate based on visual inspection. Should there be further damages found during process of repair, you will be informed prior before we carry out further repairs.

聯興噴漆公司
LIAN HENG PAINTER CO.,
 160 SIN MING DRIVE, #06-10
 SIN MING AUTOCITY
 SINGAPORE 575722
 TEL: 6453 5779 FAX: 6453 3173



Lian Heng Painter Company