

LIAN HENG PAINTER COMPANY

160 Sin Ming Drive #06-10
Sin Ming AutoCity (S) 575722
Tel: 6453 5779

Vehicle No: E9A
Model: Lexus LX570
Chassis No: JTJHY00W104174472
Claim Type: OD

Date: 19.08.2019

1	Front bumper	CRA	1			\$	420.00
2	Front bumper number plate base	X NH	1			\$	62.00
3	Front bumper centre grille	DR	1			\$	180.00
4	Front bumper retainer LH/RH		2	N/S NH O/S DR	\$ 29.00	\$	58.00
5	Front bumper centre beam	BT	1			\$	60.00
6	Front bumper absorber	CRA	1			\$	60.00
7	Front bumper reinforcement	?	1			\$	280.00
8	Radiator grille	BR	1			\$	480.00
9	Radiator grille base	?	1			\$	40.00
10	Radiator emblem	SCR	1			\$	504.00
11	Radiator grille seal	?	1			\$	14.00
12	Bonnet	BUC	1			\$	780.00
13	Bonnet hook	X NH	1			\$	47.00
14	Bonnet lock	X NH	1			\$	47.00
15	Headlamp LH/RH		2	N/S ? O/S BR	\$ 1,885.00	\$	3,770.00
16	Radiator support panel	X R	1			\$	800.00
17	Radiator deflector LH/RH	?	2		\$ 77.00	\$	154.00
18	Brace panel	?	1			\$	48.00
19	Oil cooler	?	1			\$	585.00
20	Aircon condenser	?	1			\$	740.00
21	Aircon fan assy	?	1			\$	497.00
22	Radiator	?	1			\$	1,380.00
23	Radiator fan shroud	?	1			\$	106.00
24	Radiator fan blade	?	1			\$	123.00
25	Radiator fan motor	?	1			\$	380.00

Bonnet Hinge x2 BT

Total: \$ 11,615.00
Plus 20% \$ 2,323.00
List total: \$ 13,938.00

1	Front number plate	CRA	1			\$	50.00
2	Front bumper clips	NEL	1set			\$	50.00
3	Radiator support top cover clips	NEL	1set			\$	50.00
4	Bonnet insulator clips	NEL	1set			\$	30.00
5	Radiator coolant	?	1			\$	40.00
6	GST 7% of parts		1			\$	975.66

S.Nett total: \$ 1,195.66

Parts Total: \$ 15,133.66

- 1 Rust proofing on affected area.
- 2 To check lightings & wirings. Reset fault codes & programme all related.

NH x \$ 60.00
30 \$ 80.00

3	Renew aircon condenser, refill gas R134.	\$	200.00 ?
4	Renew intercooler & radiator. Depressurise & conduct cooling test.	\$	150.00 ?
5	To remove and renew damaged parts. Re-align all affected area.	400 \$	1,500.00
6	To putty and respray all damaged parts. Touch up all affected area.	600 \$	1,800.00

Labour Total: \$ 3,790.00

Grand Total: \$ 18,923.66

Remarks

This is only an estimate based on visual inspection. Should there be further damages found during process of repair, you will be informed prior before we carry out further repairs.

聯興噴漆公司
LIAN HENG PAINTER CO.,
160 SIN MING DRIVE, #06-10
SIN MING AUTOCITY
SINGAPORE 575722
TEL: 6453 5779 FAX: 6453 3173

Lian Heng Painter Company

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: