

WENG KEE MOTOR

REPAIR ESTIMATE

VEHICLE: GZ 8820 C
MODEL: Nissan NV200

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- To apply 27-08-2019 "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: 27-08-2019

S/n	Description of part	Qty	Estimate
1	Rear bumper / CUT	1	
2	Rear bumper side bracket LH/RH / BR	2	70.60
3	Rear tailgate LH / DD	1	1,281.90
4	Rear tailgate RH / DD	1	960.90
5	Rear tailgate RH rubber stripe X	1	122.30
6	Rear tailgate LH garnish X	1	336.00
7	Rear tailgate logo / MK	1	75.00
8	Rear tailgate emblem 'NV200' / MK	1	75.00
9	Rear tailgate emblem 'Dci' / MK	1	32.20
10	Rear tailgate lock mechanism / DD	1	150.00
Sub-total 1			3,599.80
Less Discount 10%			3,239.82

11	Rear Sticker '70 km/hr' / MK	1	40.00
12	Rear Sticker '6 pax' / MK	1	40.00
13	Rear number plate X	1	50.00
14	Rear LH windscreen primer / MK	1	30.00 20
15	Rear LH windscreen support sponge / MK	1	30.00 20
16	Rear LH windscreen sealant / MK	1	45.00 40 30
17	Rear RH windscreen primer / MK	1	30.00 20
18	Rear RH windscreen support sponge / MK	1	30.00 20
19	Rear RH windscreen sealant / MK	1	45.00 30
20	Reverse sensor / SHL	1	200.00 /
Sub-total 2			540.00
Parts total			3,779.82

Labour

21	To straighten and panel beating side frame members. To remove and replace above parts.	800.00 400
22	To putty, re-spray painting and polish affected areas.	700.00 400
23	To remove and refit LH tailgate glass	150.00 80
24	To remove and refit RH tailgate glass	150.00 80
25	Repair wire harness	60.00 30

Labour total 1,860.00

Parts & Labour total 5,639.82

5 for CLKK) m m 27/8/19
5 dy 11.31a
L/S
M AL dy