

22/03/2017

ASS. REC. BY:

REF:

CS/AGI19014613/0y d3

n2

Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): My Rekhla

of

AGI

Date/Time:

21/8/19 @ 10:05am

Estimated Cost:

Bill to:

OD/IT/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GIBH 2574 G

Insured:

SJG 8788C

at Workshop m/s

AIM

Tel:

9119 8371

of

23 Kerki Bukit Ave 4 #04-01

Policy No:

Claim No:

C10003808 / ky

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 19/08/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 12:13pm @ 21/8/19

Person Contacted:

Jueyne

Vehicle IN / OUT

Date/Time	Action/Instruction	Telephone	✓
	GIBH 2574 G - C6 / AGI 8022819 / Gpa 3y2		
	SJG 8788C - X		

D.O.A. 11/12/18

ASS. REC. BY: Marcus

REF: AGI

ASSIGNMENT

From:

Date:

27/8/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

CIBH 2574 G

at Workshop m/s

AIM

of

23 Kelai Bukit Ave 4 # 04-01

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

After 12pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$55/c

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

up

589N

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBH/2574G

Regn:

4, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(M)

Make:

Toyota Dyns

C.C

2982

Colour

Sim

A/C:

Insured / Std / NI / NA

Sp. Reading

54379

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTFAT354X0K210130

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195 / 75 R15

R:

155 R12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6/6

mm

L/Bal.

6

mm

L/Bal.

6/6

mm

D.O.A.

19/8/19

D.O.I.

29/8/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

n/s ll, n/s body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA 15816

6/9/19 confirm n/s \$4200 with Kelu. (Red \$5973-58, 98%)

RECEIVED 11 SEP 2019

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

11/9/19 Typist

Days Of Repair:

4

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Week end (\$)

Survey Fee:

Transportation:

S + RS. St

Photos

Others

TOTAL

350

Report Form:

Lump Sum / I.B.E. (\$)

L/S \$4200f

Nivitha (LKK Auto)

From: Ivy Ratilla <ivy.r@budgetdirect.com.sg>
Sent: Wednesday, 21 August 2019 10:05 AM
To: Admin-D (LKKAuto)
Cc: sur@lkkauto.com; Justin Wong
Subject: TPPD Survey: Claim ref:C10003808/KY || OI- SJG8788C (White) TP- GBH2574G || Est:0.00 || Automobile Integrated
Attachments: Notice of acct GBH2574G.pdf

Hi Team,

We would like to request for TP PRS for GBH2574G.

Workshop has chosen Mr. Marcus Chua to survey the vehicle.

Please confirm.

Regards,

Ivy Ratilla
Executive, Claims Admin

T +65 6540 2185
F +65 6725 0853
E ivy.r@budgetdirect.com.sg



Customer Care +65 6221 2111
Claims +65 6221 2199
Claims (Int.) +65 6540 2199

190 Clemenceau Avenue, #03-01
Singapore Shopping Centre
Singapore
239924
budgetdirect.com.sg

auto  general

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **Budget Direct Insurance**.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

From: AIM PTE LTD <automim.claim@gmail.com>
Sent: Wednesday, 21 August 2019 9:48 AM
To: Ivy Ratilla <ivy.r@budgetdirect.com.sg>
Cc: Claims <claims@budgetdirect.com.sg>; Justin Wong <justin.wong@budgetdirect.com.sg>
Subject: Re: NOA- GBH2574G // Claim TP 19.08.2019 || C10003808

Hi Ivy Ratilla,

We would like to appoint Marcus Chua from LKK as surveyor.

Thank you.

Regards,
Jacyne

From: AIM PTE LTD <automim.claim@gmail.com>
Sent: Tuesday, 20 August 2019 5:21 PM
To: Claims <claims@budgetdirect.com.sg>
Subject: NOA- GBH2574G // Claim TP 19.08.2019

Hi,

Please find attached to advise further.

Thank you.

Regards,
Jacyne

--

AIM

tel: 91198371

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

--

AIM

tel: 91198371

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.



Automobile Integrated Management Pte Ltd

Co. & G.S.T. Reg no. 201605297G

Office: 28 Sin Ming Lane #07-147 Midview City Singapore 573972

Workshop: 23 Kaki Bukit Ave 5 #04-01 (South Wing) Singapore 415933

Email: automim.claim@gmail.com Tel: 9119 8371

By Email

Our ref: AC2019031/TP/GBH2574G-19.08.2019/NOA

20th August 2019

Budget Direct Insurance

190 Clemenceau Avenue, #03-01

Singapore Shopping Centre

Singapore 239924

Attention: Claim Officer in charge

Dear Sir / Madam,

NOTIFICATION OF ACCIDENT

**ACCIDENT INVOLVING GBH2574G AND SJG8788C ALONG ORCHARD TURN & CARPARK
FROM Ngee Ann City on 19 August 2019**

We are appointed by JET-VACS Service Pte Ltd to repair their vehicle GBH2574G and assist to make a claim against from your insured SJG8788C policy. Please let us know within 2 working days from the date of this notice if you wish to carry out a pre-repair inspection.

The vehicle is available for inspection at the below location:

23 Kaki Bukit Ave 4 #04-01 (South Wing) Singapore 415933

Kindly email or contact Jacyne/Sheryl at 91198371 to arrange for inspection.

Thank you.

Yours faithfully,

Automobile Integrated Management Pte Ltd

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/08/2019 12:17
Date Of Accident	19/08/2019 17:00
Exact Location Of Accident	ORCHARD TURN & CARPARK FROM Ngee Ann City
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBH2574G
Insured/Policyholder	
Name Of Registered Owner	JET-VACS SERVICE PTE LTD
Co Reg No	200205569N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-91192667
Vehicle Particulars	
Manufacturer	TOYOTA
Model	DYNA 150 5MT
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A 29077707 MKC (COMP)
Cover Note Number	
Driver	
Name of Driver	PERUMAL NATHAN
Passport No/FIN	G7066952N
Date Of Birth	15/05/1976
Occupation	OUTDOOR
Date Of Driving Pass	07/01/2009
Driving Experience	10 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81535810
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 3005 UBI AVENUE 3 #03-52
Postcode	408861
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : ANGRAY
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJG8788C
Vehicle Make/Model/Colour	MITSUBISHI / OUTLANDER 2.4 CVT ABS D/AIRBAG AWD S/R
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LEE SHOA YONG
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 20/8/19





Driver's Signature
(If driver is not the policyholder)
Date & Time: 20/8/19

IDAC KAKI BU
23-Kaki, Buk
Singapore
Tel: 67416697 F.
Email: info@idac.gov.sg

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on 17/01/19 at 500pm I was travelling along Orchard Turn, while vehicle no SJG8788G came out from Ngee Ann City car park and hit on left side of vehicle no. GBH2574G.

DECLARATION

We declare the foregoing particulars are true in every respect.



Policyholder's Signature

Date & Time: 20/4/19



Driver's Signature

(If driver is not the policyholder)

Date & Time: 20/4/19

IDAC KAKI BUKIT (P)

23 Kaki Bukit Ave 4

Singapore 415933

Tel: 67416697 Fax: 6749

Email: enquiry@idac.com.sg

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No:

Not Arthur
Helen Marcus
29/8/19
Helen
Wing Ho Ahn



Automobile Integrated Management Pte Ltd
Co. & G.S.T. Reg no. 201605297G
Office: 28 Sin Ming Lane #07-147 Midview City Singapore 573972
Workshop: 23 Kaki Bukit Ave 5 #04-01 (South Wing) Singapore 415933
Email: automim.claim@gmail.com Tel: 9119 8371

ESTIMATE

Our Ref: AC2019031/TP/GBH2574G - 19.08.2019

Vehicle number: GBH2574G

Vehicle Made & Model: TOYOTA DYNA

Items	Qty	List Items	Amount \$
1	1	Front door - LH	20/8/19 1,658.60
2	1	Front door outer handle	17 189.65 x
3	1	Front door w/strip	ner 181.90
4	1	Front door seal	ner 131.20
5	1	Front door inner lock	17 451.85 x
6	1	Front door glass outer moulding	17 142.60 x
7	1	Front door glass run channel	17 166.90 x
8	1	Front door rear pillar - LH	20/8/19 541.50
9	1	Front door rear pillar emblem	ner 86.50
10	1	Front door insulation	17 130.20 x
11	1	Front wheel guard - LH	gum 312.60
12	2	Front wheel arch panel mounting	17 89.90 x
13	1	Front lower arm - LH	17 635.50 x
14	1	Front knuckle arm	17 810.50 x
15	1	Front wheel bearing	17 190.60 x
16	1	Rear sidegate - LH	20/8/19 1,685.90
17	1	Rear sidegate stopper	n.s 58.80
18	1	Rear sidegate lower member	n 591.90 x
19	1	Rear side step bracket	n 241.50 x
Sub-total			8,298.10
Less 25%			2,074.53
Total List			6,223.58

Special Nett Items

20	1	R.O.V sticker	ner 50.00 30
21	1	Front wheel rim - LH	ner 480.00 x
22	1	Front tyre	ner 280.00 x
Total Special Nett			810.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date:

Labour charges

23	To remove, refix front interior trims to assist repair	120.00	60
24	To check front electrical wiring	50.00	20
25	To remove, refix front undercarriage	300.00	X
26	To check wheel alignment	120.00	60
27	To respray undercoating	150.00	60
28	To respray painting and etc	1,200.00	750
29	Panel beating, cut, weld remove & replacing above parts	1,200.00	800
Total Labour		3,140.00	

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

10,173.58

AGI

1

Not Adhul
hala marcus
29/8/19
4 days
Whore the 192-

1/5 #4200

AIM

Automobile Integrated Management Pte Ltd

Co. & G.S.T. Reg no. 201605297G

Office: 28 Sin Ming Lane #07-147 Midview City Singapore 573972

Workshop: 23 Kaki Bukit Ave 5 #04-01 (South Wing) Singapore 415933

Email: automim.claim@gmail.com Tel: 9119 8371

ESTIMATE

Our Ref: AC2019031/TP/GBH2574G - 19.08.2019

Vehicle number: GBH2574GVehicle Made & Model: TOYOTA DYNA

Items	Qty	List Items	Amount \$
1	1	Front door - LH	1,658.60
2	1	Front door outer handle	189.65
3	1	Front door w/strip	181.90
4	1	Front door seal	131.20
5	1	Front door inner lock	451.85
6	1	Front door glass outer moulding	142.60
7	1	Front door glass run channel	166.90
8	1	Front door rear pillar - LH	541.50
9	1	Front door rear pillar emblem	86.50
10	1	Front door insulation	130.20
11	1	Front wheel guard - LH	312.60
12	2	Front wheel arch panel mounting	89.90
13	1	Front lower arm - LH	635.50
14	1	Front knuckle arm	810.50
15	1	Front wheel bearing	190.60
16	1	Rear sidegate - LH	1,685.90
17	1	Rear sidegate stopper	58.80
18	1	Rear sidegate lower member	591.90
19	1	Rear side step bracket	241.50
			Sub-total 8,298.10
			Less 25% 2,074.53
			Total List 6,223.58

4657

252

3497.75

Special Nett Items

20	1	R.O.V sticker
21	1	Front wheel rim - LH
22	1	Front tyre

50.00	30
480.00	x
280.00	x
Total Special Nett	810.00

EKI Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour charges

23	To remove, refix front interior trims to assist repair	120.00	60
24	To check front electrical wiring	50.00	20
25	To remove, refix front undercarriage	300.00	X
26	To check wheel alignment	120.00	60
27	To respray undercoating	150.00	60
28	To respray painting and etc	1,200.00	750
29	Panel beating, cut, weld remove & replacing above parts	1,200.00	800
Total Labour		3,140.00	

5272.75
27.
4218

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

10,173.58



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL			Ref : CS/AGI19014693/Uyd3n2	
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Date : 20-09-2019	
			Code : AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJG 8788C	Veh. Inspected	GBH 2574G	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10003808/KY	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	21/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA (M)	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JTFAT35YX0K210130	Colour	SILVER	
Odometer	54379	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/75 R15	YOKOHAMA	6 mm	
L/H Front Tyre	195/75 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	155 R12 (D)	YOKOHAMA	6/6 mm	
L/H Rear Tyre	155 R12 (D)	YOKOHAMA	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/08/2019	Inspection Date	29/08/2019	
Survey held at	AUTOMOBILE INTEGRATED MANAGEMENT PTE.LTD (AIM) 23 KAKI BUKIT AVE 5 #04-01 (SOUTH WING) SINGAPORE 415933			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 2574G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT DOOR-LH	DENTED / BENT	1,658.60	1,658.60
1	FRONT DOOR OUTER HANDLE	NOT NECESSARY	189.65	-
1	FRONT DOOR W/STRIP	NECESSARY	181.90	181.90
1	FRONT DOOR SEAL	NECESSARY	131.20	131.20
1	FRONT DOOR INNER LOCK	NOT NECESSARY	451.85	-
1	FRONT DOOR GLASS OUTER MOULDING	NOT NECESSARY	142.60	-
1	FRONT DOOR GLASS RUN CHANNEL	NOT NECESSARY	166.90	-
1	FRONT DOOR REAR PILLAR-LH	BADLY DENTED	541.50	541.50
1	FRONT DOOR REAR PILLAR EMBLEM	NECESSARY	86.50	86.50
1	FRONT DOOR INSULATION	NOT NECESSARY	130.20	-
1	FRONT WHEEL GUARD-LH	GRAZED	312.60	312.60
2	FRONT WHEEL ARCH PANEL MOUNTING	NOT NECESSARY	89.90	-
1	FRONT LOWER ARM-LH	NOT NECESSARY	635.50	-
1	FRONT KNUCKLE ARM	NOT NECESSARY	810.50	-
1	FRONT WHEEL BEARING	NOT NECESSARY	190.60	-
1	REAR SIDEGATE-LH	DENTED / BENT	1,685.90	1,685.90
1	REAR SIDEGATE STOPPER	MISSING	58.80	58.80
1	REAR SIDEGATE LOWER MEMBER	TO REPAIR SEE LABOUR	591.90	-
1	REAR SIDE STEP BRACKET	TO REPAIR SEE LABOUR	241.50	-
	LESS 25% DISCOUNT		-2,074.52	-1,164.25
			6,223.58	3,492.75
SPECIAL NETT ITEMS				
1	R.O.V STICKER (SN)	NECESSARY	50.00	30.00
1	FRONT WHEEL RIM-LH (SN)	SERVICEABLE	480.00	-
1	FRONT TYRE (SN)	SERVICEABLE	280.00	-
			810.00	30.00
LABOUR				
	TO REMOVE,REFIX FRONT INTERIOR TRIMS TO ASSIST REPAIR.		120.00	60.00
	TO CHECK FRONT ELECTRICAL WIRING.		50.00	20.00
	TO REMOVE,REFIX FRONT UNDERCARRIAGE.	NOT NECESSARY	300.00	-
	TO CHECK WHEEL ALIGNMENT.		120.00	60.00

Report Ref No. CS/AGI19014693/Uyd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESPRAY UNDERCOATING.		150.00	60.00
	TO RESPRAY PAINTING AND ETC.		1,200.00	750.00
	PANEL BEATING,CUT,WELD REMOVE & REPLACING ABOVE PARTS.INCLUSIVE OF THE REPAIR OF REAR SIDEGATE LOWER MEMBER AND REAR SIDE STEP BRACKET.		1,200.00	800.00
			3,140.00	1,750.00
GRAND TOTAL			10,173.58	5,272.75
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,200.00

Report Ref No. CS/AGI19014693/Uyd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.