

12/07/2019

ASS. SEC. BY:

Surveyor: Mr Kim

REF: CS/CTI19014697/Byd304

Special Instruction:

ASSIGNMENT (Office)

From (Person): Chong Boonsen

of

CTI

Date/Time: 21/8/19 @ 11:26am

Estimated Cost:

Bill to:

OD / HP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKU 4887R

Insured:

YP3323T

at Workshop m/s

Tong Luek

Tel:

6250 0888

of

160 Sin Ming Drive # 07/01

Policy No:

Claim No:

SNM190203844

Sum Insured:

Excess:

Make of Veh:

D.O.A.

9/8/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:17pm @ 21/8/19

Person Contacted:

Candy

Vehicle IN/OUT

photo OK

Date/Time

Action/Instruction

Estimate ✓

SKU 4887R - CS/LPC1706S709/Kth352

Don. 21/3/17

YP3323T-X

RECEIVED 11 DEC 2019

ASS. REC. BY:

REF:

CTP

ASSIGNMENT

From:

Date:

21/08/2019

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKU 4887R

at Workshop m/s

Tong Luck

of

160 Sin Ming Drive # 07-01/06

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)


Make of Veh:

look for Candy 625 00088

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

lup

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKU 4887R

Yr Regn:

29/7/2015

Type:

M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Harrier Premium 2000 1986

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

86878

T/Radio:

Insured / Std / NI / NA

Eng/No:

3ZRB422751

C/No:

ZSU600020133

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 235/55/18

R: 235/55/18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU (PIR) / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

D.O.I.

21/8/19

Survey held at

Tong Luck Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Range 4,000/- - 5,000/-

29/8/2019

L/S 4,500/- TCCM 29/8/19
(Red \$3048-59, 40%)

MV 84,800/-

PV 54310/-

NV 29,690/-

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

9/12/19 Typist

Days Of Repair:

6

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

270

Transportation:

S + RS, SI

Photos

Others

TOTAL

270

Report Format:

Lump Sum

L.S. (\$)

\$4500/-

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Wednesday, 21 August 2019 11:26 AM
To: operation@tlauto.com.sg
Cc: assignments; Elaine Cheong
Subject: accident involving vehicle sku4887r and yp3323t on 9.8.19 along geylang lor 21

WITHOUT PREJUDICE

Dear Sir,

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle. Please merimen as usual.

Aside to LKK,

Please proceed to survey the third party vehicle on WP basis.

Thank you.

Chong Boon Sen
Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	10/08/2019 10:49
Date Of Accident	09/08/2019 18:30
Exact Location Of Accident	GEYLANG LOR .21
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKU4887R
Insured/Policyholder	
Name Of Registered Owner	HOE WAI LIN
NRIC No	S1181792J
Email Address	ANNEHOE116@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97324440
Alternative Phone No	OTHERS-NOPHONE
Vehicle Particulars	
Manufacturer	TOYOTA
Model	HARRIER
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5101534306-01
Cover Note Number	
Driver	
Name of Driver	TAN PANG KUAN, JASON
NRIC No	S9029668Z
Date Of Birth	08/08/1990
Occupation	INDOOR
Date Of Driving Pass	24/02/2009
Driving Experience	10 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97324440
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	6 LIM AH PIN ROAD #04-03
Postcode	547822
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP3323T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	ABDUL HAKIM
NRIC/Passport Number	S9307134D
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to sketch up the claim documents.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation with liability. After that Agents may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the claim as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claim (collectively the "Purposes").
- (b) All insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may, and is limited, to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes.
- (c) My Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents including their lawyers/law firms, which may be situated outside of Singapore, for one or more of the above Purposes.
- (d) My Personal Information will also be collected and used to compute claims history for the purpose of fraud detection, investigation and management (present and all future claims).
- (e) The information collected under (d) above may be shared and used:
 - (i) to administrators and/or any other third parties that assist in evaluating, investigating, controlling or preventing fraud;
 - (ii) regulators, law enforcement and government agencies as reasonably required for the purposes stated; and
 - (iii) for similar purposes upon request under any regulations issued by court orders.

Signature of Policyholder
Date & Time

Signature of Authorized Driver
Date & Time

Signature of Insurance Agent
Date & Time

CITY AUTO PTE LTD
Rm 5 Sin Ming Road
#01-58/60/62 Sin Ming Ind Est
Singapore 77643
Tel: 6453 1234 Fax: 6453 7944
(Claims Section)

1

A 3KJ4887R

A

Geylang Road

At 630pm I park my car along Geylang hor. 21 to get food. As I come back to my car I saw a note on my windscreen saying he had had my car.

Notice letter

12-10-2019
9-10-2019
10-10-2019

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	792J
Vehicle Details	
Vehicle No.:	SKU4887R
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Aug 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER PREMIUM 2.0 A
Primary Colour:	Black
Manufacturing Year:	2014
Engine No.:	3ZRB422751
Chassis No.:	ZSU600020133
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$28,177.00
Original Registration Date:	29 Jul 2015
First Registration Date:	29 Jul 2015
Transfer Count:	1
Actual ARF Paid:	\$26,448.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Jul 2025
PARF Rebate Amount:	\$19,836.00
Intended COE Rebate Details	
COE Expiry Date:	28 Jul 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$58,109.00
COE Rebate Amount:	\$34,474.00
Total Rebate Amount:	\$54,310.00

The information contained herein is correct as at 22 Aug 2019

OK

Dep 12,360/yr
1030/mth

MV 84,800/2
PV 54310/2
NV 29690/2

TTCM line
22/8/19



Posted: 21-Aug-2019

Tags: 2015 Toyota Harrier, 2015 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota

**Toyota Harrier 2.0A Elegance**

-

N.A

14-Oct-2015

1,986 cc

-

SUV

SOLD

Accident Free, Well Maintained By Current Owner. Buy With Peace Of Mind!

DIRECT OWNER

Posted: 15-Aug-2019

Tags: 2015 Toyota Harrier, 2015 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota

**Toyota Harrier 2.0A Premium Panoramic**

-

N.A

08-Oct-2015

1,986 cc

-

SUV

SOLD

Most Popular Toyota SUV For Your Family. Spacious & Reliable. Well Maintained & Service. No Further Repair Needed. Beautiful Pearl White Paintwork With Clean & Neat Leather Interior. Bank Or In-House Loan Available. Purchased With Assurance From Henly Enterprise...

PREMIUM AD

Henly Enterprises Co

Posted: 22-Jun-2019

Tags: 2015 Toyota Harrier, 2015 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota

**Toyota Harrier 2.0A Premium Panoramic****\$88,800****\$12,280 /yr**

05-Oct-2015

1,986 cc

-

SUV

Available

Highest Specs! 1 Owner, Accident Free, Spacious, Trade In/ Scrap Welcome. Pls Call For Appointment Viewing.

Posted: 24-Jul-2019

Tags: 2015 Toyota Harrier, 2015 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota

**Name your price, sell your car**

Many car sellers are now turning to consignment dealers to get their car sold. It's simple, convenient and effective with no obligations to sell!

Find out more!

**Toyota Harrier 2.0A Elegance Panoramic**

-

N.A

29-Sep-2015

1,986 cc

-

SUV

SOLD

One Owner! Original Pearl White Colour! Well Taken Care Of And Well Maintained. Excellent Condition! Owner Upgraded. 2 Tone Red And Black Interior. Low Interest Rate. Balloon Scheme, In-House Financing Options Available. Buy With A Peace Of Mind. 100% Genuine Mile...

Posted: 24-Jun-2019

Tags: 2015 Toyota Harrier, 2015 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota

**Toyota Harrier 2.0A Premium Panoramic**

-

N.A

28-Sep-2015

1,986 cc

-

SUV

SOLD

One Owner. Premium Model With Upgrade 19" Rim. Accident Free. High Trade In And Flexible Loan Package. Please Call For Test Drive Now.

Posted: 07-Jun-2019

Tags: 2015 Toyota Harrier, 2015 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota

**Toyota Harrier 2.0A Premium Panoramic**

-

N.A

22-Sep-2015

1,986 cc

-

SUV

SOLD

Nice No. Plate. Viewing Is Flexible-your Place Or My Place. Any Time, Thanks.

DIRECT OWNER

Posted: 07-Jun-2019

Tags: 2015 Toyota Harrier, 2015 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota

**Toyota Harrier 2.0A Elegance Panoramic****\$87,800****\$12,500 /yr**

10-Sep-2015

1,986 cc

40,000 km

SUV

Available

1 Owner! AA Trust Certified Quality Vehicle! Very Well Maintained By One Single Owner Only! Panoramic Sunroof Unit! Low Fuel Consumption SUV! Comfort And Sporty That Drives Well On Long Distance With Its Generous Cabin Space And Boot Space! Flexible Ban...

PREMIUM AD

AA Trust Automotive

Posted: 02-Aug-2019

Tags: 2015 Toyota Harrier, 2015 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota

**Toyota Harrier 2.0A Premium Panoramic**

-

N.A

27-Aug-2015

1,986 cc

-

SUV

SOLD

Only 1 Owner, Low Mileage Done, Excellent Condition, Call To View Now.

Posted: 02-Jul-2019

Tags: 2015 Toyota Harrier, 2015 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota

**Toyota Harrier 2.0A Premium Panoramic****\$86,800****\$12,360 /yr**

03-Aug-2015

1,986 cc

-

SUV

Available

6 Months Warranty, Excellent Condition, Accident Free, Bank Loan/In House Loan Available, Trade In Welcome.

Posted: 15-Aug-2019

Tags: 2015 Toyota Harrier, 2015 toyota harrier, Toyota Harrier, toyota harrier, Toyota, Harrier, harrier, Used Toyota

Compare

Toyota Harrier 2.0A Elegance

-

N.A

21-Jul-2015

1,986 cc

-

SUV

SOLD



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : HOE WAI LIN ANNIE (MS)
C/O BLK 160 SIN MING DRIVE #07-01
SIN MING AUTOCITY
SINGAPORE 575722

TEL : 9755 4488 FAX :

ATTN : HOE WAI LIN ANNIE (MS)

YOUR REF NO : YP3323T

CLAIM TYPE : THIRD PARTY

TP INS. CO. : CHINA TAIPING INSURANCE (SINGAPORE) PTE REG. DATE : 2014

ACCIDENT DATE : 09/08/2019

TP VEH REG NO : YP3323T

ESTIMATE

NO : QUOT201908-000048(00)

DATE : 19/08/2019

POLICY NO : 5101534306-01

VEH REG NO : SKU4887R

MAKE/MODEL : TOYOTA HARRIER

CHASSIS NO : ZSU600020133

ENGINE NO : 3ZRB422751

Estimate Repair Cost to Vehicle No : SKU4887R

Description	Quantity	Unit Price	Amount
		S\$	S\$
LIST PRICE			
1 Rear fender - RH	1	1,531.70	✓1,531.70 DD✓
2 Front fender inner shield - RH	1	189.80	✓189.80 ?DL
3 Rear fender inner shield clips -- RH	20	8.00	✓50.00 160.00 ?NEC
4 Rear bumper	1	1,698.00	1,698.00 DD✓
5 Rear bumper side retainer - RH	1	125.75	✓125.75 NEC✓
6 Rear bumper clips - RH	15	6.00	✓50.00 90.00 NEC✓
7 Rear door - RH	1	1,516.20	✓1,516.20 DD✓
8 Rear door trimboard clips - RH	20	5.00	✓50.00 100.00 NEC
		4939.15	4939.15
	@ 25 %	1234.79	1,352.86
		3704.36	4,058.59
SPECIAL NET			
9 Rear triangle glass sealant - RH	1	40.00	✓40.00 NEC✓
		40.00	40.00
LABOUR			
10 To transfer RH rear damaged door interior mechanism and glass to new door	1	150.00	100.00 150.00 ✓
11 To remove and refit RH rear triangle glass	1	80.00	60.00 80.00 ✓
12 To remove and refit RH rear interior garnishes and trim to facilitates the repairs	1	180.00	100.00 180.00 ✓
13 To remove and refit rear bumper sensor	1	100.00	60.00 100.00 ✓
14 To panel beat and straighten RH rear fender inner panel, RH rear chassis frame, to cut and weld RH rear fender, including replacement of parts align where necessary action, to refit and adjust the same	1	1,200.00	800.00 1,200.00 ✓
15 To putty and spray paint on affected areas	1	1,500.00	700.00 1,500.00
16 To check and rectify wiring system	1	80.00	30.00 80.00
17 To apply rust-proofing on replaced and repaired panels	1	160.00	80.00 160.00
		1930.00	3,450.00
TOTAL			S\$ 7,548.59
ADD GST @ 7%			528.40
GRAND TOTAL			S\$ 8,076.99

SINGAPORE DOLLAR EIGHT THOUSAND SEVENTY-SIX AND CENTS NINETY-NINE ONLY



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : HOE WAI LIN ANNIE (MS)
C/O BLK 160 SIN MING DRIVE #07-01
SIN MING AUTOCITY
SINGAPORE 575722

TEL : 9755 4488 FAX :
ATTN : HOE WAI LIN ANNIE (MS)

YOUR REF NO : YP3323T
CLAIM TYPE : THIRD PARTY
TP INS. CO. : CHINA TAIPING INSURANCE (SINGAPORE) PTE
ACCIDENT DATE : 09/08/2019
TP VEH REG NO : YP3323T

ESTIMATE

NO : QUOT201908-000048(00)
DATE : 19/08/2019
POLICY NO : 5101534306-01
VEH REG NO : SKU4887R
MAKE/MODEL : TOYOTA HARRIER
CHASSIS NO : ZSU600020133
ENGINE NO : 3ZRB422751
REG. DATE : 2014

Estimate Repair Cost to Vehicle No : SKU4887R

Description	Quantity	Unit Price	Amount
		S\$	S\$

21/8/19

Tim Lin

1520 hrs

? photo

Lump sum repair

Repair days 6

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance

Acknowledged by Repairer

Signature:

Date:

Parts 3704.36

S/N 40.00

Labour 1930.00

5673.36

@ 20% 1134.87

4539.49

L/S 4500/2

Tim Lin 29/8/19

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Nov 2019		27 Nov 2019 15:23 Edit Adj Rpt	S\$4,500.00 Edit Estimates	S\$4,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: -, Co. Reg. No.: -									
Main Claimant: HOE WAI LIN									
Vehicle Reg. No.: SKU4887R		Date of Loss: 09/08/2019 00:00 - :59 [48 Months and 11 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM19D203844C02		Policy/Cover Note No.: DMCVSN18412618000							
Vehicle Reg. No. (Insured): YP3323T		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: Tong Luck Auto Pte Ltd (HQ) 160 Sin Ming Drive, #07-01 Sin Ming AutoCity, 575722 Sin Ming - Tel: 6250 0088									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 06/12/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• CHINA_TAIPING (27/11/2019): Alert - Adj Mandate Approved (S\$0.00) - SKU4887R - Claim Handler: Chong Boon Sen									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKU4887R (SNM19D203844C02)
 [YP3323T]
 TP
 HOE WAI LIN
 Aug 9 2019 12:00AM
 [-]
 Tong Luck Auto Pte Ltd

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View [View in Browser](#) v

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	09/12/19 14:50	General View	Load JPG	<input checked="" type="checkbox"/>
2	09/12/19 14:50	General View	Load JPG	<input checked="" type="checkbox"/>
3	09/12/19 14:50	General View	Load JPG	<input checked="" type="checkbox"/>
4	09/12/19 14:50	General View	Load JPG	<input checked="" type="checkbox"/>
5	09/12/19 14:50	General View	Load JPG	<input checked="" type="checkbox"/>
6	09/12/19 14:50	General View	Load JPG	<input checked="" type="checkbox"/>
7	09/12/19 14:50	General View	Load JPG	<input checked="" type="checkbox"/>
8	09/12/19 14:50	General View	Load JPG	<input checked="" type="checkbox"/>
9	09/12/19 14:50	General View	Load JPG	<input checked="" type="checkbox"/>
10	09/12/19 14:50	General View	Load JPG	<input checked="" type="checkbox"/>
11	09/12/19 14:50	General View	Load JPG	<input checked="" type="checkbox"/>
12	09/12/19 14:50	General View	Load JPG	<input checked="" type="checkbox"/>
13	09/12/19 14:50	General View	Load JPG	<input checked="" type="checkbox"/>
14	09/12/19 14:50	General View	Load JPG	<input checked="" type="checkbox"/>
15	09/12/19 14:50	General View	Load JPG	<input checked="" type="checkbox"/>
16	09/12/19 14:50	General View	Load JPG	<input checked="" type="checkbox"/>
17	09/12/19 14:50	General View	Load JPG	<input checked="" type="checkbox"/>
18	09/12/19 14:50	General View	Load JPG	<input checked="" type="checkbox"/>
19	09/12/19 14:50	General View	Load JPG	<input checked="" type="checkbox"/>
20	09/12/19 14:50	General View	Load JPG	<input checked="" type="checkbox"/>
21	09/12/19 14:50	General View	Load JPG	<input checked="" type="checkbox"/>
22	09/12/19 14:50	General View	Load JPG	<input checked="" type="checkbox"/>
23	09/12/19 14:50	General View	Load JPG	<input checked="" type="checkbox"/>
24	09/12/19 14:50	General View	Load JPG	<input checked="" type="checkbox"/>
25	09/12/19 14:50	General View	Load JPG	<input checked="" type="checkbox"/>
26	09/12/19 14:50	General View	Load JPG	<input checked="" type="checkbox"/>
27	09/12/19 14:50	General View	Load JPG	<input checked="" type="checkbox"/>
28	09/12/19 14:50	General View	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	27/11/19 15:24	ESTIMATE	Load PDF	
2	27/11/19 15:27	REPORT OF SKU4887R	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; width: 100%; height: 80px; margin-top: 5px;"></div>			

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19014697/BYD3E2

Date: 20/12/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN18412618000

Claimant
Vehicle No : SKU4887RInsured
Vehicle No : YP3323T

Date of Loss: 09/08/2019

Nature of Claim: TP

Claim
No: SNM19D203844C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKU4887R

Make & Model: TOYOTA HARRIER, 2.0 (A)

Engine No: 3ZRB422751

Reg. Date: 29/07/2015 (Man. Year: 2014)

Chassis No: ZSU600020133

Colour: Black

Odometer: 86878 km

Engine Capacity: 1986 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R18

Rear Tyre Size: 235/55 R18

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,098.59	3,744.36	354.23	8.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,450.00	1,930.00	1,520.00	44.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,548.59	5,674.36	1,874.23	24.83
Approved Total (Overridden) (S\$)		4,500.00		
(S\$)	7,548.59	4,500.00	3,048.59	40.39
+ GST 7.00/7.00% (S\$)	528.40	315.00	213.40	40.39
Nett Amount (S\$)	8,076.99	4,815.00	3,261.99	40.39

INSPECTION

Date of Assignment: 27/11/2019

Date Inspected: 21/08/2019 Inspected At:

Tong Luck Auto Pte Ltd (HQ)
160 Sin Ming Drive, #07-01 Sin Ming
AutoCity
Singapore 575722

Estimated Period of Repair: 6.0 days

Adjuster: Lim Teow Guan

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Dec 2019)
Parts:	M1-SUV	TOYOTA HARRIER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKU4887R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER - RH	Dented	1,531.70 FL	*1,531.70 FL
2	1		*FRONT FENDER INNER SHIELD - RH	Dislodged	189.80 FL	*189.80 FL
3	20		*REAR FENDER INNER SHIELD CLIPS - RH	Necessary	160.00 FL	*50.00 FL
4	1		*REAR BUMPER	Dented	1,698.00 FL	*1,425.70 FL
5	1		*REAR BUMPER SIDE RETAINER - RH	Necessary	125.75 FL	*125.75 FL
6	1		*REAR BUMPER CLIPS - RH (15PCS)	Necessary	90.00 FL	*50.00 FL
7	1		*REAR DOOR - RH	Dented	1,516.20 FL	*1,516.20 FL
8	20		*REAR DOOR TRIMBOARD CLIPS - RH	Necessary	100.00 FL	*50.00 FL
9	1		*REAR TRIANGLE GLASS SEALANT - RH	Necessary	40.00 FS	*40.00 FS
					Sub Total (\$\$)	5,451.45
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,352.86
					Total Parts (\$\$)	4,098.59
						3,744.36

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER RH REAR DAMAGED DOOR INTERIOR MECHANISM AND GLASS TO NEW DOOR	New	150.00	100.00
2	TO REMOVE AND REFIT RH REAR TRIANGLE GLASS	New	80.00	60.00
3	TO REMOVE AND REFIT RH REAR INTERIOR GARNISHES AND TRIM TO FACILITATES THE REPAIRS	New	180.00	100.00
4	TO REMOVE AND REFIT REAR BUMPER SENSOR	New	100.00	60.00
5	TO PANEL BEAT AND STRAIGHTEN RH REAR FENDER INNER PANEL, RH REAR CHASSIS FRAME, TO CUT AND WELD RH REAR FENDER, INCLUDING REPLACEMENT OF PARTS ALIGN WHERE NECESSARY ACTION, TO REFIT AND ADJUST THE SAME	New	1,200.00	800.00
6	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS	New	1,500.00	700.00
7	TO APPLY RUST-PROOFING ON REPLACED AND REPAIRED PANELS	New	160.00	80.00
8	TO CHECK AND RECTIFY WIRING SYSTEM	New	80.00	30.00
Gross Labour Cost (S\$)			3,450.00	1,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >