



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0002895 / MSIG INSURANCE
Chassis No: MRHGM6660JT000215
License No: SLT7859X
Mileage: 49931
Engine No: L15Z15204215

Document No: SVO19054154
Printed By: SHNG
Order Date: 23. August 2019
Order Time: 2:36:28 PM
Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:B.W.TRANS OWNER INSURER: ACC DATE: SURVEYED BY: DATE: REF NO: TP INSURER: TP VEH: SUPPLEMENTARY PARTS AND LABOUR						
71101-T9A-T20ZZ	FACE, FR. BUMPER	1	459.80	25	344.85	24.14	368.99
71102-T9D-K10	GARNISH, R. FR. FOG LIGHT	1	12.60	25	9.45	0.66	10.11
71104-T9D-K10ZA	COVER, FR. TOWING HOOK	1	11.90	25	8.92	0.62	9.54
71130-T9A-T00ZZ	BEAM COMPFR.BUMPER	1	243.10	25	182.32	12.76	195.08
71140-T9A-T11	BEAM, R. FR. BUMPER UPPER	1	27.50	25	20.62	1.44	22.06
71190-T9A-T11	BEAM, L. FR. BUMPER UPPER	1	27.50	25	20.62	1.44	22.06
71193-T9A-T00	SPACERR.FR.BUMPER SIDE	1	10.40	25	7.80	0.55	8.35
71198-T9A-T00	SPACERL.FR.BUMPER SIDE	1	10.40	25	7.80	0.55	8.35
91505-TM8-003	CLIP,BUMPER	11	2.30	25	18.97	1.33	20.30
71123-T9A-T00	COVERFR.GRILLE	1	32.90	25	24.67	1.73	26.40
71125-T9A-T90	MOLDING, FR. GRILLE LOWER	1	46.50	25	34.87	2.44	37.31
71128-T9A-T00	STAYFR.GRILLE	1	6.90	25	5.17	0.36	5.53
75700-T5A-000	EMBLEM H	1	15.00	25	11.25	0.79	12.04
90301-ST0-003	NUTPUSH 3MM	2	2.10	25	3.15	0.22	3.37
33100-T9A-T61	HEADLIGHT ASSY, R.	1	565.70	25	424.27	29.70	453.97
33900-TBA-A01	LIGHT ASSYR.FR.FOG	1	305.90	25	229.42	16.06	245.48
74143-T9A-T01	RUBBERRR.HOOD SEAL	1	21.90	25	16.42	1.15	17.57
74218-T9A-T00	COWL TOP SETFR.	1	55.60	25	41.70	2.92	44.62
60210-T9A-T50ZZ	PANEL COMP,R.FR.FENDER	1	270.60	25	202.95	14.21	217.16
74100-T9A-T10	FENDER ASSY, R. FR. INNER	1	76.80	25	57.60	4.03	61.63
74105-T9A-T10	ENCLOSURER.FR.FENDER	1	6.70	25	5.02	0.35	5.37
74111-T9A-T00	COVERENGINE UNDER	1	50.50	25	37.87	2.65	40.52
74115-T9A-T00	GUARDR.FR.SPLASH	1	20.10	25	15.07	1.05	16.12
91501-TR0-003	CLIP,INNER FENDER	18	2.80	25	37.80	2.65	40.45
91514-TG1-T01	CLIPUNDER COVER	1	1.60	25	1.20	0.08	1.28
60400-T9A-T10ZZ	BULKHEAD COMP, FR.	1	337.80	25	253.35	17.73	271.08
04674-T9A-T00ZZ	EXTENSION SETR.FR.SHOCK ABS	1	84.00	25	63.00	4.41	67.41
60619-T9A-T00ZZ	BRACKETR.FR.FENDER B	1	22.90	25	17.17	1.20	18.37
60623-T9A-T00ZZ	BRACKETR.FR.FENDER A	1	28.80	25	21.60	1.51	23.11
60650-T9A-315ZZ	HOUSING SETR.FR.SHOCK ABS	1	219.30	25	164.47	11.51	175.98
60810-T9A-T00ZZ	FRAME COMPR.FR.SIDE	1	519.50	25	389.62	27.27	416.89
60812-T9A-T00ZZ	PLATER.FR.SIDE BACK	1	99.70	25	74.77	5.23	80.00
60844-T9A-T00ZZ	PLATER.SIDE FRAME GUSSET	1	44.50	25	33.37	2.34	35.71
60845-T9A-T00ZZ	GUSSETR.FR.SIDE FRAME	1	54.10	25	40.57	2.84	43.41
50200-T9A-T01	SUB FRAME COMPFR.SUSPENSION	1	340.50	25	255.37	17.88	273.25
80110-T9A-T01	CONDENSER COMP	1	406.50	25	304.87	21.34	326.21
80341-T9A-T01	PIPE COMPRECEIVER	1	98.10	25	73.57	5.15	78.72
19010-55A-Z51	RADIATOR COMP	1	1,100.50	25	825.37	57.78	883.15
91512-R21-013	CLIPINNER FENDER	1	0.60	25	0.45	0.03	0.48



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0002895 / MSIG INSURANCE
Chassis No: MRHGM6660JT000215
License No: SLT7859X
Mileage: 49931
Engine No: L15Z15204215

Document No: SVO19054154
Printed By: SHNG
Order Date: 23. August 2019
Order Time: 2:36:28 PM
Service Advisor: NG SIN HAI

77810-T9A-T82ZA	MODULE ASSYDRIVER	1	1,780.50	25	1,335.37	93.48	1,428.85
77820-T9A-J80	MODULE ASSYPASSENGER	1	2,236.80	25	1,677.60	117.43	1,795.03
77930-T5A-J01	SENSOR ASSYFR.CRASH	2	63.40	25	95.10	6.66	101.76
77960-T9A-M41	SRS UNIT	1	806.70	25	605.02	42.35	647.37
81450-T9A-T01ZD	TONGUE ASSYR.FR.SEATBELT OUT	1	404.60	25	303.45	21.24	324.69
81850-T9A-T02ZD	TONGUE ASSY,L.FR.SEATBELT	1	404.60	25	303.45	21.24	324.69
60610-T9A-T00ZZ	MEMBER COMPR.FR.WHEELHOUSE UP	1	78.20	25	58.65	4.11	62.76
60843-T9A-T00ZZ	BRACKETR.FR.BUMPER BEAM EXT	1	43.90	25	32.92	2.30	35.22
60846-T9A-T00ZZ	PATCHR.BUMPER BEAM	1	37.20	25	27.90	1.95	29.85
90682-SEA-003	CLIP ABUMPER	4	2.60	25	7.80	0.55	8.35
44305-T9A-T03	DRIVESHAFT ASSYR.	1	685.60	25	514.20	35.99	550.19
51211-T9A-T02	KNUCKLER.FR.	1	94.30	25	70.72	4.95	75.67
51320-T5A-003	LINK COMPR.FR.STABILIZER	1	44.40	25	33.30	2.33	35.63
51350-T5A-J02	ARM ASSY,R.FR.LOWER	1	166.80	25	125.10	8.76	133.86
51611-T9A-T52	ABSORBER UNITR.FR.SHOCK	1	126.90	25	95.17	6.66	101.83
51726-SFA-005	BEARINGDAMPER MT	2	17.60	25	26.40	1.85	28.25
46376-T9A-T00	PIPE W COMPBRAKE	1	5.00	25	3.75	0.26	4.01
53400-T9A-003	BOX ASSYSTEERING GEAR	1	466.70	25	350.02	24.50	374.52
53540-T5R-003	END COMPR.TIE ROD	1	42.90	25	32.17	2.25	34.42
53560-T5R-003	END COMPL.TIE ROD	1	42.90	25	32.17	2.25	34.42
76805-T9A-T01	HOSE	1	14.90	25	11.17	0.78	11.95
76806-SYP-N02	MOTORWASHER	1	51.30	25	38.47	2.69	41.16
76841-T9A-T01	TANKWASHER	1	22.20	25	16.65	1.17	17.82
77100-T9A-T10ZA	PANEL COMP, INSTRUMENT	1	1,746.10	25	1,309.57	91.67	1,401.24
08CLA-P9911LK8	COOLANT ANTI-FREEZE TYPE 2	5	23.20	25	87.00	6.09	93.09
60811-T9A-T00ZZ	FRAMER.FR.SIDE	0	105.90	25	0.00	0.00	0.00
44300-T9C-T61	BEARING ASSY,FR.HUB	1	114.90	25	86.17	6.03	92.20
44600-T5B-J00	HUB ASSYFR.	1	138.30	25	103.72	7.26	110.98
30485005-812000020	IDEMITSU BRAKE FLUID DOT4 0.5L	3	8.23	25	18.52	1.30	19.82
08269-P99-Z8FM1	HONDA HCF 2 CVT FLUID 2 3.5L	1	80.50	25	60.37	4.23	64.60
51300-T9A-T01	SPRINGFR.STABILIZER	1	93.60	25	70.20	4.91	75.11
51306-T9C-T01	BUSHR.FR.STABILIZER HOLDER	1	6.80	25	5.10	0.36	5.46
51307-T9C-T01	BUSHL.FR.STABILIZER HOLDER	1	6.80	25	5.10	0.36	5.46
51308-SWW-P50	BRACKETFR.STABILIER	2	1.80	25	2.70	0.19	2.89
42700-T9A-T72	DISK, ALUMINIUM WHEEL 16X6J	1	415.50	25	311.62	21.81	333.43
19200-RB0-003	PUMP COMPWATER	1	180.30	25	135.22	9.47	144.69
19224-RB0-000	PULLEYWATER PUMP	1	37.00	25	27.75	1.94	29.69
75490-T9A-T01	GARNISH ASSYR.FR.PILLAR CORNE	1	9.60	25	7.20	0.50	7.70
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	3.15	48.15
76208-T9A-T12	MIRROR SET, R.	1	254.30	25	190.72	13.35	204.07
72410-T9A-T01	MOLDING ASSYR.FR.DOOR	1	21.80	25	16.35	1.14	17.49
SUM PARTS:					12,566.19	879.61	13,445.80
BOSUN	0701	1	30.00		30.00	2.10	32.10
SUNDRIES							
BKBH01M	0669	1	2,800.00		2,800.00	196.00	2,996.00
REMOVE & RENEW BULKHEAD. STRAIGHTEN ALIGN CHASSIS & RENEW DAMAGE PARTS.							
BML01I	1757	1	180.00		180.00	12.60	192.60
INSPECT FR LIGHTING MECHANISMS & FOCUS HEADLIGHTS.(N)							



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: CU0002895 / MSIG INSURANCE
Chassis No: MRHGM6660JT000215
License No: SLT7859X
Mileage: 49931
Engine No: L15Z15204215

Document No: SVO19054154
Printed By: SHNG
Order Date: 23. August 2019
Order Time: 2:36:28 PM
Service Advisor: NG SIN HAI

BP06R	1610 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	1,800.00	1,800.00	126.00	1,926.00
BMI00D	0669 REMOVE & INSTALL DASHBOARD INSTRUMENTAL PANEL AUDIO WIRING HARNESS & ETC.(N)	1	1,200.00	1,200.00	84.00	1,284.00
BKBU01R	0669 REMOVE AND RENEW RHF WHEEL	1	50.00	50.00	3.50	53.50
BMS00R	1757 RENEW BOTH DRIVER & PASSENGER AIRBAG ASSY ECU & RESET SRS SYSTEM.(N)	1	1,200.00	1,200.00	84.00	1,284.00
BKOT00A	0669 PLACE VEHICLE TO BENCH FOR CHASSIS FRAME ALIGNMENT	1	1,200.00	1,200.00	84.00	1,284.00
BMC01D	1757 REMOVE & INSTALL RADIATOR WITH FITTINGS. PRESSURE TEST COOLING SYSTEM.(N)	1	380.00	380.00	26.60	406.60
BMA01D	1757 REMOVE & INSTALL A/C CONDENSER WITH FITTINGS. VACUUM & RECHARGE A/C GAS.(N)	1	330.00	330.00	23.10	353.10
BMU01R	1757 REMOVE & REPLACE FR UNDERCARRIAGE PARTS.(N)	1	1,680.00	1,680.00	117.60	1,797.60
BC012R	1757 RESET VEHICLE SMART ENTRY SYSTEM	1	560.00	560.00	39.20	599.20
BML12R	1757 REMOVE & RENEW ENGINE WIRE HARNESS. RESET ECU MEMORIES	1	1,120.00	1,120.00	78.40	1,198.40
BMS02R	1757 REMOVE & RENEW SEATBELT TENSIONER, ECU & CRASH SEN RESET SYSTEM.	1	1,120.00	1,120.00	78.40	1,198.40
BKBH12M	1757 RENEW WHEELHOUSE & CHASSIS FRAME. INCLUDING STRAIGHTEN AND FITTING ATTACHMENT ITEMS	1	1,680.00	1,680.00	117.60	1,797.60
BME00D	1757 REMOVE & INSTALL ENGINE ASSY GEARBOX & OTHERS ATTACHMENT PARTS.(N)	1	1,680.00	1,680.00	117.60	1,797.60
BP03R	1757 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(3P)	1	1,350.00	1,350.00	94.50	1,444.50
		SUM LABOUR:				
			18,360.00	1,285.20	19,645.20	
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00	180.00	12.60	192.60
		SUM EXT SERVICE:				
			180.00	12.60	192.60	
		TOTAL SGD				
			31,106.19	2,177.41	33,283.60	

Total Payable (SGD)

33,283.60



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0002895 / B.W. TRANS
Chassis No: MRHGM6660JT000215
License No: SLT7859X
Mileage: 49931
Engine No: L15Z15204215

Document No: SVO19054154
Printed By: SHNG
Order Date: 23. August 2019
Order Time: 2:36:28 PM
Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	SUPPLEMENTARY PARTS AND LABOUR						
60610-T9A-T00ZZ	MEMBER COMPR.FR.WHEELHOUSE UP	1	78.20	25	58.65	4.11	62.76
60843-T9A-T00ZZ	BRACKETR.FR.BUMPER BEAM EXT	1	43.90	25	32.92	2.30	35.22
60846-T9A-T00ZZ	PATCHR.BUMPER BEAM	1	37.20	25	27.90	1.95	29.85
90682-SEA-003	CLIP ABUMPER	4	2.60	25	7.80	0.55	8.35
44305-T9A-T03	DRIVESHAFT ASSYR.	1	685.60	25	514.20	35.99	550.19
51211-T9A-T02	KNUCKLER.FR.	1	94.30	25	70.72	4.95	75.67
51320-T5A-003	LINK COMPR.FR.STABILIZER	1	44.40	25	33.30	2.33	35.63
51350-T5A-J02	ARM ASSY,R.FR.LOWER	1	166.80	25	125.10	8.76	133.86
51611-T9A-T52	ABSORBER UNITR.FR.SHOCK	1	126.90	25	95.17	6.66	101.83
51726-SFA-005	BEARINGDAMPER MT	2	17.60	25	26.40	1.85	28.25
46376-T9A-T00	PIPE W COMPBRAKE	1	5.00	25	3.75	0.26	4.01
53400-T9A-003	BOX ASSYSTEERING GEAR	1	466.70	25	350.02	24.50	374.52
53540-T5R-003	END COMPR.TIE ROD	1	42.90	25	32.17	2.25	34.42
53560-T5R-003	END COMPL.TIE ROD	1	42.90	25	32.17	2.25	34.42
76805-T9A-T01	HOSE	1	14.90	25	11.17	0.78	11.95
76806-SYP-N02	MOTORWASHER	1	51.30	25	38.47	2.69	41.16
76841-T9A-T01	TANKWASHER	1	22.20	25	16.65	1.17	17.82
77100-T9A-T10ZA	PANEL COMP, INSTRUMENT	1	1,746.10	25	1,309.57	91.67	1,401.24
08CLA-P9911LK8	COOLANT ANTI-FREEZE TYPE 2	5	23.20	25	87.00	6.09	93.09
60811-T9A-T00ZZ	FRAMER.FR.SIDE	0	105.90	25	0.00	0.00	0.00
44300-T9C-T61	BEARING ASSY,FR.HUB	1	114.90	25	86.17	6.03	92.20
44600-T5B-J00	HUB ASSYFR.	1	138.30	25	103.72	7.26	110.98
30485005-812000020	IDEMITSU BRAKE FLUID DOT4 0.5L	3	8.23	25	18.52	1.30	19.82
08269-P99-Z8FM1	HONDA HCF 2 CVT FLUID 2 3.5L	1	80.50	25	60.37	4.23	64.60
51300-T9A-T01	SPRINGFR.STABILIZER	1	93.60	25	70.20	4.91	75.11
51306-T9C-T01	BUSHR.FR.STABILIZER HOLDER	1	6.80	25	5.10	0.36	5.46
51307-T9C-T01	BUSHL.FR.STABILIZER HOLDER	1	6.80	25	5.10	0.36	5.46
51308-SWW-P50	BRACKETFR.STABILIER	2	1.80	25	2.70	0.19	2.89
42700-T9A-T72	DISK, ALUMINIUM WHEEL 16X6J	1	415.50	25	311.62	21.81	333.43
19200-RB0-003	PUMP COMPWATER	1	180.30	25	135.22	9.47	144.69
19224-RB0-000	PULLEYWATER PUMP	1	37.00	25	27.75	1.94	29.69
75490-T9A-T01	GARNISH ASSYR.FR.PILLAR CORNE	1	9.60	25	7.20	0.50	7.70
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	3.15	48.15
76208-T9A-T12	MIRROR SET, R.	1	254.30	25	190.72	13.35	204.07
72410-T9A-T01	MOLDING ASSYR.FR.DOOR	1	21.80	25	16.35	1.14	17.49
	SUM PARTS:				3,958.87	277.11	4,235.98
BKBH12M	RENEW WHEELHOUSE & CHASSIS FRAME. INCLUDING STRAIGHTEN AND FITTING ATTACHMENT ITEMS	1	1,680.00		1,680.00	117.60	1,797.60
BME00D	REMOVE & INSTALL ENGINE ASSY GEARBOX & OTHERS ATTACHMENT PARTS.(N)	1	1,680.00		1,680.00	117.60	1,797.60
BP03R		1	1,350.00		1,350.00	94.50	1,444.50



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: CU0002895 / B.W. TRANS
Chassis No: MRHGM6660JT000215
License No: SLT7859X
Mileage: 49931
Engine No: L15Z15204215

Document No: SVO19054154
Printed By: SHNG
Order Date: 23. August 2019
Order Time: 2:36:28 PM
Service Advisor: NG SIN HAI

SPRAY PAINTING ON REPAIRED OR
REPLACED AREAS.(3P)

SUM LABOUR:	4,710.00	329.70	5,039.70
--------------------	-----------------	---------------	-----------------

TOTAL SGD	8,668.87	606.81	9,275.68
------------------	-----------------	---------------	-----------------

Total Payable (SGD)	9,275.68
----------------------------	-----------------

GST Amount is calculated from individual line(s)