

ASS. REC. BY:

REP: 08/INC19014778/Kyd3/12
Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Daniel Koh of INC Date/Time: 2/18/19 @ 9:45am

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHD 448B Insured: SICF 2649)

at Workshop in/s Truns cab Tel: 62876666

of No. 2 AMK St-63

Policy No: Claim No: MT/1058335-002

Sum Insured: Excess:

Make of Veh: D.O.A. 1/18/19
(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 10:31am @ 2/18/19 Person Contacted: Amanda Vehicle: IN OIT

Date/Time	Action/Instruction
5/9/19	81569.48 - Summit (Red 29,043.42, 95% CNO LS) confirmed by email

ASS. REC. BY: REF: INC1

ASSIGNMENT

Kenneth

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Trans Cab
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 02 days Res.: Yes or No
 Lum Sum: 1-B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: S110 4488^B Yr Regn: 09, 16
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Traller or _____
 Make: Renault Latitude c.c. 1995
 Colour: in White / Red A/C: Insured / Std / NI / NA
 Sp. Reading: 287407 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: V11 ABL 15AUC 283351
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: Bilun 215/60R16
 R: Giti
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front R/Bal. 8 mm Rear R/Bal. 8 mm
 L/Bal. 8 mm L/Bal. 8 mm
 D.O.A. 17/8/19 D.O.I. 21/8/19
 Survey held at _____ 11:26am
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
N/S / Frt
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1</u>	<u>File pass to</u>

RECEIVED 6 SEP 2019

Kenneth
4/9/2019

Date/Time, File Pass to? : Prell. Report
 : Final Report

Days Of Repair: 2
 Resurvey No. of Trip: 1

Date/Time, File Return to? 7 slr - typist

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

Survey Fee:

Transportation:	_____
S + R.S. SI	_____
Fees	_____
Others	_____
TOTAL	<u>250</u>

Report Format : TP
 Lump Sum / I.B.I: (\$) 1569.48

Nivitha (LKK Auto)

From: Daniel Koh <daniel.koh@income.com.sg>
Sent: Wednesday, 21 August 2019 3:43 PM
To: 'assignments@lkkauto.com'
Cc: admin-d@lkkauto.com
Subject: FW: TP CASES FARMED OUT TO LKK ON 21/8/2019

Dear LKK,

RESEND WITH CLAIM NUMBER & OIC

From: Daniel Koh
Sent: Wednesday, 21 August 2019 9:45 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>
Cc: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>; Teng Ken Leong <kenleong.teng@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>
Subject: FW: TP CASES FARMED OUT TO LKK ON 21/8/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	OIV	DOA	Additional Remarks
----	-----	-----------	---------	---------------	------------------	------------------	-----	-----	--------------------

1	FIONA SHEN	MT/1057247-002	SKS9427M	CARZ AUTO SERVICES PTE LTD	WOODLANDS INDUSTRIAL PARK E9 (E9 PREMIUM) #04-04 SINGAPORE 757047	Jeslyn Chua / 8322 7418	SLG4424E	13/8/2019	
2	HELENA TAN	MT/1052090-002	GBC4504Y	CYS AUTOMOBILE SERVICES PTE LTD	WOODLANDS INDUSTRIAL PARK E1 #07-17 ADMIRALTY IND PARK SINGAPORE 757700	Ms Tee Wee Sin / 62192098	FBL5374B	5/7/2019	
3	JEFF LIN	MT/1057583-002	SLV2243U	LIAN HER MOTORS	BLK 5038 #01-405 ANG MO KIO INDUSTRIAL PARK 2	Anthony Cheong / 91082728	SMJ284R	14/8/2019	1/8/2019
4	WO JESSIE	MT/1058357-002	SHB6644Y	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2-A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	Ms Lynn or Ms Irene / 65425119	PC7436A	17/8/2019	6542 7162
5	WO JESSIE	MT/1058567-001	SHD3069S	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2-A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	Ms Lynn or Ms Irene / 65425119	SGC269T	18/8/2019	6542 7162

6	QUEK SWEE KENG	MT/1058552-001	SHC286G	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2-A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	Ms Lynn or Ms Irene / 65425119	GW57H	19/8/2019	6542 7162
7	CYNDIIE YONG	MT/1058466-002	SHD9692C	TRANS-CAB AUTO SERVICES PTE. LTD.	2 ANG MO KIO STREET 63	Kek Zhewei / 62876666	SJJ4142B	19/8/2019	Avoid Lunch time : 12pm - 1pm.
8	WO JESSIE	MT/1058662-002	SHF724T	TRANS-CAB AUTO SERVICES PTE. LTD.	2 ANG MO KIO STREET 63	Candy Kong / 62876666	SJX1594B	17/8/2019	Avoid Lunch time : 12pm - 1pm.
9	CYNDIIE YONG	MT/1058299-002	SHD9594C	TRANS-CAB AUTO SERVICES PTE. LTD.	2 ANG MO KIO STREET 63	Candy Kong / 62876666	SJV6028Y	19/8/2019	avoid Lunch time : 12pm - 1pm.
10	WO JESSIE	MT/1058686-001	SHC5166L	TRANS-CAB AUTO SERVICES PTE. LTD.	2 ANG MO KIO STREET 63	Kek Zhewei / 62876666	FW7741G	19/8/2019	
11	OFFICER IN CHARGE WILL REVERT LATER	MT/1058708-001	SHC5845K	TRANS-CAB AUTO SERVICES PTE. LTD.	2 ANG MO KIO STREET 63	Candy Kong / 62876666	XE1317U	17/8/2019	Avoid Lunch time : 12pm - 1pm.
12	QUEK SWEE KENG	MT/1058335-002	SHD448B	TRANS-CAB AUTO SERVICES PTE. LTD.	2 ANG MO KIO STREET 63	Amanda Tay / 62876666	SKF2699J	17/8/2019	Avoid Lunch time : 12pm - 1pm.

Veron Chen (LKKAuto)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Friday, 23 August 2019 4:46 PM
To: Veron Chen (LKKAuto)
Cc: 'Jasmine Tan'; 'claims'
Subject: RE: BOOK VALUE

Hi Veron

Please see below for the Net Book Value.

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]
Sent: Friday, 23 August, 2019 12:47 PM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>; calvin.er@transcab.com.sg
Cc: jasminetan@transcab.com.sg
Subject: BOOK VALUE

Dear Wai Yin/Calvin,

Please provides book value

- 1) SHD 48Y-DOA: 15/8/19 -- AAD1908-108 \$ 44,654.41
- 2) SHF 649C-DOA:-12/8/19 – AAD1908-074 \$ 40,996.64
- 3) SHD 448B-DOA:17/8/19 – AAD1908-130 \$ 63,690.61

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAUTO)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Thursday, 5 September 2019 12:01 PM
To: Veron Chen (LKKAUTO)
Cc: SUR; 'Jasmine Tan'
Subject: FW: SHD 448B-DOA: 17/8/2019 -- AAD1908-130
Attachments: MARK EST.pdf

Hi Veron

Amount confirmed \$ 1,569.48 (before GST).

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Veron Chen (LKKAUTO) [<mailto:veronchen@lkkauto.com>]
Sent: Wednesday, 4 September, 2019 9:03 AM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>; calvin.er@transcab.com.sg
Cc: SUR <sur@lkkauto.com>; jasminetan@transcab.com.sg
Subject: SHD 448B-DOA: 17/8/2019

Dear Wai Yin/Calvin,

WITHOUT PREJUDICE

Amount \$1569.48 before GST @ 2 working days

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 4 September 2019 9:03 AM
To: Ng Wai Yin; calvin.er@transcab.com.sg
Cc: SUR; jasminetan@transcab.com.sg
Subject: SHD 448B-DOA: 17/8/2019
Attachments: MARK EST.pdf

Dear Wai Yin/Calvin,

WITHOUT PREJUDICE

Amount \$1569.48 before GST @ 2 working days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	878K
Vehicle Details	
Vehicle No.:	SHD448B
Vehicle to be Exported:	Yes
Intended Deregistration Date:	19 Aug 2019
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C003371
Chassis No.:	VF1ABL15AUC283351
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	16 Sep 2016
First Registration Date:	16 Sep 2016
Transfer Count:	0
Actual ARF Paid:	\$19,998.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Sep 2024
PARF Rebate Amount:	\$14,998.00
Intended COE Rebate Details	
COE Expiry Date:	15 Sep 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$42,672.00
COE Rebate Amount:	\$27,064.00
Total Rebate Amount:	\$42,062.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 19 Aug 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/08/2019 11:17
Date Of Accident	17/08/2019 13:50
Exact Location Of Accident	BLK 31 BENDEMEER ROAD CAR PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD0448B
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62876666
Vehicle Particulars	
Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VFX/P1680520
Cover Note Number	
Driver	
Name of Driver	ANG CHEE KENG
NRIC No	S7600665B
Date Of Birth	08/01/1976
Occupation	OUTDOOR
Date Of Driving Pass	03/03/2012
Driving Experience	7 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98255710
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 31 BENDEMEER ROAD #11-823
Postcode	330031
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 17.08.2019 at about 1350 hours, I was heading straight towards Blk 31 Bendemeer Road car park exit. Suddenly, I felt an impact. Vehicle B (SKF2699J) drove out from the parking lot on my left without checking for oncoming vehicle and hit onto my taxi left side portion.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKF2699J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	WANG XINHUI, JOHN
NRIC/Passport Number	S9030930G
Contact Number	90265831
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Amanda

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 448B

AAD1908-130

Not Authored

Recovery B4paing

1569.48

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration:

21 AUG 2019

SHD 448B
 VF1ABL15AUC283351
 RENAULT
 LATITUDE
 17.8.19
NTUC Income
 16/9/2016

	PART		LIST	
1	BUMPER COVER FRT	\$	<i>BULLCAT</i> 1,259.42	✓
1	BUMPER SPOILER FRT	\$	<i>SL</i> 181.75	} X
1	BUMPER ABSORBER FRT	\$	<i>SL</i> 394.68	
1	BUMPER RETAINER FRT LH	\$	<i>SL</i> 151.41	
1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88	
1	BUMPER UNDERTRAY FRT	\$	<i>SL</i> 472.83	
1	BUMPER GRILLE LOWER FRT	\$	<i>SL</i> 266.80	
1	BUMPER FOG LAMP GRILLE LH	\$	<i>SL</i> 207.21	
1	BUMPER BEAM FRT	\$	<i>R</i> 914.08	
1	HEADLAMP LH	\$	<i>SL</i> 1,184.43	
1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15	
1	FENDER PANEL FRT LH	\$	<i>R</i> 783.83	
1	WHEELARCH FRT LH	\$	<i>SL</i> 278.84	
1	FENDER BRACKET LOWER LH	\$	<i>SL</i> 15.79	
1	FENDER INSULATOR LH	\$	<i>SL</i> 130.84	
1	FRONT BRACE PANEL	\$	<i>R</i> 177.22	
1	RADIATOR GRILLE	\$	<i>SL</i> 1,707.78	
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>SL</i> 225.36	
1	RADIATOR GRILLE FRAME	\$	<i>SL</i> 1,353.75	
1	FRAME FULL SUPPORT PANEL	\$	<i>SL</i> 615.90	
1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79	
1	BONNET	\$	<i>R</i> 1,941.63	
1	BONNET INSULATOR	\$	<i>SL</i> 405.73	
1	BONNET STRUT LH	\$	<i>SL</i> 88.61	
1	BONNET STRUT RH	\$	<i>SL</i> 88.61	
1	BONNET HINGE LH	\$	<i>R</i> 348.31	
1	BONNET HINGE RH	\$	<i>R</i> 348.31	

Trans-cab Auto Services Pte Ltd

AAD1908-130

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 448B

1	BONNET LOCK	\$	305.48
1	BONNET CABLE	\$	119.19
1	BONNET CABLE COVER	\$	161.03
1	BONNET SEAL OUTER	\$	92.36
1	BONNET SEAL INNER	\$	157.28
1	AIR CLEANER BOX	\$	464.20
1	AIR CLEANER HOSE	\$	175.85
1	AIR CLEANER LOWER	\$	271.26

} X Ser

TOTAL	\$	15,655.58
10%	\$	1,565.56
	\$	14,090.02

Special Nett

1	BUMPER CLIP FRT	\$	na 66.00
1	BUMPER BRACKET CLIP FRT LH	\$	na 12.00
1	BUMPER SUPPORT CLIP FRT LH	\$	na 10.50
1	BUMPER GRILLE LOWER CLIP	\$	na 69.00
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na 70.00
2	FRAME FULL SUPPORT PANEL NUT	\$	na 20.00
2	FRAME FULL SUPPORT PANEL STUD	\$	na 30.00
1	WHEELARCH CLIP FRT LH	\$	na 30.50
1	FRONT LEFT TYRE	\$	na 300.00
1	FRONT LEFT TYRE RIM	\$	na 380.00
1SET	Front licence plate with holder	\$	na 80.00
1	WINDSCREEN SEALANT	\$	na 253.80
1	FRONT WINDSCREEN MOULDING	\$	na 120.00
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	na 100.00
6	BONNET INSULATOR CLIP L70Y	\$	na 7.30
2	BONNET STRUT L70Y	\$	na 88.61
2	BONNET CABLE CLIP L70Y	\$	na 6.31
2	BONNET CABLE COVER SCREW L70Y	\$	na 10.85
1SET	RADIATOR GRILLE FRAME CLIP	\$	na 52.00
1SET	RADIATOR GRILLE SCREW	\$	na 16.00

} X

TOTAL	\$	1,722.88
--------------	-----------	-----------------

TOTAL PARTS	\$	15,812.90
--------------------	-----------	------------------

Trans-cab Auto Services Pte Ltd

AAD1908-130

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 448B

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	6,000.00	150d
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of front fender fittings, attachment and perform water seepage test.	\$	L 380.00	X
To transfer of front windscreen fittings and conduct water seepage test.	\$	5 170.00	X
To check steering geometry and computer wheel alignment	\$	7 220.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	L 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	1 170.00	X
Putty and spray painting of the affected portion.	\$	6,000.00	220d
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	nn 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X
To Check Electrical Lighting Concerned.	\$	nn 170.00	X
To rust-proofing of the affected areas.	\$	nn 170.00	X

TOTAL \$ 14,800.00

Over All Total \$ 30,612.90

PART BY PART (REPAIR DAY)

20 days
2 day

Trans-cab Auto Services Pte Ltd
 • To survey before and after repair
 • To display damaged areas and survey
 • Parts price list
 • Third party insurance
 • To replace parts
 • To repair
 • To paint
 • To rust proofing
 • To align
 • To check electrical lighting
 • To transfer of front bumper fittings, attachment and perform water seepage test.
 • To transfer of front fender fittings, attachment and perform water seepage test.
 • To transfer of front windscreen fittings and conduct water seepage test.
 • To check steering geometry and computer wheel alignment
 • To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.
 • To transfer of tire, rim and on wheel balancing.
 • Putty and spray painting of the affected portion.
 • To transfer of bonnet fittings, attachment and perform water seepage test.
 • Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.
 • To Check Electrical Lighting Concerned.
 • To rust-proofing of the affected areas.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19014778/Kvd3n2
73 BRAS BASAH ROAD Date: 10-09-2019
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556



ATTN: QUEK SWEE KENG

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKF 2699J	Veh. Inspected	SHD 448B
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1058335-002	Excess (\$)	0.00
Assign From	DANIEL KOH	Assign Date	21/08/2019

2. Vehicle Particulars & Condition

Make & Model	RENAULT LATITUDE (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	VF1ABL15AUC283351	Colour	METALLIC WHITE / RED
Odometer	287407 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	SAILUN	8 mm
L/H Front Tyre	215/60 R16	SAILUN	8 mm
R/H Rear Tyre	215/60 R16	GITI	8 mm
L/H Rear Tyre	215/60 R16	GITI	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	17/08/2019	Inspect Date / Time	21/08/2019 (11:26 AM)
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **2 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 448B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BUMPER COVER FRT	BUCKLED / CRACKED	1,259.42	1,259.42
1	BUMPER SPOILER FRT	SERVICEABLE	181.75	-
1	BUMPER ABSORBER FRT	SERVICEABLE	394.68	-
1	BUMPER RETAINER FRT LH	SERVICEABLE	151.41	-
1	BUMPER SUPPORT FRT	SERVICEABLE	123.88	-
1	BUMPER UNDERTRAY FRT	SERVICEABLE	472.83	-
1	BUMPER GRILLE LOWER FRT	SERVICEABLE	266.80	-
1	BUMPER FOG LAMP GRILLE LH	SERVICEABLE	207.21	-
1	BUMPER BEAM FRT	TO REPAIR SEE LABOUR	914.08	-
1	HEADLAMP LH	SERVICEABLE	1,184.43	-
1	HEADLAMP PANEL FRT LH	TO REPAIR SEE LABOUR	152.15	-
1	FENDER PANEL FRT LH	TO REPAIR SEE LABOUR	783.83	-
1	WHEELARCH FRT LH	SERVICEABLE	278.84	-
1	FENDER BRACKET LOWER LH	SERVICEABLE	15.79	-
1	FENDER INSULATOR LH	SERVICEABLE	130.84	-
1	FRONT BRACE PANEL	TO REPAIR SEE LABOUR	177.22	-
1	RADIATOR GRILLE	SERVICEABLE	1,707.78	-
1	RADIATOR GRILLE BADGE "RENAULT"	SERVICEABLE	225.36	-
1	RADIATOR GRILLE FRAME	SERVICEABLE	1,353.75	-
1	FRAME FULL SUPPORT PANEL	SERVICEABLE	615.90	-
1	FRAME FULL SUPPORT BRACKET	TO REPAIR SEE LABOUR	89.79	-
1	BONNET	TO REPAIR SEE LABOUR	1,941.63	-
1	BONNET STRUT LH	SERVICEABLE	88.61	-
1	BONNET STRUT RH	SERVICEABLE	88.61	-
1	BONNET HINGE LH	TO REPAIR SEE LABOUR	348.31	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BONNET HINGE RH	TO REPAIR SEE LABOUR	348.31	-
1	BONNET LOCK	SERVICEABLE	305.48	-
1	BONNET CABLE	SERVICEABLE	119.19	-
1	BONNET CABLE COVER	SERVICEABLE	161.03	-
1	BONNET SEAL OUTER	SERVICEABLE	92.36	-
1	BONNET SEAL INNER	SERVICEABLE	157.28	-
1	AIR CLEANER BOX	SERVICEABLE	464.20	-
1	AIR CLEANER HOSE	SERVICEABLE	175.85	-
1	AIR CLEANER LOWER	SERVICEABLE	271.26	-
1	BONNET INSULATOR	SERVICEABLE	405.73	-
	LESS 10% DISCOUNT		-1,565.56	-125.94
			14,090.03	1,133.48
	<u>SPECIAL NETT ITEMS</u>			
1	BUMPER CLIP FRT (SN)	NECESSARY	66.00	66.00
1	BUMPER BRACKET CLIP FRT LH (SN)	NOT NECESSARY	12.00	-
1	BUMPER SUPPORT CLIP FRT LH (SN)	NOT NECESSARY	10.50	-
1	BUMPER GRILLE LOWER CLIP (SN)	NOT NECESSARY	69.00	-
1	SET FRAME FULL SUPPORT PANEL CLIP (SN)	NOT NECESSARY	70.00	-
2	FRAME FULL SUPPORT PANEL NUT (SN)	NOT NECESSARY	20.00	-
2	FRAME FULL SUPPORT PANEL STUD (SN)	NOT NECESSARY	30.00	-
1	WHEELARCH CLIP FRT LH (SN)	NOT NECESSARY	30.50	-
1	FRONT LEFT TYRE (SN)	SERVICEABLE	300.00	-
1	FRONT LEFT TYRE RIM (SN)	SERVICEABLE	380.00	-
1	SET FRONT LICENCE PLATE WITH HOLDER (SN)	SERVICEABLE	80.00	-
1	WINDSCREEN SEALANT (SN)	NOT NECESSARY	253.80	-
1	FRONT WINDSCREEN MOULDING (SN)	NOT NECESSARY	120.00	-
1	FRONT WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
6	BONNET INSULATOR CLIP L70Y (SN)	NOT NECESSARY	7.30	-
2	BONNET STRUT L70Y (SN)	NOT NECESSARY	88.61	-
2	BONNET CABLE CLIP L70Y (SN)	NOT NECESSARY	6.31	-
2	BONNET CABLE COVER SCREW L70Y (SN)	SERVICEABLE	10.85	-
1	SET RADIATOR GRILLE FRAME CLIP (SN)	NOT NECESSARY	52.00	-

Report Ref No. CS/INC19014778/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET RADIATOR GRILLE SCREW (SN)	NOT NECESSARY	16.00	-
			1,722.87	66.00
	LABOUR			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BUMPER BEAM FRT,HEADLAMP PANEL FRT LH,FENDER PANEL FRT LH,FRONT BRACE PANEL,FRAME FULL SUPPORT BRACKET,BONNET,BONNET HINGE LH AND BONNET HINGE RH.		6,000.00	150.00
	TO TRANSFER OF FRONT BUMPER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FRONT FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FRONT WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	220.00
	TO TRANSFER OF BONNET FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.	NOT NECESSARY	170.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	-		-	-
	-		-	-
	-		-	-
			14,800.00	370.00
	GRAND TOTAL		30,612.90	1,569.48

Report Ref No. CS/INC19014778/Kvd3n2



RECOMMENDED COST OF REPAIRS (CONFIRMED)			1,569.48
--	--	--	-----------------

Report Ref No. CS/INC19014778/Kvd3n2

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

**BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE**

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.