

ASS. REC. BY:

REF: CS/INC19014785/ETf302

Special Instruction:

INVEST: SEVE

ASSIGNMENT (Office)

From (Person): Daniel Koh

of INC

Date/Time: 22.8.2019 9:47 a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBD 85702

Insured: CB 5965L

at Workshop m/s: Carz Auto Service

Tel: 83227418

of 61 Woodland Industrial Park E9 #104-04

Policy No:

Claim No: MT/1058265-002

Sum Insured:

Excess:

Make of Veh:

D.O.A. 19.8.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 22.8.19 9:55 a.m

Person Contacted: Jeslyn

Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	CB 5965L : X
	GBD 85702 : X
	Lump Sum \$13,000 confirm (Red: 16019.73; 55%)

ASS. REC. BY:

Steve

REF:

INC

ASSIGNMENT

From:

Date:

22.8.2019

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

GBD 85702

at Workshop m/s

Carz Auto Service

of 61 woodland Industrial Park E9 904-04

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☒
N/S	O/S
☐	☐

Est. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBD 85702

Yt Regn:

17/6/15

Type: M.Car / M.Cycle / Bus / Van / Truck / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Dyna 150

C.O.

2982

Colour:

Silk

A/C: Insured / Std / NI / NA

Sp Reading

T/Radio: Insured / Std / NI / NA

Eng No:

C/No:

JTFATJ5Y70K204429

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Knock / Jammed / Leaked / Burnt orBrake: Knock / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185R15C

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

19/8/19

D.O.I.

22/8/19

1147aw

Survey held at

Carz Auto

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV- 43000 22/8/19 Inform workshop Alex 13K repair limit, will confirm need to repair or not.
PV- 32257 27/8/19 Email to workshop 13K repair limit.
NV- 12743 4/9/19 Finalize confirm 13K, 12 days (ALEX)

RECEIVED 05 SEP 2019

Date/Time, File Path to?

1) 419 Typist

Date/Time, File Path to?

2)



: Prel. Report



: Final Report

Days Of Repair: 12

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Insp (\$)



: Weekend (\$)

Survey Fee:

290

Transportation:

S + RS \$

Photos

Others

TOTAL

290

Report Format:

Lump Sum / U/C: (\$)

Tp

13000+

Catherine Chong (LKK Auto)

From: Daniel Koh <daniel.koh@income.com.sg>
Sent: Thursday, 22 August, 2019 10:15 AM
To: 'assignments@lkkauto.com'
Cc: admin-d@lkkauto.com
Subject: FW: TP CASES FARMED OUT TO LKK ON 22/8/2019

Dear LKK,

Resend herewith claim ref. number & OIC

From: Daniel Koh
Sent: Thursday, 22 August 2019 9:47 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>
Cc: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>; Teng Ken Leong <kenleong.teng@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>
Subject: FW: TP CASES FARMED OUT TO LKK ON 22/8/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OIV	DOA	Adi Rei
1	DAVID PHUA	MT/1058265-002	GBD8570Z	CARZ AUTO SERVICES PTE LTD	61 WOODLANDS INDUSTRIAL PARK E9 (E9 PREMIUM) #04-04 SINGAPORE 757047	Jeslyn Chua / 8322 7418		CB5965L	19/8/2019	
2	CHRYLLIS QUAH	MT/1058537-002	XE4126J	CHENG HOE MOTOR PTE LTD	38 WOODLANDS INDUSTRIAL PARK E1 #05-04/05 ADMIRALTY IND PARK SINGAPORE 757700	Efeeda / 67556142	10:00-16:00	XD1384E	17/8/2019	
3	SERENE LIM	MT/1057986-002	YP1799S	CHEONG CHEONG MOTOR SERVICE PTE. LTD.	BLK 5032 #01-293 ANG MO KIO INDUSTRIAL PARK 2	Angela Ng / 6481 4152		YL552P	16/8/2019	

					SINGAPORE 569535					
4	JARED LIU	MT/1058602- 002	SLR6843H	L SOON AUTO SERVICES	10 ANG MO KIO INDUSTRIAL PARK 2A #03- 18 AMK AUTOPOINT SINGAPORE 568047	/ 6482 1513		GX7292T	19/8/2019	
5	WO JESSIE	MT/1058786- 001	SHC2924K	SOON HOCK MOTOR PTE LTD	10 ANG MO KIO IND PK 2- A #01-05/06 AMK AUTOPOINT SINGAPORE 568047	Lynn or Ms Irene / 65425119		SGU8990X	13/8/2019	65 or 71
6	AZHARI	MT/1058175- 002	PA9030J	THE ONE HOLDINGS PTE LTD	8 WOODLANDS INDUSTRIAL PARK E3 WOODLANDS INDUSTRIAL PARK E SINGAPORE 757786	Muhd.Hilmi Deres / 97480340	10:00- 12:00	SLZ2322D	16/8/2019	

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Daniel Koh
Senior Admin Assistant
Motor Insurance
T +65 6430 7901
www.income.com.sg

income
made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify. Find out more at Income.com.sg/careers

in wit
yo

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/08/2019 13:57
Date Of Accident	19/08/2019 09:15
Exact Location Of Accident	CROSS JUNC JALAN BOON LAY & JALAN AHMAD IBRAHIM
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBD8570Z
Insured/Policyholder	
Name Of Registered Owner	DELI HUB CATERING PTE LTD
Co Reg No	200414557H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-84217146
Alternative Phone No	OFFICE-84217146

Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA 150 MANUAL
Exact Purpose for which vehicle was being used at time of accident	COMMERCIALS UES

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	B29120951MKF
Cover Note Number	

Driver

Name of Driver	RAMOS DARYL CAGUNTAS
Work Permit No	G8463955P
Date Of Birth	14/08/1989
Occupation	OUTDOOR
Date Of Driving Pass	23/08/2016
Driving Experience	2 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84217146
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	49 JURONG EAST AVE 1 #04-01 PARC OASIS
Postcode	609781
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	JURONG WEST NPC
Police Station Address	ROAD: 700 CORPORATION ROAD , POSTCODE: 649818 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER POLICE REPORT NO : T/20190820/2040

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	CB5965L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	BUS
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	RAMOS DARYL CAGUNTAS
Approximate Age	30
Injuries Sustain	CHEST AND NECK
Injured person in which vehicle?	GBD8570Z
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	YES
Address	49 JURONG WET AVE 1 #04-01 PARC OASIS
Postcode	609781

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to police report
Police report number T/20190820/2040

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

quarant SketchPlanForm_V3



**SINGAPORE
POLICE FORCE**



T/20190820/2040

1 of 3

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

Report No. T/20190820/2040

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/08/2019 11:33		Vide Report No.:		Station Diary No.: 47	
Informant's Particulars					
Name of Informant: RAMOS DARYL CAGUNTAS			Address: 49 JURONG EAST AVENUE 1 #04-01 PARC OASIS SINGAPORE 609781		
ID Type / ID No.: FIN NO / G8463955P			Contact No.: Home/Office: Mobile: 84217146		
Nationality: FILIPINO			Email:		
Sex: Male	Age: 30	Date of Birth: 14/08/1989	Type of Informant: Driver		
Race: Others			Language:		Institution / School Name:
Occupation: CATERING EXECUTIVE			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 19/08/2019 09:15	Type of Location: X-Junction
Location: Along Road 1 Traveling Toward Road 2 JALAN BOON LAY JALAN AHMAD IBRAHIM The cross junction of Jalan Boon Lay and Jalan Ahmad Ibrahim				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
CB5965L	Bus/Coach/Minibus				Seriously Damaged	0
GBD8570Z	Lorry				Seriously Damaged	0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190820/2040

2 of 3

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

Report No. T/20190820/2040

CONTINUATION OF REPORT

Driver			
Name	RAMOS DARYL CAGUNTAS	ID No.	G8463955P
Related Vehicle	GBD8570Z (Lorry)	Contact No.	84217146
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	19/08/2019	Date Discharge	19/08/2019
No. of Days granted Medical Leave	05	Degree of Injury	Slight

Brief Details.

On the above mentioned date and time, I was driving my company vehicle GBD8570Z along Jalan Boon Lay and I proceeding straight. I did so as the traffic light was green in my favour. Subsequently, a bus CB5965L came speeding from my left side (Jalan Ahmad Ibrahim) and the front of said bus collided with the left side of my vehicle. The impact of the collision caused my vehicle to swerve to the right. Due to the collision, I suffered pains to my chest and neck and an ambulance was called for me. I was then conveyed to NTFGH and did not manage to exchange particulars with the driver. At the hospital, I was treated and discharged on the same day; was issued a five-day medical certificate (MC), ref: 58595768. My vehicle was too damaged to move hence it was towed away. Subsequently, a witness contacted my company and informed that he has video footage of the incident. The witness is namely;

Jeffrey Yeo, HP: 96806602

Traffic Police were also at scene and I was issued a case card J/20190819/0052, IO: Daniel Yan, TEL: 65476252



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999



T/20190820/2040

3 of 3

Report No. T/20190820/2040

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: J / Sgt 2 CHIA SHUN ZHENG	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 20/08/2019 11:33
Officer In Charge Of Case: TP / GIT / Sr Staff Sgt RAZIZ BIN TAHAR Contact No.: 65476200	Classification Of Case:
Authentication Stamp NP158 Signature:	

2017 Toyota Corolla
Ailis new Facelift

Nice / Rare Vehicle
Registration Number

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Choose from our best classified listings having great views!



View more...
Ailis new Facelift
Ailis new Facelift
Ailis new Facelift
Ailis new Facelift



Post an Ad Advertiser Login Ways of Selling

Show to Category + Back (5 2) Home Sort by Date Posted 10 results/page

21 vehicles									
Items date									
Toyota Dyna									
Price Depreciation Year Cost Mileage Vch Type Status									
Search Selection									
Toyota Dyna 150 3.0M									
Fuel Type: Diesel									
In House Loan Available! Full Cash! Trade In Available. Power Combined With Reliability! (OWNERS! Genuine Mileage! Best Condition Guaranteed! No Repairs Needed! Most Reliable Popular Lorry For Business Usage. Contact Us To Arrange For Viewing.									
Car (5) Pte Ltd									
Posted: 19-Aug-2015 Tags: 2015 Toyota Dyna, 2015 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Used Toyota									
Toyota Dyna 150 3.0M									
Fuel Type: Diesel									
The Most Fuel Efficiency And Reliable Dyna 197T Lorry! Low Mileage! Powerful Engine! Low Fuel Consumption! Very Good Condition, Call Now For Viewing And Test Drive.									
Posted: 19-Jul-2015 Tags: 2015 Toyota Dyna, 2015 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Used Toyota									
Toyota Dyna 150 3.0M									
Fuel Type: Diesel									
Power Sunroof, BT215 Tyres, Reverse Camera, Front Recorder Camera, Window Sunshade.									
Posted: 19-Jul-2015 Tags: 2015 Toyota Dyna, 2015 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Used Toyota									
Toyota Dyna 150 3.0M									
Fuel Type: Diesel									
New Arrival One Ownership, Low Mileage, Original Paint, Accident Free And Full Gas Plate One Year Road Tax Call Now To View									
Posted: 19-Aug-2015 Tags: 2015 Toyota Dyna, 2015 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Used Toyota									
The Mitsubishi Outlander is no-frills good									
The Mitsubishi Outlander now comes with a 2.0-litre four-cylinder engine, and is more appealing than ever.									
Find out more!									
Toyota Dyna 150 3.0M									
Fuel Type: Diesel									
Well Maintained LHM, High Loan And High Trade In Is Available, Don't Miss This New LHM! Call Now For Viewing									
Company Auto									
Posted: 19-Aug-2015 Tags: 2015 Toyota Dyna, 2015 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Used Toyota									
Toyota Dyna 150 3.0M									
Fuel Type: Diesel									
1 Owner! Most Reliable And Hardly Used In Market! Vehicle In Good Condition! Buy With Confidence! High Trade In Available! Up To 100% Loan! Call Our Friendly Staff For Your Very Own Viewing Now!									
Red Lion Motors Pte Ltd									
Posted: 19-Aug-2015 Tags: 2015 Toyota Dyna, 2015 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Used Toyota									
Toyota Dyna 150 3.0M									
Fuel Type: Diesel									
1 Owner Unit, Come With 2 High Seated Car Seats! Excellent Working Condition, Come With Fresh Coat Of Paintwork Worth \$1000, Newly Worn Seats Upholstery Worth \$200, Full Checked Rate That Cost \$1000 & Half Camper That Cost \$750! Lots Of Saving...									
Car (5) Pte Ltd									
Posted: 19-Aug-2015 Tags: 2015 Toyota Dyna, 2015 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Used Toyota									
Toyota Dyna 150 3.0M									
Fuel Type: Diesel									
Vehicle In Fantastic Condition.									
Posted: 19-Aug-2015 Tags: 2015 Toyota Dyna, 2015 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Used Toyota									
Toyota Dyna 150 3.0M									
Fuel Type: Diesel									
1 Owner, Original Paintwork, Accident Free, High Trade In And Flexible Loan Available, Please Call For Test Drive Now.									
Posted: 19-Aug-2015 Tags: 2015 Toyota Dyna, 2015 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Used Toyota									
Toyota Dyna 150 3.0M									
Fuel Type: Diesel									
Most Saving For Freezer Truck Needed, In Top Top Good Condition Like Brand New, Temperature At Negative 20 Degree! Big Storage Space! Definitely Keeping Your Frozen Food At 24 Hours! No Repairs Needed, Flexible Loan Packages, 100% Loan Available! Good Buy...									
Car (5) Pte Ltd									
Posted: 19-Aug-2015 Tags: 2015 Toyota Dyna, 2015 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Used Toyota									
Sell with Gstar! Get \$3,000 more than Trade-In!									
Trading? Owners who sell with sgCarMart! Quite receive up to \$3,000 above market value, getting you the highest selling price in SG. Get your Free Car Valuation Today.									
Find out more!									
Followers									
Toyota Dyna 150 3.0M									
Price Depreciation Year Cost Mileage Vch Type Status									



Fuel Type: Diesel
Super Good Condition! 18 Feet Lorry, No Repairs Needed. Buy With Peace Of Mind. 1 Owner Only. Call Now Before This Beauty Gone.
Model: 2015 Toyota Dyna **Tags:** 2015 Toyota Dyna, 2015 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna



Toyota Dyna 150 3.0M **\$41,888** **\$5,322 /yr** **04-Sep-2015** **2,982 cc** **-** **Truck** **Available**
Fuel Type: Diesel
1 Owner Only! Well Maintained, Comes With A Full Canopy. Excellent Condition! In House Loan Available, High Trade In Available. Call For More Enquiries!
By: Vap Motor Trading
Model: 2015 Toyota Dyna **Tags:** 2015 Toyota Dyna, 2015 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna



Toyota Dyna 150 3.0M **\$42,800** **\$7,100 /yr** **11-Oct-2015** **2,982 cc** **58,300 km** **Truck** **Available**
Fuel Type: Diesel
Only 1 Owner! Very Rare Unit Of Low Mileage And Super Ultra Used! Even The Original Upholstery Looks Like New! Well No More Before Its Gone. One Of The Very Good Condition In Singapore, Almost Like New. Come Down Test Drive! You Will Not Regret Buying...
Car (3) Per Lot
Model: 2015 Toyota Dyna **Tags:** 2015 Toyota Dyna, 2015 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna



Toyota Dyna 150 3.0M **\$44,888** **\$7,290 /yr** **26-Oct-2015** **2,982 cc** **-** **Truck** **Available**
Fuel Type: Diesel
Well Available And Handy Model In Market! Vehicle In Good Condition! Buy With Confidence! High Trade In Available! Up To 100% Loan!
Call Our Friendly Staff For Your Very Own Viewing Now!
Net LTR Parkers Per Lot
Model: 2015 Toyota Dyna **Tags:** 2015 Toyota Dyna, 2015 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna



Toyota Dyna 150 3.0M **\$43,888** **\$7,080 /yr** **02-Nov-2015** **2,982 cc** **-** **Truck** **Available**
Fuel Type: Diesel
Low Interest Rate With 100% In House Loan/High Trade In, View By Appointment...Call Our Friendly Sales Person Now!
40000 (1994) Per Lot
Model: 2015 Toyota Dyna **Tags:** 2015 Toyota Dyna, 2015 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna



Toyota Dyna 150 3.0M **\$45,800** **\$7,360 /yr** **11-Nov-2015** **2,982 cc** **-** **Truck** **Available**
Fuel Type: Diesel
Fully Serviced By Barrow Motors. Guarantee No Leak And Genuine Condition. Low Mileage. Very Original Exterior And Interior. 1 Owner. Comes With Open Top Canopy Worth \$1,000. 100% Accident Free. Come And See!
Model: 2015 Toyota Dyna **Tags:** 2015 Toyota Dyna, 2015 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna



Toyota Dyna 150 3.0M **\$42,800** **\$6,850 /yr** **19-Nov-2015** **2,982 cc** **-** **Truck** **Available**
Fuel Type: Diesel
1 Owner. Good Condition, High In House Loan Available! Call Our Friendly Sales Team For Viewing Now.
40000 (1994) Per Lot
Model: 2015 Toyota Dyna **Tags:** 2015 Toyota Dyna, 2015 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna



Toyota Dyna 150 3.0M **\$45,888** **\$7,180 /yr** **26-Nov-2015** **2,982 cc** **60,246 km** **Truck** **Available**
Fuel Type: Diesel
Best Deal! Tremendously Well Maintained By 1 Private Owner! Low Mileage, Accident Free! Ideal For All Types Of Business Usage! Low On Diesel And Maintenance Costs! Test Drive To Believe It! Feel Free To Call Now!
Model: 2015 Toyota Dyna **Tags:** 2015 Toyota Dyna, 2015 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna



Toyota Dyna 150 3.0M **\$43,888** **\$6,510 /yr** **04-Dec-2015** **2,982 cc** **56,000 km** **Truck** **Available**
Fuel Type: Diesel
1 Owner, Accident Free, Low Mileage Done, No Leak And No Repair Needed, Workshop Inspection Welcome. 100% Loan Available. Bank In House Finance Loan Packages All Available. Price Negotiable. Arranged For Viewing Now!
Model: 2015 Toyota Dyna **Tags:** 2015 Toyota Dyna, 2015 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna



Toyota Dyna 150 3.0M **\$41,888** **\$6,375 /yr** **11-Dec-2015** **2,982 cc** **-** **Truck** **Available**
Fuel Type: Diesel
Please Call To Arrange For Viewing, Thanks.
Model: 2015 Toyota Dyna **Tags:** 2015 Toyota Dyna, 2015 Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna, Toyota Dyna

Save the search criteria, to get email alerts whenever a match is found.

Model Price Depreciation Fuel Type Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads.

< Back (5 / 2) Next >

20 results/page

Home New Cars Used Cars Sell My Car Directory Products Insurance Article Forum Resources

sgCarMart is the number one car classified for parallel-import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from entry trucks, water cars, luxury cars, sports cars or ultra-luxury cars, MPV, hatchbacks, 4x4 cars & SUV cars. You can also buy from a car auction, take up job loans, financial services, low mileage cars, car brands, car parts & car accessories. Find the used Toyota cars, Toyota Dyna Singapore, used Toyota Dyna Singapore, used Toyota Dyna, used Toyota Singapore or even buy used Toyota from Singapore. We have new car dealers, car financing services, car insurance, car dealers, and car dealers at our site. Find new car price lists, new car launches and new car promotions. Visit our website for job openings for Singapore with our career opportunities for sales, service, car performance parts, car accessories, car insurance, car financing, car insurance, car insurance & car insurance.

All prices and other information displayed on sgCarMart.com are gathered from various and based on algorithms that are selected by sgCarMart.com to be reliable, but no assurance can be given that the information is accurate, complete or correct. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of the information.

Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap Terms of Service | Privacy Policy | Personal Data Protection Statement
©2014-2019 sgCarMart. All rights reserved.



CARZ AUTO SERVICES PTE LTD

UEN/ GST 201409457D

61 WOODLANDS INDUSTRIAL PARK E9 (E9 PREMIUM) #04-04 Singapore 757047

Email: alex@carzauto.com.sg

Tel: 65 6493 1924

Fax: 65 6493 1928

Insurance Company: NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Address: 75 Bras Basah Road (NTUC INCOME CENTRE), Singapore 189557

Telephone: 6788 6616

Fax: 6338 1500

Email:

Make/ Model: TOYOTA DYNA

Date: 21/8/2019

Chassis No: JTEAT35Y70K204429

Vehicle No: GBD 8570 Z

Date/Time of Accident: 19/8/2019 9:15

Materials Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$	PARTS DISCOUNT	FINAL PRICE \$
1	FRONT BUMPER / DD	1	\$ 475.80	25%	\$ 356.85
2	FRONT BUMPER BRACKET X NAI	2	\$ 378.00	25%	\$ 283.50
3	FRONT TOWING HOOD X NAI	1	\$ 206.70	25%	\$ 155.03
4	FRONT RADIATOR GRILLE / BR	1	\$ 509.10	25%	\$ 381.83
5	FRONT RADIATOR GRILLE SEAL / MC	1	\$ 21.83	25%	\$ 16.37
6	FRONT RADIATOR GRILLE BRACKET X NAI	2	\$ 90.22	25%	\$ 67.67
7	FRONT HEAD LAMP RH ? / LH / BR	2	\$ 631.65	25%	\$ 473.74
8	FRONT CORNER PANEL LH / DD	1	\$ 255.50	25%	\$ 191.63
9	FRONT CORNER PANEL GARNISH LH (BLACK) / MJS	1	\$ 255.50	25%	\$ 191.63
10	FRONT HEAD LAMP SIDE GARNISH / BR	2	\$ 14.61/29.22	25%	\$ 21.92
11	FRONT CENTRE PANEL / DD	1	\$ 1,012.30	25%	\$ 759.23
12	FRONT CENTRE PANEL GARNISH (BLACK) X BR NAI	1	\$ 313.20	25%	\$ 234.90
13	FRONT CENTRE PANEL EMBLEM X NAI	1	\$ 64.85	25%	\$ 48.64
14	FRONT PANEL "DYNA" EMBLEM X NAI	1	\$ 55.20	25%	\$ 41.40
15	CABIN FLOOR PANEL ? / DD	1	\$ 579.50	25%	\$ 434.63
16	CABIN MOUNTING SET ? X NN	1	\$ 346.10	25%	\$ 259.58
17	FRONT WIPER PANEL / DD	1	\$ 368.70	25%	\$ 276.53
18	FRONT WIPER ARM X NAI	2	\$ 122.80	25%	\$ 92.10
19	FRONT WIPER SCREW COVER / MJS	1	\$ 8.41/16.80	25%	\$ 12.60
20	FRONT WIPER ARM LINK ? X NN	1	\$ 324.60	25%	\$ 243.45
21	FRONT WIPER MOTOR X NN	1	\$ 807.60	25%	\$ 605.70
22	FRONT WINDSCREEN GLASS / BR	1	\$ 1,340.30	25%	\$ 1,005.23
23	FRONT WINDSCREEN MOULDING / CRV	1	\$ 283.40	25%	\$ 212.55
24	FRONT SIDE MIRROR LH / MJS	1	\$ 543.80	25%	\$ 407.85
25	FRONT SIDE MIRROR BRACKET LH / MJS	1	\$ 20.40	25%	\$ 15.30
26	FRONT SIDE MIRROR COVER LH / MJS	1	\$ 127.10	25%	\$ 95.33
27	FRONT SIDE MIRROR STAND LH X NN	1	\$ 242.80	25%	\$ 182.10
28	FRONT DOOR / DD	2	\$ 1,682.80	25%	\$ 1,262.10
29	FRONT DOOR HINGE / DD	2	\$ 434.5/86.90	25%	\$ 65.18
30	FRONT DOOR GLASS LH / BR	1	\$ 436.80	25%	\$ 327.60
31	FRONT DOOR OUTER DOOR HANDLE LH / BR	1	\$ 185.60	25%	\$ 139.20
32	FRONT DOOR INNER DOOR HANDLE LH / CRV	1	\$ 56.00	25%	\$ 42.00
33	FRONT DOOR PILLAR INNER LH / DD	1	\$ 366.60	25%	\$ 274.95
34	FRONT DOOR PILLAR INNER GARNISH LH / CRV	1	\$ 132.70	25%	\$ 99.53
35	FRONT DOOR PILLAR OUTER LH / DD	1	\$ 398.60	25%	\$ 298.95

36	FRONT DOOR INNER TRIM BOARD LH / CRV	1	\$	718.00	25%	\$	538.50
37	FRONT DOOR GLASS RUN CHANNEL LH / DD	1	\$	236.00	25%	\$	177.00
38	FRONT DOOR WEATHERSTRIP / CRV	1	\$	182.60	25%	\$	136.95
39	FRONT DOOR GLASS RUBBER / CVT	1	\$	124.50	25%	\$	93.38
40	FRONT DOOR OUTER MOULDING / CVT	1	\$	135.30	25%	\$	101.48
41	FRONT DOOR GLASS MOTOR LH ? / JOINED	1	\$	613.70	25%	\$	460.28
42	FRONT DOOR GLASS REGULATOR LH / DD	1	\$	275.00	25%	\$	206.25
43	FRONT DOOR POWER WINDOW SWITCH LH X NN	1	\$	112.00	25%	\$	84.00
44	FRONT DOOR LOCK ASSY LH / JOINED	1	\$	111.75	25%	\$	83.81
45	FRONT DOOR INNER CHECKER LH X NN	1	\$	46.43	25%	\$	34.82
46	FRONT STEP PANEL LH ? / DD	1	\$	150.79	25%	\$	113.09
47	FRONT HORN LH X NN	1	\$	45.12	25%	\$	33.84
48	FRONT A/C CONDENSER ? / DD	1	\$	785.40	25%	\$	589.05
49	FRONT A/C DISCHARGE PIPE X NN	1	\$	186.50	25%	\$	139.88
50	FRONT A/C LIQUID PIPE X NN	1	\$	160.60	25%	\$	120.45
51	FRONT A/C BLOWER MOTOR ASSY ? / BR	1	\$	1,809.98	25%	\$	1,357.49
52	FRONT A/C COOLING COIL ASSY ? / BR	1	\$	1,455.75	25%	\$	1,091.81
53	FRONT A/C FAN ASSY X NN	1	\$	1,322.55	25%	\$	991.91
54	FRONT RADIATOR ? X NN	1	\$	2,351.30	25%	\$	1,763.48
55	FRONT RADIATOR FAN BLADE ? X NN	1	\$	223.00	25%	\$	167.25
56	FRONT RADIATOR FAN COWING BOTTOM ? X NN	1	\$	228.50	25%	\$	171.38
57	FRONT RADIATOR TOP HOSE X NN	1	\$	44.40	25%	\$	33.30
58	FRONT RADIATOR BOTTOM HOSE X NN	1	\$	63.80	25%	\$	47.85
59	FRONT RADIATOR PRESSURE SWITCH X NN	1	\$	126.40	25%	\$	94.80
60	FRONT DASHBOARD ASSY / CRV	1	\$	965.50	25%	\$	724.13
61	FRONT DASHBOARD AUDIO CASING / CRV	1	\$	533.50	25%	\$	400.13
62	FRONT SPEEDOMETER ASSY / BR	1	\$	985.65	25%	\$	739.24
63	FRONT DASHBOARD CONSOLE COVER (LH) CRV	1	\$	454.75	25%	\$	341.06
64	FRONT WASHER TANK ? X NN	1	\$	154.80	25%	\$	116.10
65	FRONT FUSE BOX ? X NN	1	\$	230.20	25%	\$	172.65
66	FRONT STEERING TIE ROD END X NN	2	\$	123.80	25%	\$	92.85
67	FRONT WHEEL KNUCKLE ARM X NN	2	\$	367.50	25%	\$	275.63
68	FRONT WHEEL LOWER ARM LH X NN	1	\$	268.70	25%	\$	201.53
69	FRONT WHEEL TOP ARM LH X NN	1	\$	258.20	25%	\$	193.65
70	FRONT WHEEL BEARING X NN	2	\$	55.40	25%	\$	41.55
71	FRONT WHEEL SHOCKABSOBER X NN	2	\$	126.90	25%	\$	95.18
72	FRONT ENGINE MOUNTING ? X NN	2	\$	122.40	25%	\$	91.80
73	FRONT GEAR BOX MOUNTING ? X NN	2	\$	110.00	25%	\$	82.50

SPECIAL ITEMS	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	FRONT RADIATOR GRILLE CLIP / NPC	1 SET	\$ 30.00	\$ 22 30.00
2	FRONT WINDSCREEN GLASS SEALANT X NN	2	\$ 60.00	\$ 60.00
3	FRONT ERP BRACKET / NPC	1	\$ 24.00	\$ 22 24.00
4	FRONT DOOR COMPANY STICKER / NPC	2	\$ 48.00	\$ 48.00
5	FRONT WHEEL RIM TYRE LH X BE NN	1	\$ 150.00	\$ 150.00
6	FRONT WHEEL RIM LH / DT	1	\$ 320.00	\$ 200 320.00
7	FRONT WIPER BLADE / BR	1 SET	\$ 90.00	\$ 50 90.00
Total Cost				\$ 22,498.73

17605.81
- 25%
13,204.35

338

Labour Works/ Panel Beating Related Works	
Job Scope	Quotation
TO RENEW FRONT DAMAGED PARTS, REPLACED AND REALIGNED HYDRAULIC, ALIGNED ALL PARTS	\$ 2,500.00
Spray Painting	
Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 1,600.00
Others Cost (Accident Repair Related Expenses)	
Job Scope	Quotation
TOWING	\$ 150.00
TO CONDUCT WATER LEAKAGE TEST	\$ 100.00
TO REMOVE AND RENEW FRONT AND REAR DOOR MECHANISM	\$ 200.00
REAR CHASSIS ALIGNMENT	\$ 250.00
TO TUFFCOAT AFFECT AREAS	\$ 150.00
TO RENEW FRONT WINDSCREEN GLASS	\$ 150.00
TO RENEW ENGINE MOUNTING AND GEAR BOX MOUNTING	\$ 250.00
TO REMOVE/REFIT AIRCON CONDENSOR, PIPINGS, VACUUM AND RECHARGE AIRCON GAS	\$ 180.00
TO REMOVE/REFIT REPLACE DASHBOARD	\$ 200.00
TO REMOVE AND REFIT INTERIOR UPHOLSTERY, CUSHION SEAT AND CLEANING	\$ 150.00
TO REMOVER/REFIT WIRING CHECK	\$ 60.00
TO REMOVE/REPLACE SIDE PANEL & ALUMINIUM	\$ 150.00
TO REMOVE/REPLACE FRONT UNDERCARRIAGE LH	\$ 350.00
TO FOUR WHEEL ALIGNMENT	\$ 80.00
Total Others Cost	\$ 2,420.00
GRAND TOTAL	\$ 29,018.73

1600

800

1000

60

30

50

X

30

100

? X

? 100

100

100

30

X

X

60

3260

Steve (LKK)

8377 8813

VHL Rep'dir 22/5/19, 1230pm

12 day

L/S

By AL sy



CARZ AUTO SERVICES PTE LTD

Person Incharge: Ms Jeslyn Chua
 Job Title: Motor Claim
 Mobile: 65 8322 7418
 Email: jeslyn@carzauto.com.sg

P - 13,209.35

AI - 338

L - 3260

16,802.35

L/S - 13,441.88

= 13,450.00

limit repair - 13K

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



CARZ AUTO SERVICES PTE LTD

UEN/ GST 201409457D

61 WOODLANDS IND PARK E9 (E9 PREMIUM) #04-04 Singapore 757047

Email: alex@carzauto.com.sg

Tel: 65 6493 1924

Fax: 65 6493 1928

Insurance Company: NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Address: 75 Bras Basah Road (NTUC INCOME CENTRE), Singapore 189557

Telephone: 6788 6616

Fax: 6338 1500

Email:

Make/ Model : TOYOTA DYNA

Date: 21/8/2019

Chassis No : JTFAT35Y70K204429

Vehicle No: GBD 8570 Z

Date/Time of Accident : 19/8/2019 9:15

Steve 26/8/19, 2.47pm

Materials Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$	PARTS DISCOUNT	FINAL PRICE \$
1	FRONT BUMPER / DD	1	\$ 475.80	25%	\$ 356.85
2	FRONT BUMPER BRACKET X	2	\$ 378.00	25%	\$ 283.50
3	FRONT TOWING HOOD X	1	\$ 206.70	25%	\$ 155.03
4	FRONT RADIATOR GRILLE / BR	1	\$ 509.10	25%	\$ 381.83
5	FRONT RADIATOR GRILLE SEAL / MC	1	\$ 21.83	25%	\$ 16.37
6	FRONT RADIATOR GRILLE BRACKET X	2	\$ 90.22	25%	\$ 67.67
7	FRONT HEAD LAMP RH ? / BLH / OR	2	\$ 631.65	25%	\$ 473.74
8	FRONT CORNER PANEL LH / DD	1	\$ 255.50	25%	\$ 191.63
9	FRONT CORNER PANEL GARNISH LH (BLACK) / MJ	1	\$ 255.50	25%	\$ 191.63
10	FRONT HEAD LAMP SIDE GARNISH / BR	2	\$ 29.22	25%	\$ 21.92
11	FRONT CENTRE PANEL / DD	1	\$ 1,012.30	25%	\$ 759.23
12	FRONT CENTRE PANEL GARNISH (BLACK) X BR	1	\$ 313.20	25%	\$ 234.90
13	FRONT CENTRE PANEL EMBLEM X	1	\$ 64.85	25%	\$ 48.64
14	FRONT PANEL "DYNA" EMBLEM X	1	\$ 55.20	25%	\$ 41.40
15	CABIN FLOOR PANEL ? / DD	1	\$ 579.50	25%	\$ 434.63
16	CABIN MOUNTING SET ? X	1	\$ 346.10	25%	\$ 259.58
17	FRONT WIPER PANEL / DD	1	\$ 368.70	25%	\$ 276.53
18	FRONT WIPER ARM X	2	\$ 122.80	25%	\$ 92.10
19	FRONT WIPER SCREW COVER / MJ	12	\$ 16.80	25%	\$ 12.60
20	FRONT WIPER ARM LINK ? X	1	\$ 324.60	25%	\$ 243.45
21	FRONT WIPER MOTOR X	1	\$ 807.60	25%	\$ 605.70
22	FRONT WINDSCREEN GLASS / BR	1	\$ 1,340.30	25%	\$ 1,005.23
23	FRONT WINDSCREEN MOULDING / CRV	1	\$ 283.40	25%	\$ 212.55
24	FRONT SIDE MIRROR LH / MJ	1	\$ 543.80	25%	\$ 407.85
25	FRONT SIDE MIRROR BRACKET LH / MJ	1	\$ 20.40	25%	\$ 15.30
26	FRONT SIDE MIRROR COVER LH / MJ	1	\$ 127.10	25%	\$ 95.33
27	FRONT SIDE MIRROR STAND LH X	1	\$ 242.80	25%	\$ 182.10
28	FRONT DOOR / DD	2	\$ 1,682.80	25%	\$ 1,262.10
29	FRONT DOOR HINGE / DD	4	\$ 86.90	25%	\$ 65.18
30	FRONT DOOR GLASS LH / BR	1	\$ 436.80	25%	\$ 327.60
31	FRONT DOOR OUTER DOOR HANDLE LH / BR	1	\$ 185.60	25%	\$ 139.20
32	FRONT DOOR INNER DOOR HANDLE LH / CRV	1	\$ 56.00	25%	\$ 42.00
33	FRONT DOOR PILLAR INNER LH / DD	1	\$ 366.60	25%	\$ 274.95
34	FRONT DOOR PILLAR INNER GARNISH LH / CRV	1	\$ 132.70	25%	\$ 99.53
35	FRONT DOOR PILLAR OUTER LH / DD	1	\$ 398.60	25%	\$ 298.95

Steve Chen (LKK Auto)

From: alex@carzauto.com.sg
Sent: Wednesday, September 04, 2019 9:44 AM
To: Steve Chen (LKK Auto)
Cc: jeslyn@carzauto.com.sg; Denise Tay (LKKAuto)
Subject: RE: FINALIZE GBD 8570 Z

Hi Steve
We are able to accepted your offer @ lamp sum \$13k/- 12 days

Thanks Regards

Alex

-----Original Message-----

From: Steve Chen (LKK Auto) <SteveChen@lkkauto.com>
Sent: Wednesday, September 4, 2019 9:30 AM
To: alex@carzauto.com.sg
Cc: jeslyn@carzauto.com.sg; Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Subject: FINALIZE GBD 8570 Z

Dear Alex,

The above vehicle finalize 13k (L/S, before GST). 12 repair days.

Kindly confirm.

Thanks

Best Regards,
Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: alex@carzauto.com.sg [<mailto:alex@carzauto.com.sg>]
Sent: Tuesday, September 03, 2019 12:37 PM
To: Steve Chen (LKK Auto)
Cc: jeslyn@carzauto.com.sg
Subject: FINALIZE GBD 8570 Z

Hi Steve

36	FRONT DOOR INNER TRIM BOARD LH / CRV	1	\$	718.00	25%	\$	538.50
37	FRONT DOOR GLASS RUN CHANNEL LH / DD	1	\$	236.00	25%	\$	177.00
38	FRONT DOOR WEATHERSTRIP / CRV	1	\$	182.60	25%	\$	136.95
39	FRONT DOOR GLASS RUBBER / CRV	1	\$	124.50	25%	\$	93.38
40	FRONT DOOR OUTER MOULDING / CRV	1	\$	135.30	25%	\$	101.48
41	FRONT DOOR GLASS MOTOR LH / ? / Jarnid	1	\$	613.70	25%	\$	460.28
42	FRONT DOOR GLASS REGULATOR LH / DD	1	\$	275.00	25%	\$	206.25
43	FRONT DOOR POWER WINDOW SWITCH LH / X	1	\$	112.00	25%	\$	84.00
44	FRONT DOOR LOCK ASSY LH / Jarnid	1	\$	111.75	25%	\$	83.81
45	FRONT DOOR INNER CHECKER LH / X	1	\$	46.43	25%	\$	34.82
46	FRONT STEP PANEL LH / ? / DD	1	\$	150.79	25%	\$	113.09
47	FRONT HORN LH / X	1	\$	45.12	25%	\$	33.84
48	FRONT A/C CONDENSER / ? / DD	1	\$	785.40	25%	\$	589.05
49	FRONT A/C DISCHARGE PIPE / X	1	\$	186.50	25%	\$	139.88
50	FRONT A/C LIQUID PIPE / X	1	\$	160.60	25%	\$	120.45
51	FRONT A/C BLOWER MOTOR ASSY / ? / CR	1	\$	1,809.98	25%	\$	1,357.49
52	FRONT A/C COOLING COIL ASSY / ? / CR	1	\$	1,455.75	25%	\$	1,091.81
53	FRONT A/C FAN ASSY / X	1	\$	1,322.55	25%	\$	991.91
54	FRONT RADIATOR / ? / X	1	\$	2,351.30	25%	\$	1,763.48
55	FRONT RADIATOR FAN BLADE / ? / X	1	\$	223.00	25%	\$	167.25
56	FRONT RADIATOR FAN COWING BOTTOM / ? / X	1	\$	228.50	25%	\$	171.38
57	FRONT RADIATOR TOP HOSE / X	1	\$	44.40	25%	\$	33.30
58	FRONT RADIATOR BOTTOM HOSE / X	1	\$	63.80	25%	\$	47.85
59	FRONT RADIATOR PRESSURE SWITCH / X	1	\$	126.40	25%	\$	94.80
60	FRONT DASHBOARD ASSY / / CRV	1	\$	965.50	25%	\$	724.13
61	FRONT DASHBOARD AUDIO CASING / / CRV	1	\$	533.50	25%	\$	400.13
62	FRONT SPEEDOMETER ASSY / / BR	1	\$	985.65	25%	\$	739.24
63	FRONT DASHBOARD CONSOLE COVER (LH) (CRV)	1	\$	454.75	25%	\$	341.06
64	FRONT WASHER TANK / ? / X	1	\$	154.80	25%	\$	116.10
65	FRONT FUSE BOX / ? / X	1	\$	230.20	25%	\$	172.65
66	FRONT STEERING TIE ROD END / X	2	\$	123.80	25%	\$	92.85
67	FRONT WHEEL KNUCKLE ARM / X	2	\$	367.50	25%	\$	275.63
68	FRONT WHEEL LOWER ARM LH / X	1	\$	268.70	25%	\$	201.53
69	FRONT WHEEL TOP ARM LH / X	1	\$	258.20	25%	\$	193.65
70	FRONT WHEEL BEARING / X	2	\$	55.40	25%	\$	41.55
71	FRONT WHEEL SHOCKABSOBER / X	2	\$	126.90	25%	\$	95.18
72	FRONT ENGINE MOUNTING / ? / X	2	\$	122.40	25%	\$	91.80
73	FRONT GEAR BOX MOUNTING / ? / X	2	\$	110.00	25%	\$	82.50

SPECIAL ITEMS	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	FRONT RADIATOR GRILLE CLIP / / MC	1 SET	\$ 30.00	\$ 22 30.00
2	FRONT WINDSCREEN GLASS SEALANT / X	2	\$ 60.00	\$ 60.00
3	FRONT ERP BRACKET / / MC	1	\$ 24.00	\$ 70 24.00
4	FRONT DOOR COMPANY STICKER / / MC	2	\$ 48.00	\$ 48.00
5	FRONT WHEEL RIM TYRE LH / X / BE	1	\$ 150.00	\$ 150.00
6	FRONT WHEEL RIM LH / / BT	1	\$ 320.00	\$ 320.00
7	FRONT WIPER BLADE / / BR	1 SET	\$ 90.00	\$ 90.00
Total Cost				\$ 22,498.73

Labour Works/ Panel Beating Related Works	
Job Scope	Quotation
TO RENEW FRONT DAMAGED PARTS, REPLACED AND REALIGNED HYDRAULIC, ALIGNED ALL PARTS	\$ 2,500.00
Spray Painting	
Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 1,600.00
Others Cost (Accident Repair Related Expenses)	
Job Scope	Quotation
TOWING	\$ 150.00
TO CONDUCT WATER LEAKAGE TEST	\$ 100.00
TO REMOVE AND RENEW FRONT AND REAR DOOR MECHANISM	\$ 200.00
REAR CHASSIS ALIGNMENT	\$ 250.00
TO TUFFCOAT AFFECT AREAS	\$ 150.00
TO RENEW FRONT WINDSCREEN GLASS	\$ 150.00
TO RENEW ENGINE MOUNTING AND GEAR BOX MOUNTING	\$ 250.00
TO REMOVE/REFIT AIRCON CONDENSOR, PIPINGS, VACUUM AND RECHARGE AIRCON GAS	\$ 180.00
TO REMOVE/REFIT REPLACE DASHBOARD	\$ 200.00
TO REMOVE AND REFIT INTERIOR UPHOLSTERY, CUSHION SEAT AND CLEANING	\$ 150.00
TO REMOVE/REFIT WIRING CHECK	\$ 60.00
TO REMOVE/REPLACE SIDE PANEL & ALUMINIUM	\$ 150.00
TO REMOVE/REPLACE FRONT UNDERCARRIAGE LH	\$ 350.00
TO FOUR WHEEL ALIGNMENT	\$ 80.00
Total Others Cost	\$ 2,420.00
GRAND TOTAL	\$ 29,018.73



Steve (LKK)
5377 8813

W/L Rep'd 22/5/19, 12.30pm
12 days
L/I
By AL sy

CARZ AUTO SERVICES PTE LTD

Person Incharge: Ms Jeslyn Chua
Job Title: Motor Claim
Mobile: 65 8322 7418
Email: jeslyn@carzauto.com.sg



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19014785/Etf3e2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 11-09-2019



ATTN : DAVID PHUA

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	CB 5965L	Veh. Inspected	GBD 8570Z
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1058265-002	Excess (\$)	0.00
Assign From	DANIEL KOH	Assign Date	22/08/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA 150	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JTFAT35Y70K204429	Colour	SILVER
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185 R15C	YOKOHAMA	5 mm
L/H Front Tyre	185 R15C	YOKOHAMA	5 mm
R/H Rear Tyre	185 R15C	YOKOHAMA	5 mm
L/H Rear Tyre	185 R15C	YOKOHAMA	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	19/08/2019	Inspect Date / Time	22/08/2019 (11:47 AM)
Survey held at	61 WOODLAND INDUSTRIAL PARK E9 # 04-04		
Repairer	CARZ AUTO SERVICES PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	12 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 8570Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DENTED	475.80	475.80
2	FRONT BUMPER BRACKET	NOT NECESSARY	378.00	-
1	FRONT TOWING HOOD	NOT NECESSARY	206.70	-
1	FRONT RADIATOR GRILLE	BROKEN	509.10	509.10
1	FRONT RADIATOR GRILLE SEAL	NECESSARY	21.83	21.83
2	FRONT RADIATOR GRILLE BRACKET	NOT NECESSARY	90.22	-
2	FRONT HEAD LAMP	BROKEN	631.65	631.65
1	FRONT CORNER PANEL LH	DENTED	255.50	255.50
1	FRONT CORNER PANEL GARNISH LH (BLACK)	MISSING	255.50	255.50
2	FRONT HEAD LAMP SIDE GARNISH	BROKEN-1PC ONLY	29.22	14.61
1	FRONT CENTRE PANEL	DENTED	1,012.30	1,012.30
1	FRONT CENTRE PANEL GARNISH (BLACK)	NOT NECESSARY	313.20	-
1	FRONT CENTRE PANEL EMBLEM	NOT NECESSARY	64.85	-
1	FRONT PANEL "DYNA" EMBLEM	NOT NECESSARY	55.20	-
1	CABIN FLOOR PANEL	DENTED	579.50	579.50
1	SET CABIN MOUNTING	NOT NECESSARY	346.10	-
1	FRONT WIPER PANEL	DENTED	368.70	368.70
2	FRONT WIPER ARM	NOT NECESSARY	122.80	-
2	FRONT WIPER SCREW COVER	MISSING-1PC ONLY	16.80	8.40
1	FRONT WIPER ARM LINK	NOT NECESSARY	324.60	-
1	FRONT WIPER MOTOR	NOT NECESSARY	807.60	-
1	FRONT WINDSCREEN GLASS	BROKEN	1,340.30	1,340.30
1	FRONT WINDSCREEN MOULDING	CRUSHED	283.40	283.40
1	FRONT SIDE MIRROR LH	MISSING	543.80	543.80
1	FRONT SIDE MIRROR BRACKET LH	MISSING	20.40	20.40
1	FRONT SIDE MIRROR COVER LH	MISSING	127.10	127.10
1	FRONT SIDE MIRROR STAND LH	NOT NECESSARY	242.80	-
1	FRONT DOOR	DENTED	1,682.80	1,682.80
4	FRONT DOOR HINGE	DENTED-2PCS ONLY	86.90	43.45
1	FRONT DOOR GLASS LH	BROKEN	436.80	436.80

Report Ref No. CS/INC19014785/Etf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT DOOR OUTER DOOR HANDLE LH	BROKEN	185.60	185.60
1	FRONT DOOR INNER DOOR HANDLE LH	CRUSHED	56.00	56.00
1	FRONT DOOR PILLAR INNER LH	DENTED	366.60	366.60
1	FRONT DOOR PILLAR INNER GARNISH LH	CRUSHED	132.70	132.70
1	FRONT DOOR PILLAR OUTER LH	DENTED	398.60	398.60
1	FRONT DOOR INNER TRIM BOARD LH	CRUSHED	718.00	718.00
1	FRONT DOOR GLASS RUN CHANNEL LH	DENTED	236.00	236.00
1	FRONT DOOR WEATHERSTRIP	CRUSHED	182.60	182.60
1	FRONT DOOR GLASS RUBBER	CUT	124.50	124.50
1	FRONT DOOR OUTER MOULDING	CUT	135.30	135.30
1	FRONT DOOR GLASS MOTOR LH	JAMMED	613.70	613.70
1	FRONT DOOR GLASS REGULATOR LH	DENTED	275.00	275.00
1	FRONT DOOR POWER WINDOW SWITCH LH	NOT NECESSARY	112.00	-
1	FRONT DOOR LOCK ASSY LH	JAMMED	111.75	111.75
1	FRONT DOOR INNER CHECKER LH	NOT NECESSARY	46.43	-
1	FRONT STEP PANEL LH	DENTED	150.79	150.79
1	FRONT HORN LH	NOT NECESSARY	45.12	-
1	FRONT A/C CONDENSER	DENTED	785.40	785.40
1	FRONT A/C DISCHARGE PIPE	NOT NECESSARY	186.50	-
1	FRONT A/C LIQUID PIPE	NOT NECESSARY	160.60	-
1	FRONT A/C BLOWER MOTOR ASSY	BROKEN	1,809.98	1,809.98
1	FRONT A/C COOLING COIL ASSY	BROKEN	1,455.75	1,455.75
1	FRONT A/C FAN ASSY	NOT NECESSARY	1,322.55	-
1	FRONT RADIATOR	NOT NECESSARY	2,351.30	-
1	FRONT RADIATOR FAN BLADE	NOT NECESSARY	223.00	-
1	FRONT RADIATOR FAN COWING BOTTOM	NOT NECESSARY	228.50	-
1	FRONT RADIATOR TOP HOSE	NOT NECESSARY	44.40	-
1	FRONT RADIATOR BOTTOM HOSE	NOT NECESSARY	63.80	-
1	FRONT RADIATOR PRESSURE SWITCH	NOT NECESSARY	126.40	-
1	FRONT DASHBOARD ASSY	CRUSHED	965.50	965.50
1	FRONT DASHBOARD AUDIO CASING	CRUSHED	533.50	533.50
1	FRONT SPEEDOMETER ASSY	BROKEN	985.65	985.65
1	FRONT DASHBOARD CONSOLE COVER (LH)	CRUSHED	454.75	454.75

Report Ref No. CS/INC19014785/Etf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT WASHER TANK	NOT NECESSARY	154.80	-
1	FRONT FUSE BOX	NOT NECESSARY	230.20	-
2	FRONT STEERING TIE ROD END	NOT NECESSARY	123.80	-
2	FRONT WHEEL KNUCKLE ARM	NOT NECESSARY	367.50	-
1	FRONT WHEEL LOWER ARM LH	NOT NECESSARY	268.70	-
1	FRONT WHEEL TOP ARM LH	NOT NECESSARY	258.20	-
2	FRONT WHEEL BEARING	NOT NECESSARY	55.40	-
2	FRONT WHEEL SHOCK ABSORBER	NOT NECESSARY	126.90	-
2	FRONT ENGINE MOUNTING	NOT NECESSARY	122.40	-
2	FRONT GEAR BOX MOUNTING	NOT NECESSARY	110.00	-
	LESS 25% DISCOUNT		-7,258.91	-4,822.15
			21,776.73	14,466.46
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT RADIATOR GRILLE CLIP (SN)	NECESSARY	30.00	20.00
2	FRONT WINDSCREEN GLASS SEALANT (SN)	NOT NECESSARY	60.00	-
1	FRONT ERP BRACKET (SN)	NECESSARY	24.00	20.00
2	FRONT DOOR COMPANY STICKER (SN)	NECESSARY	48.00	48.00
1	FRONT WHEEL RIM TYRE LH (SN)	NOT NECESSARY	150.00	-
1	FRONT WHEEL RIM LH (SN)	BENT	320.00	200.00
1	SET FRONT WIPER BLADE (SN)	BROKEN	90.00	50.00
			722.00	338.00
	<u>LABOUR</u>			
	TO RENEW FRONT DAMAGED PARTS, REPLACED AND REALIGNED HYDRAULIC, ALIGNED ALL PARTS.		2,500.00	1,600.00
	TO RESPRAY AFFECTED AREAS.		1,600.00	1,000.00
	TOWING.		150.00	60.00
	TO CONDUCT WATER LEAKAGE TEST.		100.00	30.00
	TO REMOVE AND RENEW FRONT AND REAR DOOR MECHANISM.		200.00	50.00
	REAR CHASSIS ALIGNMENT.	NOT NECESSARY	250.00	-
	TO TUFFCOAT AFFECT AREAS.		150.00	30.00
	TO RENEW FRONT WINDSCREEN GLASS.		150.00	100.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RENEW ENGINE MOUNTING AND GEAR BOX MOUNTING.	NOT NECESSARY	250.00	-
	TO REMOVE / REFIT AIRCON CONDENSOR, PIPINGS, VACUUM AND RECHARGE AIRCON GAS.		180.00	100.00
	TO REMOVE / REFIT REPLACE DASHBOARD.		200.00	100.00
	TO REMOVE AND REFIT INTERIOR UPHOLSTERY, CUSHION SEAT AND CLEANING.		150.00	100.00
	TO REMOVER / REFIT WIRING CHECK.		60.00	30.00
	TO REMOVE / REPLACE SIDE PANEL & ALUMINIUM.	NOT NECESSARY	150.00	-
	TO REMOVE / REPLACE FRONT UNDERCARRIAGE LH.	NOT NECESSARY	350.00	-
	TO FOUR WHEEL ALIGNMENT.		80.00	60.00
			6,520.00	3,260.00
GRAND TOTAL			29,018.73	18,064.46

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			13,000.00
---	--	--	------------------

Report Ref No. CS/INC19014785/Etf3e2

CHEN TSUE YEE

Automotive Assessor

K.K. LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.