

NEO AUTOMOTIVE PTE LTD
53 UBI AVE 1 #05-44 PAYA UBI INDUSTRIAL PARK S408934
Tel: 6385 5262 FAX: 6385 8262

ESTIMATE

Vehicle No: SLM 4224 J
Make/Model: Toyota Axio

LIST ITEM

1 pc L/H rear wheel bearing ? → (photo)

Less 25%

\$
215.00
53.75
161.25

S/NETT ITEM

1 pc L/H rear wheel rim 15 inch SCR ✓

Labour charges.

Spray-painting, Rear Door L/H, Rear Fender L/H

To remove/renew L/H rear wheel bearing.

To wheel alignment.

Total

~~500.00~~ \$280
~~500.00~~ \$200
~~700.00~~ \$400
~~150.00~~ \$60 - ? (photo)
140.00 \$60
2,151.25

L/S report
23/8/19 8.30 Am
Hock Ann
85311883
resurvey after paint
without prejudice
Hock Ann @ 1klkauto.com
2 Long

1klk Auto Consultants hence notify
the Repairer of the following:

- To be done before after spray painting
- To inspect damaged part(s) during resurvey
- Parts prices are subject to confirmation survey
- Third party survey is on a "Without Prejudice" basis
- No Third party modification(s) is allowed on "Prejudice" basis
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____