ASSIGNMENT

Froin Date	Veh No: SKR 24074 Yr Regn: 2015 / JAN
Estimated Cost:	Type: (A.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD TP/ WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No: SKR 24074	Make: AWO A62-07FS 1M4 c.c 1984
at Workshop m/s PREMIUM	Colour 8 CACK A/C: Insured / Std / NI / NA
of 281, MEXAMORA RO	Sp.Reading S6536 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: WAY 2224GXEN 165215
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess: 76A 800	Steering: Morder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: (norder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil VS/Rtm / STD A/Rim or
/o : mov	Tyre Size: F: 225/55 R17
(Policy Condition) (O. ov burns	R: 5~
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PR / SUMI /
repair at the time of inspection.	TOYO/YOKO or
Bal, or Market Value: 97 K	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm R/Bal. 6 rim
GIA / PR Sean; Consistent? : Yes or No	L/Bal. L/Bal. nm
Est. Repairs: days Res.: Yes or No	D.O.A. 29 01 19 D.O.I. 28 08/19
Lum Sum: % 3 Val.: Yes or No	Survey held at PRENIMM
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time   Action / Instruction	The Dro 1 chassis halle 1 body chactare anoded due to component
SKR, 2407 Y - CC4 / LPC 19052031	1Adb3 D.o.A. 29/01/2019
23 8 19 Sent Merinen to	Mandak and wait for Authorise Repair George Wang Premium to Authorise
26/8/19 Sente-mail to (	George Wang Premium to Authorise
21010 6 0 0 6 16	+ +222, 20 /+ Para (Ra) +(13786 64%)
	nt \$3321.20 (5 days (Red \$603780,64%)
	DV pass to Typist
RECEIVED	7 NOV 2019
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 5
i) : Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2) 7/11/19 Typist Add Fee	
2 7 17	: Interview (\$) Photos
Pepopt Formet:	c Tech, Invs (\$) Other
Lump Sum (LB.): 1	Weet end 15
PIP = \$3321-20	TOTAL

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

and the second second	OLDER TRA	Approximate the second	Taurauccare	Tadi Det	Adi Subi	mitted	Ins Auth'ed	Status		
Case Main	Notified 04 Feb 2019	Est Submitted	23 Aug 2019 11:24 Edit Adj Rpt	Adj Rpt	(AU) 300	11115550	110,100,00	Pending for Surve Report Cancel Case		ey
,	Main	Re	ference		laim Details		Docume	nts	<u>s</u>	how All
CLAIM SU	BFOLDER DI	ETAILS		S W SPAN S SAME		[Create	d by insurer]			
Insured:	LEE CHO	According 1800 for the	65501H, Tel:	+6596784431	l, Email: LEE@	IRCORP.C	OM.SG			
Vehicle Reg No.:	SKR240	)7Y			Date of Loss:	29/01/20	/2019 17:00 - :59			
Claim Type	OD / 20	99329112SG			Policy/Cover Note No.: 2100398966-04 (Comprehensive)					
					Excess:					
Repairer:	Premium	Automobiles Pt	e Ltd (UBI) 55	Ubi Road 1, 4	08699 Ubi - Tel	: 6768982	8/9827/9911			
Handling Insurer:		Pacific Insurance							02/00/20	1101
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel	: 6256-3561 .	[Handled by	MOHD RA	SUL] [Final	Rpt due	03/09/20	119]
Driver/Cust dian:		R HENG (57 / Male								
ASSOCIA	TED MAIL R	ECEIVED						View All	Compose	Case Mail
There are r	no mail for thi	s case.								
ALL ASS	CIATED TA	sks <sup>=</sup>				View A	II Search Tasks	Create I	New Task	Complete
Due Dat	36	/ Type Task	Group Sub	oject Han	dler Assig	ned By	Completed (	On Cr	eated On	Done

# Yvonne Wong (LKK Auto)

From:

Yvonne Wong (LKK Auto)

Sent:

Monday, August 26, 2019 4:55 PM

To:

Claims; SUR

Subject:

OD CLAIMS FOR SKR 2407 Y

### Dear George Wong

As instructed by our client, please proceed to repair the insured vehicle SKR2407Y (excess \$800/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <a href="mailto:yvonnewong@lkkauto.com">yvonnewong@lkkauto.com</a> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [mailto:claims@premiumauto.com.sg]

Sent: Wednesday, August 21, 2019 5:19 PM

To: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>

Cc: claims@premiumauto.com.sg Subject: OD CLAIMS FOR SKR 2407 Y

Dear all,

Please assist to register own policy claim for the above mentioned vehicle.

Attached is the GIA for your reference.

Kindly arrange for survey on this coming Friday @ 10am.

Address: 281 Alexandra Road Singapore 159938

Thank you.

# Claim Audit

	UDIT TRAIL	00	Province (dame)	22
lo.	On	Audit	Remarks	Ву
1	30 Jan 2019	Clm Veh Model Changed		[] Merimen Administrator
	15:10	20 C C C C C C C C C C C C C C C C C C C	D. H. GKR3407V B-Est No. 3100309066 04 Acet Date: 3010/01/29 Claim Typ	
2	30 Jan 2019 15:10	Clm Created	Reg No: SKR2407Y. Policy No: 2100398966-04. Acct Date: 2019/01/29. Claim Typ e: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notificatio n. Created from SAS:MPA119014356	[I] Merimen Administrato
	22 4 2010	Clas Booletsation		[] Nivitha
3	23 Aug 2019 11:24	Clm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	Govindasam
4	23 Aug 2019 11:24	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] Nivitha Govindasam
5	23 Aug 2019 11:24	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Nivitha Govindasam
	23 Aug 2019		New Partifical Bet Due Date: 2019/09/03	[A] Nivitha
6	11:24	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/09/03	Govindasam
_ 3	23 Aug 2019		Annual 9000 00 Painer Adi decides	[A] Nivitha
7	11:24	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	Govindasam
	23 Aug 2019	Clm Registration	D1427 - 200611	[A] Nivitha
8	11:24	Modified	Rep:1137->200611.	Govindasam
	23 Aug 2019		(DOLLARS) ALIDY AS DIG TEST MILLIAN	[A] Nivitha
9	11:24	Clm Veh Model Changed	(201410) AUDI A6 2.0 TFSI MU (A).	Govindasam
500	23 Aug 2019			[A] Nivitha
10	11:24	Adj Adjuster Assigned	[None] -> MOHD RASUL	Govindasam
				[A] YVONNE
11	23 Aug 2019 14:00	Adj Rpt Initiated		WONG YIN CHENG
				[A] YVONNE
12	23 Aug 2019	Clm Dtl Modified	JPJ Reg. Date: -> 2015/01/27.	WONG YIN
	14:00			CHENG
				[A] YVONNI
13	23 Aug 2019 14:00	Clm Details Notified		WONG YIN CHENG
				[A] YVONN
14	23 Aug 2019	Adj Im. Advice	Next Rpt:Final Rpt.Due Date:2019/09/03	WONG YIN
14	14:17	Submitted	and the state of t	CHENG
				[A] YVONN
15	23 Aug 2019 14:20	Adj Mandate Request	Cur.Req:4055.00:DAMAGED CONSISTENT, REPAIR COST ECONOMICAL	WONG YIN CHENG
	22 4 2242	Cim Donistration		[I] Chan,
16	23 Aug 2019 15:05	Clm Registration Modified	Init.Est.:->5,000 - 6,000. 2F Remarks: -> Not Applicable. GST: -> 7.00.	Yoke Shi
17	23 Aug 2019 15:10	Clm Registration Modified	Acct Time:17:30:00->17:00:00. Pol No:2100398966-04->2100398966.	[I] Chan, Yoke Shi
18	26 Aug 2019 07:57	Clm Registration Modified	Excess: -> 800.00.	[I] Chan, Yoke Shi
19	26 Aug 2019	Label Added	(20226):Coverage Confirmed.	[A] Merime Administrate
20	26 Aug 2019	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/09/03, Mandate Remarks: Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK
21	15:39 26 Aug 2019 15:39	Adj Mandate Set	Approved:3555.00:Re-inspection to be done for damage check and supplementary items / labour. Reinsp:Yes.	[I] Koh, Victor-CK

AC	TIVITY
No	record

derimen Billin	g for this case - '	Transaction H	istory				
Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2255581	23/08/2019 14:00	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKR2407Y		11.77

### Note: This document has not been finalised.

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building

78 Shenton Way #08-16 Singapore 079120

From:

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25

Paya Ubi Industrial Park

Singapore 408933

Attn:

Date:

23 Aug 2019

### **Preliminary Advice**

Vehicle No

: SKR2407Y

Accident Date

: 29/01/2019

Make

: AUDI A6

Policy No.

: 2100398966-04

Assignment Date

Excess

:S\$

: \$\$0.00

: 23/08/2019

Date of Inspection : 23/08/2019

Est. Duration of Repair

Inspection At

: PREMIUM AUTOMOBILES PTE LTD (UBI)

55 UBI ROAD 1

SINGAPORE 408699

: 5.00

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages O/S REAR portion and parts claimed are consistent to the accident.

:S\$	9,359.00
:S\$	3,555.00
:S\$	500.00
:S\$	4,055.00
	:S\$ :S\$

Lump Sum Repair

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	97,000.00
COE / PARF Rebate	:S\$	72,551.00
Salvage Value	:S\$	
Margin for Repair	:S\$	24,449.00

#### Remarks

(	X	)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
(		)	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
(		)	Other comments :

#### SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

Gender

Mobile Number

Fax Number Contact Number

**EMail Address** 

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Charles and Charles and Charles	ACCIDENT STATEMENT
Date Of Report	30/01/2019 14:53
Date Of Accident	29/01/2019 17:30
Exact Location Of Accident	CARPARK OF BLK 273 BT BATOK EAST AVE 4
Country/State of Loss	SINGAPORE
D	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SKR2407Y
Insured/Policyholder	
Name Of Registered Owner	LEE CHOR HENG
NRIC No	S1465501H
Email Address	LEE@IRCORP.COM.SG
Mobile Phone No	(LOCAL) +65-96784431
Alternative Phone No	OTHERS-96784431
Vehicle Particulars	
Manufacturer	AUDI
Model	A6 C7 2.0 TFSI MU 4G
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE, LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100398966-04
Cover Note Number	
Driver	
Name of Driver	LEE CHOR HENG
NRIC No	S1465501H
Date Of Birth	19/05/1961
Occupation	INDOOR
Date Of Driving Pass	14/07/1982
Driving Experience	36 YEARS AND 6 MONTHS

MALE

(LOCAL) +65-96784431

LEE@IRCORP.COM.SG

OTHERS-96784431

Address

72 JALAN GUMILANG

Postcode

668911

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Insurance Company of Driver's Own Vehicle

### General Information of the Accident

Type Of Accident

COLLISION - MAJOR/MINOR RD

Weather Conditions

CLEAR

Road Surface

DRY

#### Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

NO

Was any body injured in the Accident?

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

#### **Details of Police Action**

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

### Circumstances of Accident

AFTER PULLING OUT OF THE CARPARK SPACE, I STOPPED JUST BEFORE THE EXIST BECAUSE OF CARS COMING IN. A CAR THEN KNOCKED ONTO THE BACK OF MY CAR, WHILE HE WAS TRYING TO REVERSE INTO A PARKING SPACE.

### Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO NO

### **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number

Was there any audio recorded?

SJX2668R

Vehicle Make/Model/Colour

**Details Of Properties** 

PRIVATE CAR

Vehicle Category Name of Driver

CHONG KUM PING

NRIC/Passport Number

S2568008A

Contact Number

Address

Postcode

Insurance Company Name

LONPAC INSURANCE BHD

Nature Of Damage

No. Of Passenger (Including Driver)

### Sketch Plan

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims,
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

### Sketch Plan #2

SKETCH PLAN BIK	273 Burket Butok East	the 4
1	1 Car Pa	r(4   \ \ )
	ES OF THE ACCIDENT	Audi - SKR 24694  B - SJX 2668R
A cas then	whe exist because Knock and the was trying to rei	se of Cars comming in.
DECLARATION  I/We declare the tellegoing part	ticulars are true in every respect.	Quality (See
Policyholder's Signature Date & Time:	Oriver's Signature (If driver is not the policyholder) Date & Time:	Reporting Centre Personnel's Signature Name NRIC/FIN NO



# CERTIFICATE OF INSURANCE

# 

#### ABOUT THE COVER

Make/Model

: AUDI A6 C7 2.0 TFSI MU

Engine Capacity/Tonnage: 1,984.00 CC

Sum Insured : Market Value

First Year of Registration : 2015

Driver Restriction : NA

Off Peak Car : No

Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive\*:

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than years' driving experience.

: All Age Condition Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuttion, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

#### **EXCESS**

Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen: \$100

Named Driver and Excess (where applicable)

LEE CHOR HENG - \$800 (Own Damage)

### APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS).

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AlG Authorised Repairers, please contact our 24-hour accident emergency hottine at +85 6338 6200. Alternatively, you may refer to AlG website www.aig.com.ag or AlG SG Mobile App. Simply search and download "AlG SG" from ITunes or Google Play.

#### IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: NA

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of State Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia). the Road Trensport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125207

PREMIUM LEASING - SLEE
281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd. AUTHORISED REPRESENTATIVE

78 Shenton Way #07:16 AIG Building S079120 | T:+65 6419 3000 | www.aig.com.sg

AIG Asia Pacific Insurance Pte 11 Inf

# > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	501H
Vehicle No.:	SKR2407Y
Vehicle to be Exported:	Yes
Intended Deregistration Date:	23 Aug 2019
Vehicle Make:	AUDI
Vehicle Model:	A6 2.0 TFSI MU
Primary Colour:	Black
Manufacturing Year:	2014
Engine No.:	CDN411191
Chassis No.:	WAUZZZ4GXEN165215
Maximum Power Output:	132.0 kW (177 bhp)
Open Market Value:	\$38,658.00
Original Registration Date:	27 Jan 2015
First Registration Date:	27 Jan 2015
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$41,122.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jan 2025
PARF Rebate Amount: Intended COE Rebate Details	\$30,841.00
COE Expiry Date:	26 Jan 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$76,889.00
COE Rebate Amount:	\$41,710.00
Total Rebate Amount:	\$72,551.00

The information contained herein is correct as at 23 Aug 2019



#### Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE 6 Raffin Quay #18-90 Singapore 048580

6 RaPics Quay #18-00 Singapore 0405-80 Tel (85) 6274 0010 Fax (65) 6224 0090 Operating Hours : Monday to Enday, 09:00 – 17:00 UNE 506560206 / GAT Reg. No.: Me00027735

IMPORTANT NOTE: Please submit the completed Addendum form to the <u>same</u> Authorised Reporting Centre with whom you submitted the Original Report.

# with whom you submitted the Original Report. ADDENDUM (A) PARTICULARS OF PERSON MAKING THE AMENDMENTS: Original Report No : MPA119014356 Vehicle Registration No: SKR2407Y Name (105 shown in NBIC): LEE CHOR HENG \_NRIC/FIN/PassportNo : S1465501H (\*Vehicle Driver / Vehicle Owner) (\*) Please delete as appropriate 72 JALAN GUMILANG Address \_Singapore(668911) +65-96784431 Contact (Tel) Mobile No.:\_ LEE@IRCORP.COM.SG Email Address Date of Accident 29/01/2019 \_Time of Accident: 17:30 Place of Accident : CARPARK OF BLK 273 BT BATOK EAST AVE 4 Insurance Company: AIG ASIA PACIFIC INSURANCE PTE. LTD. (B) ADDITIONALINFORMATION / AMENDMENTS: I have made a report on the above mentioned accident and would like to include additional information or make the following amendments: CONVERT ACCIDENT REPORT FROM TP CLAIMS TO OD CLAIMS AND DO RECOVERY LATER. Policyholder / Driver's Signature Asporting Centre Personnel's Signature Date: Name: World KHONG SEALL, GOOD

NRIC/FINNO : 61-48743 X

Date: 21/8/19

# Yvonne Wong (LKK Auto)

From:

jiayee.yap@premiumauto.com.sg

Sent:

Saturday, September 28, 2019 10:00 AM

To:

Adrian Ling (LKKAuto); CS A Team; Admin A; SUR; Rasul (LKKAuto)

Cc:

'Boo seng yak'; 'Carrine Leong'; 'Chang Chee Sing'

Subject:

FINAL REVISION - SKR2407Y- OD AIG - SURVEYED 23 AUG 19

Attachments:

PA01432019-SKR 2407 Y- A6 C7 2.0 TFSI MU - REAR BUMPER (LONPAC).xls

Follow Up Flag:

Follow up

Flag Status:

Flagged

Hi Adrian, Rasul and all,

Revised estimate is attached.

Please confirm repair cost of \$3321.20 @ 5 days of repair exclude 1 Sunday.

Your early closure is well appreciated.

Thanks & Best Regard JiaYee Yap

Claims Administrator

### Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183

e. jiavee.yap@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

#### Telefax

Estimate Workshop Accident Repairs

Workshop Contact No : Ubi Road 1 : 6366 2323

Fax No Reference : 6841 1183 : PA/OD/0143/2018/GW

Date

: 30-Jan-19

Kindly arrange for survey.

Your insured vehicle no. SKR 2407 T

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120 Hi Rasul, 5 days - ok - Jy - 28 SEP 2019

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name

: Mr. Lee Chor Heng : 72 Jalan Gumilang

Singapore 668911

Telephone

Address

96784431

Type of Claim Policy No.

: Own Policy Claims : 2100398966-04 : SKR 2407 Y

Vehicle No Model Code

Audi A6 C7 2.0 TFSI Mu

Model / Year

: Jan-15

Engine No

: CDN 411191

Chassis No

: WAUZZZ4GXEN165215

Mileage

: .

Date In

.

Liability

: -

**Excess Cost** 

: Johnny Boo / Allan Wu

Estimated By Accident Date

: 29-Jan-19

Place of Accident

: Car Park of Blk 273 BT Batok East Ave 4

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

### Telefax

# Estimated Labour Charges for Accident Vehicle SKR 2407 Y

S/N	Nature of Jobs		Estimated Charges	
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function.	S/N	\$ 360.00	\$ 360.00
2	To dismantle and renew rear bumper. To repair rhs rear fender. Reorganise crash management components. Reinstall all parts removed.		\$ 1,400.00	\$ 750.00
3	To respray rear bumper and rhs rear fender.		\$ 1,600.00	\$ 1,100.00
4	To carry out diagnostic check.	S/N	\$ 192.00	\$ 192.00
	TOTAL LABOUR CHARGES		\$ 3,552.00	\$ 2,402.00

All charges are not inclusive of GST.

Remarks (OK) = Approved, Remarks (X) = Not approved

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

### Telefax

# Material List for Accident Vehicle Regn No. SKR 2407 Y

				Damage Pa	ırts &	Prices
S/N	Parts Description		5	S/NETT R	EMAR	RKS
1	REAR BUMPER		\$	2,343.00		
2	REAR BUMPER SITCKY PAD		\$	21.00		
3	REAR BUMPER FIXING PARTS		\$	249.00		
4	REAR BUMPER SPOILER		\$	316.00		
5	REAR BUMPER SECURING STRIP		\$	157.00		
6	REAR BUMPER GUIDE PROFILE -RH UPPER		\$	53.00		
7	REAR BUMPER SECURING ELEMENT		\$	6.00		
8	REAR BUMPER GUIDE SECTION-RH		\$	30.00		
9	REAR BUMPER CONNECTING PIECE		\$	11.00		
10	REAR BUMPER LOWER GUIDE SECTION-RH		\$	48.00		
11	REAR BUMPER COVER FIXING PARTS		\$	24.00		
12	REAR BUMPER CARRIER COVER		\$	105.00		
13	REAR SENSOR		\$	231.00		
14	REAR SENSOR SEAL RING - INNER/OUTER	4	\$	5.00		
15	LED TAILLIGHT-RH		\$	1,148.00	\$	919.20
16	LED TAILIGHT COVER-RH		\$	43.00		
17	EXHAUST TAIL PIPE TRIM		\$	517.00		
18	SUNDRIES		\$	500.00		
	TOTAL SPARE PARTS		\$	5,807.00	\$	919.20
	TOTAL LABOUR CHARGES		\$	3,552.00	\$	2,402.00
	GRAND TOTAL	9	\$	9,359.00	\$	3,321.20

All charges are not inclusive of GST.

Legend:

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

# Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :

Liability : Remarks :

**Please Note** 

This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel:6768 9828 for appointment.

Yours faithfully, Premium Automobiles Pte Ltd

Johnny Boo Body Repair Manager Allan Wu Claims Consultant

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

### Telefax

 Estimate
 : Accident Repairs

 Workshop
 : Ubi Road 1

 Contact No
 : 6366 2323

 Fax No
 : 6841 1183

Reference : PA/OD/0143/2018/GW

Date : 30-Jan-19

Kindly arrange for survey.

Your insured vehicle no. SKR 2407 T

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Lee Chor Heng Address : 72 Jalan Gumilang

Singapore 668911

Telephone : 96784431

 Type of Claim
 : Own Policy Claims

 Policy No.
 : 2100398966-04

 Vehicle No
 : SKR 2407 Y

 Model Code
 : Audi A6 C7 2.0 TFSI Mu

Model / Year : Jan-15

Engine No : CDN 411191

Chassis No : WAUZZZ4GXEN165215

Mileage :

Liability : Excess Cost : -

Estimated By : Johnny Boo / Allan Wu

Accident Date : 29-Jan-19

Place of Accident : Car Park of Blk 273 BT Batok East Ave 4

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

# Telefax

# Estimated Labour Charges for Accident Vehicle SKR 2407 Y

Nature of Jobs			Estimated Charges
To remove and transfer rear parking aid and rear lid kick sensor. Check function.	S/N	\$	360.00
To dismantle and renew rear bumper. To repair rhs rear fender. Reorganise crash management components. Reinstall all parts removed.		\$	1,400.00 750
To respray rear bumper and rhs rear fender.		\$	1,606.00 11 00
To carry out diagnostic check.	S/N	\$	192.00
TOTAL LABOUR CHARGES	:	\$	3,552.00
	To remove and transfer rear parking aid and rear lid kick sensor. Check function.  To dismantle and renew rear bumper. To repair rhs rear fender. Reorganise crash management components. Reinstall all parts removed.  To respray rear bumper and rhs rear fender.  To carry out diagnostic check.	To remove and transfer rear parking aid and rear lid kick sensor. Check function.  To dismantle and renew rear bumper. To repair rhs rear fender. Reorganise crash management components. Reinstall all parts removed.  To respray rear bumper and rhs rear fender.  To carry out diagnostic check.  S/N	To remove and transfer rear parking aid and rear lid kick sensor. Check function.  To dismantle and renew rear bumper. To repair rhs rear fender. Reorganise crash management components. Reinstall all parts removed.  S/N \$  To respray rear bumper and rhs rear fender.  \$  To carry out diagnostic check.  \$  \$  \$  \$  \$  \$  \$  \$  \$  \$  \$  \$  \$

All charges are not inclusive of GST.

Remarks (OK) = Approved, Remarks (X) = Not approved

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

# Telefax

# Material List for Accident Vehicle Regn No. SKR 2407 Y

		Damage Parts & Price			
S/N	Parts Description			REMARKS	
1	REAR BUMPER TEPAN	\$	2,343.0	0	
2	REAR BUMPER SITCKY PAD ★ 5~	\$	21.0	0	
3	REAR BUMPER FIXING PARTS 🗡	\$	249.0	0	
4	REAR BUMPER SPOILER X	\$	316.0	0	
5	REAR BUMPER SECURING STRIP X	\$	157.0	0	
6	REAR BUMPER GUIDE PROFILE -RH UPPER X XSVC	\$	53.0	0	
7	REAR BUMPER SECURING ELEMENT X	\$	6.0	0	
8	REAR BUMPER GUIDE SECTION-RH X	\$	30.0	0	
9	REAR BUMPER CONNECTING PIECE X	\$	11.0	0	
10	REAR BUMPER LOWER GUIDE SECTION-RH X	\$	48.0	0	
11	REAR BUMPER COVER FIXING PARTS ×	\$	24.0	0	
12	REAR BUMPER CARRIER COVER X	\$	105.0	0	
13	REAR SENSOR ★	\$	231.0	0	
14	REAR SENSOR SEAL RING - INNER/OUTER 🌬 📉 4	\$	5.0	0	
15	LED TAILLIGHT-RH CM	\$	1,148.0	0 919.20	
16	LED TAILIGHT COVER-RH X WC	\$	43.0		
17	EXHAUST TAIL PIPE TRIM MA CAPUL	\$	517.0	0	
18	SUNDRIES 7 122	\$	500.00	0	
	TOTAL SPARE PARTS :	\$	5,807.00	<u> </u>	
	TOTAL LABOUR CHARGES :	\$			
	GRAND TOTAL	\$			
				4	

All charges are not inclusive of GST.

Legend: Re

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Surveyed Date

**Authorised Date** 

**Excess Cost** 

Liability Remarks

RASIL - HP 90010068

23/08/19 @ 1000 hrs

5 days

EXCESS: Tha

Revery

Revery after report

**Please Note** 

This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the

progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16 AIG Building Singapore 079120

Attn: Motor Claims Dept Yr Ref: SKR 2407 Y Norah Khai 6768 9911 6841 1183

Nora.khai@premiumauto.com.sg Body & Paint Dept PA/OD/0143/2019/KK

7 Nov 2019

from

Telephone +65-Telefax +65-

EMail

Our department Our Ref

Your Ref Date

total pages

Dear Sir.

RE: INSURANCE CLAIM FOR SKR 2407 Y, Audi A6 C7 2.0 TFSI MU.

With reference to the above-mentioned vehicle, no. SKR 2407 Y, claimant, Mr. Lee Chor Heng, please find the related document per attached.

- A copy of the Original invoice no. 85014437 S\$ 2,697.68.
- 2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai Claims Dept

Encl AIG – SKR 2407 Y Premium Automobiles Pte Ltc

Showroom 9 Leng Kee Road Singapore 159090

Telephone (65) 6566 1111 Telefax (65) 6471 3733

Service & Parts Centres 55 Ubi Rd 1 Singapore 408699 Telephone (65) 6336 2323 Telefax (65) 684 11183

# **Premium Automobiles Pte Ltd**



Audi Centre Singapore 281 Alexandra Road Singapore 159938 Main Telephone 6836 2223 Main Telefax 6471 3733

Alexandra Service Centre 281 Alexandra Road Singapore 159938 Main Telephone 6388 2223 Main Telefax 6475 1023

Ubi Service Centre 55 Ubi Road 1 Singapore 408699 Main Telephone 6388 2323 Main Telefax 6841 1183

**Customer Service** Service Appointment 24-hour Breakdown Service 6366 2323 9828 1233 customer care@premiumauto.com.sg Email

#### INS TAX INVOICE

Page

14:49

Company Reg. No. 199902271W

GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD

MOTOR CLAIM DEPT AIG BUILDING

78 SHENTON WAY

#07-16

SINGAPORE 079120 079120

Invoice No: 85014437

Account: A0006

AIG ASIA PACIFIC INSURANCE PTE LTD

Date : 06/11/2019

Order: SKR2407Y

MOTOR CLAIM DEPT AIG BUILDING

78 SHENTON WAY

#07-16

SINGAPORE 079120

Regn No: SKR2407Y

(V 24020) Regn Date: 27/01/2015

Term : 30

Mileage: 57267

WIP No.: 41509

Model: A6 C7 2.0 TFSI MU 4G207H (YOM

Chassis: WAUZZZ4GXEN165215

Engine: CDN 411191

Dept: U

You have been assisted by :- UB-Tony Foong

(33)

		Details	Qty	Unit Price	Amount
2	EXC	M: 8888 Insurance Excess/Liability	-800.00	1.00	-800.00
	BODYWORK	M: TO REMOVE AND TRANSFER REAR PARKING AID AND REAR	360.00	1.00	360.00
	BODYWORK	JID KICK SENSOR, CHECK FUNCTION. M: O DISMANTLE AND REPAIR REAR BUMPER & RHS REAR FEN REORGANISE CRASH MANAGEMENT COMPONENTS.	750.00	1.00	750.00
	BODYWORK	REINSTALL ALL PARTS REMOVED.  M: TO RESPRAY REAR BUMPER AND RHS REAR FENDER.	1100.00	1.00	1,100.00
	BODYWORK	TO CARRY OUT DIAGNOSTIC CHECK.	192.00	1.00	192.00
	A4G5945096A	LED TAIL LIGHT Less 020%	1.00	1149.00	919.20
	Parts 919.2	0		Sub-Total	2,521.2

2,402.00 Sublet Menus 0.00 Lubricant 0.00

176.48 7% GST 2,697.68 **Grand Total** 

Received by

For & on behalf of Premium Automobiles Pte Ltd

# Telefax

to AIG Asia Pacific Insurance Pte Ltd Norah Khai 78 Shenton Way 6768 9828 #07-16 AIG Building 6841 1183 Singapore 079120 Motor Claims Dept Body Repair Yr Ref: SKR2407Y PA/OD/0143/2019/TF 18 September 2019 1 RE: CLAIM - OWNER'S SATISFACTION/DISCHARGE VOUCHER Make & Model Audi A6 C7 2.0 TFSI MU : Vehicle Chassis No. WAUZZZ4GXEN165215 : Vehicle Regn No. : SKR2407Y Vehicle Mileage 57233KM : Vehicle Owner Mr. Lee Chor Heng : Certificate No 2100398966-04 Own Damage Excess : \$856.00 (Inclusive GST) Accident Date 29/1/2019 Place Car park of Blk 273 BT Batok East Ave4 S\$ 2,697.68 Repair Cost WIP No. 41509 Repairer's Name Premium Automobiles Pte Ltd

from

Mobile

Our Ref Date

total pages

Showroom

Telefax

55 Ubi Road 1 Singapore 408699

9 Leng Kee Road Singapore 159090

Telephone +65-

Telefax +65-

Our department

Your Claim Ref

+65-

Premium Automobiles Pte Ltc

Telephone (65) 6566 1111

Service & Parts Centres

Telephone (65) 6366 2323 Telefax (65) 6841 1183

(65) 6471 3733

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Time : 17 / 4 / 4

# ...CLAIM SUBFOLDER...(Pending for Survey Report)

Case 1	Votified	Est Submitted	Adj Assigned	Adj Rpt	Aid	Submitted	In	s Auth'ed	Status		
	04 Feb 2019		23 Aug 2019 11:24 Edit Adj Rpt	S\$3,321.20 Edit Estimate	CONTRACT BEAUTY	3,321.20 lew Rpt			Pending for Survey Report Cancel Case		vey
м	ain	Re	ference	C	aim Deta	nils		Document	s		Show All
CLAIM SUE	FOLDER DE	TAILS				[Crea	ted b	y insurer]			
Insured:	LEE CHOR	HENG, ID: S14	65501H, Tel: -	+6596784431,	Email:	LEE@IRCORP	COM	.SG			
Vehicle Reg. No.:	SKR240	7Y			Date of I			17:00 - :59 and <b>2</b> Days Fro	m LTA Re	g Date (M	an Yr)]
Claim Type: <b>OD</b> / 2099329112SG				Policy/Co Note No.	211013	2100398966 (Comprehensive)					
	Excess: \$\$800.00										
Repairer:	Premium	Automobiles Pte	Ltd (UBI) 55	Jbi Road 1, 40	8699 Ubi	- Tel: 67689	828/9	827/9911			
Handling Insurer:	The second second	Pacific Insuranc									
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-3561	. [Handle	by MOHD	RASU	L] [Final R	pt due	03/09/20	019]
Driver/Custo dian:	LEE CHOR	HENG (57 / Male)	, NRIC: S146	5501H, Tel:	+659678	4431 Email:	LEE@	IRCORP.COM.SC	6		
ASSOCIAT	ED MAIL RE	CEIVED							/iew All	Compose	Case Mail
AIG_SG (     AIG_SG (	26/08/2019) 26/08/2019)	: Alert - Adj Man : SKR2407Y / OI	date Approved 0 / 29/01/201	(S\$3555.00 9 / Coverage	) - SKR24 & Exces	407Y - Clain s update	n Han	dler: Chan, Yo	ke		
ALL ASSO	CIATED TAS	SKS <sup>□</sup>				View	All	Search Tasks	Create N	lew Task	Complete
Due Date	Priority	Type Task	Group Sub	ject Hand	ler A	ssigned By		Completed On	Cre	ated On	Done

# **Claim Documents**

\*SKR2407Y (2099329112SG) OD Jan 29 2019 5:00PM [LEE CHOR HENG] Premium Automobiles Pte Ltd

Up	oad Documents Uplo	ad Photos   Compose New Letter   Upload Video   Upload Audio	View View in	Browser ▼
Ass	essment Reports		1 per page	¥ Ø
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		nail Print
1	23/08/19 14:17	Adjuster Immediate Advice	Load H	TM
Pho	tos/Images		3 per page	¥ Ø
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumb	nail Print
1	23/08/19 17:14	General View	① Load )	PG 🗹
2	23/08/19 17:14	General View	① Load )	PG 🗷
3	23/08/19 17:14	General View	① Load )	PG 🗹
4	23/08/19 17:14	General View	① Load )	PG 🗹
5	23/08/19 17:14	General View	<b>⑥</b> Load J	PG 🗹
6	23/08/19 17:14	General View	① Load )	PG 🗹
7	23/08/19 17:14	General View	● Load J	PG 🗹
8	23/08/19 17:14	General View	① Load J	PG 🗹
9	23/08/19 17:14	General View	<b>₫</b> Load J	PG 🗹
10	23/08/19 17:14	General View	① Load J	PG 🗹
11	23/08/19 17:14	General View	<b>❸</b> Load 3	PG 🗷
12	23/08/19 17:14	General View	<b>③</b> Load J	PG 🗹
13	23/08/19 17:14	General View	① Load J	PG 🗹
14	23/08/19 17:14	General View	① Load J	PG 🕝
15	23/08/19 17:14	General View	1 Load J	PG 🗷
16	23/08/19 17:14	General View	① Load J	PG 🗹
17	23/08/19 17:14	General View	① Load J	PG 🗹
18	23/08/19 17:14	General View	① Load J	PG 🗹
19	23/08/19 17:14	General View	① Load J	PG 🗹
20	23/08/19 17:14	General View	6 Load 3	IPG 🗹
21	23/08/19 17:14	General View	① Load J	PG 🗷
Do	cumentation		1 per page	¥ Ø
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumb	nail Print
1	23/08/19 14:18	ESTIMATE	① Load F	DF
2	23/08/19 17:16	INSURANCE CERT, DL, NIRC	① Load F	DF
3	14/11/19 09:23	DISCHARGE VOUCHER	O Load F	DF
4	14/11/19 09:23	WORKSHOP INVOICE	€ Load F	DF

# **Linked Accident Report Documents**

			View   View in Browser		
Ass	essment Reports	sment Reports 1 per page		age ▼	•
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	30/01/19 15:10	Accident Statement	0	Load HTM	
2	21/08/19 17:13	Addendum Sheet	0	Load JPG	•
3	21/08/19 17:13	Accident Statement Addm. #1	0	Load HTM	4
Pho	tos/Images		3 per p	age ▼	•
No.	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print

Ass	Assessment Reports		1 per	page ▼	•
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	30/01/19 15:07	Accident Photo	0	Load JPG	•
2	30/01/19 15:07	Accident Photo	0	Load JPG	•
3	30/01/19 15:07	Accident Photo	0	Load JPG	•
4	30/01/19 15:07	Accident Photo	0	Load JPG	<b>(2)</b>
5	30/01/19 15:07	Accident Photo	0	Load JPG	•
6	30/01/19 15:07	Accident Photo	0	Load JPG	•
7	30/01/19 15:07	Accident Photo	0	Load JPG	•
8	30/01/19 15:07	Accident Photo	0	Load JPG	•
9	30/01/19 15:07	Accident Photo	0	Load JPG	V
Doc	umentation		1 per	page ▼	•
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	30/01/19 15:02	Sketch Plan	0	Load JPG	•
2	30/01/19 15:03	Sketch Plan #2	0	Load JPG	•

# **Documents Checklist**

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: Handling Insurer  Note: Remarks are private unless you show it to other parties.	

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way #08-16

Singapore 079120

Our File No:

CC3/AIG19014827/R1YD3S2

Date:

14/11/2019

REFERENCE

Date of Loss:

Insured/Claimant:

LEE CHOR HENG 29/01/2019

Policy No:

Nature of Claim:

2100398966

OD

Claim No:

2099329112SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SKR2407Y

Make & Model:

AUDI A6, 2.0 TFSI MU (A)

27/01/2015 (Man. Year: 2014)

Engine No: Chassis No: Odometer:

CDN411191 WAUZZZ4GXEN165215

56536 km

Reg. Date: Colour:

Black

Engine Capacity: Market Value/New Car Price:

1984 cc \$\$97,000.00

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Fair

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Engine Modification:

Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size: Front Left Side:

225/55 R17 Pirelli 6 mm Rear Tyre Size: Rear Left Side: Rear Right Side: 225/55 R17 Pirelli 6 mm Pirelli 6 mm

Pirelli 6 mm Front Right Side: The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,807.00	919.20	4,887.80	84.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,552.00	2,402.00	1,150.00	32.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,359.00	3,321.20	6,037.80	64.51
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	8,559.00	2,521.20	6,037.80	70.54
+ GST 7.00/7.00% (S\$)	599.13	176.48	422.65	70.54
Nett Amount (S\$)	9,158.13	2,697.68	6,460.45	70.54

INSPECTION

Date of Assignment:

23/08/2019

Date Inspected:

23/08/2019

281 ALEXANDRA ROAD

Repairer: Premium Automobiles Pte Ltd

Estimated Period of Repair:

5.0 days

MOHD RASUL Adjuster:

Manager:

YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Inspected At:

# **REPAIR DETAILS**

Recommended	Parts
-------------	-------

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	2,343.00 FS	*-FS
2	1		*REAR BUMPER STICKY PAD	Serviceable	21.00 FS	*-FS
3	1		*REAR BUMPER FIXING PARTS	Serviceable	249.00 FS	*-FS
4	1		*REAR BUMPER SPOILER	Serviceable	316.00 FS	*-FS
5	1		*REAR BUMPER SECURING STRIP	Serviceable	157.00 FS	*-FS
6	1		*REAR BUMPER GUIDE PROFILE - RH UPPER	Serviceable	53.00 FS	*-FS
7	1		*REAR BUMPER SECURING ELEMENT	Serviceable	6.00 FS	*-FS
8	1		*REAR BUMPER GUIDE SECTION - RH	Serviceable	30.00 FS	*-FS
9	1		*REAR BUMPER CONNECTING PIECE	Serviceable	11.00 FS	*-FS
10	1		*REAR BUMPER LOWER GUIDE SECTION - RH	Serviceable	48.00 FS	*-FS
11	1		*REAR BUMPER COVER FIXING PARTS	Serviceable	24.00 FS	*-FS
12	1		*REAR BUMPER CARRIER COVER	Serviceable	105.00 FS	*-FS
13	1		*REAR SENSOR	Serviceable	231.00 FS	*- FS
14	4		*REAR SENSOR SEAL RING - INNER / OUTER	Not Necessary	5.00 FS	*-FS
15	1		*LED TAILLIGHT - RH	Cracked	1,148.00 FS	*919.20 FS
16	1		*LED TAILLIGHT COVER - RH	Serviceable	43.00 FS	*-FS
17	1		*EXHAUST TAIL PIPE TRIM	Repair	517.00 FS	*-FS
18	1		*SUNDRIES	Not Necessary	500.00 FS	*-FS
F=Fr	anchise	e part. S=Spcl	Nett.			
				Total Parts (S\$)	5,807.00	919.20

2

3

4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour				
No	Particulars	Lab.Type	Repairer's	
Lab	our Items			
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID	New	360.00	

KICK SENSOR. CHECK FUNCTION.

TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR RHS REAR New 1,400.00 750.00 FENDER. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.

TO RESPRAY REAR BUMPER AND RHS REAR FENDER. New 1,600.00 1,100.00 TO CARRY OUT DIAGNOSTIC CHECK. New 192.00 192.00

Gross Labour Cost (S\$) 3,552.00 2,402.00

Amount

360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >