

Merimer

ASSIGNMENT

From: Date: 23/8/19

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 3MG2105C

at Workshop m/s Premium

of 55 Ubi Road 1

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

IBA \$609

(Client's Record)

Make of Veh: 10:30am (waiting)

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 1031c

IDAC Accident Rpt: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: 05 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: 3MG2105C Yr Regn: 2018 / Dec

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A3 c.c. 999

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 12456 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WAUZZ28VK1007221

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: 225/40R18.

R: 225/40R18.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 23/08/19

Survey held at: Premium.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front o/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

00 ALG.

3MG2105C - X

RECEIVED 07 NOV 2019

23/08/19 @ 15:53 pm received PA to ALG via merimer.

23/08/19 @ 16:17 pm mandate approved authorise repair to ALG via merimer.

26/08/19 @ 10:30 am mandate approved by Victor Koh via merimer.

26/08/19 @ 14:01 pm inform CH to Syatig (Superior) via email.

11/10/19 confirmed P/P \$ 9,268.72 @ 5 days with advice \$ 5,372.28 Red - 39%.

Cost/Time, File Page to?

☐ : Prel. Report

Days Of Repair: 5

1) Typist

☒ : Final Report

Resurvey No. of Trip: 2

Cost/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech Insp (\$

☐ : Weekend (\$

Report Format:

Lump Sum (L.B.): 9,268.72 P/P

Survey Fee:

Transportation:

3 + RS 31

Phone

Other:

TOTAL

200

11

211

Enquire PARF/COE Rebate for Registered Vehicle

Singapore NRIC

2191

SMG2105C

No

23 Aug 2019

AUDI

A3 SEDAN 1.0 TFSI S TRONIC (LED)

Grey

2018

CHZB22757

WAUZZZ8VOK1007221

85.0 kW (113 bhp)

\$22,105.00

10 Dec 2018

10 Dec 2018

\$22,947.00

Yes

09 Dec 2028

\$17,210.00

09 Dec 2028

A - Car up to 1600cc & 97kW (130bhp)

10

\$23,568.00

\$21,903.00

\$39,113.00

OK

Re: FINAL REVISION - SMG2105C- OD AIG - SURVEYED 23 AUG 19**Shirley Hiew (LKK Auto)**

Fri 11/10/2019 2:46 PM

To: Carrine Leong <carrine.leong@premiumauto.com.sg>

Cc: 'Boo seng yak' <boojohnny@gmail.com>; 'Chang Chee Sing' <claims@premiumauto.com.sg>; Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; jiajee.yap@premiumauto.com.sg <jiajee.yap@premiumauto.com.sg>; SUR <sur@lkkauto.com>

Dear Carrine,

Confirmed \$ 9,268.72 @ 5 days of repairs before excess \$ 600/- & GST.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte LtdPhone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Carrine Leong <carrine.leong@premiumauto.com.sg>**Sent:** Friday, 11 October 2019 2:22 PM**To:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>**Cc:** 'Boo seng yak' <boojohnny@gmail.com>; 'Chang Chee Sing' <claims@premiumauto.com.sg>; Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; jiajee.yap@premiumauto.com.sg <jiajee.yap@premiumauto.com.sg>; SUR <sur@lkkauto.com>**Subject:** RE: FINAL REVISION - SMG2105C- OD AIG - SURVEYED 23 AUG 19

Hi Shirley,

Noted, please take out labour for alignment fee.

Thanks & Best Regard**Carrine Leong**

Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183

e. carrine.leong@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

**Email Disclaimer**

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]**Sent:** Friday, 11 October, 2019 1:55 PM**To:** 'Carrine Leong' <carrine.leong@premiumauto.com.sg>**Cc:** 'Boo seng yak' <boojohnny@gmail.com>; 'Chang Chee Sing' <claims@premiumauto.com.sg>; Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; jayee.yap@premiumauto.com.sg; SUR <sur@lkkauto.com>**Subject:** Re: FINAL REVISION - SMG2105C- OD AIG - SURVEYED 23 AUG 19

Hi Carrine,

According to our surveyor, since the front rim is not due to the accident, hence the wheel alignment test (labour no.4) should not be included in the repair cost.

Please check & revert us.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jayee.yap@premiumauto.com.sg <jayee.yap@premiumauto.com.sg>**Sent:** Tuesday, 1 October 2019 11:15 AM**To:** Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>; Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>**Cc:** 'Boo seng yak' <boojohnny@gmail.com>; 'Carrine Leong' <carrine.leong@premiumauto.com.sg>; 'Chang Chee Sing' <claims@premiumauto.com.sg>**Subject:** FINAL REVISION - SMG2105C- OD AIG - SURVEYED 23 AUG 19

Hi Adrian and all,

Revised estimate and photographs is attached.

Please confirm repair cost of repair \$9548.72 @ 5 days of repair.

Re: OD CLAIM FOR SMG 2105 C ON 16/8/2019

Shirley Hiew (LKK Auto)

Mon 26/8/2019 2:01 PM

To: Claims <claims@premiumauto.com.sg>; Admin A <admin-a@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>

 1 attachments (2 MB)

ESTIMATE.pdf;

Dear Syafiq,

As instructed by our client, please proceed to repair the insured vehicle **SMG 2105C (Excess S 600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte LtdPhone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>**Sent:** Tuesday, 20 August 2019 8:36 PM**To:** Admin A <admin-a@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>**Cc:** 'Claims' <claims@premiumauto.com.sg>**Subject:** RE: OD CLAIM FOR SMG 2105 C ON 16/8/2019

Dear all,

Attached is the estimate for your kind reference.

Best Regards,**Syafiq****Claims Admin Assistant**

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

**Email Disclaimer**

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Claims <claims@premiumauto.com.sg>

Sent: Monday, 19 August 2019 9:59 AM

To: 'Admin A' <admin-a@lkkauto.com>; 'Admin-D (LKKAuto)' <admin-d@lkkauto.com>; 'SUR' <sur@lkkauto.com>

Cc: 'Claims' <claims@premiumauto.com.sg>

Subject: OD CLAIM FOR SMG 2105 C ON 16/8/2019

Dear All,

Kindly register OD claims for this vehicle. Attached is GIA report for your reference.

We will forward you the estimate once is available.

Please arrange survey on 21/8/2019, 10.30am. Owner waiting.

Best Regards,

Syafiq

Claims Admin Assistant

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

**Email Disclaimer**

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

Niyitha (LKK Auto)

From: Claims <claims@premiumauto.com.sg>
Sent: Monday, 19 August 2019 9:59 AM
To: 'Admin A'; 'Admin-D (LKKAuto)'; 'SUR'
Cc: 'Claims'
Subject: OD CLAIM FOR SMG 2105 C ON 16/8/2019
Attachments: SMG 2105 C - 16082019.PDF; SAftersales19081910030_0001.jpg;
SAftersales19081910030_0002.jpg

Dear All,

Kindly register OD claims for this vehicle. Attached is GIA report for your reference.

We will forward you the estimate once is available.

Please arrange survey on 21/8/2019, 10.30am. Owner waiting.

Best Regards,
Syafiq
Claims Admin Assistant

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

View Received Message

This mail is associated with :

***SMG2105C (9000329752SG)**

OD

Aug 16 2019 1:00PM

[AZLI BIN AHMED]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 26/08/2019 10:30 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$10819.00) - SMG2105C - Claim Handler: Nadaraja, Deeban

Approved:10819,00:RH front rim damage not consistent to take out part and labour 4. Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

Since the front rim is not due to the accident, hence
the wheel alignment test should not be included in the repair cost.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 23 Aug 2019

Preliminary Advice

Vehicle No	: SMG2105C	Accident Date	: 16/08/2019
Make	: AUDI A3	Policy No.	: 1800144899
Assignment Date	: 23/08/2019	Excess	: S\$0.00
Date of Inspection	: 23/08/2019	Est. Duration of Repair	: 5 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,146.00
Revised Amount	:S\$	10,819.00
Check Items (Estimated)	:S\$	548.00
Total	:S\$	11,367.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	103,000.00
COE / PARF Rebate	:S\$	39,113.00
Salvage Value	:S\$	
Margin for Repair	:S\$	63,887.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/08/2019 09:41
Date Of Accident	16/08/2019 13:00
Exact Location Of Accident	KEPPEL ROAD AT SENTOSA GATEWAY TOWARDS VIVOCITY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMG2105C
Insured/Policyholder	
Name Of Registered Owner	AZLI BIN AHMED
NRIC No	S7726219I
Email Address	AZLI.AHMED@GMAIL.COM
Mobile Phone No	(LOCAL) +65-92382394
Alternative Phone No	OFFICE-92382394

Vehicle Particulars

Manufacturer	AUDI
Model	A3 SEDAN 1.0 TFSI 8V
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800144899
Cover Note Number	

Driver

Name of Driver	AZLI BIN AHMED
NRIC No	S7726219I
Date Of Birth	11/09/1977
Occupation	INDOOR
Date Of Driving Pass	27/07/2004
Driving Experience	15 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92382394
Fax Number	
Contact Number	OFFICE-92382394
Email Address	AZLI.AHMED@GMAIL.COM

Address	BLK 851 TAMPINES ST 83 #02-190
Postcode	520851
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AT 16 AUG 2019 AT ABOUT 1PM, I WAS TRAVELLING ALONG KEPPEL ROAD TOWARDS VIVOCITY. AT SENTOSA GATEWAY JUNCTION, I WANTED TO MOVE RIGHT AS IT WAS A MERGING LANE FROM LANE 2. I SIGNALLED RIGHT, TURNED IN WITH BLINDSPOT CLEAR AND SUDDENLY, A WHITE NISSAN TEANA MOVED IN FROM THE RIGHT AND HIT MY FRONT RIGHT BUMPER. HE CONTINUED TO MOVE FORWARD AND MY CAR HIT AND GRAZED HIS TWO LEFT SIDE DOORS.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLN6160R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

E. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If Driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 16 Aug 2019 at about 1pm, I was travelling along Keppel road towards Vivacity. At Senton gateway junction, I wanted to move right as it was a merging lane from lane 2. I signalled right, turned in with blinker clear and suddenly, a white Nissan Teana moved in from the right and hit my front right bumper. He continued to move forward and my car hit and grazed his two left side doors.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PPN No.:

Signature of Reporting Officer


Accident Photo



Accident Photo



Accident Photo





COVER NOTE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

The following risk described on this Cover Note is hereby HELD COVERED on the terms and conditions of the policy issued to the Policyholder.

Name of Policyholder: AZLI BIN AHMED ✓
Period of Insurance: 10 Dec 2018 to 9 Dec 2020
Engine No.: CHZ B22757 ✓
Chassis No.: WAUZZZ8V0K1007221 ✓

Vehicle No.:
Cover Note No.: 1800144899
Endorsement No.:
Issued Date: 06 Dec 2018

ABOUT THE COVER

Make/Model: AUDI A3 Sedan 1.0 TFSI S tronic ✓
Engine Capacity/Tonnage: 999.00 CC Sum Insured: Market Value First Year of Registration: 2018
Driver Restriction: NA ✓ Off Peak Car: No ✓ Insuring with COE/PAFF: Yes
Person or Classes of Persons Entitled to Drive*:

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition: All Age Condition
Limitation as to use*:

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen: \$100

Named Driver and Excess (where applicable)
AZLI BIN AHMED - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG 90 Mobile App. Simply search and download "AIG 90" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

If you do not receive your Certificate of Insurance and policy documents within 30 days from the inception date stated on this cover note, please contact AIG immediately.
We hereby certify that this Cover Note is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1958 (Malaysia). For Corporate Policies, this Cover Note is valid for 60 days from the commencement date of the period of insurance.

0504125211

PREMIUM LEASING - NC

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.

AUTHORISED REPRESENTATIVE

Staffany Lim

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMG 2105 C

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Rehanded</i>	\$ 1,830.00	✓
2	FRONT BUMPER FIXING PART <i>New</i>	\$ 170.00	✓
3	FRONT BUMPER GUIDE SECTION - RH <i>? (OK) New</i>	\$ 35.00	?
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 488.00	✓
5	FRONT BUMPER CLOSING ELEMENT - RH <i>New</i>	\$ 270.00	✓
6	FRONT BUMPER COVER TRIM - RH <i>New</i>	\$ 148.00	✓
7	WHEEL HOUSING LINER ADAPTER - RH <i>New</i>	\$ 34.00	✓
8	FRONT BUMPER AIR GUIDE GRILLE - RH <i>Not New</i>	\$ 171.00	✓
9	FENDER <i>Rehanded</i>	\$ 778.00	✓
10	FENDER ATTACHMENT PARTS ?	\$ 65.00	?
11	FENDER BRACKET - RH ?	2 \$ 25.00	?
12	FENDER BRACKET - RH ?	\$ 35.00	?
13	FENDER BRACE <i>bt</i>	\$ 88.00	?
14	WHEEL HOUSING LINER SEAL - RH ?	\$ 31.00	✓
15	WHEEL HOUSING LINER - RH <i>Cut New</i>	\$ 158.00	✓
16	WHEEL HOUSING LINER ATTACHMENT PARTS <i>New</i>	\$ 81.00	✓
17	LED HEADLIGHT - RH <i>Cut</i>	\$ 5,029.00	✓
18	HEADLIGHT WASHER SYSTEM LIFT CYLINDER - RH <i>New</i>	\$ 128.00	✓
19	FRONT RIM - RH (BY OWNER) <i>Cut</i>	TBC	✓
20	SUNDRIES ?	\$ 300.00	?
TOTAL SPARE PARTS		\$ 9,864.00	
TOTAL LABOUR CHARGES		\$ 5,282.00	
GRAND TOTAL		\$ 15,146.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Rare
28/08/19

Premium Automobiles

55 Ubi Road 1, Singapore 408695

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0993/2019/NS
Date : 20-Aug-19

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : MR AZLI BIN AHMED
Address : BLK 851 TAMPINES ST 83
#02-190
Singapore 520851
Telephone : HP +65 92382394
Type of Claim : Own Damage Claims
Policy No. : 1800144899
Vehicle No : **SMG 2105 C**
Model Code : Audi A3 Sedan 1.0 TFSI 8V
Model / Year : Dec-18
Engine No : CHZ B22757
Chassis No : WAUZZZ8VOK1007221
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 16-Aug-19
Place of Accident : KEPPEL ROAD AT SENTOSA GATEWAY TOWARDS CITY

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMG 2105 C

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensore and headlight washer assy.	S/N \$ 360.00 ✓	
2	To dismantle and renew front bumper, rhs front fender and rhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 2,450.00 1250	
3	To respray front bumper and rhs front fender.	\$ 2,000.00 1100	
4	To renew rhs front rim and carry out wheel alignme	S/N \$ 280.00 X	
5	To carry out diagnostic checks.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: <u>\$ 5,282.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMG 2105 C

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Deformed</i>	\$ 1,830.00	✓ 1464
2	FRONT BUMPER FIXING PART <i>new</i>	\$ 170.00	+
3	FRONT BUMPER GUIDE SECTION - RH <i>Angd / new</i>	\$ 35.00	? ✓ 27.52
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 488.00	+
5	FRONT BUMPER CLOSING ELEMENT - RH <i>new</i>	\$ 270.00	+
6	FRONT BUMPER COVER TRIM - RH <i>new</i>	\$ 148.00	+
7	WHEEL HOUSING LINER ADAPTER - RH <i>new</i>	\$ 34.00	+
8	FRONT BUMPER AIR GUIDE GRILLE - RH <i>Not new</i>	\$ 171.00	+
9	FENDER <i>Deformed</i>	\$ 778.00	✓ 622
10	FENDER ATTACHMENT PARTS <i>Not New</i>	\$ 65.00	? X
11	FENDER BRACKET - RH <i>Not New</i>	2 \$ 25.00	? X
12	FENDER BRACKET - RH <i>Not New</i>	\$ 35.00	? X
13	FENDER BRACE <i>Bar</i>	\$ 88.00	? ✓ 69.24
14	WHEEL HOUSING LINER SEAL - RH <i>new</i>	\$ 31.00	+
15	WHEEL HOUSING LINER - RH <i>from Deformed</i>	\$ 158.00	x ✓ 126.00
16	WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	\$ 81.00	+
17	LED HEADLIGHT - RH <i>cut</i>	\$ 5,029.00	✓ 4023.70
18	HEADLIGHT WASHER SYSTEM LIFT CYLINDER - RH <i>rep</i>	\$ 128.00	+
19	FRONT RIM - RH (BY OWNER) <i>cut</i>	180	- X
20	SUNDRIES <i>Not</i>	\$ 300.00	? ✓ 34.16
TOTAL SPARE PARTS		\$ 9,864.00	
TOTAL LABOUR CHARGES		\$ 5,282.00	
GRAND TOTAL		\$ 15,146.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 23/08/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 05 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0993/2019/NS
Date : 20-Aug-19

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian,

5 days - ok - Jy - 01 Oct 2019

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : MR AZLI BIN AHMED
Address : BLK 851 TAMPINES ST 83
#02-190
Singapore 520851
Telephone : HP +65 92382394
Type of Claim : Own Damage Claims
Policy No. : 1800144899
Vehicle No : **SMG 2105 C**
Model Code : Audi A3 Sedan 1.0 TFSI 8V
Model / Year : Dec-18
Engine No : CHZ B22757
Chassis No : WAUZZZ8V0K1007221
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 16-Aug-19
Place of Accident : KEPPEL ROAD AT SENTOSA GATEWAY TOWARDS CITY

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMG 2105 C

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensors and headlight washer assy.	S/N \$ 360.00	\$ 360.00
2	To dismantle and renew front bumper, rhs front fender and rhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 2,450.00	\$ 1,250.00
3	To respray front bumper and rhs front fender.	\$ 2,000.00	\$ 1,100.00
4	To renew rhs front rim and carry out wheel alignment.	S/N \$ 280.00	\$ 280.00
5	To carry out diagnostic checks.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		\$ 5,282.00	\$ 3,182.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMG 2105 C

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 1,830.00	\$ 1,464.00
2	FRONT BUMPER FIXING PART	\$ 170.00	
3	FRONT BUMPER GUIDE SECTION - RH	\$ 35.00	\$ 27.52
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 488.00	
5	FRONT BUMPER CLOSING ELEMENT - RH	\$ 270.00	
6	FRONT BUMPER COVER TRIM - RH	\$ 148.00	
7	WHEEL HOUSING LINER ADAPTER - RH	\$ 34.00	
8	FRONT BUMPER AIR GUIDE GRILLE - RH	\$ 171.00	
9	FENDER	\$ 778.00	\$ 622.00
10	FENDER ATTACHMENT PARTS	\$ 65.00	
11	FENDER BRACKET - RH	2 \$ 25.00	
12	FENDER BRACKET - RH	\$ 35.00	
13	FENDER BRACE	\$ 88.00	\$ 69.84
14	WHEEL HOUSING LINER SEAL - RH	\$ 31.00	
15	WHEEL HOUSING LINER - RH	\$ 158.00	\$ 126.00
16	WHEEL HOUSING LINER ATTACHMENT PARTS	\$ 81.00	
17	LED HEADLIGHT - RH	\$ 5,029.00	\$ 4,023.20
18	HEADLIGHT WASHER SYSTEM LIFT CYLINDER - RH	\$ 128.00	
19	FRONT RIM - RH (BY OWNER)	TBC	
20	SUNDRIES	\$ 300.00	\$ 34.16
	TOTAL SPARE PARTS	\$ 9,864.00	\$ 6,366.72
	TOTAL LABOUR CHARGES	\$ 5,282.00	\$ 3,182.00
	GRAND TOTAL	\$ 15,146.00	\$ 9,548.72

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SMG 2105 C

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0993/2019/KK

7 Nov 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SMG 2105 C, Audi A3 SEDAN 1.0 TFSI.

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

With reference to the above-mentioned vehicle, no. **SMG 2105 C**, claimant, **Mr. Azli Bin Ahmad**, please find the related document per attached.

1. A copy of the Original invoice no. 85014435 – S\$ 9,275.53.
2. A copy of the Discharge Voucher duly signed by client.

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SMG 2105 C

Premium Automobiles Pte Ltd



Audi Centre Singapore
261 Alexandra Road
Singapore 159938
Main Telephone 6886 2223
Main Telefax 6471 3733

Alexandra Service Centre
261 Alexandra Road
Singapore 159938
Main Telephone 6886 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6386 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6386 2323
24-hour Breakdown Service 9826 1233
Email: customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 14:10

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014435	Account: A0006 (T 0)
	Date : 06/11/2019	AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
	Order : SMG2105C	
	Term : 30	

Regn No: SMG2105C (V 40273) Regn Date: 10/12/2018 Mileage: 12730 WIP No.: 64438

Model: A3 SEDAN 1.0 TFSI 8VMANG Chassis: WAUZZZ8V0K1007221 Engine: CHZ B22757 Dept: U

You have been assisted by :- UB-Tony Poong (33)

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	M: TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	360.00	1.00	360.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FEN AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	1250.00	1.00	1,250.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	1100.00	1.00	1,100.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK.	192.00	1.00	192.00
X	A8V0941774D	(SK) HEADLIGHT	1.00	5029.00	4,023.20
X	A8V5821106A	FENDER (LAST)	1.00	777.50	622.00
X	A8V5821172	WHEEL HOUS	1.00	157.50	126.00
X	A8V5807065R GRU	COVER	1.00	1830.00	1,464.00
X	A8V5807184	GUIDE	1.00	34.40	27.52
X	A8V0821136A	SUPPORT	1.00	87.30	69.84
X	A8V5821472A	BRACKET	1.00	24.70	19.76
X	AN 0161857	POP-RIVET	5.00	3.00	12.00
X	AN 91022001	NUT	2.00	1.50	2.40

Parts 6,366.72
Labour 0.00
Sublet 2,902.00
Menus 0.00
Lubricant 0.00

Sub-Total 8,668.72

7% GST 606.81

Grand Total 9,275.53



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SMG 2105 C

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0993/2019/EH
1 September 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE: CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A3 SEDN 1.0 TFSI 8V
Vehicle Chassis No. : WAUZZZ8V0K1007221
Vehicle Regn No. : SMG 2105 C
Vehicle Mileage : 12730 KM
Vehicle Owner : Mr. Azli Bin Ahmad
Certificate No : 1800144899
Own Damage Excess : \$642.00 (Inclusive GST)
Accident Date : 16 August 2019
Place : Keppel Rd at Sentosa Gateway Towards Vivocity
Repair Cost : S\$ 9,275.53
WIP No. : 64438
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time : 1730 hrs
Date : 2/9/19

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Aug 2019		23 Aug 2019 15:17 Edit Adj Rpt	S\$9,268.72 Edit Estimates	S\$9,268.72 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: AZLI BIN AHMED , ID: S77262191, Tel: +6592382394, Email: AZLI.AHMED@GMAIL.COM									
Vehicle Reg. No.: SMG2105C		Date of Loss: 16/08/2019 13:00 - :59 [8 Months and 6 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 9000329752SG		Policy/Cover Note No.: 1800144899 (Comprehensive) Coverage: 10/12/2018 - 09/12/2020 Excess: S\$600.00							
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Nadaraja, Deeban] Deeban@nadaraja.Nadaraja@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 03/09/2019]									
Driver/Customer: AZLI BIN AHMED (41 / Male) , NRIC: S77262191, Tel: +6592382394 Email: AZLI.AHMED@GMAIL.COM									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (26/08/2019): Alert - Adj Mandate Approved (S\$10819.00) - SMG2105C - Claim Handler: Nadaraja, ... - AIG_SG (26/08/2019): SMG2105C / OD / 16/08/2019 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMG2105C (9000329752SG)

OD

Aug 16 2019 1:00PM

[AZLI BIN AHMED]

Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser	
Assessment Reports													1 per page		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print		
1	23/08/19 15:53	Adjuster Immediate Advice											Load HTM			
Photos/Images													3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print		
1	23/08/19 16:16	General View											Load JPG	☒		
2	23/08/19 16:16	General View											Load JPG	☒		
3	23/08/19 16:16	General View											Load JPG	☒		
4	23/08/19 16:16	General View											Load JPG	☒		
5	23/08/19 16:16	General View											Load JPG	☒		
6	23/08/19 16:16	General View											Load JPG	☒		
7	23/08/19 16:16	General View											Load JPG	☒		
8	23/08/19 16:16	General View											Load JPG	☒		
9	23/08/19 16:16	General View											Load JPG	☒		
10	23/08/19 16:16	General View											Load JPG	☒		
11	23/08/19 16:16	General View											Load JPG	☒		
12	23/08/19 16:16	General View											Load JPG	☒		
13	23/08/19 16:16	General View											Load JPG	☒		
14	23/08/19 16:16	General View											Load JPG	☒		
15	23/08/19 16:16	General View											Load JPG	☒		
16	23/08/19 16:16	General View											Load JPG	☒		
17	23/08/19 16:16	General View											Load JPG	☒		
18	04/10/19 11:13	Reinspection Photo											Load JPG	☒		
19	04/10/19 11:13	Reinspection Photo											Load JPG	☒		
20	04/10/19 11:13	Reinspection Photo											Load JPG	☒		
21	04/10/19 11:13	Reinspection Photo											Load JPG	☒		
22	04/10/19 11:13	Reinspection Photo											Load JPG	☒		
23	04/10/19 11:13	Reinspection Photo											Load JPG	☒		
24	04/10/19 11:13	Reinspection Photo											Load JPG	☒		
25	04/10/19 11:13	Reinspection Photo											Load JPG	☒		
26	04/10/19 11:13	Reinspection Photo											Load JPG	☒		
27	04/10/19 11:13	Reinspection Photo											Load JPG	☒		
Documentation													1 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail		Print		
1	23/08/19 16:14	SMG 2105C GIA.pdf											Load PDF			
2	23/08/19 16:14	ESTIMATE.pdf											Load PDF			
3	23/08/19 16:14	DRIVING & CN.pdf											Load PDF			
4	11/10/19 14:44	ESTIMATE MARKED.pdf											Load PDF			
5	22/11/19 08:40	Workshop Invoice											Load PDF			
6	22/11/19 08:40	Discharge Voucher											Load PDF			

Linked Accident Report Documents

										View		View in Browser	
Assessment Reports										1 per page		☒	
No	Finalized On	Premium Automobiles Pte Ltd (UB1)						Thumbnail		Print			

Assessment Reports				1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	19/08/19 09:54	Accident Statement		Load HTML	

Photos/Images				3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	19/08/19 09:51	Accident Photo		Load JPG	☒
2	19/08/19 09:51	Accident Photo		Load JPG	☒
3	19/08/19 09:51	Accident Photo		Load JPG	☒
4	19/08/19 09:51	Accident Photo		Load JPG	☒
5	19/08/19 09:51	Accident Photo		Load JPG	☒
6	19/08/19 09:51	Accident Photo		Load JPG	☒
7	19/08/19 09:51	Accident Photo		Load JPG	☒
8	19/08/19 09:51	Accident Photo		Load JPG	☒
9	19/08/19 09:51	Accident Photo		Load JPG	☒
10	19/08/19 09:51	Accident Photo		Load JPG	☒
11	19/08/19 09:51	Accident Photo		Load JPG	☒
12	19/08/19 09:51	Accident Photo		Load JPG	☒
13	19/08/19 09:51	Accident Photo		Load JPG	☒
14	19/08/19 09:51	Accident Photo		Load JPG	☒
15	19/08/19 09:51	Accident Photo		Load JPG	☒
16	19/08/19 09:51	Accident Photo		Load JPG	☒
17	19/08/19 09:51	Accident Photo		Load JPG	☒
18	19/08/19 09:51	Accident Photo		Load JPG	☒
19	19/08/19 09:51	Accident Photo		Load JPG	☒
20	19/08/19 09:51	Accident Photo		Load JPG	☒
21	19/08/19 09:51	Accident Photo		Load JPG	☒
22	19/08/19 09:51	Accident Photo		Load JPG	☒
23	19/08/19 09:51	Accident Photo		Load JPG	☒
24	19/08/19 09:51	Accident Photo		Load JPG	☒
25	19/08/19 09:51	Accident Photo		Load JPG	☒
26	19/08/19 09:51	Accident Photo		Load JPG	☒

Documentation				1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	19/08/19 09:53	Sketch Plan		Load JPG	☒
2	19/08/19 09:53	Sketch Plan #2		Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19014868/ASF3E2

Date: 22/11/2019

REFERENCE

Insured/Claimant:	AZLI BIN AHMED	Policy No:	1800144899	
Date of Loss:	16/08/2019	Nature of Claim:	OD	Claim No: 9000329752SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG2105C		
Make & Model:	AUDI A3, 999cc TFSI (A)	Engine No:	CHZB22757
Reg. Date:	10/12/2018 (Man. Year: 2018)	Chassis No:	WAUZZZ8V0K1007221
Colour:	Grey	Odometer:	12456 km
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$103,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,864.00	6,366.72	3,497.28	35.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,282.00	2,902.00	2,380.00	45.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,146.00	9,268.72	5,877.28	38.80
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	14,546.00	8,668.72	5,877.28	40.40
+ GST 7.00/7.00% (S\$)	1,018.22	606.81	411.41	40.40
Nett Amount (S\$)	15,564.22	9,275.53	6,288.69	40.40

INSPECTION

Date of Assignment:	23/08/2019	
Date Inspected:	23/08/2019	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days	

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,830.00 FS	*1,484.00 FS
2	1		*FRONT BUMPER FIXING PART	Not Necessary	170.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION - RH	Damaged	35.00 FS	*27.52 FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	488.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - RH	Not Necessary	270.00 FS	*- FS
6	1		*FRONT BUMPER COVER TRIM - RH	Not Necessary	148.00 FS	*- FS
7	1		*WHEEL HOUSING LINER ADAPTER - RH	Not Necessary	34.00 FS	*- FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Not Necessary	171.00 FS	*- FS
9	1		*FENDER	Dented	778.00 FS	*622.00 FS
10	1		*FENDER ATTACHMENT PARTS	Not Necessary	65.00 FS	*- FS
11	2		*FENDER BRACKET - RH	Not Necessary	25.00 FS	*- FS
12	1		*FENDER BRACKET - RH	Not Necessary	35.00 FS	*- FS
13	1		*FENDER BRACE	Bent	88.00 FS	*69.84 FS
14	1		*WHEEL HOUSING LINER SEAL - RH	Not Necessary	31.00 FS	*- FS
15	1		*WHEEL HOUSING LINER - RH	Deformed	158.00 FS	*126.00 FS
16	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	81.00 FS	*- FS
17	1		*LED HEADLIGHT - RH	Cut	5,029.00 FS	*4,023.20 FS
18	1		*HEADLIGHT WASHER SYSTEM LIFT CYLINDER - RH	Not Necessary	128.00 FS	*- FS
19	1		*SUNDRIES	Necessary	300.00 FS	*34.16 FS
Total Parts (\$\$)					9,864.00	6,366.72

F=Franchise part. S=SpcNetL.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSORE AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,450.00	1,250.00
3	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	2,000.00	1,100.00
4	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	0.00
5	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
Gross Labour Cost (\$\$)			5,282.00	2,902.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >