

Hsiao Tong (LKKAuto)

From: Tan Lee Gek (Auto Svcs/Claims & IA/Claims & IA/Taxis) <LeeGek@smrt.com.sg>
Sent: Thursday, 3 October 2019 5:52 PM
To: CS A Team; Admin A
Subject: LOD Re: Accident on 22/8/2019 involving SHB 5717C & SHD 311L (AXA's insured)
Our Ref: TAX/08/19/2075/lg
Attachments: img-X03173435-0001.pdf

Dear All,

We quantify our own losses as follows:-

Cost of Repair	\$1354.88
Loss of Rental	\$495.68 (4.25 days x \$116.63)
Total	\$1850.56

We enclose the following documents:

- 1) Repair invoice
- 2) Proof of rental rate
- 3) Police/GIA reports
- 4) Accident vehicle laid-up report

We have notified AXA of PRS on 23/8/2019 at 9.46am and our taxi was surveyed on 23/8/2019 at 3.47pm. We attach our email for your perusal.

Our hirer is claiming his injury and loss of income through his own lawyer.

Please let us have your offer soon. Thanks.

Regards

Tan Lee Gek (DID: 6866 2647)

Claims Department

SMRT Automotive Services Pte Ltd





Customer Code: 3000063

SMRT TAXIS PTE LTD

Block Unit

60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705



SMRT Automotive Services Pte Ltd
251 North Bridge Road Singapore 179102
Tel: 65 63311000 Fax: 65 63340247

Tax Invoice

GST Reg No. : MR-8500001-7
CRN : 199004280Z
Invoice No. : IV190900482
Date : 25.09.2019
Vehicle No. : SHB5717C
Your Ref No. : TAX/08/19/2075
Our Ref No. : 24102965
Terms : 30 Days

Description	Qty	Unit Cost	Add %	/ (Discount) Amount	Amount
Parts					
PIXEL STICKER	2.00	\$ 60.00	0.00	\$ 0.00	\$ 120.00
PANEL SUB-ASSY, REAR DOOR , LH	1.00	\$1243.90	(100.00)	\$1243.90	\$ 0.00
MOULDING ASSY, BODY ROCKER PANEL , LH	1.00	\$ 576.00	(100.00)	\$ 576.00	\$ 0.00
PANEL SUB-ASSY, FENDER REAR LH	1.00	\$ 824.80	(100.00)	\$ 824.80	\$ 0.00
LINER, REAR FENDER , LH	0.00	\$ 135.80	0.00	\$ 0.00	\$ 0.00
WHEEL, DISC	1.00	\$1555.10	(100.00)	\$1555.10	\$ 0.00
COVER, RR BUMPER ASSY	1.00	\$ 423.90	(100.00)	\$ 423.90	\$ 0.00
REAR BUMPER REINFORCEMENT	0.00	\$ 318.80	0.00	\$ 0.00	\$ 0.00
COVER, RR BUMPER ASSY	0.00	\$ 423.90	0.00	\$ 0.00	\$ 0.00
RETAINER, RR BUMPER, LH	1.00	\$ 111.50	(25.00)	\$ 27.87	\$ 83.63
SEAL, RR BUMPER , LH	0.00	\$ 85.20	0.00	\$ 0.00	\$ 0.00
CLIPS PIECE, FRT & RR BUMPER	10.00	\$ 1.50	(25.00)	\$ 3.75	\$ 11.25
FILLER, RR BUMPER , LH	0.00	\$ 119.90	0.00	\$ 0.00	\$ 0.00
SENSOR REVERSE	0.00	\$ 180.00	0.00	\$ 0.00	\$ 0.00
Sub-Total					\$ 214.88
Labour					
TO REPAIR LEFT REAR PORTION	1.00	\$ 300.00	0.00	\$ 0.00	\$ 300.00
Others					
TO REPSRAY REAR DOOR LH	1.00	\$ 200.00	0.00	\$ 0.00	\$ 200.00
TO RESPRAY FRONT FENDER LH	1.00	\$ 200.00	0.00	\$ 0.00	\$ 200.00
TO RESPRAY RIM	1.00	\$ 50.00	0.00	\$ 0.00	\$ 50.00
TO RESPRAY REAR BUMPER	1.00	\$ 200.00	0.00	\$ 0.00	\$ 200.00
TO RESPRAY ROCKER PANEL MOULDING	1.00	\$ 150.00	0.00	\$ 0.00	\$ 150.00

Authorised Signature
for SMRT Automotive Services Pte Ltd



SMRT Automotive Services Pte Ltd
251 North Bridge Road Singapore 179102
Tel: 65 63311000 Fax: 65 63340247

Tax Invoice

GST Reg No. : MR-8500001-7
CRN : 199004280Z
Invoice No. : IV190900482
Date : 25.09.2019
Vehicle No. : SHB5717C
Your Ref No. : TAX/08/19/2075
Our Ref No. : 24102965
Terms : 30 Days

Customer Code: 3000063

SMRT TAXIS PTE LTD

Block Unit

60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

Description	Qty	Unit Cost	Add %	/ (Discount) Amount		Amount
TO WASH AND VACUUM	0.00	\$ 60.00	0.00	\$	0.00	\$ 0.00
TO REPLACE SUNDRY PARTS	1.00	\$ 20.00	0.00	\$	0.00	\$ 20.00
TO CHECK WIRING AND SYSTEM FUNCTION	1.00	\$ 20.00	0.00	\$	0.00	\$ 20.00
TO TRANSFER DOOR MECHANISM	0.00	\$ 120.00	0.00	\$	0.00	\$ 0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	0.00	\$ 120.00	0.00	\$	0.00	\$ 0.00

GRAND TOTAL \$ 1,354.88

Remark :

Make/Model : PRIUS4
Accident Date : 22.08.2019

N.B. Payment by cheque should be crossed and
made payable to 'SMRT Automotive Services Pte Ltd'.
No receipt will be issued unless requested.

Authorised Signature
for SMRT Automotive Services Pte Ltd



SMRT Taxis Pte Ltd

MEMORANDUM

To: Claims Dept

Our Ref: TAX/08/19/2075

From: SMRT Taxis Pte Ltd

Date: 27/08/2019

**ACCIDENT INVOLVING SHB5717C AND SHD311L ON 22/8/2019
12:40 PM ALONG SERANGOON ROAD.**

This is to confirm that the daily rental rate for SHB5717C is \$116.63 per day.

Please proceed to recover any rental loss from the third party as a result of the above accident.

Thank you.

Yours sincerely
SMRT TAXIS PTE LTD



for Manager



Laid Up Report

Accident Start Date : 01/08/2019
Accident End Date : 29/08/2019
Date Generated : 30/08/2019
User Name : LeeGek

Case Reference Number	Vehicle Registration Number	Company Type	Vehicle Make	Vehicle Model	Job Card Number	Date and Time (Accident Repair)	Date and Time (Repair Completed)
TAX/08/19/2075	SHB5717C	SMRT Taxis Pte Ltd	TOYOTA	PRIUS4	24102965	22/08/2019 2:58 PM	27/08/2019 10:29 AM