

 $51\; UBI\; AVE\; 1, \#02-25\; PAYA\; UBI\; INDUSTRIAL\; PARK, SINGAPORE\; 408933\;\; TEL: \\ (065)\; 62563561\;\; FAX: \\ (065)\; 62564315\;\; FAX: \\ (065)\; 62563561\;\; FAX: \\ (065)\; 625635$

Immediate Advice

To: AXA Insurance Pte Ltd Date: 30/10/2019

Survey Details:

F	
Date of loss	22.08.2019
Date of appointment	23.08.2019
Date of survey	23.08.2019
Location of survey	SMRT AUTOMOTIVE SERVICES PTE LTE

Vehicle Details:

Claim Type:	Third party	
Vehicle number	SHB5717C	
Make and Model	Toyota Prius (1797cc)	
Date of registration	12.10.2017	
Excess		
Market Value/ Book Value		(est)
Parf/COE Rebate		(est)
Nett Loss		(est)

Repair details:

Initial Estimate	Ċ	7 156 35
Initial Estimate	>	/,150.35

Proposed/Revised repair cost:

Parts	\$ 214.88
Check items (estimate)	NIL
Labour	\$ 1,140.00
Supplementary	NIL
Total	\$ 1,354.88
Lump Sum(if applicable)	NIL

Number of days for repair	<u>3</u>



 $51\,UBI\,AVE\,1, \#02-25\,PAYA\,UBI\,INDUSTRIAL\,PARK, SINGAPORE\,408933\,TEL: (065)\,62563561\,FAX: (065)\,62564315$

Remarks:

TP submitted video(front & rear). Third party filtered out from the
right lane and hit by our insured who was changing lane from left to
right. Both parties should exercise caution. Propose 50/50.

Mandate:

Liability(TP)	50%	
Proposed repair cost	\$ 1,354.88	
Loss of use	NIL	
Loss of rental	\$ 466.52	(4days x \$116.63)
Loss of income	NIL	
	\$ 1,821.40	
50%	\$ 910.70	
LTA/GIA search fees	NIL	
Others	NIL	
Proposed Total	\$ 910.70	