

INS. CASE OWNER:

JOEL GOH

CC4/EQ119014880/ R1 ga3

LKK:

IDAC:

ASSIGNMENT

Surveyor:

RASUL

DOI: 27/08/2019

Date / Time :

22/08/2019

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. : GBB 3533A

Claim No. : DM19HO02323-JG

Name of Insured : AIN'S OPERATIONS

Policy No. :

Insured Tel No. : HP:

Make / Model :

Excess Sec II :S\$

D.O.A : 16/08/2019

Place of Accident :

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age :

Adam Bin Ismail

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. :

(V/L: YES / NO)

Insured Liability : % Final ? Yes / No

SHA 9222S



INSRS:

WSP:

Tel : DING AUTOMOTIVE

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/Time		STAGE	DATE / PIC
	SHA 9222S - NA/INC10018679/r ; DOA : 18/09/10	Non-Reporting ltr (1st):	
	GBB 3533A - NA/UOI13005985/e1; DOA: 31/3/13	Non-Reporting ltr (2nd):	
31/10	EMAIL LOT.	Non-Reporting ltr (Final):	
	REC LOR to TP (Pending LOD)	Notification ltr (if non-pickup):	
	TO offer to offer 10/11/19.	Call OE:	
13/11	offer \$1489.60 (Pending acceptance)	After call ltr to OE:	
	Settle @ \$1489.60, NO BV required. File pass	Documentation Check List: Handler Typist	
	MC to close.	Notification ltr (if non-pickup)	
		After call ltr to OE:	
		Authorisation To Act:	
		Release Voucher:	
		Final Repair Bill:	
		Car Rental Invoice:	
		Towing Invoice:	
		LTA / GIA :	
		Medical Bill:	
		PDR:	
		Mandate/Reject Instruction:	
		LOD:	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

PRELIMINARY ADVICE	Date/Time:	Sent By:	Confirm by: Rasul.
FINALIZATION	Date/Time:	Confirm with:	Confirm by: Rasul.
Repair Cost: 45	S\$ 100.00	(3 days) Reduction: \$288.52% 68	Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time: 12/11/19	Confirm with: Hachim	Email ☒ Call ☐
Final Liability:	% (100)	(Agreed / Assessed) BOLA S/N No. : 27	If NO or B 25, Ass. Lia :
Repair Cost: (W1689)	S\$ 1177.00		
Loss of Rental (LOR):	S\$ 210.60	(2 days) x \$105.30	
Loss of Use (LOU):	S\$ -	(5 x days)	
Loss of Income (LOI):	S\$ 100.00	(550 x 2 days)	
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☒		(Tick only one)	
GIA/LTA Search	S\$ 2.00		
Medical:	S\$ -		
Disbursement:	S\$ -	(e.g. Tow/ Independent)	
Legal Cost	S\$ -		
Total:	S\$ 1489.60	Global Sum S\$:	
FINAL PAYMENT	Date/Time:	Confirm with:	Email ☒ Call ☐
Payee 1:	S\$ 1489.60	Name 1: Ding Automotive Pte Ltd	
Payee 2: (Strike if N.A.)	S\$ -	Name 2:	
Payee 3: (Strike if N.A.)	S\$ -	Name 3:	

COPY SENT
13/11/190/1
14/11
0/1

Passive

REF:

EQT

8396

ASSIGNMENT

From: 27.8.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHA 9222S

at Workshop n/o: Ding Auto

of 31 Corporation Road

Insured

Policy No

Claims No

Sum Insured

Excess:

(Client's Record)

Make of Veh: 11-000.m

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res: Yes or No

Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

mp

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SHA 9222S Yr Make: 2015 / OCT

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai I40 1.7 CC: 1688

Colour: Yellow AC: Insured / Std / NI / NA

Sp. Reading: 577179 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KM HLB4 / UMG 40-79761

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or WSTLACE

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A: 16/08/19 D.O.I: 27/08/19

Survey held at: Ding Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

45 \$11001-

CRed = \$2288.52 / 68.1.7

Date/Time, File Pass to:

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to:

2)

Days Of Repair:

Resurvey No. of Trip:

Report Format :

Lump Sum / L.B.I.; (\$

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Insp (\$

☐ : Weekend (\$

Survey Fee

Transportation

\$ + RL \$

Phone

Other

TOTAL

Cecilia

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

23/08/2019 13:53

JOB-NO: 50111955

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)
ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0CONTACT: 65533080
64739522

Page 1 of 2

VEHICLE DETAILS

LICENSE NO: SHAB222S TRANS: AUTO
MAKE / MODEL: HYUNDAI / i40
OWNER'S INSURER: MS First Capital Insurance Limited
JOB-CODE: TP SA: Ding Auto User 2CHASSIS: KMHLB41UMGU079761
ENGINE: D4FDGU662621

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 CHECK WIRING SYS	1.00	120.00	0.00	120.00		Y	260
2 DIAGNOSTIC & REPROGRAMMED ELECTRICAL SYS	1.00	200.00	0.00	200.00		Y	260
3 STRAIGHTEN AND PANEL BEAT REAR PORTION & ACCIDENT AREAS	1.00	600.00	0.00	600.00		Y	250 110
4 SPRAY REAR BUMPER	1.00	250.00	0.00	250.00		Y	250
TOTAL:		1,170.00	0.00	1,170.00			

MATERIALS

1 REAR BUMPER LOWER SPOILER part repair	1.00	318.00	63.60	254.40	L	Y	
2 REAR BUMPER RETAINER RH X SUC	1.00	48.63	9.73	38.90	L	Y	
3 REAR BUMPER RETAINER LH X SUC	1.00	48.63	9.73	38.90	L	Y	
4 REAR BUMPER REINFORCEMENT 2 LL	1.00	488.40	97.68	390.72	L	Y	
5 REAR BUMPER sch	1.00	669.50	133.90	535.60	L	Y	
6 REAR BUMPER CLIPS sch	1.00	100.00	0.00	100.00	S	Y	
7 RHR FENDER STICKER sch	1.00	180.00	0.00	180.00	S	Y	
8 LHR FENDER STICKER sch	1.00	180.00	0.00	180.00	S	Y	
9 REAR BUMPER STICKER sch	1.00	150.00	0.00	150.00	S	Y	
10 REVERSE SENSOR 2 SUC	1.00	200.00	0.00	200.00	S	Y	
11 REAR BUMPER TOP PADDING sch	1.00	150.00	0.00	150.00	S	Y	
TOTAL:		2,533.16	314.64	2,218.52			

TOTAL PARTS & LABOUR: 3,703.16 314.64 3,388.52

EXCESS/LOADING: \$ 0.00

No. Of Day: 3 days

RE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR (LUMP SUM) \$

DATE OF SURVEY: 27 / 08 / 19 @ 1100

SURVEYED BY: Raseul

CONTACT NO: 90010568 FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

23/08/2019 13:53

JOB-NO: 50111955

OWNER'S PARTICULARSNAME: CityCab PTE LTD (Fleet)
ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0CONTACT: 65533880
64739522

Page 1 of 2

VEHICLE DETAILSLICENSE NO: SHA9222S
MAKE / MODEL: HYUNDAI / i40

TRANS: AUTO

CHASSIS: KMHLB41UMGU079761
ENGINE: D4FDGU662621

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 CHECK WIRING SYS	1.00	120.00	0.00	120.00		Y	<u>260</u>
2 DIAGNOSTIC & REPROGRAMMED ELECTRICAL SYS	1.00	200.00	0.00	200.00		Y	<u>X</u>
3 STRAIGHTEN AND PANEL BEAT REAR PORTION & ACCIDENT AREAS	1.00	600.00	0.00	600.00		Y	<u>250</u>
4 SPRAY REAR BUMPER	1.00	250.00	0.00	250.00		Y	<u>200</u>
TOTAL:		1,170.00	0.00	1,170.00			
<u>MATERIALS</u>							
1 REAR BUMPER LOWER SPOILER <i>repair</i>	1.00	318.00	63.60	254.40	L	Y	
2 REAR BUMPER RETAINER RH <i>X</i>	1.00	48.63	9.73	38.90	L	Y	
3 REAR BUMPER RETAINER LH <i>X</i>	1.00	48.63	9.73	38.90	L	Y	
4 REAR BUMPER REINFORCEMENT <i>?</i>	1.00	488.40	97.68	390.72	L	Y	
5 REAR BUMPER <i>sch</i>	1.00	669.50	133.90	535.60	L	Y	
6 REAR BUMPER CLIPS <i>me</i>	1.00	100.00	0.00	100.00 40	S	Y	
7 RHR FENDER STICKER <i>me</i>	1.00	180.00	0.00	180.00 100	S	Y	
8 LHR FENDER STICKER <i>me</i>	1.00	180.00	0.00	180.00 100	S	Y	
9 REAR BUMPER STICKER <i>me</i>	1.00	150.00	0.00	150.00 80	S	Y	
10 REVERSE SENSOR <i>?</i>	1.00	200.00	0.00	200.00	S	Y	
11 REAR BUMPER TOP PADDING <i>me</i>	1.00	150.00	0.00	150.00 50	S	Y	
TOTAL:		2,533.16	314.64	2,218.52			
TOTAL PARTS & LABOUR :		3,703.16	314.64	3,388.52			

EXCESS/LOADING: S\$ 0.00

No. Of Day:

3 days

RE-SURVEY: BEFORE/AFTER PAINTING

PART-BY-PART OR LUMP SUM S\$DATE OF SURVEY: 27 / 08 / 19 @ 1100

SURVEYED BY:

Rafael

CONTACT NO:

90010568

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

LKK Auto Consultants hereby notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged parts for survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be approved by LKK is subject to final approval from insurance Company

Acknowledged by Repairer:

Date:

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
ESTIMATOR							
STA AUTOCENTRE							
TEL:		FAX:					



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: DM19HO02323-JG
Our ref: CC4/EQI19014880/R1ga3

Date: 29/08/2019

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

PRELIMINARY ADVICE OF VEHICLE NO.

SHA 9222S

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 27/08/2019 at the premises of M/s Ding Automotive Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	3,388.52
Revised Estimate Amount	: S\$	1,415.60
"Check" Items Amount	: S\$	590.72
Total (Including Check Items)	: S\$	2,006.32
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3.0 days

Yours faithfully,

MOHD. RASUL
Licensed Appraiser

Satisfaction Voucher

Date: 28/08/2019

MS First Capital Insurance Limited

Attention: MOTOR CLAIMS DEPT

28 AUG '19 9:56

Dear Sir/Madam

TEO TRONG HOE

I/We hereby acknowledge having received from Singapore Technologies Kinetics

Ltd., 249 Jalan Boon Lay, Singapore 619523, my/our vehicle number SHA9222S

which has been repaired to my/our satisfaction and acceptance. I/We admit that

the payment of SGD _____ account for such repairs is in full discharge

of my/our claim upon the corporation under the policy number D-18088937MFSH

reference claim number 50111955 in respect of the damage caused to the

said vehicle in an accident that occurred thereto or about the 23/08/2019

at EXIT PAYA LEBAR RD FROM PIE

Dated this day of 28/8/2019

Signature: [Signature]

NRIC No: 87245511/H

Name: CityCab PTE LTD (Fleet)

Address: 383 SIN MING DRIVE
SINGAPORE 575717 0

Company Stamp if applicable

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Thursday, 22 August 2019 5:11 PM
To: assignments
Subject: FW: ACCIDENT INVOLVING SHA9222S AND GBB3533A ON 16/08/2019 SURVEYOR ARRANGEMENT (DM19HO02323-JG)

11:26am @ 23/8/19
vehicle not in
person @ mohan
arrange on 27/8/19

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joel Goh <joel.goh@eqinsurance.com.sg>
Sent: Thursday, 22 August 2019 5:10 PM
To: Taxis Customer Service <taxiscs@stengg.com>
Cc: kelly.ding@dingauto.sg; dd.hashim@dingauto.sg; Claims@dingautomotive.com.sg; Admin A <admin-a@lkkauto.com>
Subject: RE: ACCIDENT INVOLVING SHA9222S AND GBB3533A ON 16/08/2019 SURVEYOR ARRANGEMENT (DM19HO02323-JG)

Without Prejudice
Save As To Cost

Dear Vadivelan

Thank you for your confirmation.
We will arrange accordingly.

Dear LKK

Please assist on this PRS.
Our insured has not reported this accident.

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Taxis Customer Service [mailto:taxiscs@stengg.com]
Sent: Thursday, August 22, 2019 1:31 PM
To: Joel Goh
Cc: kelly.ding@dingauto.sg; dd.hashim@dingauto.sg; Claims@dingautomotive.com.sg
Subject: RE: ACCIDENT INVOLVING SHA9222S AND GBB3533A ON 16/08/2019 SURVEYOR ARRANGEMENT (DM19HO02323-JG)

Hi Joel,

I would like appoint LKK Auto Consultants Pte Ltd for vehicle survey. Kindly please advise on time & date of survey as I can make arrangement with driver. Appreciate for arrangement.

Best Regards,
Vadivelan Mohan
Ding Automotive Pte Ltd
Hp : 96891857 / 62657130

From: Joel Goh <joel.goh@eqinsurance.com.sg>
Sent: Thursday, August 22, 2019 1:24 PM
To: Taxis Customer Service <taxiscs@stengg.com>
Cc: kelly.ding@dingauto.sg; dd.hashim@dingauto.sg; Claims@dingautomotive.com.sg
Subject: RE: ACCIDENT INVOLVING SHA9222S AND GBB3533A ON 16/08/2019 SURVEYOR ARRANGEMENT (DM19HO02323-JG)

WARNING! THIS EMAIL ORIGINATES FROM OUTSIDE ST ENGINEERING.

Without Prejudice
Save As To Costs

Dear Vadivelan

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please revert within 2 working days if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

1) AJAX Inspection Services Pte Ltd Tel: 6255 0808 Fax: 6849 9155	2) Automobile Inspection Services Pte Ltd Tel: 6286 0155 Fax: 6284 1539 Contact Person: Sophia
3) LBS Automotive Appraisal Pte Ltd	4) Priority Services

Tel: 6281 6690 / 62832866 Fax: 6281 8748 Contact Person: Amy/ Grace	Tel: 6293 4822 Fax: 6296 3283 Contact Person: Sharon
5) RT Appraisal Pte Ltd Tel: 6748 6076 Fax: 6748 0361 Contact Person: Elson/Elgene	6) LKK Auto Consultants Pte Ltd Tel: 6256 3561 Fax: 6741 4108
7) Kelvin Automotive Appraising Services Tel: 8182 5263 Fax: 6746 1148 Contact Person: Kelvin	8) Automotive Appraiser & Surveying Services Tel: 9662 3655 Fax: 6765 5662 Contact Person: Mr Chee
9) JP Knights Pte Ltd Tel: 6345 0068 Fax: 6344 5328	10) Appraisals Associates Pte Ltd Tel : 6747 2822 Fax: 6747 0070
11) Infiniti Appraisal Service Tel : 9668 4818/9009 9001 Fax: 6458 7432	12) Formteam Adjusters Pte Ltd Tel: 6509 1788 Fax: 6509 6221

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days. Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
 did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg

A Member of Crystalline

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

From: Taxis Customer Service [<mailto:taxiscs@stengg.com>]
Sent: Thursday, August 22, 2019 8:49 AM
To: Janet Tan; Joel Goh
Cc: kelly.ding@dingauto.sg; dd.hashim@dingauto.sg; Claims@dingautomotive.com.sg
Subject: ACCIDENT INVOLVING SHA9222S AND GBB3533A ON 16/08/2019 SURVEYOR ARRAGEMENT

Dear Officer ,

Kindly please pre-arrange for survey vehicle number SHA9222S. Vehicle still on road and once confirm survey date&time I will make arrangement with driver to ground vehicle. Please advise .Appreciate for your arrangement.

Thanks

Best Regards,
Vadivelan Mohan
Ding Automotive Pte Ltd
Hp : 96891857 / 62657130

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Corporation Limited [Registration No. 200300002K]

This message contains a suspicious attachment type.
Although there were no detectable virus in it,
please take proper precautions on opening the attachment.

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Corporation Limited [Registration No. 200300002K]

Mei Kwan (LKKAUTO)

From: Joel Goh <joel.goh@eqinsurance.com.sg>
Sent: Monday, 7 October, 2019 1:43 PM
To: Mei Kwan (LKKAUTO)
Cc: CS A Team; Admin A; Cecilia Chong (LKK Auto)
Subject: RE: ACCIDENT INVOLVING SHA9222S AND GBB3533A ON 16/08/2019 SURVEYOR ARRANGEMENT (DM19HO02323-JG)
Attachments: GBB3533A.PDF
Categories: HMK

Dear Mei Kwan

Attached insured's accident report for your attention.

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the

From: Janet Tan
Sent: Tuesday, September 10, 2019 9:33 AM
To: Mei Kwan (LKKAUTO); Joel Goh
Cc: CS A Team; Admin A; Cecilia Chong (LKK Auto)
Subject: RE: ACCIDENT INVOLVING SHA9222S AND GBB3533A ON 16/08/2019 SURVEYOR ARRANGEMENT (DM19HO02323-JG)

Dear Mei Kwan,

OI yet to report. We shall follow up.

Regards,

Janet Tan
Senior Executive | Claims



Enclosed for your perusal is:

- TP estimated cost of repair
- Preliminary advice

Kindly advise whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Our case handler in-charge is Cecilia and she can be contacted at DID: 6749 4274.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>

Sent: Friday, 23 August, 2019 11:28 AM

To: 'Joel Goh' <joel.goh@eqinsurance.com.sg>; assignments <assignments@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: ACCIDENT INVOLVING SHA9222S AND GBB3533A ON 16/08/2019 SURVEYOR ARRAGEMENT (DM19HO02323-JG)

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that vehicle is not in the workshop, repairer arrange on 27/08/2019.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joel Goh <joel.goh@eqinsurance.com.sg>

Sent: Thursday, 22 August 2019 5:10 PM

To: Taxis Customer Service <taxiscs@stengg.com>

Cc: kelly.ding@dingauto.sg; dd.hashim@dingauto.sg; Claims@dingautomotive.com.sg; Admin A <admin-a@lkkauto.com>

Subject: RE: ACCIDENT INVOLVING SHA9222S AND GBB3533A ON 16/08/2019 SURVEYOR ARRAGEMENT (DM19HO02323-JG)

Without Prejudice

Save As To Cost

Dear Vadivelan

Thank you for your confirmation.

WARNING! THIS EMAIL ORIGINATES FROM OUTSIDE ST ENGINEERING.

**Without Prejudice
Save As To Costs**

Dear Vadivelan

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please revert within 2 working days if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

1) AJAX Inspection Services Pte Ltd Tel: 6255 0808 Fax: 6849 9155	2) Automobile Inspection Services Pte Ltd Tel: 6286 0155 Fax: 6284 1539 Contact Person: Sophia
3) LBS Automotive Appraisal Pte Ltd Tel: 6281 6690 / 62832866 Fax: 6281 8748 Contact Person: Amy/ Grace	4) Priority Services Tel: 6293 4822 Fax: 6296 3283 Contact Person: Sharon
5) RT Appraisal Pte Ltd Tel: 6748 6076 Fax: 6748 0361 Contact Person: Elson/Elgene	6) LKK Auto Consultants Pte Ltd Tel: 6256 3561 Fax: 6741 4108
7) Kelvin Automotive Appraising Services Tel: 8182 5263 Fax: 6746 1148 Contact Person: Kelvin	8) Automotive Appraiser & Surveying Services Tel: 9662 3655 Fax: 6765 5662 Contact Person: Mr Chee
9) JP Knights Pte Ltd Tel: 6345 0068 Fax: 6344 5328	10) Appraisals Associates Pte Ltd Tel : 6747 2822 Fax: 6747 0070
11) Infiniti Appraisal Service Tel : 9668 4818/9009 9001 Fax: 6458 7432	12) Formteam Adjusters Pte Ltd Tel: 6509 1788 Fax: 6509 6221

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days. Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Best Regards,

Joel Goh
Executive | Claims


Motor Cycle & Boat

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Corporation Limited [Registration No. 200300002K]



AVG

This email has been checked for viruses by AVG antivirus software.
www.avg.com

Cecilia Chong (LKK Auto)

From: Dd hashim <dd.hashim@dingauto.sg>
Sent: Wednesday, 13 November 2019 9:27 AM
To: Cecilia Chong (LKK Auto)
Cc: Kelly Ding; claims; Ding Ding Auto; taxiscs
Subject: Re: 50111955 BILLING FOR SHA9222S/TP G8B3533A/16/08/2019-PENDING
OFFER/REF:--

Morning Cecilia,

Offer accepted, please send me your discharge voucher.

Thanks.

~Best Regards~

SINCERELY

DD HASHIM

HP: +65 81160811 / +65 92394128

FAX: +65 64520614

On Wed, Nov 13, 2019 at 9:24 AM Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com> wrote:

WITHOUT PREJUDICE

Dear Hashim,

We are pleased to offer total amount of \$1,489.60 (all-in).

Kindly confirm acceptance.

Thanks

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

DING AUTOMOTIVE PTE LTD

Business Reg. No : 201619222G

BLK 10, #01-20 SIN MING IND EST. SEC C, SINGAPORE 575645

Tel: 6452 1208 Fax: 6452 0614

TAX INVOICE**EQ INSURANCE COMPANY LIMITED**5 MAXWELL ROAD
#17-00, TOWER BLOCK
SINGAPORE 069110

ATTN : MOTOR CLAIMS DEPT


TEL : FAX :

INVOICE : I-000835
DATE : 13/11/2019
GST REG NO : 201619222G
TERMS : C.O.D.
PO NO : GBB3533A
OUR REF : SHA9222S
PAGE : 1 of 1

ITEM NO.	DESCRIPTION	QUANTITY	UNIT PRICE	AMOUNT
1.	Cost of repair-SHA9222S	1	1,100.00	1,100.00
2.	Gia search fee	1	1.87	1.87
3.	Loss of rental (w/o gst)	2	105.30	210.60
4.	Loss of income (w/o gst)	2	50.00	100.00

REMARKS :Job card:50111955
Your ref:GBB3533A
Oic:Ms Cecilia (LKK)
Doa:15/08/2019
Remarks:DV Waived**Without Prejudice**
to our driver's Injury claim**SUB TOTAL** : 1,412.47
GST : 77.13
TOTAL SGD : **1,489.60**
DEPOSIT :
O/S BALANCE :

FOR DING AUTOMOTIVE PTE LTD


Authorized Signature

Customer Signature

I have inspected and hereby confirmed that
the job done and the amount due herein
are entire to my satisfaction



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 18/11/2019

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	GBB 3533A	(Insd Veh)	Your Ref. No. : DM19HO02323-JG
	SHA 9222S	(TP Veh)	Our Ref. No. : CC4/EQI19014880/R1ga3q2
Date of Accident	16/8/2019		

Liability	100%	
Final Repair Cost	: \$ 1,177.00	
Loss of Income	: \$ 100.00	2 days
Rental (If any)	: \$ 210.60	2 days
Others:	: \$ 2.00	
	: \$	
	1,489.60	
Final Settlement Sum	: \$ 1,489.60	
Remarks	:	

Payment Instruction: Payee's Breakdown

1)	DING AUTOMOTIVE PTE LTD	: \$ 1,489.60
		: \$

JOANNE LEE

LKK Auto Consultants Pte Ltd

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC4/EQ19014880/R1ga3q2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 18-11-2019	
			Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBB 3533A	Veh. Inspected	SHA 9222S	
Policy No.	DMCPHQ19-000557	Coverage (\$)	0.00	
Claim No.	DM19HO02323-JG	Excess (\$)	0.00	
Assign From	JOEL	Assign Date	22/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI I40 1.7	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KMHLB41UMGU079761	Colour	YELLOW	
Odometer	577179	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	WEST LAKE	6 mm	
L/H Front Tyre	205/60 R16	WEST LAKE	6 mm	
R/H Rear Tyre	205/60 R16	WEST LAKE	6 mm	
L/H Rear Tyre	205/60 R16	WEST LAKE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/08/2019	Inspection Date	27/08/2019	
Survey held at	31 CORPORATION ROAD			
Repairer	DING AUTOMOTIVE PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 9222S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER LOWER SPOILER	TO REPAIR SEE LABOUR	318.00	-
1	REAR BUMPER RETAINER RH	SERVICEABLE	48.63	-
1	REAR BUMPER RETAINER LH	SERVICEABLE	48.63	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	488.40	-
1	REAR BUMPER	SCRATCHED	669.50	669.50
	LESS 20% DISCOUNT		-314.63	-133.90
			1,258.53	535.60
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER CLIPS (SN)	NECESSARY	100.00	40.00
1	RHR FENDER STICKER (SN)	NECESSARY	180.00	100.00
1	LHR FENDER STICKER (SN)	NECESSARY	180.00	100.00
1	REAR BUMPER STICKER (SN)	NECESSARY	150.00	80.00
1	REVERSE SENSOR (SN)	SERVICEABLE	200.00	-
1	REAR BUMPER TOP PADDING (SN)	NECESSARY	150.00	50.00
			960.00	370.00
<u>LABOUR</u>				
	CHECK WIRING SYS.	NOT NECESSARY	120.00	60.00
	DIAGNOSTIC & REPROGRAMMED ELECTRICAL SYS.		200.00	-
	STRAIGHTEN AND PANEL BEAT REAR PORTION & ACCIDENT AREAS.INCLUSIVE OF THE REPAIR OF REAR BUMPER LOWER SPOILER .		600.00	250.00
	SPRAY REAR BUMPER .		250.00	200.00
			1,170.00	510.00
GRAND TOTAL			3,388.53	1,415.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,100.00

Report Ref No. CC4/EQI19014880/R1ga3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.