

ASSIGNMENT

Surveyor: **ADRIAN**

DOI: **22/08/2019**

Date / Time: **22/08/2019**

Registered in Merimen: **23/08/2019**

Pre-assign / CCU / FTE



Insured Vehicle No. : **SHC 1891C**

Claim No. : _____

Name of Insured : **COMFORT TRANSPORTATION PTE LTD**

Policy No. : _____

Insured Tel No. : _____ HP: _____
Excess Sec II :S\$ _____ D.O.A : **20/08/2019 01:50**

Make / Model : **TOYOTA PRIUS**

Place of Accident : **GEYLANG RD TWDS LAVENDER ST**

Is driver the owner? (YES / **NO**) Nature of Accident : _____

If NO, Driver Name / Age : **LAM KEE LEONG**

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. : **+65-81186868** (V/L: YES / NO)

Insured Liability : **%** Final ? Yes / **No**

SFK 562R



INSRS:
WSP: **HUA MENG**
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time		STAGE	DATE / PIC
	SFK 562R	Non-Reporting ltr (1st):	
	- CS/TMI19014599/K11f3, DOA: 20/8/19	Non-Reporting ltr (2nd):	
	SHC 1891C - NA/TMI19014722/z4, DOA: 20/8/19	Non-Reporting ltr (Final):	
	- CC3/III19008610/K1pa3, DOA: 11/5/19	Notification ltr (if non-pickup):	
	- CS3/III17001032/H1h3m2, DOA: 15/1/17	Call OI:	
	<i>3919 - Reg/AVP Ann born parties.</i>	After call ltr to OI:	
	<i>1110 - OI Adv in merimen. to seek approval to reject TP claim. TPV encroached BID lane.</i>	Documentation Check List: Handler Typist	
	<i>412 - Rejection email send TP</i>	Notification ltr (if non-pickup)	
	<i>612 - Kindly mv new chop. & sign.</i>	After call ltr to OI:	
	<i>612 - Pls pass me to close.</i>	Authorisation To Act:	
		Release Voucher:	
		Final Repair Bill:	
		Car Rental Invoice:	
		Towing Invoice:	
		LTA / GIA :	
		Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

PRELIMINARY ADVICE	Date/Time:	Sent By:
--------------------	------------	----------

FINALIZATION	Date/Time:	Confirm with:	Confirm by:
Repair Cost:	46 S\$ 4000-	5 days Reduction: 5545.50 % 60	Email ☐ Call ☐

FINAL SETTLEMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
------------------	------------	---------------	--

Final Liability:	%	(Agreed / Assessed) BOLA S/N No. :	If NO or B 28, Ass. Lia :
Repair Cost:	S\$		
Loss of Rental (LOR):	S\$	(days)	
Loss of Use (LOU):	S\$	(S x days)	
Loss of Income (LOI):	S\$	(S x days)	
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐		(Tick only one)	

GIA/LTA Search:	S\$		
Medical:	S\$		
Disbursement:	S\$	(e.g. Tow/ Independent)	
Legal Cost:	S\$		
Total:	S\$	Global Sum S\$:	

FINAL PAYMENT	Date/Time:	Confirm with:	Email ☐ Call ☐
---------------	------------	---------------	--

Payee 1:	S\$	Name 1:	
Payee 2: (Strike if N.A.)	S\$	Name 2:	
Payee 3: (Strike if N.A.)	S\$	Name 3:	

COPY SENT

350

ADRIAN

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S

O/S

Bal. or Market Value:

IDAC Accident Rpt Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted: Vehicle: IN / OUT

Veh No: SFK562R Yr Regn: 2006 / Dec

Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover / ☐ Truck / ☐ Trailer or

Make: Honda Stream c.c 1799

Colour: Bronze A/C: Insured / Std / Nil / NA

Sp. Reading 193575 T/Radio: Insured / Std / Nil / NA

Eng/No:

C/No: RA6101866

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: Nil / ☒ S/Rim / ☐ STD A/Rim or

Tyre Size: F: 205/55R16 R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Continental

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.A. 32/28/13

Survey held at Hun Meng

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or Front N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	COE Expiry: 18/12/21
	US \$4000/- (Red - \$5925.00/60%)
	MV: 18K
	PV: 12.8K
	Nett: 5.2K

Date/Time, File Pass to? Date/Time, File Return to?

1) 2)

3) 4)

5) 6)

Prel. Report

Final Report

Part Prices Check:

IN OUT

Survey Fee:

Basic & Add.

S + RS, \$

Photos

Others

TOTAL

Date:

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

PUNGGOL EAST CAR RENTAL

663C PUNGGOL DRIVE

#12-232 WATERWAY SUNBEAM

S 823663

TP III

Cecilia

Date

:27.08.2019

Vehicle No

:SFK 562 R

Make/Model

:HONDA STREAM

Accident date

:20.08.2019

No	DESCRIPTION	Qty	Amount (\$\$)
<u>List Items</u>			
1	Front bumper <i>deformed</i>	1	\$ 699.2 ✓
2	Front bumper side holder @ \$ 41.80 <i>LH Dented</i>	2	\$ 83.6 <i>32</i>
3	Front bumper LH fod lamp <i>cracked</i>	1	\$ 451.2 <i>225</i>
4	Front bumper LH fod lamp cover <i>Nol nec</i>	1	\$ 107.8 x
5	Front bumper lower centre grille <i>Nol nec</i>	1	\$ 162.8 x
6	Front bumper reinforcement <i>system</i>	1	\$ 327.8 x
7	Front bumper sponge	1	\$ 103.4 x
8	Front bumper clips (1set) <i>nec</i>	1	\$ 66 <i>30</i>
9	Front grille <i>cracked</i>	1	\$ 328.6 ✓
10	Front grille H emblem <i>nec</i>	1	\$ 52.8 ✓
11	Front LH headlamp <i>lot</i>	1	\$ 640.2 ✓
12	Front LH headlamp lower bracket <i>Nol nec</i>	1	\$ 53.9 x
13	Front LH fender <i>Dented</i>	1	\$ 423.5 ✓
14	Front LH fender inner shield <i>torn</i>	1	\$ 198 ✓
15	Front LH fender inner shield clips (1 set) <i>nec</i>	1	\$ 66 <i>30</i>
16	Front LH fender signal lamp <i>Nol nec</i>	1	\$ 30.8 x
17	Front LH sport rim <i>lot</i>	1	\$ 1078 <i>450 (SN)</i>
18	Front LH tyre <i>stem</i>	1	\$ 308 x
19	Front LH shock absorber <i>best</i>	1	\$ 528 <i>330</i>
20	Front LH drive shaft <i>stem</i>	1	\$ 1078 x
21	Front LH lower arm <i>best</i>	1	\$ 638 <i>328</i>
22	Front LH knuckle arm <i>Dented</i>	1	\$ 632.5 <i>397</i>
23	Front LH knuckle arm bearing <i>nec</i>	1	\$ 159.5 ✓
24	Front LH linkage <i>stem</i>	1	\$ 121 x
			\$ 8338.6
Less 20% Disc			\$ 1643.1
Total			\$ 6695.5

3943.80

3155 04

SN: 450

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

PUNGGOL EAST CAR RENTAL
663C PUNGGOL DRIVE
#12-232 WATERWAY SUNBEAM
S 823663

Date :27.08.2019
Vehicle No :SFK 562 R
Make/Model :HONDA STREAM
Accident date :20.08.2019

No	DESCRIPTION	Qty	Amount (\$\$)
Labour Cost			
1	To check wheel alignment		\$ 100 ⁸⁰
2	Remove & reinstall front LH suspension		\$ 480 ²²⁰
3	Remove & reinstall air con fill in gas		\$ 150 ^x
4	Remove ,replace & repair consistent to the accident	1200	\$ 1300 ⁶⁰⁰
5	Respray painting		\$ 1100 ⁵⁰⁰
6	Tuff kote		\$ 100 ^x
Total			\$ 3230
Grand Total			\$ 9925.5

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: \$9925.04
h/s: HK

05Days

4K

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle & Owner Details

Owner ID Type:	Business
Owner ID:	281E
Vehicle No.:	SFK562R
Vehicle to be Exported:	Yes
Intended Deregistration Date:	22 Aug 2019
Vehicle Make:	HONDA
Vehicle Model:	STREAM 1.8 A
Primary Colour:	Brown
Manufacturing Year:	2006
Engine No.:	R18A1721380
Chassis No.:	RN61018666
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$19,226.00
Original Registration Date:	19 Dec 2006
First Registration Date:	19 Dec 2006
Transfer Count:	6
Actual ARF Paid:	\$21,149.00

Intended Exportation Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Renewal Details

COE Expiry Date:	18 Dec 2021
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$27,594.00
COE Rebate Amount:	\$12,806.00
Total Rebate Amount:	\$12,806.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 22 Aug 2019

OK



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)


Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad
 Advertiser Login
 Ways of Selling

2006 Japan Manufactured Toyota Wish.



Extremely Reliable With No
History Of Breakdown.

Direct Owner StarAd



ABWIN

ONE-STOP



Browse by Category

Save Search

Print

Back (1 2 3 4) Next

Sort by Date Posted

20 results/page

77 vehicles

Search honda stream

Advanced Search

Search

View All

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Search Selection honda stream Any Any > 10 year(s) old Any Any Any Available



☐ Honda Stream 1.8A X (COE till 11/2026) \$48,500 \$6,660 /yr 14-Dec-2006 1,799 cc 109,880 km MPV Available

1 Owner Only, Low Mileage, Cheapest And Low Depreciation, Very Well Maintained By Previous Owner, Original Paintwork, Most Wear And Tears Replaced, No Repair Needed. 100% Accident Free, View To Believe It. (High And Flexible Loan Available Up To 100% At Low...

Hamilton Autzhub Pte Ltd

Posted: 24-Aug-2019

Tags: 2006 Honda Stream, 2006 honda stream, Honda Stream, honda stream, Honda Stream, stream, Used Honda



☐ Honda Stream 1.8A (COE till 12/2021) \$18,800 \$8,050 /yr 22-Dec-2006 1,799 cc - MPV Available

Well Maintained, Excellent Condition, Accident Free, Bank And In House Loan Available, Trade In Are Welcome, Powerful Engine And Smooth Transmission, Buy With Confidence! Call Us Now To Make An Appointment To Viewing.

Car Search

Posted: 26-Jun-2019

Tags: 2006 Honda Stream, 2006 honda stream, Honda Stream, honda stream, Honda Stream, stream, Used Honda



☐ Honda Stream 1.8A (COE till 01/2027) \$42,800 \$5,800 /yr 08-Jan-2007 1,799 cc 144,000 km MPV Available

Original Paint, Very Well Taken Care By Previous Owners. Smooth Engine And Responsive Gearbox. Trade In And High Loan Available. View To Believe! Hurry Call Us Now For A Non Obligation Test Drive.

Posted: 21-Jul-2019

Tags: 2007 Honda Stream, 2007 honda stream, Honda Stream, honda stream, Honda Stream, stream, Used Honda



☐ Honda Stream 1.8A (COE till 01/2022) \$21,800 \$9,140 /yr 10-Jan-2007 1,799 cc - MPV Available

1 Owner Only, 100% Accident Free, Very Original Condition With Extended Warranty, Must View, Up To 100% Flexible Loan. We Provide Lowest Interest Rate. Flexible Loan And High Trade In Are Available. Package With Unrivalled Warranty Complete With Certificate And Te...

Classic Credit Pte Ltd

Posted: 29-Jul-2019

Tags: 2007 Honda Stream, 2007 honda stream, Honda Stream, honda stream, Honda Stream, stream, Used Honda

GET YOUR
COE
RENEWAL
LOAN

Is your COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.



☐ Honda Stream 1.8A (COE till 01/2022) \$18,500 \$7,710 /yr 15-Jan-2007 1,799 cc 152,889 km MPV Available

Very Well Maintain By Owner, Reliable Japanese 7 Seater Model, No Repair Needed, High Trade In And Loan Available.

Posted: 14-Apr-2019

Tags: 2007 Honda Stream, 2007 honda stream, Honda Stream, honda stream, Honda Stream, stream, Used Honda



☐ Honda Stream 1.8A (COE till 04/2022) \$31,000 \$11,530 /yr 30-Apr-2007 1,799 cc - MPV Available

Beautiful Red Honda Stream! Spacious And Reliable 7 Seater. Great For Families And For Grab Usage! Owner Selling To Upgrade. Parts Are Easily Available For This Model And Maintenance Is Low. Consignment Unit! Trade In And Loan Available! Call Us Now For Viewing!

Prem Ray Motoring

Posted: 28-Jul-2019

Tags: 2007 Honda Stream, 2007 honda stream, Honda Stream, honda stream, Honda Stream, stream, Used Honda

UNREGISTERED REPORT

Compare

Print Received Message

This mail is associated with :

***SFK562R (MCT19080457)**

[SHC1891C]

TP

PUNGGOL EAST CAR RENTAL

Aug 20 2019 1:00AM

Hua Meng Spray Painting Workshop

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 02/10/2019 09:28 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$0.00) - SFK562R - Claim Handler: Zuhaidah Bte Samsuri

Approved:0.00:Please proceed to reject TP claim.

Cecilia Chong (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Tuesday, 1 October 2019 4:29 PM
To: 'Hua Meng'
Subject: RE: YOUR REF: SFK 562R (OUR REF: CC6/III19014889/Aga3) *** ACCIDENT INVOLVING SHC 1891C & SFK 562R ON 20/08/2019 ***
Attachments: SHC 1891C .mp4

Your Ref: **SFK 562R** Without Prejudice
Our Ref: CC6/III19014889/Aga3

Dear Sirs/Madam,

ACCIDENT INVOLVING SHC 1891C (III) & SFK 562R ON 20/08/2019

We refer to the above matter.

Attached is a copy of our insured car video footage for your easy reference. We have reviewed the matter and we are of the view that our driver is not liable for the accident. Our Insured is driving on his lane and your client is the one encroaching into Our Insured's driver's lane.

In view of the above, we have our principal instruction to deny liability and unable to look into your client's matter.

Thank you.

Note: This video footage is solely for investigation and shall not be reproduced. You undertake to preserve its confidentiality and will not disclose, provide or make available the video footage in whole or in part, to any third party.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Hua Meng [<mailto:huameng@live.com.sg>]
Sent: Tuesday, 1 October 2019 1:24 PM
To: Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com>

Subject: Re: YOUR REF: SFK 562R (OUR REF: CC6/III19014889/Aga3) *** ACCIDENT INVOLVING SHC 1891C & SFK 562R ON 20/08/2019 ***

Dear Cecilia

Kindly forward us a copy of video footage mention in the OI's report.

Thank You.

Regards,
Jing Yee
Hua Meng Spray Painting Workshop
Tel : 6746 5519 Fax : 6743 4896

From: Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com>

Sent: Saturday, September 28, 2019 10:54 AM

To: Hua Meng <huameng@live.com.sg>

Subject: YOUR REF: SFK 562R (OUR REF: CC6/III19014889/Aga3) *** ACCIDENT INVOLVING SHC 1891C & SFK 562R ON 20/08/2019 ***

WITHOUT PREJUDICE

Dear Sir/Mdm,

We refer to the above matter

The liability is unclear.

Kindly email us a copy of AVF to review the liability.

Attached is a copy of OI's report.

Thanks

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Sep 2019 Edit Reg		22 Aug 2019 00:00 Edit Adj Rpt	S\$4,000.00 Edit Estimates	S\$4,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Main Claimant:	PUNGGOL EAST CAR RENTAL, Co. Reg. No.: 53338281E								
Vehicle Reg. No.:	SFK562R	Date of Loss:	20/08/2019 01:00 - :59 [152 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19080457	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHC1891C	Policy No. (Claimant):	18-MJ001819-R00						
		Excess:							
Repairer:	Hua Meng Spray Painting Workshop (HQ) No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67478064, 67465519								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]								
Claimant's Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 03/09/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (06/12/2019): Alert - Adj Mandate Approved (S\$0.00) - SFK562R - Claim Handler: Zuhaidah Bte Sa... - III_SG (02/10/2019): Alert - Adj Mandate Approved (S\$0.00) - SFK562R - Claim Handler: Zuhaidah Bte Sa... - III_SG (30/09/2019): Alert - Adj Mandate Maintained - SFK562R - Claim Handler: Zuhaidah Bte Samsuri									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SFK562R (MCT19080457)
[SHC1891C]
TP
PUNGGOL EAST CAR RENTAL
Aug 20 2019 1:00AM
[COMFORT TRANSPORTATION PTE LTD]
Hua Meng Spray Painting Workshop

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Video									1 per page			☒		
No	Finalized On	India International Insurance Pte Ltd (HQ)							Thumbnail			Print		
1	30/09/19 15:02	Video - Accident (OIV)										Load MP4		
Photos/Images									3 per page			☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail			Print		
1	17/10/19 17:45	General View										Load JPG		
2	17/10/19 17:45	General View										Load JPG		
3	17/10/19 17:45	General View										Load JPG		
4	17/10/19 17:45	General View										Load JPG		
5	17/10/19 17:45	General View										Load JPG		
6	17/10/19 17:45	General View										Load JPG		
7	17/10/19 17:45	General View										Load JPG		
8	17/10/19 17:45	General View										Load JPG		
9	17/10/19 17:45	General View										Load JPG		
10	17/10/19 17:45	General View										Load JPG		
11	17/10/19 17:45	General View										Load JPG		
12	17/10/19 17:45	General View										Load JPG		
13	17/10/19 17:45	General View										Load JPG		
14	17/10/19 17:45	General View										Load JPG		
15	17/10/19 17:45	General View										Load JPG		
16	17/10/19 17:45	General View										Load JPG		
17	17/10/19 17:45	General View										Load JPG		
18	17/10/19 17:45	General View										Load JPG		
19	17/10/19 17:45	General View										Load JPG		
20	17/10/19 17:45	General View										Load JPG		
21	17/10/19 17:45	General View										Load JPG		
22	17/10/19 17:45	General View										Load JPG		
23	17/10/19 17:45	Reinspection Photo										Load JPG		
24	17/10/19 17:45	Reinspection Photo										Load JPG		
25	17/10/19 17:45	Reinspection Photo										Load JPG		
26	17/10/19 17:45	Reinspection Photo										Load JPG		
27	17/10/19 17:45	Reinspection Photo										Load JPG		
28	17/10/19 17:45	Reinspection Photo										Load JPG		
29	17/10/19 17:45	Reinspection Photo										Load JPG		
30	17/10/19 17:45	Reinspection Photo										Load JPG		
31	17/10/19 17:45	Reinspection Photo										Load JPG		
32	17/10/19 17:45	Reinspection Photo										Load JPG		
33	17/10/19 17:45	Reinspection Photo										Load JPG		
34	17/10/19 17:45	Reinspection Photo										Load JPG		
35	17/10/19 17:45	Reinspection Photo										Load JPG		
36	17/10/19 17:45	Reinspection Photo										Load JPG		
37	17/10/19 17:45	Reinspection Photo										Load JPG		
38	17/10/19 17:45	Reinspection Photo										Load JPG		
39	17/10/19 17:45	Reinspection Photo										Load JPG		
40	17/10/19 17:45	Reinspection Photo										Load JPG		

Video			1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
				☒
41	17/10/19 17:45	Reinspection Photo	 Load JPG	☒
42	17/10/19 17:45	Reinspection Photo	 Load JPG	☒
43	17/10/19 17:45	Reinspection Photo	 Load JPG	☒
44	17/10/19 17:45	Reinspection Photo	 Load JPG	☒
45	17/10/19 17:45	Reinspection Photo	 Load JPG	☒
46	17/10/19 17:45	Reinspection Photo	 Load JPG	☒
47	17/10/19 17:45	Reinspection Photo	 Load JPG	☒
48	17/10/19 17:45	Reinspection Photo	 Load JPG	☒
49	17/10/19 17:45	Reinspection Photo	 Load JPG	☒
50	17/10/19 17:45	Reinspection Photo	 Load JPG	☒
51	17/10/19 17:45	Reinspection Photo	 Load JPG	☒
52	17/10/19 17:45	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/08/19 21:13	TP GIA REPORT	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	23/08/19 16:22	Singapore Accident Statement IV SHC1891C	 Load PDF	
2	30/11/19 18:27	Letter of Demand from Third Party TPD LOD FROM VISION LAW (SPK562R)	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III19014889/AGA3Q2

Date: 19/12/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant
 Vehicle No : SFK562R Insured Vehicle No : SHC1891C
 Date of Loss: 20/08/2019 Nature of Claim: TP Claim No: MCT19080457

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFK562R
 Make & Model: HONDA STREAM, 1.8 L (A) Engine No: R18A1721380
 Reg. Date: 19/12/2006 (Man. Year: 2006) Chassis No: RN61018666
 Colour: Bronze Odometer: 193575 km
 Engine Capacity: 1799 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
 Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,670.88	3,605.04	3,065.84	45.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,230.00	1,400.00	1,830.00	56.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,900.88	5,005.04	4,895.84	49.45
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	9,900.88	4,000.00	5,900.88	59.60
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 22/08/2019
 Date Inspected: 22/08/2019 Inspected At: Hua Meng Spray Painting Workshop (HQ)
 No 1 Kaki Bukit Avenue 6, #01-61
 Autobay@Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Dec 2019)
Parts:	M1-MPV	HONDA STREAM 1.8 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFK562R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	699.20 FL	*699.20 FL
2	1		*FRONT BUMPER SIDE HOLDER	N/S Damaged	83.60 FL	*32.00 FL
3	1		*FRONT BUMPER LH FOG LAMP	Cracked	451.20 FL	*295.00 FL
4	1		*FRONT BUMPER LH FOG LAMP COVER	Not Necessary	107.80 FL	*- FL
5	1		*FRONT BUMPER LOWER CENTRE GRILLE	Not Necessary	162.80 FL	*- FL
6	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	327.80 FL	*- FL
7	1		*FRONT BUMPER SPONGE	Not Necessary	103.40 FL	*- FL
8	1		*SET FRONT BUMPER CLIPS	Necessary	66.00 FL	*30.00 FL
9	1		*FRONT GRILLE	Cracked	328.60 FL	*328.60 FL
10	1		*FRONT GRILLE H EMBLEM	Necessary	52.80 FL	*52.80 FL
11	1		*FRONT LH HEADLAMP	Cut	640.20 FL	*640.20 FL
12	1		*FRONT LH HEADLAMP LOWER BRACKET	Not Necessary	53.90 FL	*- FL
13	1		*FRONT LH FENDER	Dented	423.50 FL	*423.50 FL
14	1		*FRONT LH FENDER INNER SHIELD	Torn	198.00 FL	*198.00 FL
15	1		*SET FRONT LH FENDER INNER SHIELD CLIPS	Necessary	66.00 FL	*30.00 FL
16	1		*SET FRONT LH FENDER SIGNAL LAMP	Not Necessary	30.80 FL	*- FL
17	1		*FRONT LH SPORT RIM	Cut	862.40 FS	*450.00 FS
18	1		*FRONT LH TYRE	Not Necessary	308.00 FL	*- FL
19	1		*FRONT LH SHOCK ABSORBER	Bent	528.00 FL	*330.00 FL
20	1		*FRONT LH DRIVE SHAFT	Not Necessary	1,078.00 FL	*- FL
21	1		*FRONT LH LOWER ARM	Bent	638.00 FL	*328.00 FL
22	1		*FRONT LH KNUCKLE ARM	Damaged	632.50 FL	*397.00 FL
23	1		*FRONT LH KNUCKLE ARM BEARING	Necessary	159.50 FL	*159.50 FL
24	1		*FRONT LH LINKAGE	Not Necessary	121.00 FL	*- FL

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	8,123.00	4,393.80
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,452.12	788.76
Total Parts (\$\$)	6,670.88	3,605.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WHEEL ALIGNMENT	New	100.00	80.00
2	REMOVE & REINSTALL FRONT LH SUSPENSION	New	480.00	220.00
3	REMOVE & REINSTALL AIR CON FILL IN GAS	New	150.00	0.00
4	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	1,300.00	600.00
5	RESPRAY PAINTING	New	1,100.00	500.00
6	TUFF KOTE	New	100.00	0.00
Gross Labour Cost (S\$)			3,230.00	1,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >