

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

PUNGGOL EAST CAR RENTAL
663C PUNGGOL DRIVE
#12-232 WATERWAY SUNBEAM
S 823663

TP III
Cecilia

Date :27.08.2019
Vehicle No :SFK 562 R
Make/Model :HONDA STREAM
Accident date :20.08.2019

No	DESCRIPTION	Qty	Amount (\$\$)
<u>List Items</u>			
1	Front bumper <i>deformed</i>	1	\$ 699.2 ✓
2	Front bumper side holder @ \$ 41.80 <i>LH Dgd</i>	2	\$ 83.6 <i>32</i>
3	Front bumper LH fod lamp <i>cracked</i>	1	\$ 451.2 <i>295</i>
4	Front bumper LH fod lamp cover <i>Not nec</i>	1	\$ 107.8 X
5	Front bumper lower centre grille <i>Not nec</i>	1	\$ 162.8 X
6	Front bumper reinforcement <i>Not nec</i>	1	\$ 327.8 X
7	Front bumper sponge	1	\$ 103.4 X
8	Front bumper clips (1set) <i>nec</i>	1	\$ 66 <i>30</i>
9	Front grille <i>cracked</i>	1	\$ 328.6 ✓
10	Front grille H emblem <i>nec</i>	1	\$ 52.8 ✓
11	Front LH headlamp <i>lt</i>	1	\$ 640.2 ✓
12	Front LH headlamp lower bracket <i>Not nec</i>	1	\$ 53.9 X
13	Front LH fender <i>Dented</i>	1	\$ 423.5 ✓
14	Front LH fender inner shield <i>torn ?</i>	1	\$ 198 ✓
15	Front LH fender inner shield clips (1 set) <i>nec</i>	1	\$ 66 <i>30</i>
16	Front LH fender signal lamp <i>Not nec</i>	1	\$ 30.8 X
17	Front LH sport rim <i>lt</i>	1	\$ 1078 <i>450(SW)</i>
18	Front LH tyre <i>Not nec</i>	1	\$ 308 X
19	Front LH shock absorber <i>Best</i>	1	\$ 528 <i>330</i>
20	Front LH drive shaft <i>Not nec</i>	1	\$ 1078 X
21	Front LH lower arm <i>Best</i>	1	\$ 638 <i>328</i>
22	Front LH knuckle arm <i>Dgd</i>	1	\$ 632.5 <i>397</i>
23	Front LH knuckle arm bearing <i>nec</i>	1	\$ 159.5 ✓
24	Front LH linkage <i>Not nec</i>	1	\$ 121 X
			\$ 8338.6
Less 20% Disc			\$ 1643.1
Total			\$ 6695.5

3943.80

3155 04

S.N: 450

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

PUNGGOL EAST CAR RENTAL
663C PUNGGOL DRIVE
#12-232 WATERWAY SUNBEAM
S 823663

Date :27.08.2019
Vehicle No :SFK 562 R
Make/Model :HONDA STREAM
Accident date :20.08.2019

No	DESCRIPTION	Qty	Amount (\$\$)
Labour Cost			
1	To check wheel alignment		\$ 100 80.
2	Remove & reinstall front LH suspension		\$ 480 220.
3	Remove & reinstall air con fill in gas		\$ 150 X
4	Remove ,replace & repair consistent to the accident	1400	\$ 1300 600
5	Respray painting		\$ 1100 500
6	Tuff kote		\$ 100 X
Total			\$ 3230
Grand Total			\$ 9925.5

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 9925.04
h/s: 41c

05Days.

41c.

McWell Ventures Pte Ltd

51 Ubi Avenue 1 #01-05

Paya Ubi Industrial Park

Singapore 408933

Phone Number: 6844 4640

Fax Number: 6844 4641

Customer:			Date: 23/8/2019 2:48 PM			
Company:			VIN			
License NO: SFK562R			Technician:			
Odometer:			Order NO:			
VEHICLE ALIGNMENT REPORT						
HONDA, STREAM RN6, RN8 (2WD, 17" Wheel), 06-12 (Customized)						
Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	----	3°20'	5°20'	---
		Right	----	3°20'	5°20'	---
	Camber	Left	0°24'	-0°45'	0°45'	0°24'
		Right	-0°54'	-0°45'	0°45'	-0°54'
	Toe	Left	1°06'	-0°05'	0°05'	1°03'
		Right	0°24'	-0°05'	0°05'	0°24'
Total		1°30'	-0°10'	0°10'	1°30'	
Rear	Camber	Left	-1°30'	-1°45'	-0°15'	-1°30'
		Right	-1°42'	-1°45'	-0°15'	-1°42'
	Toe	Left	-0°12'	0°03'	0°11'	-0°12'
		Right	-0°09'	0°03'	0°11'	-0°09'
		Total	-0°21'	0°05'	0°21'	-0°21'
	Thrust Angle		0°01'	----		0°01'
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left	----	----	11°05'	11°05'	----
	Right	----	----	11°05'	11°05'	----
Included Angle	Left	----	----	----	----	----
	Right	----	----	----	----	----
Toe Out On Turns	Left	----	----	----	----	----
	Right	----	----	----	----	----
Max Turn Inside	Left	----	----	----	----	----
	Right	----	----	----	----	----
Toe Curve Change	Left	----	----	----	----	----
	Right	----	----	----	----	----
Setback	Front	0.1"	----	----	----	0.1"
	Rear	-0.0"	----	----	----	-0.0"
Track Width Diff.			0.2"			0.2"
Wheel Base Diff.			0.1"			0.1"
Front Ride Height	Left	----	----	----	----	----
	Right	----	----	----	----	----
Rear Ride Height	Left	----	----	----	----	----
	Right	----	----	----	----	----
Frame Angle						----

McWell Ventures Pte Ltd

51 Ubi Avenue 1 #01-05

Paya Ubi Industrial Park

Singapore 408933

Phone Number: 6844 4640

Fax Number: 6844-4641

Customer:			Date: 26/8/2019 3:23 PM			
Company:			VIN			
License NO: SKF562R			Technician:			
Odometer:			Order NO:			
VEHICLE ALIGNMENT REPORT HONDA, STREAM RN6, RN8 (2WD, 17" Wheel), 06-12 (Customized)						
Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	----	3°20'	5°20'	----
		Right	----	3°20'	5°20'	----
	Camber	Left	0°30'	-0°45'	0°45'	0°30'
		Right	-0°42'	-0°45'	0°45'	-0°42'
	Toe	Left	-0°06'	-0°05'	0°05'	-0°06'
		Right	0°03'	-0°05'	0°05'	0°03'
Total		-0°03'	-0°10'	0°10'	-0°03'	
Rear	Camber	Left	-1°36'	-1°45'	-0°15'	-1°36'
		Right	-1°42'	-1°45'	-0°15'	-1°42'
	Toe	Left	0°03'	0°03'	0°11'	0°03'
		Right	-0°03'	0°03'	0°11'	-0°03'
		Total	0°00'	0°05'	0°21'	0°00'
	Thrust Angle		-0°03'	----	----	-0°03'
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left	----	----	11°05'	11°05'	----
	Right	----	----	11°05'	11°05'	----
Included Angle	Left	----	----	----	----	----
	Right	----	----	----	----	----
Toe Out On Turns	Left	----	----	----	----	----
	Right	----	----	----	----	----
Max Turn Inside	Left	----	----	----	----	----
	Right	----	----	----	----	----
Toe Curve Change	Left	----	----	----	----	----
	Right	----	----	----	----	----
Setback	Front	0.0"	0.0"	----	----	0.0"
	Rear	0.0"	0.0"	----	----	0.0"
Track Width Diff.			0.2"			0.2"
Wheel Base Diff.			0.0"			0.0"
Front Ride Height	Left	----	----	----	----	----
	Right	----	----	----	----	----
Rear Ride Height	Left	----	----	----	----	----
	Right	----	----	----	----	----
Frame Angle						----