

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 27 Aug 2019

Preliminary Advice

Insured Vehicle No	: SLM9740C		
TP Vehicle No	: SHB8985A	Accident Date	: 21/08/2019
Make	: KIA OPTIMA	Assignment Date	: 23/08/2019
Date of Inspection	: 26/08/2019	Est. Duration of Repair	: 3 days
Inspection At	: Premier Automotive Services Pte Ltd (HQ) 23 Changi South Ave 2, #01-02 Singapore 486443		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,806.15
Revised Amount	:S\$	1,837.45
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,837.45

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.