

768.84 x
90. %
691.96 *

0. c

100. +

220. +

=

320.00 *

0. c

66. +

40. =

106.00 *

0. c

691.96 +

320. +

106. =

1,117.96 *

1,117.96 x

80. %

894.37 *

0. c

419 900.00 ♦

\$	n	225.95
\$	n	225.95
\$	n	1,471.77
\$	sn	404.56
\$	sn	552.55
\$	n	986.70
\$	sn	552.55
\$	n	986.70
\$	n	2,872.68
\$	sn	470.06
\$	sn	323.05
\$	sn	493.35
\$	sn	493.35
\$	nn	225.36
\$	nn	225.36
\$	sn	276.08
\$	sn	276.08
\$	n	367.84
\$	n	367.84

ans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5459S

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

23 AUG 2019

PART

- 1 1 BUMPER COVER REAR
- 2 1 BUMPER LOWER REAR
- 3 1 BUMPER BRACKET CTR REAR
- 4 1 BUMPER BRACKET SIDE RH REAR
- 5 1 BUMPER RETAINER RH REAR
- 6 1 BUMPER REFLECTOR RH
- 7 1 BUMPER BRACKET SIDE LH REAR
- 8 1 BUMPER RETAINER LH REAR
- 9 1 BUMPER REFLECTOR LH
- 10 1 BUMPER BEAM REAR
- 11 1 BUMPER BEAM BRACKET LH REAR
- 12 1 BUMPER BEAM BRACKET RH REAR
- 13 1 OUTER PANEL REAR (End Panel)
- 14 1 OUTER PANEL REAR (End Panel)TRIM
- 15 1 TAILLAMP RH
- 16 1 TAILLAMP PANEL RH
- 17 1 TAILLAMP LH
- 18 1 TAILLAMP PANEL LH
- 19 1 BOOT REAR
- 20 1 BOOT FINISHER
- 21 1 BOOT WHEATERSTRIP
- 22 1 BOOT REFLECTOR LAMP LH
- 23 1 BOOT REFLECTOR LAMP RH
- 24 1 BOOT BADGE 'RENAULT'
- 25 1 BOOT BADGE
- 26 1 BOOT STRUT LH
- 27 1 BOOT STRUT RH
- 28 1 BOOT HINGE LH
- 29 1 BOOT HINGE RH