



南方摩哆 SOUTHERN MOTOR

Business Reg. No: 234147/00L
Block 1006, Bukit Merah Lane 2, #01-10, Singapore 159762
Tel: 6273-0369 (3 Lines) Fax: 6274-6614

23rd August 2019

India International Insurance Pte Ltd
64 Cecil Street #05-00
IOB Building
SINGAPORE (049711)

Dear Sirs,

RE: Cost of repair to Yamaha Jupiter 135 - FBK789B

1pc of Cover Set <i>cm</i> ✓		S\$ 580.00
1pc of Handle Bar <i>? bt</i> ✓		68.00
1pc of Front Fork Complete <i>repair</i>		380.00 R-100 (Labour)
1pc of Mirror <i>MIS</i> ✓		45.00
1pc of Handle Grip <i>cut</i> ✓		35.00
1pc of Front Footrest <i>bt</i> ✓	1887	68.00
1pc of Footrest Rubber <i>cut</i> ✓	10%	20.00
1pc of Spoke Rim <i>repair</i>	1698.30	480.00 R-100 (Labour)
1pc of Exhaust Pipe <i>sea</i> ✓		580.00
1pc of Rear Mudguard <i>cm</i> ✓		65.00
1pc of Brake Lever <i>*(pedal) bt</i> ✓		68.00
2pc of Rear Footrest <i>cm</i> ✓		40.00
1pc of Rear Headlight <i>? X sea</i>		110.00 X
2pc of Rear Footrest Stand <i>* (cm) (bracket)</i>		110.00
1pc of Steering Corn <i>na</i> ✓		85.00
1pc of Repair Brake Body R		180.00 120
1pc of Seat Bar <i>sea</i> ✓		55.00
1pc of Gear Lever <i>bt</i> ✓		68.00
		3,037.00
	Less 10%	303.70
	Nett	2,733.30
Transport Labour		40.00
		350.00
		<u>S\$ 3,123.30</u>

Yours Faithfully,
Southern Motor

[Signature]

LKK Auto Consultants hereby certify that the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Issue
Hp 9001068
4 days
26/08/19 @ 1500
Resurvey after repair

(Labour)
320
1698.30
320.00
2018.30
20%
1614.64
48-1,600
4 days



Ignore



Junk ▾

Delete

Delete



Reply

Reply
All

Forward



Meeting



More ▾

Respond



Move to: ?



Team E-mail



Reply & Delete



To Manager



Done



Create New

Quick Steps

From: Southern Motor <soumotor@hotmail.com>
To: Rasul (LKKAUTO)
Cc:
Subject: Re: FBK 789B DOA : 29/07/19

Dear Sir,

We confirm the finalised amount \$ 1,600 / 4 days of lump sum repair .

Thank you

From: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Sent: Friday, May 8, 2020 12:15 PM
To: Southern Motor <soumotor@hotmail.com>
Subject: FBK 789B DOA : 29/07/19

Hi,

Refer to attachment

Finalised amount is \$ 1,600 / 4 days of lump sum repair

Kindly confirm

Best Regards,

Rasul | Assessor

Southern Motor

All Items

Re: FBH677G

FBH677G