



SOUTHERN MOTOR

Blk 1006, Bukit Merah Lane 2 #01-10 Singapore 159762

Tel:62730369 Fax:62746614 CO/GST Reg No:23414700L

TAX INVOICE NO : INV28707
Invoice Date : 6th August 2020
Payment Terms : CASH
Vehicle No. : FBK789B - YAMAHA JUPITER
LC135
Mechanic : CASH

India International Insurance Pte Ltd - II001
64 CECIL STREET #05-00 IOB BUILDING Singapore 049711

Tel: 63476100 Fax: 62244174

<u>S/No</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>U/PRICE</u>	<u>Amount</u>
1	7% GST ON COST OF LUMP SUM REPAIR	1	\$52.34	\$52.34
2	COST OF LUMP SUM REPAIR	1	\$747.66	\$747.66
3	LOSS OF USE FOR 4 DAYS AT \$25.00 PER DAY	1	\$100.00	\$100.00
TOTAL				\$900.00
BALANCE				\$900.00

Goods Sold Are Not Returnable. Deposit Paid Are Not Refundable. All cheques should be made payable to "**SOUTHERN MOTOR**".
Interest Rate of ____ % per month will be imposed on overdue Accounts. Thank you.

Received by

Issued by

AUTHORIZATION TO ACT

I, Nor Dinie Bin Mohamad Nor ("the third party claimant")
of Blk 510 Jelapang Road #04-70 Singapore 670510 (address),
being the owner of FBK 789B (vehicle no) hereby authorize
Southern Motor ("the workshop") to act

for me

with respect to my claim for repair cost and/ or rental and/ or loss of use ("claim") for my
vehicle


bearing registration no FBK 789B that was damaged pursuant to the accident
which occurred on 29.7.2019 15:00 PM along Jalan Bahar

involving vehicle XD 4155 E ("the
accident")

I further authorize the workshop to settle my above mentioned claim in a manner that
they deem fit and the workshop is further authorized to receive payment further to
settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a
without prejudice and without admission of liability in so far as the driver/owner/insurers
of the other vehicle is concerned.

Dated this 06 day of Aug (month) 20 20 (year)


Signed by "the third party claimant"

 **SOUTHERN MOTOR**
Blk 1006, Bukit Merah Lane 2
#01-10, Singapore 159762
Tel: 62730369 Fax: 62748614

Signed by "the workshop"



SOUTHERN MOTOR

Blk 1006, Bukit Merah Lane 2 #01-10 Singapore 159762

Tel:62730369 Fax:62746614 CO/GST Reg No:23414700L

TAX INVOICE NO : INV28707
Invoice Date : 6th August 2020
Payment Terms : CASH
Vehicle No. : FBK789B - YAMAHA JUPITER
LC135
Mechanic : CASH

India International Insurance Pte Ltd - II001
64 CECIL STREET #05-00 IOB BUILDING Singapore 049711

Tel: 63476100 Fax: 62244174

<u>S/No</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>U/PRICE</u>	<u>Amount</u>
1	7% GST ON COST OF LUMP SUM REPAIR	1	\$52.34	\$52.34
2	COST OF LUMP SUM REPAIR	1	\$747.66	\$747.66
3	LOSS OF USE FOR 4 DAYS AT \$25.00 PER DAY	1	\$100.00	\$100.00
TOTAL				\$900.00
BALANCE				\$900.00

Goods Sold Are Not Returnable. Deposit Paid Are Not Refundable. All cheques should be made payable to "**SOUTHERN MOTOR**".
Interest Rate of ____ % per month will be imposed on overdue Accounts. Thank you.

Received by

Issued by