

ASS. REC. BY:

Surveyor: Kenneth

REF: CS/INC19014974/Krd3n

Special Instruction:

ASSIGNMENT (Office)

From (Person): Annie Koh

of

INC

Date/Time:

23/8/19 @ 5:46pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 9594C

Insured:

SV 6028Y

at Workshop n/s

Thns carb

Tel:

62576666

of

Mo. 2 Amk 87-63

Policy No:

Claim No:

MT/1058299002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19/8/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

12:26pm 8/8/19

Person Contacted:

Candy

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction
	Shmole ✓
	SHD 9594C - X
	SV 6028Y - X
3/9/19	54404.16 Car to Limit (Red 27,988.55, 86/9)

ASS. REC. BY:

REF:

INC/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.:

Yes or No

Lum Sum:

1.31

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S11D 9594C

Yr Regn:

08, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Prius

c.c

1798

Colour

M.P. White / Blue

A/C: Insured / Std / NI / NA

Sp. Reading

5624

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB31F4503082434

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modf: Nil / S/Rim / STD / Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

19/8/19

D.O.I.

26/8/19

Survey held at

2.03pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt body

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 03 SEP 2019

Date/Time, File Pass to?

☐

Prell. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

3/9 - typist

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + P.S. \$

Fees:

Others:

250

TOTAL

Report Format :

TP

Lump Sum / I.B.I. (\$

4404.16

Nivitha (LKK Auto)

From: MTSurvey <MTSurvey@income.com.sg>
Sent: Friday, 23 August 2019 5:46 PM
To: Admin-D (LKKAuto); 'assignments@lkkauto.com'
Subject: FW: Arrange for survey SHD9594C
Attachments: image002.wmz; image006.wmz

Hi LKK,

Please follow-up.

Warmest Regards

Annie Koh
Senior Admin,
Motor Insurance
T +65 64307899
www.income.com.sg



From: Candy Kong [mailto:candy.kong@transcab.com.sg]
Sent: Friday, 23 August 2019 2:36 PM
To: MTSurvey <MTSurvey@income.com.sg>
Cc: MTCL@income.com.sg
Subject: Arrange for survey SHD9594C

Dear all,

Please arrange for survey as below :

SJV6028Y – 19.08.2019 AT 1035Hrs - SHD9594C

Lunch time : 12pm - 1pm.

Kindly pls dun arrange survey during lunch time.

"We agree to let your In-house surveyor assess/ survey our vehicle with estimate."

Thks & Rds
Candy Kong

Claims Service Assistant



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111

Main Line : (65) 6287 6666 Fax Line: (65) 6257 1330

Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Candy Kong [mailto:candy.kong@transcab.com.sg]
Sent: Tuesday, 20 August, 2019 2:50 PM
To: 'MTSurvey@income.com.sg' <MTSurvey@income.com.sg>
Cc: 'mtcl@income.com.sg' <mtcl@income.com.sg>
Subject: Arrange for survey SHD9594C

Dear all,

Please arrange for survey as below :

SJV6028Y – 19.08.2019 AT 1035Hrs - SHD9594C

Lunch time : 12pm - 1pm.

Kindly pls dun arrange survey during lunch time.

"We agree to let your In-house surveyor assess/ survey our vehicle with estimate."

Thks & Rdgs

Candy Kong

Claims Service Assistant



TRANS-CAB SERVICES PTE LTD

No. 2 Ang Mo Kio Street 63, Singapore 569111

Main Line : (65) 6287 6666 Fax Line: (65) 6257 1330

Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Disclaimer

Veron Chen (LKKAUTO)

From: Ng Wai Yin <waiyin.ng@transcab.com.sg>
Sent: Tuesday, 3 September 2019 1:31 PM
To: Veron Chen (LKKAUTO)
Cc: SUR; 'Jasmine Tan'
Subject: FW: SHD 9594C-DOA: 19/8/2019 -- AAD1908-132
Attachments: MARKING.pdf

Dear Veron

Amount confirmed \$ 4,404.16 (before GST).

Thank You
Best Regards,
Ng Wai Yin
Finance Department
TEL: 6603 1265 Ext.308

***** Please be reminded that all claims correspondence to be send to claims@transcab.com.sg**



TRANS-CAB SERVICES PTE LTD
No. 2 Ang Mo Kio Street 63, Singapore 569111
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

From: Veron Chen (LKKAUTO) [<mailto:veronchen@lkkauto.com>]
Sent: Tuesday, 3 September, 2019 10:06 AM
To: Ng Wai Yin <waiyin.ng@transcab.com.sg>; calvin.er@transcab.com.sg
Cc: SUR <sur@lkkauto.com>; jasminetan@transcab.com.sg
Subject: SHD 9594C-DOA: 19/8/2019

Dear Wai Yin/Calvin,

WITHOUT PREJUDICE

Amount \$4404.16 before GST @ 3 working days.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 3 September 2019 10:06 AM
To: Ng Wai Yin; calvin.er@transcab.com.sg
Cc: SUR; jasminetan@transcab.com.sg
Subject: SHD 9594C-DOA: 19/8/2019
Attachments: MARKING.pdf

Dear Wai Yin/Calvin,

WITHOUT PREJUDICE

Amount \$4404.16 before GST @ 3 working days.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	878K

Vehicle Details

Vehicle No.:	SHD9594C
Vehicle to be Exported:	Yes
Intended Deregistration Date:	19 Aug 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	2ZR2C40446
Chassis No.:	JTDKB3FU503082434
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,605.00
Original Registration Date:	01 Aug 2019
First Registration Date:	01 Aug 2019
Transfer Count:	0
Actual ARF Paid:	\$14,247.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Jul 2027
PARF Rebate Amount:	\$10,685.00

Intended COE Rebate Details

COE Expiry Date:	31 Jul 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$23,463.00
COE Rebate Amount:	\$18,770.00
Total Rebate Amount:	\$29,455.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 19 Aug 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/08/2019 11:31
Date Of Accident	19/08/2019 10:35
Exact Location Of Accident	MAXWELL ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD9594C
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS-1.8 HYBRID CVT (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VFX/P2203857
Cover Note Number	

Driver

Name of Driver	OMAR ABDULLAH LIM @ LIM CHIN TECK
NRIC No	S1679788Z
Date Of Birth	18/06/1964
Occupation	OUTDOOR
Date Of Driving Pass	20/11/1992
Driving Experience	26 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90261691
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 240 BUKIT BATOK EAST AVENUE 5 #01-255
Postcode	650240
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 19.08.2019 at about 1035hours, I was travelling straight on the second lane along Maxwell Road. Suddenly I felt an impact. Vehicle B (SJV6028Y) which was travelling on my left swerved into my lane and hit onto my taxi's left side portion.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJV6028Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pls see attach GVA Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

26/8/19

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9594C

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

26 AUG 2019

AAD1908-132

Not Authored

Resony B4 paint

84404.16

SHD 9594C

JTDCB3FU503082434

TOYOTA

PRIUS

19.8.19

NTUC Income

1/8/2019

PART		LIST	
1	1 FRONT BUMPER	\$	509.10
2	1 BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$	101.20
3	1 REINFORCEMENT, FRONT BUMPER	\$	708.10
4	1 REINFORCEMENT, FRONT BUMPER, NO.2	\$	242.80
5	1 COVER, FRONT BUMPER HOLE, LH	\$	29.00
6	1 ABSORBER, FRONT BUMPER, LOWER	\$	130.20
7	1 ABSORBER, FRONT BUMPER ENERGY	\$	78.10
8	1 FRONT BUMPER SIDE RETAINER LH	\$	112.70
9	1 FRONT BUMPER SUPPORT	\$	81.70
10	1 COVER SUB-ASSY, ENGINE, NO.1	\$	466.00
11	1 COVER SUB-ASSY, ENGINE UNDER, NO.2	\$	238.70
12	1 EXTENSION, FRONT BUMPER, RH	\$	118.50
13	1 EXTENSION, FRONT BUMPER, LH	\$	118.50
14	1 FRONT LED LAMP (LOWER) LH	\$	907.75
15	1 FRONT HEADLAMP LH	\$	2,909.04
16	1 COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	\$	492.30
17	1 MOTOR, HEADLAMP LEVELING, LH	\$	413.10
18	1 FRONT FENDER LH	\$	963.80 ✓
19	1 EXTENSION, FRONT FENDER, LH	\$	48.80 X
20	1 COVER SUB-ASSY, FRONT PILLAR, UPR LH	\$	98.30 X
21	1 LINER, FRONT FENDER, LH	\$	200.70 ✓
22	1 FRONT FENDER EMBLEM LH	\$	86.50 ✓
23	1 SEAL, FENDER APRON MUDGUARD, LH	\$	50.90 X
24	1 PROTECTOR, FRONT FENDER SIDE PANEL, LH	\$	92.30 X
25	1 GRILLE SUB-ASSY, RADIATOR	\$	341.60 X
26	1 GRILLE, RADIATOR, LOWER NO.1	\$	167.90 X
27	1 FRONT BONNET	\$	969.00 X
28	1 HINGE ASSY, HOOD, LH	\$	58.00 X
29	1 PANEL SUB-ASSY, FRONT DOOR, LH	\$	1,264.00 ✓

Trans-cab Auto Services Pte Ltd**AAD1908-132**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9594C

30	1	WEATHERSTRIP, FRONT DOOR OPENING TRIM, LH	\$	Sn	316.90
31	1	CHECK ASSY, FRONT DOOR	\$	Sn	156.60
32	1	WEATHERSTRIP, FRONT DOOR FIX WINDOW, LH	\$	Sn	75.50
33	1	RUN, FRONT DOOR GLASS, LH	\$	Sn	151.20
34	1	WEATHERSTRIP, FRONT DOOR, LH	\$	Sn	228.10
35	1	LOCK ASSY, FRONT DOOR W/MOTOR, LH	\$	∩	592.70
36	1	HANDLE ASSY, FRONT DOOR, OUTSIDE LH	\$	Sn	383.40
37	1	FRONT DOOR OUTER MOULDING LH	\$	Sn	188.60
38	1	MOULDING, FRONT DOOR WINDOW FRAME, FRONT LH	\$	Sn	38.10
39	1	HINGE ASSY, FRONT DOOR, LOWER LH	\$	∩	94.10
40	1	HINGE ASSY, FRONT DOOR, UPPER LH	\$	∩	83.40
41	1	MOTOR ASSY, POWER WINDOW REGULATOR, LH	\$	Sn	791.50
42	1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, LH	\$	Sn	235.10
43	1	MOULDING ASSY, BODY ROCKER PANEL, LH	\$	∩	583.30
44	1	REINFORCE SUB-ASSY, ROCKER, OUTER LH	\$	∩	572.10
45	1	REINFORCEMENT SUB-ASSY, ROCKER PANEL, LH	\$	∩	336.60
46	1	LEFT SIDE VIEW MIRROR	\$	Sn	1,275.52
47	1	WIRE, FRONT DOOR, LH	\$	Sn	454.10
48	1	PANEL SUB-ASSY, REAR DOOR, LH	\$	∩	1,264.00

TOTAL \$ 19,819.41**25% \$ 4,954.85****\$ 14,864.56****Special Nett**

1	1	FRONT WHEEL RIM	\$	Nett	1,570.55 ✓
2	1	FRONT WHEEL RIM COVER	\$	Sn	175.80 X
3	1	FRONT TYRE 195/65/15	\$	Sn	350.00 X
4	1	CLIP, FRONT FENDER LINER	\$	nn	22.00 X
5	1	FRONT DOOR STICKER 'TRANS-CAB'	\$	nn	80.00 60sn
6	1	FRONT NUMBER PLATE WITH MOULDING	\$	Sn	200.00 X
7	1	BUMPER CLIP FRT	\$	na	66.00 X
8	1	WINDSCREEN SEALANT	\$	nn	253.80 X
9	1	FRONT WINDSCREEN MOULDING	\$	nn	120.00 X
10	1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00 X
11	1	REAR DOOR STICKER "6555-3333"	\$	nn	80.00 X

TOTAL \$ 3,018.15**TOTAL PARTS \$ 17,882.71**

Trans-cab Auto Services Pte Ltd**AAD1908-132**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9594C**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	6601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	4001
To Rust-Proofing Of The Affected Areas.	\$	170.00	601
To transfer of Fender fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To transfer of Front Bumper fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	201
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X
To transfer of Bonnet fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To check steering geometry and computer wheel alignment	\$	220.00	601
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To transfer of front door fittings, attachment and perform water seepage test.	\$	170.00	601
To transfer of front windscreen fittings, attachment and perform water seepage test.	\$	nn 170.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	nn 170.00	X

Trans-cab Auto Services Pte Ltd**AAD1908-132**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9594C

TOTAL	\$	14,510.00
--------------	-----------	------------------

Over All Total	\$	32,392.71
-----------------------	-----------	------------------

(PART-BY-PART) Repair Days**20 days***3 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental parts must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT				
NTUC INCOME INSURANCE CO-OPERATIVE LTD		Ref: CS/INC19014974/Kvd3n2		
73 BRAS BASAH ROAD		Date: 05-09-2019		
#05-01 NTUC TRADE UNION HOUSESINGAPORE				
189556				
ATTN: CYNDIE YONG		Code: INC		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJV 6028Y	Veh. Inspected	SHD 9594C	
Policy No.		Coverage (\$)	0.00	
Claim No.	MT/1058299-002	Excess (\$)	0.00	
Assign From	ANNIE KOH	Assign Date	23/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	JTDKB3FU503082434	Colour	M. P.WHITE / RED	
Odometer	5624 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	GOODYEAR	9 mm	
L/H Front Tyre	195/65 R15	GOODYEAR	9 mm	
R/H Rear Tyre	195/65 R15	GOODYEAR	9 mm	
L/H Rear Tyre	195/65 R15	GOODYEAR	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/08/2019	Inspect Date / Time	26/08/2019 (02:03 PM)	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9594C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	TO REPAIR SEE LABOUR	509.10	-
1	BRACKET,FRONT BUMPER EXTENSION MOUNTING	SERVICEABLE	101.20	-
1	REINFORCEMENT,FRONT BUMPER	TO REPAIR SEE LABOUR	708.10	-
1	REINFORCEMENT,FRONT BUMPER,NO.2	TO REPAIR SEE LABOUR	242.80	-
1	COVER,FRONT BUMPER HOLE,LH	SERVICEABLE	29.00	-
1	ABSORBER,FRONT BUMPER,LOWER	SERVICEABLE	130.20	-
1	ABSORBER,FRONT BUMPER ENERGY	SERVICEABLE	78.10	-
1	FRONT BUMPER SIDE RETAINER LH	SERVICEABLE	112.70	-
1	FRONT BUMPER SUPPORT	SERVICEABLE	81.70	-
1	COVER SUB-ASSY,ENGINE,NO.1	SERVICEABLE	466.00	-
1	COVER SUB-ASSY,ENGINE UNDER,NO.2	SERVICEABLE	238.70	-
1	EXTENSION,FRONT BUMPER,RH	SERVICEABLE	118.50	-
1	EXTENSION,FRONT BUMPER,LH	SERVICEABLE	118.50	-
1	FRONT LED LAMP (LOWER) LH	SERVICEABLE	907.75	-
1	FRONT HEADLAMP LH	SERVICEABLE	2,909.04	-
1	COMPUTER SUB-ASSY,HEADLAMP,LH NO.1	SERVICEABLE	492.30	-
1	MOTOR HEADLAMP LEVELING,LH	SERVICEABLE	413.10	-
1	FRONT FENDER LH	BENT	963.80	963.80
1	EXTENSION,FRONT FENDER,LH	SERVICEABLE	48.80	-
1	COVER SUB-ASSY,FRONT PILLAR,UPR LH	SERVICEABLE	98.30	-
1	LINER,FRONT FENDER,LH	DISTORTED	200.70	200.70
1	FRONT FENDER EMBLEM LH	NECESSARY	86.50	86.50
1	SEAL FENDER APRON MUDGUARD,LH	SERVICEABLE	50.90	-
1	PROTECTOR,FRONT FENDER SIDE PANEL,LH	SERVICEABLE	92.30	-
1	GRILLE SUB-ASSY,RADIATOR	SERVICEABLE	341.60	-
1	GRILLE RADIATOR,LOWER NO.1	SERVICEABLE	167.90	-
1	FRONT BONNET	TO REPAIR SEE LABOUR	969.00	-
1	HINGE ASSY,HOOD,LH	TO REPAIR SEE LABOUR	58.00	-

Report Ref No. CS/INC19014974/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	PANEL SUB-ASSY,FRONT DOOR,LH	BENT	1,264.00	1,264.00
1	WEATHERSTRIP,FRONT DOOR OPENING TRIM,LH	SERVICEABLE	316.90	-
1	CHECK ASSY,FRONT DOOR	SERVICEABLE	156.60	-
1	WEATHERSTRIP,FRONT DOOR FIX WINDOW,LH	SERVICEABLE	75.50	-
1	RUN,FRONT DOOR GLASS,LH	SERVICEABLE	151.20	-
1	WEATHERSTRIP,FRONT DOOR,LH	SERVICEABLE	228.10	-
1	LOCK ASSY,FRONT DOOR W/MOTOR,LH	TO REPAIR SEE LABOUR	592.70	-
1	HANDLE ASSY,FRONT DOOR,OUTSIDE LH	SERVICEABLE	383.40	-
1	FRONT DOOR OUTER MOULDING LH	SERVICEABLE	188.60	-
1	MOULDING,FRONT DOOR WINDOW FRAME,FRONT LH	SERVICEABLE	38.10	-
1	HINGE ASSY,FRONT DOOR,LOWER LH	TO REPAIR SEE LABOUR	94.10	-
1	HINGE ASSY,FRONT DOOR,UPPER LH	TO REPAIR SEE LABOUR	83.40	-
1	MOTOR ASSY,POWER WINDOW REGULATOR,LH	SERVICEABLE	791.50	-
1	REGULATOR SUB-ASSY,FRONT DOOR WINDOW,LH	SERVICEABLE	235.10	-
1	MOULDING ASSY,BODY ROCKER PANEL,LH	TO REPAIR SEE LABOUR	583.30	-
1	REINFORCE SUB-ASSY,ROCKER,OUTER LH	TO REPAIR SEE LABOUR	572.10	-
1	REINFORCEMENT SUB-ASSY,ROCKER PANEL,LH	TO REPAIR SEE LABOUR	336.60	-
1	LEFT SIDE VIEW MIRROR	SERVICEABLE	1,275.52	-
1	WIRE,FRONT DOOR,LH	SERVICEABLE	454.10	-
1	PANEL SUB-ASSY,REAR DOOR,LH	TO REPAIR SEE LABOUR	1,264.00	-
	LESS 25% DISCOUNT		-4,954.85	-628.75
			14,864.56	1,886.25
1	FRONT WHEEL RIM	DENTED	1,570.55	1,570.55
	LESS 25% DISCOUNT		-	-392.64
			1,570.55	1,177.91
	SPECIAL NETT ITEMS			
1	FRONT WHEEL RIM COVER (SN)	SERVICEABLE	175.80	-

Report Ref No. CS/INC19014974/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT TYRE 195/65/15 (SN)	SERVICEABLE	350.00	-
1	CLIP,FRONT FENDER LINER (SN)	NOT NECESSARY	22.00	-
1	FRONT DOOR STICKER "TRANS-CAB" (SN)	NECESSARY	80.00	60.00
1	FRONT NUMBER PLATE WITH MOULDING (SN)	SERVICEABLE	200.00	-
1	BUMPER CLIP FRT (SN)	NOT NECESSARY	66.00	-
1	WINDSCREEN SEALANT (SN)	NOT NECESSARY	253.80	-
1	FRONT WINDSCREEN MOULDING (SN)	NOT NECESSARY	120.00	-
1	FRONT WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	REAR DOOR STICKER "6555-3333" (SN)	NOT NECESSARY	80.00	-
			1,447.60	60.00
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	660.00
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF FRONT BUMPER,REINFORCEMENT,FRONT BUMPER,REINFORCEMENT,FRONT BUMPER,NO.2,FRONT BONNET,HINGE ASSY,HOOD,LH,LOCK ASSY,FRONT DOOR W/MOTOR,LH,HINGE ASSY,FRONT DOOR,LOWER LH,HINGE ASSY,FRONT DOOR,UPPER LH,MOULDING ASSY,BODY ROCKER PANEL,LH,REINFORCE SUB-ASSY,ROCKER,OUTER LH,REINFORCEMENT SUB-ASSY,ROCKER PANEL,LH AND PANEL SUB-ASSY,REAR DOOR,LH.		6,000.00	400.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	60.00
	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF FRONT BUMPER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.		170.00	20.00
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO TRANSFER OF BONNET FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-

Report Ref No. CS/INC19014974/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO TRANSFER OF FRONT DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO TRANSFER OF FRONT WINDSCREEN FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
			14,510.00	1,280.00
	GRAND TOTAL		32,392.71	4,404.16
RECOMMENDED COST OF REPAIRS (CONFIRMED)				4,404.16

Report Ref No. CS/INC19014974/Kvd3n2

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.