

ASS. REC. BY:

Surveyor: Kenneth

REF: es/INC19014982/Kqd3n2

Special Instruction:

ASSIGNMENT (Office)

From (Person): Daniel Koh

of INC

Date/Time: 26/8/19 9:38am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No: SLU 9482E

Insured: GBC 3787D

at Workshop m/s Autosoon

Tel: 6748 6558

of Blk 176 Sin Ming Drive #01-10

Policy No:

Claim No: MT/1059034-002

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 20/8/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:27am @ 26/8/19

Person Contacted: Agnes

Vehicle IN / OUT

Date/Time	Action/Instruction
	<u>Johny? ✓</u>
	<u>SLU 9482E - X</u>
	<u>GBC 3787D - X</u>
<u>2/8</u>	<u>@ 24,085.57 email & confirmed.</u>
	<u>(lead @ 11642.74, 33%)</u>

Nivitha (LKK Auto)

From: Daniel Koh <daniel.koh@income.com.sg>
Sent: Monday, 26 August 2019 1:05 PM
To: 'assignments@lkkauto.com'
Cc: admin-d@lkkauto.com
Subject: FW: TP CASES FARMED OUT TO LKK ON 26/8/2019

Dear LKK,

Resend with claim number & OIC

From: Daniel Koh
Sent: Monday, 26 August 2019 9:38 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>
Cc: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>; Teng Ken Leong <kenleong.teng@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>
Subject: FW: TP CASES FARMED OUT TO LKK ON 26/8/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OIV	DOA	Additional Remarks
----	-----	-----------	---------	---------------	------------------	------------------	-------------	-----	-----	--------------------

1	MUHAMMAD AIRWAN	MT/1058656-002	SJT7959P	AUBURN AUTO PTE LTD	176 SING MING DRIVE #04-18 SIN MING AUTOCARE SINGAPORE 575721	Edmund / 8787 5012	GBH4856E	19/8/2019	Call workshop first before going down**
2	JEFF LIN	MT/1059034-002	SLU9482E	AUTOSOON PTE LTD	BLK 176 SIN MING DRIVE #01-10 SIN MING AUTOCARE 176 SIN MING DRIVE #02-01 SIN MING AUTOCARE SINGAPORE 575721	Agnes Lee/ 6846 9428 / 6748 6558	GBC3787D	22/8/2019	
3	SERENE LIM	MT/1058714-002	GBG1889K	HOME ADDRESS	55 NEWTON ROAD # REVENUE HOUSE B4 CARPARK SINGAPORE 307987	LK Wong 9736 8619 /	SMK6038R	20/8/2019	LKW Auto Services
4	AZHARI	MT/1058762-001	QX447S	HOME ADDRESS	160 SIN MING DRIVE #02-13 SIN MING AUTOCITY	Sufyan / 6355 2240	SJS4980B	2/8/2019	SINGAPORE CUSTOMS - Revenue House B4 carpark (call Sufyan first @6355240)
5	ENG HUEY HUEY	MT/1059241-002	SLM6796L	LEONG AUTO PTE LTD		Daniel Tan/Cady Lee / 9692 4113	SLX8891Z	23/8/2019	

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Daniel Koh
Senior Admin Assistant
Motor Insurance
T +65 6430 7901
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

Find out more at income.com.sg/careers

in with you

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



31 Aug - 1 Sep 2019
DOWNTOWN EAST
10am to 8pm

GREAT PRICES. BETTER CARS. COE Renewed Cars



• \$0 Down payment • Low Monthly Installments • 1 Year Warranty • 100% Approvals

C O S M O
AUTOMOBILES

DEALS starting from as low as **\$450 /mth**

Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

BMW 525i XL Black (New COE till 31 May 2029):



2 Owners Only! Well Maintained Car! No Engine/Transmission Issues.
Direct Owner

Think One Automobile

NEW & USED COMMERCIAL VEHICLES



Post an Ad Advertiser Login Ways of Selling

Browse by Category ◀ Back (1 2) Next ▶ Sort by Date Posted 20 results/page

26 vehicles

toyota chr

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
toyota chr		Any	Any	2017	Any	Any	Any	Available
	Toyota C-HR Hybrid 1.8A S	\$83,500	\$10,010 /yr	28-Sep-2017	1,797 cc	68,600 km	SUV	Available
Fuel Type: Petrol-Electric Just Arrived! 1 Owner, Accident Free, No Repairs Needed, Full Servicing With Reputable Workshop With Receipt Records, Well-Maintained By Car Lover, Sporty Looking With Newly Installed Tires On 18" Breyton Rims And Lighted C-HR Scuff Plate. Call For Viewing Appointment...								
Posted: 26-Aug-2019 Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota								
	Toyota C-HR Hybrid 1.8A G	\$83,800	\$10,200 /yr	21-Jul-2017	1,797 cc	26,000 km	SUV	Available
Fuel Type: Petrol-Electric Best Reliable Fuel Saver! Executive Owner! Never Used For Grab! New Car Condition! High Loan/In House Loan Available!								
Posted: 25-Aug-2019 Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota								
	Toyota C-HR Hybrid 1.8A S	\$81,800	\$10,020 /yr	27-Jul-2017	1,797 cc	33,000 km	SUV	Available
Fuel Type: Petrol-Electric Excellent Condition. Very Well Maintained By Previous Owner. View To Believe. Bank Loan/Loan/In House Loan Available! Trade In Most Welcome! Call/SMS/WhatsApp Our Friendly Sales Reps Today To Arrange For Viewing And Test Drive.								
Posted: 24-Aug-2019 Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota								
	Toyota C-HR Hybrid 1.8A S	\$82,900	\$10,060 /yr	22-Aug-2017	1,797 cc	-	SUV	Available
Fuel Type: Petrol-Electric Elegant Silver SUV, Almost Brand New Condition, One Owner Only, Low Fuel Consumption With Hybrid, Low Maintenance Cost, With Warranty, Easy Financing, Flexible In- House Loan Packages Available.								
Prime Motor & Leasing Posted: 24-Aug-2019 Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota								
	Alpine with Installation + Water Proof Cam	Alpine X008EU @ \$2699 Comes with Perfect Fit Alpine Audio Panel, SKB Water Proof Camera & 1year Warranty.						
Find out more!								
	Toyota C-HR Hybrid 1.8A G	\$93,900	\$10,940 /yr	22-Dec-2017	1,797 cc	-	SUV	Available
Fuel Type: Petrol-Electric Elegant Blue SUV, "G" Edition Model With High Specifications, Low Fuel Consumption With Hybrid, Almost Brand New Condition, With Warranty, Easy Financing, Flexible In-house Loan Packages Available.								
Prime Motor & Leasing Posted: 24-Aug-2019 Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota								
	Toyota C-HR Hybrid 1.8A S	\$85,900	\$10,010 /yr	26-Dec-2017	1,797 cc	-	SUV	Available
Fuel Type: Petrol-Electric Elegant Black SUV, Almost New Condition, Low Fuel Consumption With Hybrid, One Owner Only, Low Maintenance Cost, With Warranty, Easy Financing, Flexible In-house Loan Packages Available.								
Prime Motor & Leasing Posted: 23-Aug-2019 Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota								
Compare	toyota C-HR Hybrid 1.8A G	\$82,800	\$10,180 /yr	01-Jun-2017	1,797 cc	-	SUV	Available
Fuel Type: Petrol-Electric								



Low Mileage, Like New Without Any Dent Car, Loaded With Lots Of Aftermarket Accessories. Preference Would Be For Someone Who Can Take Over (No Deposit Required), As Advertised Directly By Owner.

Posted: 13-Aug-2019 Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota



Toyota C-HR Hybrid 1.8A S **\$77,800** **\$9,820 /yr** **28-Apr-2017** **1,797 cc** **49,000 km** **SUV** **Available**

Fuel Type: Petrol-Electric

Elegant Sporty Silver SUV, C-HR Hybrid 1.8A S, Totally Like New Condition, Low Mileage, One Careful Owner, 100% Accident Free, Low Fuel Consumption With Hybrid, Low Maintenance Cost.

EXACT OWNER

Posted: 08-Aug-2019 Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota



Toyota C-HR Hybrid 1.8A G **\$84,000** **\$9,690 /yr** **27-Dec-2017** **1,797 cc** **40,000 km** **SUV** **Available**

Fuel Type: Petrol-Electric

Consignment Code: A239. Flexible And Attractive Loan Available To Choose From. Trade In Available For Your Car! No Hidden Costs. For Further Information Or If You Have Any Questions Please Do Not Hesitate To Contact Us.

CONSIGNMENT

Posted: 06-Aug-2019 Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota



Toyota C-HR Hybrid 1.8A G **\$91,800** **\$10,680 /yr** **28-Dec-2017** **1,797 cc** **49,000 km** **SUV** **Available**

Fuel Type: Petrol-Electric

1 Owner! AA Trust Certified Pre-Owned Vehicle! Highest Spec 'G' Model! CH-R Is The Most Sought After SUV With It's Hybrid System Which Allows The Lowest Fuel Consumption! Flexible Bank/In House Loan Available! Trade In Most Welcome! Hurry And Call For Appoin...

AA Trust Automotive

Posted: 05-Aug-2019 Tags: 2017 Toyota C-HR, 2017 toyota CHR, Toyota C-HR, toyota CHR, Toyota, C-HR, CHR, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view [Expired ads](#)

« Back (1 2) Next »

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & DPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used toyota chr, toyota chr Singapore, used toyota chr Singapore, used toyota chr, used vehicles Singapore or even buy used toyota chr Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

Compare

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	156G

Vehicle Details

Vehicle No.:	SLU9482E
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Aug 2019
Vehicle Make:	TOYOTA
Vehicle Model:	C-HR HYBRID 1.8S CVT
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	2ZR8244811
Chassis No.:	ZYX102086510
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,580.00
Original Registration Date:	19 Dec 2017
First Registration Date:	19 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Dec 2027
PARF Rebate Amount:	\$3,750.00

Intended COE Rebate Details

COE Expiry Date:	18 Dec 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,711.00
COE Rebate Amount:	\$44,616.00
Total Rebate Amount:	\$48,366.00

The information contained herein is correct as at 27 Aug 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/08/2019 15:58
Date Of Accident	22/08/2019 11:25
Exact Location Of Accident	ALONG AYE TOWARDS ALEXANDRA ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLU9482E
Insured/Policyholder	
Name Of Registered Owner	CHUNG CHEE MENG EDMUND
NRIC No	S1735156G
Email Address	CHUNGCME@YAHOO.COM
Mobile Phone No	(LOCAL) +65-96253117
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	TOYOTA
Model	C-HR HYBRID-1.8 S (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VA1/GA306299
Cover Note Number	

Driver

Name of Driver	CHUNG CHEE MENG EDMUND
NRIC No	S1735156G
Date Of Birth	11/09/1966
Occupation	INDOOR
Date Of Driving Pass	29/01/1999
Driving Experience	20 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96253117
Fax Number	
Contact Number	OFFICE-NOPHONE
EMail Address	CHUNGCME@YAHOO.COM

Address	BLK 114 #04-140 BEDOK RESERVOIR ROAD
Postcode	470114
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE5233L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	LIEW SIAN LOCK
NRIC/Passport Number	G2656072T
Contact Number	8381 4392
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	GBC3787D
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

LYE BOON HOOI

NRIC/Passport Number

S2569715D

Contact Number

8249 0717

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE


VEHICLE NO: 86U9422E
ACCIDENT DATE: 22/08/19 @ 11:35

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

NOTE: DO NOTE THAT YOU MAY HAVE A 14-DAYS TIMEFRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE REFER TO YOUR POLICY FOR MORE INFORMATION.


 Policyholder's Signature
 Date & Time: 22/8/19 2:57pm

Driver's Signature
 (if driver is not the policyholder)
 Date & Time:


 CHARN'S CUSTOMCRAFT
 Reporting Centre Personnel's Signature
 Name:
 NRIC/Fin No.:

SLU 9482

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 22 Aug 2019 at about 11:25am I was driving my car SLU 9482 E and started the road out from PTE (towards city) and had stopped at the junction before turning to Alexander Road. Suddenly the vehicle UBE 3187D came from behind and banged my vehicle. The force of the impact was so big that my vehicle moved forward and my vehicle banged into UBE 5233Z.

There is no injury to all the drivers and to myself at this point. My vehicle was stationary at the time the UBE 3187D banged into the back of my car. I am also sure that the driver had reversed his vehicle some distance after he had banged into my car. When I asked him, he denied he had reversed his vehicle!

OWN DAMAGE () 3RD PARTY CLAIM (/) REPORTING ONLY () OWN WORKSHOP (/)

DECLARATION

We declare the foregoing particulars are true in every respect.

Policyholder's Signature: *[Signature]*
 Date & Time: 22/8/19 2:53pm

Driver's Signature (if driver is not the policyholder):
 Date & Time:

[Signature]
 CHARN'S CUSTOMCRAFT
 Reporting Centre Personnel's Signature
 Name:
 NRIC/IN No.:

AutoSoon Pte Ltd

176 Sin Ming Drive #01-10
 Sin Ming AutoCare Singapore 575721
 Tel No. : 6452 6657 Fax No. : 6451 4618
 E-Mail : autosoon1@gmail.com
 Tax Reg. No. : 200709808N Buss. Reg. No. : 200709808N

CHUNG CHEE MENG EDMUND
 144 BEDOK RESERVOIR ROAD
 #04-140 470114
 SINGAPORE

Contact : 96253117

Not Notional
Return B4 paint
14
12 days

824085.57

Estimate : ES000376

Date : 23/08/2019
 Vehicle Num. : SLU 9482 E
 Make/Model : TOYOTA C-HR HYBRID 1.8S CVT
 Chassis/Eng# : ZYX10-2086510
 Accident Date : 22/08/2019
 Claim No. : NTUC
 Reference : TP/04/08/19
 Policy No. :

S/N Quantity Particular Unit Price Amount SS

LIST ITEMS :

1.	1P	Bonnet assy
2.	2P	Bonnet hinges
3.	1P	Bonnet insulator
4.	8P	Bonnet insulator clips
5.	5P	Bonnet instruction manual sticker
6.	1P	Bonnet lock assy
7.	1P	Bonnet lock brace panel
8.	1P	Radiator grille assy
9.	1P	Radiator grille emblem
10.	1P	Radiator grille millimeter wave radar assy
11.	1P	Radiator top panel
12.	1P	Radiator top panel garnish
13.	10P	Radiator top garnish clip
14.	1P	Radiator fan cowling
15.	2P	Radiator fan motor assy
16.	2P	Radiator fan blade
17.	1P	Radiator assy
18.	2P	Radiator side support panel
19.	1P	Air con condenser unit
20.	1P	Air con condenser discharge pipe
21.	1P	Air con condenser suction pipe
22.	1P	Air filter ducting
23.	1	Air filter housing complete
24.	1	Bumper facial assy
25.	10	Bumper facial clips
26.	1	Bumper top beam

<i>BU</i>		835.00	
<i>Reform</i>	66.00	<i>D11</i>	132.00
<i>nn</i>			334.90
<i>nn</i>	5.00	<i>nn</i>	40.00
<i>nn</i>	35.00		175.00
		<i>D17</i>	109.00
		<i>R2</i>	211.33
		<i>CM</i>	367.70
		<i>CM</i>	367.90
		<i>addition</i>	1,158.00
		<i>R1</i>	297.60
		<i>D17</i>	193.16
<i>nn</i>	5.00		50.00
		<i>CM</i>	211.90
	465.30	<i>Tm</i>	930.60
	189.90	<i>D17</i>	379.80
		<i>Pu</i>	1,323.30
<i>R1</i>	271.00		542.00
		<i>Pu</i>	1,279.36
		<i>Sn</i>	358.36
		<i>Sn</i>	449.37
		<i>Od</i>	161.43
		<i>CM</i>	788.60
		<i>R1</i>	576.30
	5.00	<i>nn</i>	50.00
		<i>R1</i>	346.51

258

CONTINUE / ...

10821-19

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

AutoSoon Pte Ltd

176 Sin Ming Drive #01-10
 Sin Ming AutoCare Singapore 575721
 Tel No. : 6452 6657 Fax No. : 6451 4618
 E-Mail : autosoon1@gmail.com
 Tax Reg. No. : 200709808N Buss. Reg. No. : 200709808N

CHUNG CHEE MENG EDMUND
 144 BEDOK RESERVOIR ROAD
 #04-140 470114
 SINGAPORE

Contact : 96253117

Estimate : ES000376

Date : 23/08/2019
 Vehicle Num. : SLU 9482 E
 Make/Model : TOYOTA C-HR HYBRID 1.8S CVT
 Chassis/Eng# : ZYX10-2086510
 Accident Date : 22/08/2019
 Claim No. : NTUC
 Reference : TP/04/08/19
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$	
27.	1	Bumper top grille	DIT	389.30	✓
28.	1	Bumper sponge	CM	77.60	✓
29.	1	Bumper reinforcement	B	383.60	✓
30.	1	Bumper lower air grille	CM	369.00	✓
31.	2P	Bumper reinforcement block panel	o/s M	386.32	✓
32.	2P	Bumper side retainer	DIT	193.16	✓
33.	2P	Head lamp assy, LED	Mg CM	116.00	✓
34.	2P	Head lamp support sub panel		1,897.60	✓
35.	2P	Head lamp side bracket	B	391.30	✓
36.	2P	Fender assy	Bu	131.00	✓
37.	2P	Fender badge		489.30	✓
38.	1P	Windshield moulding		99.12	✓
39.	1P	Tail gate assy		981.45	✓
40.	1P	Tail gate emblem		123.30	✓
41.	2P	Tail gate model badge		89.36	✓
42.	1P	Tail gate lower lid garnish		178.72	✓
43.	1P	Tail gate licence plate garnish		341.30	✓
44.	2P	Tail gate licence lamp assy		882.20	✓
45.	2P	Tail gate reflector lamp		1,697.34	✓
46.	1P	Tail gate weatherstrip		231.47	✓
47.	1P	Tail gate lock actuator assy		463.63	✓
48.	1P	Tail gate lock striker		298.46	✓
49.	1P	Tail gate lock cover		369.43	✓
50.	1P	Tail end panel assy		44.30	X
51.	2P	Tail lamp assy		53.97	✓
52.	1P	Rear bumper facial		689.60	✓
53.	10P	Rear bumper fascia clips		893.47	✓
54.	1P	Rear bumper lower pad		5.00	✓
				289.87	✓

CONTINUE / ...

13854.98

AutoSoon Pte Ltd

176 Sin Ming Drive #01-10
 Sin Ming AutoCare Singapore 575721
 Tel No. : 6452 6657 Fax No. : 6451 4618
 E-Mail : autosoon1@gmail.com
 Tax Reg. No. : 200709808N Buss. Reg. No. : 200709808N

CHUNG CHEE MENG EDMUND
 144 BEDOK RESERVOIR ROAD
 #04-140 470114
 SINGAPORE

Contact : 96253117

Estimate : ES000376

Date : 23/08/2019
 Vehicle Num. : SLU 9482 E
 Make/Model : TOYOTA C-HR HYBRID 1.8S CVT
 Chassis/Eng# : ZYX10-2086510
 Accident Date : 22/08/2019
 Claim No. : NTUC
 Reference : TP/04/08/19
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
55.	1P	Rear bumper reinforcement		249.97 ✓
56.	1P	Rear bumper side garnish		84.73 ✓
57.	1P	Rear bumper side retainer		97.36 ✓
58.	1P	Rear towing cover		49.86 X
59.	1S	Rear reverse sensor		280.00 2005n
List TotalS\$:				29,193.56
LABOUR :				
1		To tow vehicle to workshop	80.00	80.00 60l
2		To supply windshield sealant and dam rubber in repair	90.00	180.00 140l
1		To remove windshield to facilitate tail gate replacment	150.00	150.00 120l
1		To replace air con compressor include vacuum charge gas	150.00	150.00 100l
1		To remove compartment trims, boards, end panel covers to facilitate cut/hot works and weld panels	80.00	80.00 60l
1		To remove/rewire front and rear lamps, replace radiator motors, transfer rear wiper and heater wire harness to new tail gate in repair	80.00	80.00 60l
1		To undersealing damaged front and rear panel in repair	180.00	180.00 60l
1		To putty and respray front, rear section include rear top spoiler and roof in repair	1,800.00	1,800.00 1600l
1		To remove/cut damaged rear end panel, restraighten/condition rear chassis frame and panel beat affected damaged panels. To weld/refit end panel and realgn bumpers in repair	2,200.00	2,200.00 1600l
1		To computer/check diagonstic hybrid system malfunction, reset and reprogram forward recognition camera module an barake assist and lane depart in repair	450.00	450.00 750l
Labour Total S\$:				5,350.00

Total S\$: 34,543.56
 GST @ 7% S\$: 2,418.05
 Amount Due S\$: 36,961.61
 =====


 AutoSoon Pte Ltd

35777-81

AutoSoon Pte Ltd

176 Sin Ming Drive #01-10
 Sin Ming AutoCare Singapore 575721
 Tel No. : 6452 6657 Fax No. : 6451 4618
 E-Mail : autosoon1@gmail.com
 Tax Reg. No. : 200709808N Buss. Reg. No. : 200709808N

Handwritten:
 2/2/19

CHUNG CHEE MENG EDMUND
 144 BEDOK RESERVOIR ROAD
 #04-140 470114
 SINGAPORE

Tax Invoice : ES000378

Date : 30/08/2019
 Vehicle Num. : SLU 9482 E
 Make/Model : TOYOTA C-HR HYBRID 1.8S CVT
 Chassis/Eng# : ZYX10-2086510
 Accident Date : 30/08/2019
 Claim No. : NTUC
 Reference : TP/04A/08/19
 Policy No. :

Contact : 96253117

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	Radiator grille weatherstrip	<i>M</i>	73.30 ✓
2.	1	Radiator grille support garnish	<i>M</i>	171.60 ✓
3.	1	Radiator grille retainer	<i>M</i>	68.70 ✓
4.	1	Radiator top tank padding	<i>M</i>	78.30 ✓
5.	1	Radiator lower tank padding	<i>M</i>	169.30 ✓
6.	1	Radiator lower member	<i>M</i>	347.60 ✓
7.	1	Bumper lower beam	<i>M</i>	386.30 ✓
8.	1	Bumper lower beam sponge	<i>M</i>	115.30 ✓
9.	2	Tail gate hinges	84.30 <i>M</i>	168.60 ✓

List TotalS\$:

25.00% Discount S\$:

1,579.00

394.75

1,184.25

LABOUR :

1 Kindly be inform while removeing damaged section for repair, we discovered additional spare parts is require to fic good your damaged vehicle, without additional labours charges.

Labour Total S\$:

E & O.E.

Total S\$: 1,184.25
 GST @ 7% S\$: 82.90
 Amount Due S\$: 1,267.15

for AutoSoon Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT				
NTUC INCOME INSURANCE CO-OPERATIVE LTD		Ref:	CS/INC19014982/Kqd3n2	
73 BRAS BASAH ROAD		Date:	04-11-2019	
#05-01 NTUC TRADE UNION HOUSESINGAPORE				
189556				
ATTN: JEFF LIN		Code:	INC	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBC 3787D	Veh. Inspected	SLU 9482E	
Policy No.		Coverage (\$)	0.00	
Claim No.	MT1059034-002	Excess (\$)	0.00	
Assign From	DANIEL KOH	Assign Date	26/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA C-HR (A)	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	ZYX102086510	Colour	METALLIC BLUE	
Odometer	23883 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R17	BRIDGESTONE	8 mm	
L/H Front Tyre	215/60 R17	BRIDGESTONE	8 mm	
R/H Rear Tyre	215/60 R17	BRIDGESTONE	8 mm	
L/H Rear Tyre	215/60 R17	BRIDGESTONE	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	22/08/2019	Inspect Date / Time	26/08/2019 (02:48 PM)	
Survey held at	AUTOSOON PTE LTD BLK 176 SIN MING DRIVE #01-10 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 9482E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET ASSY	BUCKLED	835.00	835.00
2	BONNET HINGES @\$66.00	DISTORTED	132.00	132.00
1	BONNET INSULATOR	DEFORMED	334.90	334.90
8	BONNET INSULATOR CLIPS @\$5.00	NOT NECESSARY	40.00	-
5	BONNET INSTRUCTION MANUAL STICKER @\$35.00	NECESSARY	175.00	175.00
1	BONNET LOCK ASSY	DISTORTED	109.00	109.00
1	BONNET LOCK BRACE PANEL	BENT	211.33	211.33
1	RADIATOR GRILLE ASSY	CRACKED	367.70	367.70
1	RADIATOR GRILLE EMBLEM	CRACKED	367.90	367.90
1	RADIATOR GRILLE MILLIMETER WAVE RADAR ASSY	DENTED / SHORTED	1,158.00	1,158.00
1	RADIATOR TOP PANEL	BENT	297.60	297.60
1	RADIATOR TOP PANEL GARNISH	DISTORTED	193.16	193.16
10	RADIATOR TOP GARNISH CLIP @\$5.00	NECESSARY	50.00	50.00
1	RADIATOR FAN COWLING	CRACKED	211.90	211.90
2	RADIATOR FAN MOTOR ASSY @\$465.30	JAMMED	930.60	930.60
2	RADIATOR FAN BLADE @\$189.90	DISTORTED	379.80	379.80
1	RADIATOR ASSY	PUNCTURE	1,323.30	1,323.30
2	RADIATOR SIDE SUPPORT PANEL @\$271.00	BENT	542.00	542.00
1	AIR CON CONDENSER UNIT	PUNCTURE	1,279.36	1,279.36
1	AIR CON CONDENSER DISCHARGE PIPE	SERVICEABLE	358.36	-
1	AIR CON CONDENSER SUCTION PIPE	SERVICEABLE	449.37	-
1	AIR FILTER DUCTING	DENTED	161.43	161.43
1	AIR FILTER HOUSING COMPLETE	CRACKED	788.60	788.60
1	BUMPER FACIAL ASSY	BENT	576.30	576.30
10	BUMPER FACIAL CLIPS @\$5.00	NECESSARY	50.00	50.00
1	BUMPER TOP BEAM	BENT	346.51	346.51
1	BUMPER TOP GRILLE	DISTORTED	389.30	389.30
1	BUMPER SPONGE	CRACKED	77.60	77.60
1	BUMPER REINFORCEMENT	BENT	383.60	383.60
1	BUMPER LOWER AIR GRILLE	CRACKED	369.00	369.00

Report Ref No. CS/INC19014982/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	BUMPER REINFORCEMENT BLOCK PANEL @\$193.16	O/S BENT	386.32	193.16
2	BUMPER SIDE RETAINER @\$116.00	DISTORTED	232.00	232.00
2	HEAD LAMP ASSY,LED @\$1897.60	MTG CRACKED	3,795.20	3,795.20
2	HEAD LAMP SUPPORT SUB PANEL @\$391.30	BENT	782.60	782.60
2	HEAD LAMP SIDE BRACKET @\$131.00	DISTORTED	262.00	262.00
2	FENDER ASSY @\$489.30	BUCKLED	978.60	978.60
2	FENDER BADGE @\$99.12	NECESSARY	198.24	198.24
1	WINDSHIELD MOULDING	NECESSARY	123.30	123.30
1	TAIL GATE ASSY	BENT	1,103.35	981.45
1	TAIL GATE EMBLEM	NECESSARY	93.64	93.64
2	TAIL GATE MODEL BADGE @\$89.36	NECESSARY	178.72	178.72
1	TAIL GATE LOWER LID GARNISH	CRACKED	341.30	341.30
1	TAIL GATE LICENCE PLATE GARNISH	CRACKED	1,697.34	882.20
2	TAIL GATE LICENCE LAMP ASSY @\$231.47	N/S CRACKED / O/S SERVICEABLE	462.94	231.47
2	TAIL GATE REFLECTOR LAMP @\$463.63	N/S CRACKED / O/S SERVICEABLE	927.26	463.63
1	TAIL GATE WEATHERSTRIP	DENTED	298.46	298.46
1	TAIL GATE LOCK ACTUATOR ASSY	JAMMED	369.43	369.43
1	TAIL GATE LOCK STRIKER	TO REPAIR SEE LABOUR	44.30	-
1	TAIL GATE LOCK COVER	DENTED	53.97	53.97
1	TAIL END PANEL ASSY	BENT	689.60	689.60
2	TAIL LAMP ASSY @\$893.47	DENTED / CUT	1,786.94	749.00
1	REAR BUMPER FACIAL	BUCKLED	397.64	397.64
10	REAR BUMPER FACIAL CLIPS @\$5.00	NECESSARY	50.00	50.00
1	REAR BUMPER LOWER PAD	CRACKED	289.87	289.87
1	REAR BUMPER REINFORCEMENT	BENT	249.97	249.97
1	REAR BUMPER SIDE GARNISH	CRACKED	84.73	84.73
1	REAR BUMPER SIDE RETAINER	DISTORTED	97.36	97.36
1	REAR TOWING COVER	SERVICEABLE	49.86	-
	LESS 25% DISCOUNT		-	-6,277.11
			28,913.56	18,831.32

Report Ref No. CS/INC19014982/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RADIATOR GRILLE WEATHERSTRIP (ADDITIONAL)	NECESSARY	73.30	73.30
1	RADIATOR GRILLE SUPPORT GARNISH (ADDITIONAL)	DISTORTED	171.60	171.60
1	RADIATOR GRILLE RETAINER (ADDITIONAL)	DISTORTED	68.70	68.70
1	RADIATOR TOP TANK PADDING (ADDITIONAL)	DISTORTED	78.30	78.30
1	RADIATOR LOWER TANK PADDING (ADDITIONAL)	DISTORTED	169.30	169.30
1	RADIATOR LOWER MEMBER (ADDITIONAL)	BUCKLED	347.60	347.60
1	BUMPER LOWER BEAM (ADDITIONAL)	BENT	386.30	386.30
1	BUMPER LOWER BEAM SPONGE (ADDITIONAL)	CRACKED	115.30	115.30
2	TAIL GATE HINGES @\$84.30 (ADDITIONAL)	BENT	168.60	168.60
	LESS 25% DISCOUNT		-394.75	-394.75
			1,184.25	1,184.25
	SPECIAL NETT ITEMS			
1	REAR REVERSE SENSOR (SN)	SHORTED	280.00	200.00
			280.00	200.00
	LABOUR			
	TO TOW VEHICLE TO WORKSHOP.		80.00	60.00
	TO SUPPLY WINDSHIELD SEALANT AND DAM RUBBER IN REPAIR.		180.00	60.00
	TO REMOVE WINDSHIELD TO FACILITATE TAIL GATE REPLACEMENT.		150.00	120.00
	TO REPLACE AIR CON COMPRESSOR INCLUDE VACUUM CHARGE GAS.		150.00	100.00
	TO REMOVE COMPARTMENT TRIMS,BOARDS,END PANEL COVERS TO FACILITATE CUT/HOT WORKS AND WELD PANELS.		80.00	60.00
	TO REMOVE/REWIRE FRONT AND REAR LAMPS,REPLACE RADIATOR MOTORS,TRANSFER REAR WIPER AND HEATER WIRE HARNESS TO NEW TAIL GATE IN REPAIR.		80.00	60.00
	TO UNDERSEALING DAMAGED FRONT AND REAR PANEL IN REPAIR.		180.00	60.00
	TO PUTTY AND RESPRAY FRONT,REAR SECTION INCLUDE REAR TOP SPOILER AND ROOF IN REPAIR.		1,800.00	1,600.00

Report Ref No. CS/INC19014982/Kqd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE/CUT DAMAGED REAR END PANEL,RESTRAIGHTEN/CONDITION REAR CHASSIS FRAME AND PANEL BEAT AFFECTED DAMAGED PANELS.TO WELD/REFIT END PANEL AND REALIGN BUMPERS IN REPAIR.INCLUSIVE OF THE REPAIR OF TAIL GATE LOCK STRIKER.		2,200.00	1,600.00
	TO COMPUTER/CHECK DIAGNOSTIC HYBRID SYSTEM MALFUNCTION,RESET AND REPROGRAM FORWARD RECOGNITION CAMERA MODULE AN BARAKE ASSIST AND LANE DEPART IN REPAIR.		450.00	150.00
			5,350.00	3,870.00
GRAND TOTAL			35,727.81	24,085.57
RECOMMENDED COST OF REPAIRS (CONFIRMED)				24,085.57

Report Ref No. CS/INC19014982/Kqd3n2

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.