

来發 (明記) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0023058
Khadija Kalimuddin Mrs Khadija
Mackenzie

Page 1 of 1
Your ref. TP-SCY 6968B AXA
Job No. 70797
Our ref. 19.08.31
Payment
Date 26/8/2019

Attn

Vehicle No SGP 6876H
Vehicle Model : Subaru Forester
Accident on ... 21/8/2019

*Not Withdraw
Return by pain
2 days*

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts - Nett item:					
1.00	Pc	Rear bumper	880.00		880.00 ✓
1.00	Pc	Rear bumper exhaust cover LH	34.50		34.50 ✓
Labour & Misc:					
1.00		To transfer rear parking sensor	40.00		40.00 ✓
1.00		To dismantle and renew of parts	250.00		250.00 200
1.00		To spray paint (Pearl white)	350.00		350.00 250

*Nett
Net*

Sub-Total
GST 7.00%
Total

S\$ 1,663.32

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

1,554.50

108.82

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."