



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18019018/Utbe2

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 12-04-2019



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 2899E	Veh. Inspected	YN 3780S
Policy No.		Coverage (\$)	0.00
Claim No.	XD2899E/SA/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	19/10/2018

2. Vehicle Particulars & Condition

Make & Model	mitsubishi FM65FM1RDEA	c.c	7545
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	FM65FMA10021	Colour	WHITE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	295/80 R22.5	YOKOHAMA	6 mm
L/H Front Tyre	295/80 R22.5	YOKOHAMA	6 mm
R/H Rear Tyre	295/80 R22.5 (D)	YOKOHAMA	6/6 mm
L/H Rear Tyre	295/80 R22.5 (D)	YOKOHAMA	6/6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. THE UNDERCARRIAGE, CHASSIS FRAME AND CABIN AFFECTED DUE TO COLLISION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	17/10/2018	Inspection Date	19/10/2018
Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	20 Working Days
--	------------------------