

ASS. REC. BY:

REF: CS/INC19015067/ESF3 S2

Special Instruction:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person): Daniel Loh

of IHL

Date/Time: 27.8.19 9.39a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMJ 9095K

Insured:

PC 4792R

at Workshop m/s: Auto Insure Pte LTD

Tel:

97436363

of 6 Morsling Lane

Policy No:

Claim No: MT1 1059382-001

Sum Insured:

Excess:

Make of Veh:

D.O.A. 24.8.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

mp

H.O.D. Endorsement:

Date/Time: 27.8.19 9.47a.m

Person Contacted:

Mr Sam

Vehicle: IN/OUT

Date/Time

Action/Instruction (✓) Estimate

PC 4792R: X

SMJ 9095K: X

Steve

REF: INC

ASSIGNMENT

From

Date

27.8.2019

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMJ 9095K

at Workshop m/s: Auto Insure PRE LTD
of 6 Marsling Lane

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

mup '1

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No.

SMJ 9095K

In Regn

25/3/19

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

OPEL Astra

C.C.

1598

Colour

Black

A/C: Insured / Std / NI / NA

Sp. Reading

44282

T/Radio: Insured / Std / NI / NA

Eng/No.

C/No.

W0V 008E 67K 8031631

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

24/8/19

D.O.I.

27/8/19

11:34am

Survey held at

Auto Insure

Des. of Damages: Frt / Rear / O/S / ☒ N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time:

Action / Instruction

17/2/20

MV- 9SK

Final \$12,206.30, 8 days (Chong)

C \$20,581.28

Red - 63%

RECEIVED 17 FEB 2020

Date/Time, File Pass to?

17/2/20

1) T. 24

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.P. (\$) 12,206.30 p/a



Preli. Report



Final Report

Days Of Repair:

8

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Insp (\$)



Weekend (\$)

Survey Fee:

Transportation

S + RS. \$

Photos

Others

TOTAL

Nivitha (LKK Auto)

From: Daniel Koh <daniel.koh@income.com.sg>
Sent: Tuesday, 27 August 2019 10:05 AM
To: 'assignments@lkkauto.com'
Cc: admin-d@lkkauto.com
Subject: FW: TP CASES FARMED OUT TO LKK ON 27/8/2019

Dear LKK,

Resend with full details.

From: Daniel Koh
Sent: Tuesday, 27 August 2019 9:39 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>
Cc: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>; Teng Ken Leong <kenleong.teng@income.com.sg>; Thio Tse Kiat <tsekiat.thio@income.com.sg>
Subject: FW: TP CASES FARMED OUT TO LKK ON 27/8/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OIV	DOA	Additional Remarks
1	MUHAMMAD AIRWAN	MT/1059382-001	SMJ9095K	AUTO INSURE PTE LTD	6 MARSILING LANE	Mr Sam Goh / 9743 6363		PC4792R	24/8/2019	3157 2624 / 3157 2628

2	ENG HUEY	MT/1058999-002	SJW7925X	AUTOLUTION INDUSTRIAL PTE LTD	19 UBI ROAD 4 SINGAPORE 408623	Elmer Alfonso / 9645 0084	14:00-16:00	SIZ4235J	21/8/2019	67038691
3	SERENE LIM	MT/1056837-002	SMH5725M	BORNEO MOTORS UBI SERVICE CENTRE	BLK 17 UBI ROAD 4 SINGAPORE 408611	Raymond Seah / 9776 2689	13:00-15:00	SJE9665C	6/8/2019	
4	DAVID PHUA	MT/1059292-002	SKX1688C	MY CAR CONSULTANT PTE LTD	53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934	Kai Ling / 9868 6000		SKJ4629C	22/8/2019	
5	SERENE LIM	MT/1059373-001	SFR4607H	PROGRESSIVE CAR CARE PTE LTD	BLK 3022A #01-45/46 UBI ROAD 1 SINGAPORE 408716	Pei Wen NG / 6741 5336		SJA2264T	24/8/2019	
6	FIONA SHEN	MT/1055613-001	SKP7070L	PROGRESSIVE CAR CARE PTE LTD	BLK 3022A #01-45/46 UBI ROAD 1 SINGAPORE 408716	Pei Wen NG / 6741 5336	14:00-16:00	FN8375X	27/7/2019	

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Daniel Koh
Senior Admin Assistant
Motor Insurance
T +65 6430 7901
www.income.com.sg

income

made different



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.

Find out more at income.com.sg/careers

in with you

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

Steve Chen (LKK Auto)

From: AutoInsure (Claims) <claims01@autoinsure.com.sg>
Sent: Friday, February 14, 2020 10:49 AM
To: Steve Chen (LKK Auto)
Cc: Shirley Hiew (LKK Auto)
Subject: Re: FINALIZATION - SMJ9095K

WITHOUT PREJUDICE

Dear Mr Steve

We agree to close at \$12,206.30 (P/P before GST)and 8days repair

Thank You.

Regards

Chong
did: (65) 3157 2624 / 3157 2628
mobile: (65) 9743 6363
e: claims01@autoinsure.com.sg

Auto Insure Pte. Ltd.
201437380M
6 Marsiling Lane S739145

t: (65) 3157 2626
f: (65) 6368 0081
w: www.autoinsure.com.sg
g.e: claims@autoinsure.com.sg

-- Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail.--

Data Privacy Policy Notice: Auto Insure Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

On Mon, Dec 30, 2019 at 6:36 PM Steve Chen (LKK Auto) <SteveChen@lkkauto.com> wrote:

Dear Sam,

Kindly refer our finalize \$12,206.30 (P/P, before GST). 8 repair days.

Adrian Ling (LKKAuto)

From: Suhaimi <suhaimi@firstautoworks.com.sg>
Sent: Thursday, 26 December, 2019 8:57 AM
To: Adrian Ling (LKKAuto)
Subject: fw: re: SMJ9095K - OPEL / ASTRA ST 1.6 TURBO DIESEL (A)

Dear Adrian,
Prices as listed here

- 1 - LHF Door - \$2166
- 2 - LHR Door - \$2880
- 3- LHR Door Window Glass - \$312
- 4 - LH Rocker Panel - \$1938
- 5 - Sports Rim 16 inch - \$460
- 6 - LHR Fender - \$2600

Thanks & Regards

Suhaimi Ong
Service Executive
1st Autoworks Pte Ltd
23 Kaki Bukit Ave 4,
#04-01 (South Wing)
S'pore 415933
Tel : 6844 1985
Fax : 6844 5185

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/08/2019 13:26
Date Of Accident	24/08/2019 05:50
Exact Location Of Accident	JUNCTION OF ALEXANDRA RD & JLN BUKIT MERAH AFTER E
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMJ9095K
Insured/Policyholder	
Name Of Registered Owner	BIS MOTORING PTE LTD
Co Reg No	201735055D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-31572626

Vehicle Particulars

Manufacturer	OPEL
Model	ASTRA ST 1.6 TURBO DIESEL (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999994322
Cover Note Number	

Driver

Name of Driver	TEO KIM PENG
NRIC No	S1723382C
Date Of Birth	16/09/1965
Occupation	OUTDOOR
Date Of Driving Pass	19/10/1999
Driving Experience	19 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97381193
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 412 SAUJANA ROAD #02-64
Postcode	670412
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : NA GENDER: : FEMALE
Passenger 2	NAME: : NA GENDER: : FEMALE
Passenger 3	NAME: : NA GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 24/8/2019 AROUND 0550HRS . I WAS TRAVELLING THE JUNCTION OF ALEXANDRA ROAD . THERE WAS A GREEN LIGHT IN MY FAVOUR I THEN A PROCEED TO TURN , SUDDENLY VEHICLE B BEAT THE RED LIGHT AND HIT ONTO MY VEHICLE . THIS INCIDENT WAS CAPTURED BY MY IN-CAR CAMERA .

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE IS TOO LARGE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PC4792R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE

Name of Driver

MOHAMED JAPRI BIN JOHARI

NRIC/Passport Number

S1525841A

Contact Number

96990279

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:




Driver's Signature
(if driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 24/12/2024 around 08:00pm. I was travelling the junction of Alexandra Rd. There was a green light in my favour I then proceed to turn suddenly vehicle B beat the red light and hit onto my vehicle. The incident was captured by my in-car camera.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

DRMNC-SKETCHPLAN-FORM-03

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	055D

Vehicle Details

Vehicle No.:	SMJ9095K
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Aug 2019
Vehicle Make:	OPEL
Vehicle Model:	ASTRA ST 1.6 TURBO DIESEL (A)
Primary Colour:	Black
Manufacturing Year:	2019
Engine No.:	A2183049JR5X0213
Chassis No.:	W0VBD8EG7K8031631
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$21,882.00
Original Registration Date:	25 Mar 2019
First Registration Date:	25 Mar 2019
Transfer Count:	0
Actual ARF Paid:	\$22,635.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Mar 2029
PARF Rebate Amount:	\$16,976.00
Intended COE Rebate Details	
COE Expiry Date:	24 Mar 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$34,509.00
COE Rebate Amount:	\$33,016.00
Total Rebate Amount:	\$49,992.00

The information contained herein is correct as at 27 Aug 2019

OK

Our Ref: SMJ9095K

Your Ref: PC4792R

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
PARTS REPLACEMENT - LIST ITEMS				
1	1	FRONT DOOR ASSY LH / DD		\$ 2,259.00
2	1	FRONT DOOR CHECKER LH X		\$ -443.00
3	1	FRONT DOOR FRAME CHROME MOULDING LH X		\$ 339.00
4	1	FRONT DOOR GRASS OUTER MOULDING LH X		\$ 239.00
5	1	FRONT DOOR INNER TRIM BOARD LH X		\$ 839.00
6	1	FRONT DOOR LOCK ASSY LH X		\$ 580.00
7	1	FRONT DOOR WEATHER STRIP LH X		\$ 319.00
8	1	FRONT DOOR POWER WINDOW MOTOR LH X		\$ 689.00
9	1	FRONT DOOR POWER WINDOW REGULATOR LH X		\$ 595.00
10	1	FRONT DOOR HINGE UPPER LH X		\$ 219.00
11	1	FRONT DOOR HINGE LOWER LH X		\$ 219.00
12	1	FRONT DOOR HANDER LH X		\$ 446.00
13	1	REAR DOOR ASSY LH / DD ?		\$ 2,105.00
14	1	REAR DOOR CHECKER LH X		\$ 443.00
15	1	REAR DOOR GRASS OUTER MOULDING / DD		\$ 315.00
16	1	REAR DOOR FRAME CHROME MOULDING LH / DD		\$ 329.00
17	1	REAR DOOR INNER TRIM BOARD LH / CR4		\$ 750.00
18	1	REAR DOOR LOCK ASSY LH / DT		\$ 580.00
19	1	REAR DOOR GRASS LH / BR		\$ 1,055.00
20	1	REAR DOOR TRIANGLE GRASS X		\$ 830.00
21	1	REAR DOOR TRIANGLE GRASS MOULDING X		\$ 239.00
22	1	REAR DOOR WEATHER STRIP LH ? X		\$ 319.00
23	1	REAR DOOR POWER WINDOW MOTOR LH X		\$ 689.00
24	1	REAR DOOR POWER WINDOW REGULATOR LH ? X		\$ 595.00
25	1	REAR DOOR HINGE UPPER LH / DT		\$ 219.00
26	1	REAR DOOR HINGE LOWER LH / DT		\$ 219.00
27	1	SIDE MIRROR HOUSING ASSY LH X		\$ 890.00
28	1	MIRROR INDICATOR LENS LH X		\$ 310.00
29	1	MIRROR COVER LH X		\$ 250.00
30	1	REAR HANDER LH X R ? / DD		\$ 446.00
31	1	ROCKER PANEL LH ?		\$ 1,580.00
32	1	B PILLER LH ? X		\$ 1,390.00
33	1	B PILLER INNER GARNISH LH X		\$ 890.00
34	1	REAR BUMPER ASSY X R		\$ -2,055.00
34	1	REAR QUARTER PANEL LH / DD		\$ 1,950.00
35	1	REAR QUARTER PANEL INNER TRIM LH X		\$ 690.00
36	1	REAR QUARTER GRASS MOULDING LH X		\$ 210.00
37	1	REAR WHEEL AXLE X		\$ 1,055.00
37	1	REAR WHEEL HUB BEARING LH ? X		\$ 580.00
38	1	REAR SHOCK ABSORBER LH X		\$ 690.00
39	1	REAR SPORT RIMS LH / DT		\$ 1,455.00
SUB TOTAL			\$	30,314.00
LESS 10%			\$	3,031.40
TOTAL AMOUNT			\$	27,282.60

16,143.00

1614.30

14,528.70

Steve 10/10/19 Resumay



Auto Insure Pte. Ltd.
6 Marsiling Lane
Singapore (739145)
E: claims01@autoinsure.com.sg
W: www.autoinsure.com.sg
T: 3157 2626 F: 6368 0081
GST No.: 201437380M

Page No.1

AUTOMOBILE ASSESSMENT REPORT

Our Ref: **SMJ9095K**
Your Ref: **PC4792R**

Date:

BY EMAIL ONLY
(claims01@autoinsure.com.sg)

ATTENTION: MOTOR CLAIMS DEPT

DirectAsia Insurance

20 Anson Rd, #08-01, Singapore 079912

Assessed Vehicle No : **SMJ9095K**
Car Make and Model : **OPEL ASTRA ST 1.6 TURBO DIESEL (A)**
Date of Accident : **21-Aug-19**
Date of Assessment : **22-Aug-19**

We have carried out a physical assessment of SMJ9095K at our workshop Auto Insure Pte Ltd sustained damages to the LH SIDE portion of the vehicle.


4. DESCRIPTION OF DAMAGE

At the time of the inspection observed that this vehicle had sustained damages to the LH SIDE portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

Estimated Amount : P/P
Adjusted Amount : **\$ 32,787.58**
Est. Repair Days : 12



***In considering that our client's vehicle is fairly new
we will not agree to any repair of parts and only replacement will be done***

Pursuant to your instruction, we have **NOT AUTHORIZED** repair.
The assessment was conducted on a **"WITHOUT PREJUDICE"** basis.

If we are not notified of anything within 14 Days from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss of occurrence in which the assessed vehicle is involved.

No liability or responsibility whatsoever shall be held by

AUTO INSURE PTE. LTD. For any reliance on this report by any third party.

Our Ref: SMJ9095K

Your Ref: PC4792R

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
PARTS REPLACEMENT - LIST ITEMS				
1	1	FRONT DOOR ASSY LH / DD		\$ 2,259.00
2	1	FRONT DOOR CHECKER LH X NN		\$ 443.00
3	1	FRONT DOOR FRAME CHROME MOULDING LH X NN		\$ 339.00
4	1	FRONT DOOR GLASS OUTER MOULDING LH X NN		\$ 239.00
5	1	FRONT DOOR INNER TRIM BOARD LH X NN		\$ 839.00
6	1	FRONT DOOR LOCK ASSY LH X NN		\$ 580.00
7	1	FRONT DOOR WEATHER STRIP LH X NN		\$ 319.00
8	1	FRONT DOOR POWER WINDOW MOTOR LH X NN		\$ 689.00
9	1	FRONT DOOR POWER WINDOW REGULATOR LH X NN		\$ 595.00
10	1	FRONT DOOR HINGE UPPER LH X NN		\$ 219.00
11	1	FRONT DOOR HINGE LOWER LH X NN		\$ 219.00
12	1	FRONT DOOR HANDER LH X NN		\$ 446.00
13	1	REAR DOOR ASSY LH / DD		\$ 2,105.00
14	1	REAR DOOR CHECKER LH ? X NN		\$ 443.00
15	1	REAR DOOR GLASS OUTER MOULDING / DD		\$ 315.00
16	1	REAR DOOR FRAME CHROME MOULDING LH / DD		\$ 329.00
17	1	REAR DOOR INNER TRIM BOARD LH / CRV		\$ 750.00
18	1	REAR DOOR LOCK ASSY LH / DT		\$ 580.00
19	1	REAR DOOR GLASS LH / BR		\$ 1,055.00
20	1	REAR DOOR TRIANGLE GLASS X NN		\$ 830.00
21	1	REAR DOOR TRIANGLE GLASS MOULDING X NN		\$ 239.00
22	1	REAR DOOR WEATHER STRIP LH ? X NN		\$ 319.00
23	1	REAR DOOR POWER WINDOW MOTOR LH X NN		\$ 689.00
24	1	REAR DOOR POWER WINDOW REGULATOR LH ? X NN		\$ 595.00
25	1	REAR DOOR HINGE UPPER LH / DT		\$ 219.00
26	1	REAR DOOR HINGE LOWER LH / DT		\$ 219.00
27	1	SIDE MIRROR HOUSING ASSY LH X NN		\$ 890.00
28	1	MIRROR INDICATOR LENS LH X NN		\$ 310.00
29	1	MIRROR COVER LH X NN		\$ 250.00
30	1	REAR HANDER LH X R ? / DD		\$ 446.00
31	1	ROCKER PANEL LH ? X NN		\$ 1,580.00
32	1	B PILLAR LH ? X NN		\$ 1,390.00
33	1	B PILLAR INNER GARNISH LH X NN		\$ 890.00
34	1	REAR BUMPER ASSY X R		\$ 2,055.00
34	1	REAR QUARTER PANEL LH / DD		\$ 1,950.00
35	1	REAR QUARTER PANEL INNER TRIM LH X NN		\$ 690.00
36	1	REAR QUARTER GLASS MOULDING LH X NN		\$ 210.00
37	1	REAR WHEEL AXLE X NN		\$ 1,055.00
37	1	REAR WHEEL HUB BEARING LH ? X NN		\$ 580.00
38	1	REAR SHOCK ABSORBER LH X NN		\$ 690.00
39	1	REAR SPORT RIMS LH / CRV		\$ 1,455.00
SUB TOTAL			\$	30,314.00
LESS 10%			\$	3,031.40
TOTAL AMOUNT			\$	27,282.60

2166/

/

/

/

402/

312/

/

/

/

/

460/

10,807

-10%

9726.30

Our Ref: **SMJ9095K**

Your Ref: **PC4792R**

S/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. BY WORKSHOP
1	1SET	FRONT DOOR INNER TRIM BOARD CLIP		\$ 60.00
2	1SET	REAR DOOR INNER TRIM BOARD CLIP		\$ 70.00
3	1	REAR TYRE LH X <i>MM</i>		\$ 95.00
4	1	QUARTER GLASS SEALANT X <i>MM</i>		\$ 40.00
SUB TOTAL				\$ 130.00
TOTAL PARTS COST				\$ 27,412.60

265

Our Ref: **SMJ9095K**

Your Ref: **PC4792R**

S/NO	DESCRIPTION	EST. BY WORKSHOP
LABOUR & PAINTWORK		
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	\$ 1,500.00
2	TO TRANSFER FRONT & REAR DOOR FITTING AND WINDOW MECHANISM TO NEW DOOR	\$ 300.00
3	WHEEL ALIGNMENT	\$ 120.00
3	TO REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 250.00
3	TO REMOVE / REFIX WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS	\$ 150.00
	TO REMOVE & REINSTALL QUARTER GLASS	\$ 60.00
4	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUTTY ON PARTS REPLACED	\$ 1,200.00
5	SUNDRIES (SAND PAPER, WELDING WIRE ETC.)	\$ <i>new</i> 80.00
TOTAL BEFORE GST		\$ 30,642.60
GST 7%		\$ 2,144.98
TOTAL (PARTS & LABOUR):		\$ 32,787.58

Adjustments / Recommendations

Our estimator have thoroughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

Our Workshop has agreed to undertake the job at a **sum of \$32,700.00** for part by part with the third party insurance.

Yours Faithfully,

Jason Heng
Claims Director

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Steve (LKK)
83225513

WLC *27/5/19, 12.15pm*

5 days

P/P

R- Af spy

P/P

P- 9726-30

N- 60

L- 2420

12,206-30

31207.60

2420

30 3660

30

100

60

100

1100



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19015067/Esf3s2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE

189556

Date: 19-02-2020



ATTN: MUHAMMAD AIRWAN

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PC 4792R	Veh. Inspected	SMJ 9095K
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1059382-001	Excess (\$)	0.00
Assign From	DANIEL KOH	Assign Date	27/08/2019

2. Vehicle Particulars & Condition

Make & Model	OPEL ASTRA	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	W0VBD8EG7K8031631	Colour	BLACK
Odometer	44282 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	CONTINENTAL	6 mm
L/H Front Tyre	205/55 R16	CONTINENTAL	6 mm
R/H Rear Tyre	205/55 R16	CONTINENTAL	6 mm
L/H Rear Tyre	205/55 R16	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	24/08/2019	Inspect Date / Time	27/08/2019 (11:34 AM)
Survey held at	AUTO INSURE PTE LTD 6 MARSILING LANE S739145		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMJ 9095K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT DOOR ASSY LH	DENTED	2,259.00	2,166.00
1	FRONT DOOR CHECKER LH	NOT NECESSARY	443.00	-
1	FRONT DOOR FRAME CHROME MOULDING LH	NOT NECESSARY	339.00	-
1	FRONT DOOR GLASS OUTER MOULDING LH	NOT NECESSARY	239.00	-
1	FRONT DOOR INNER TRIM BOARD LH	NOT NECESSARY	839.00	-
1	FRONT DOOR LOCK ASSY LH	NOT NECESSARY	580.00	-
1	FRONT DOOR WEATHER STRIP LH	NOT NECESSARY	319.00	-
1	FRONT DOOR POWER WINDOW MOTOR LH	NOT NECESSARY	689.00	-
1	FRONT DOOR POWER WINDOW REGULATOR LH	NOT NECESSARY	595.00	-
1	FRONT DOOR HINGE UPPER LH	NOT NECESSARY	219.00	-
1	FRONT DOOR HINGE LOWER LH	NOT NECESSARY	219.00	-
1	FRONT DOOR HANDER LH	NOT NECESSARY	446.00	-
1	REAR DOOR ASSY LH	DENTED	2,105.00	2,105.00
1	REAR DOOR CHECKER LH	NOT NECESSARY	443.00	-
1	REAR DOOR GLASS OUTER MOULDING	DENTED	315.00	315.00
1	REAR DOOR FRAME CHROME MOULDING LH	DENTED	329.00	329.00
1	REAR DOOR INNER TRIM BOARD LH	CRUSHED	750.00	750.00
1	REAR DOOR LOCK ASSY LH	BENT	580.00	402.00
1	REAR DOOR GLASS LH	BROKEN	1,055.00	312.00
1	REAR DOOR TRIANGLE GLASS	NOT NECESSARY	830.00	-
1	REAR DOOR TRIANGLER GLASS MOULDING	NOT NECESSARY	239.00	-
1	REAR DOOR WEATHER STRIP LH	NOT NECESSARY	319.00	-
1	REAR DOOR POWER WINDOW MOTOR LH	NOT NECESSARY	689.00	-
1	REAR DOOR POWER WINDOW REGULATOR LH	NOT NECESSARY	595.00	-
1	REAR DOOR HINGE UPPER LH	BENT	219.00	219.00
1	REAR DOOR HINGE LOWER LH	BENT	219.00	219.00
1	SIDE MIRROR HOUSING ASSY LH	NOT NECESSARY	890.00	-
1	MIRROR INDICATOR LENS LH	NOT NECESSARY	310.00	-
1	MIRROR COVER LH	NOT NECESSARY	250.00	-
1	REAR HANDER LH	TO REPAIR SEE LABOUR	446.00	-

Report Ref No. CS/INC19015067/Esf3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ROCKER PANEL LH	DENTED	1,580.00	1,580.00
1	B PILLAR LH	NOT NECESSARY	1,390.00	-
1	B PILLAR INNER GARNISH LH	NOT NECESSARY	890.00	-
1	REAR BUMPER ASSY	TO REPAIR SEE LABOUR	2,055.00	-
1	REAR QUARTER PANEL LH	DENTED	1,950.00	1,950.00
1	REAR QUARTER PANEL INNER TRIM LH	NOT NECESSARY	690.00	-
1	REAR QUARTER GLASS MOULDING LH	NOT NECESSARY	210.00	-
1	REAR WHEEL AXLE	NOT NECESSARY	1,055.00	-
1	REAR WHEEL HUB BEARING LH	NOT NECESSARY	580.00	-
1	REAR SHOCK ABSORBER LH	NOT NECESSARY	690.00	-
1	REAR SPORT RIMS LH	CUT	1,455.00	460.00
	LESS 10% DISCOUNT		-3,031.40	-1,080.70
			27,282.60	9,726.30
	SPECIAL NETT ITEMS			
1	SET FRONT DOOR INNER TRIM BOARD CLIP (SN)	NECESSARY	60.00	30.00
1	SET REAR DOOR INNER TRIM BOARD CLIP (SN)	NECESSARY	70.00	30.00
1	REAR TYRE LH (SN)	NOT NECESSARY	95.00	-
1	QUARTER GLASS SEALANT (SN)	NOT NECESSARY	40.00	-
1	SUNDRIES (SAND PAPER, WELDING WIRE ETC.) (SN)	NECESSARY	80.00	30.00
			345.00	90.00
	LABOUR			
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS. INCLUSIVE OF THE REPAIR OF REAR HANDER LH AND REAR BUMPER ASSY.		1,500.00	1,100.00
	TO TRANSFER FRONT & REAR DOOR FITTING AND WINDOW MECHANISM TO NEW DOOR.		300.00	100.00
	WHEEL ALIGNMENT.		120.00	60.00
	TO REMOVE AND REFIX REAR UNDERCARRIAGE.		250.00	100.00
	TO REMOVE / REFIX WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS.		150.00	30.00
	TO REMOVE & REINSTALL QUARTER GLASS.	NOT NECESSARY	60.00	-

Report Ref No. CS/INC19015067/Esf3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUTTY O PARTS REPLACED.		1,200.00	1,000.00
			3,580.00	2,390.00
GRAND TOTAL			31,207.60	12,206.30
RECOMMENDED COST OF REPAIRS (CONFIRMED)				12,206.30

Report Ref No. CS/INC19015067/Esf3s2

CHEN TSUE YEE
Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.