

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

GBD 6483E
 TP/AXA

M/S : AXA INSURANCE (S) PTE LTD
 8 SHENTON WAY
 #27-02 AXA TOWER
 SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

Estimate No: ES1992057/YISHUN

Date: 21 Sep 2019

Policy No: Z/18/VC00/102421

Veh Reg No: GBD6483E

Make/Model: NISSAN CABSTAR 3.0
 5M/T ABS 2DR 2WD
 EURO 5

WS Ref: TP/AXA

Claim Type: Third Party

Accident Date: 22/08/2019

TP Veh Reg No: SGN8754Z

Chassis No: JN1SC2F24Z0856901

Engine No: ZD30345041K

Reg. Date: 11/02/2015

Estimate Repair Cost to Vehicle No :GBD6483E

PAGE:1/1

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Net Price				
1 FRONT BUMPER	1,155.10	1 PC	1,155.10	✓
2 FRONT BUMPER RH BRACKET	283.10	1 PC	283.10	?
3 FRONT BUMPER CLIPS	3.50	6 PCS	21.00	✓
4 FRONT GRILLE	461.90	1 PC	461.90	?
5 FRONT GRILLE CLIPS	5.00	6 PCS	30.00	?
6 RH HEADLAMP	473.40	1 PC	473.40	?
7 RH HEADLAMP LOWER GARNISH	81.30	1 PC	81.30	✓
8 FRONT RH CORNAL PANEL	398.00	1 PC	398.00	?
9 FRONT RH DOOR	1,474.80	1 PC	1,474.80	✓
10 FRONT RH DOOR LAMP	109.80	1 PC	109.80	✓
11 FRONT RH DOOR BOTTOM HINGE	99.80	1 PC	99.80	?
12 FRONT PANEL EMBLEM "CABSTAR"	74.30	1 PC	74.30	✓
13 FRONT RH SIDE MIRROR	171.80	1 PC	171.80	?
			4,834.30	
	Less 10%		483.43	4,350.87
Special Net				
14 FRONT RH DOOR COY STICKER	20.00	1 PC	20.00	✓
			20.00	20.00
Labour				
15 REMOVE & REFIX FRT BUMPER ASSY,GRILLE,HEADLAMPS,FRT RH CORNAL PANEL,FRT RH DOOR & ATTACHMENT,TO STRAIGHTEN,KNOCK & REPAIR FRT RH W/SCREEN PILLAR & REALIGN THE SAME	700.00	1 LA	700.00	Good
16 REMOVE & REFIX FRT RH DOOR GLASS,CHECK CENTRAL LOCKING & POWER MIRROR	60.00	1 LA	60.00	✓
17 PUTTY & RESPRAY PAINT ON FRT BUMPER BRACKET,FRT RH DOOR,FRT RH W/SCREEN PILLAR,FRT RH CORNAL PANEL,FRT PANEL & ALL AFFECTED AREAS	700.00	1 LA	700.00	Good
18 RUSTPROOFING	30.00	1 LA	30.00	✓
19 TO REWRITE ADVERTISEMENT	180.00	1 LA	180.00	?
			1,670.00	1,670.00
			Total	SS 6,040.87
			Add GST @ 7%	422.86
			Total Amount Payable	SS 6,463.73

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE