

BEST Solution Autocare Pte Ltd

53 Ubi Avenue 1, #03-01, Paya Ubi Industrial Park, Singapore 408934

Business Reg. No.: 201626438D

☎ 6744 0777

☎ 6744 2377

Estimate Quotation

Quotation No	AUG 004/2019
Date	26/08/19
Vehicle No	SMC6582C
Make / Model	Hyundai Elantra

TPA IG.
Vic

To:

Address:

KMH D841CmJ4704609

Qty	DESCRIPTION	UNIT	Amount
	Items		
1 pc	front bumper <i>Rehd</i>		\$ 585.00 ✓
1 pc	front bumper reinforcement <i>Rehd</i>		\$ 695.00 +
1 pc	front bumper lower lip <i>Rehd</i>		\$ 302.00 +
1 pc	front grille <i>Rehd</i>		\$ 1,082.00 x.
1 pc	o/s front bumper side retainer <i>Rehd</i>		\$ 68.00 ✓
1 pc	o/s fog lamp <i>Rehd</i>		\$ 295.00 + ?
1 pc	o/s fog lamp garnish <i>Rehd</i>		\$ 65.00 + ?
1 pc	o/s fog lamp chrome cover <i>Rehd</i>		\$ 155.00 +
1 pc	o/s head lamp <i>Rehd</i>		\$ 1,886.00 ✓
1 pc	o/s head lamp lower bracket <i>Rehd</i>		\$ 95.00 +
1 pc	o/s front fender <i>Rehd</i>		\$ 985.00 520.50 ✓
1 pc	o/s front fender inner shield <i>Rehd</i>		\$ 115.00 ✓
1 set	o/s front fender inner shield clip <i>Rehd</i>		\$ 40.00 30 ✓
1 pc	o/s front sport rim <i>Rehd</i>		\$ 680.00 480(SN) ✓
1 pc	o/s front tyre <i>Rehd</i>		\$ 250.00 180(SN) ✓
1 pc	o/s front shock absorber <i>Rehd</i>		\$ 395.00 +
1 pc	o/s front lower arm <i>Rehd</i>		\$ 356.00 +
1 pc	o/s front knuckle arm <i>Rehd</i>		\$ 435.00 +
1 pc	o/s front knuckle arm bearing <i>Rehd</i>		\$ 482.00 +
1 set	front bumper clip <i>Rehd</i>		\$ 30.00 ✓
1 set	front grille clip <i>Rehd</i>		\$ 30.00 +
	Labour Charge		
1	to dismantle damaged parts, panel beat, repair		\$ 800.00 500 ✓
2	to putty and spray painting on affected area		\$ 700.00 500 ✓
3	air con		\$ 80.00 +
4	wiring		\$ 50.00 30 ✓
5	anti rust		\$ 150.00 +
6	undercarriage		\$ 250.00 +
7	wheel alignment		\$ 150.00 80 ✓
8	towing		\$ 60.00 +
	Subtotal:		\$ 11,266.00

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

BEST SOLUTION AUTOCARE PTE LTD

total: 4645.60

h/s: 37K

Authorised Signature

Adrian Lim
4/5 27/08/19
OS Day