

SURVEYOR: Marcus

ASSIGNMENT (Office)

merimen

From (Person): Ruth Chua Gek Tiang of SMO Date/Time: 27/08/2019

Estimated Cost: _____ Bill to: _____

OD / TP / AWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLD 9833R Insured: SKX 6113L

at Workshop m/s S M Spray Painting Pte Ltd Tel: 6384 1755 / 6384 1766

of 25 Kaki Bukit Road 4 #05-30

Policy No: D19MTPV01008758 Claim No: CMTD1904070

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 25/08/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS ^{"wp"} H.O.D. Endorsement: _____

Date/Time: 27/08/2019 05:15pm Person Contacted: Wendy Vehicle IN/OUT: OUT

| Date/Time | Action/Instruction (✓) Estimate |
|-----------|---|
| | SKX 6113L : X |
| | SLD 9833R : X |
| 03/09/19 | @ 14:52 pm revised IA to Ruth Chua via merimen. |

NAME: Marcus

REF: SMD

ASSIGNMENT

From:
 Date: 2.9.2019
 Estimated Cost:
 OD (TP) / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SLD 9833R
 at Workshop n/s S M Spray Painting
 of 25 Teluk Bukit Road 4 #08-30
 Insured
 Policy No.
 Claims No.
 Sum Insured:
 Excess:
 (Client's Record)
 Make of Veh: 2.30 p.m

Veh No: SLD 9833R Yr Reg: 7, 16
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA /
 Make: Mercedes Benz GLA 180 C.C 1595
 Colour: white A/C: Insured / Std / NI / NA
 Sp. Reading: 49370 T/Radio: Insured / Std / NI / NA
 Eng/No:
 C/No: WDC 1569 422J2 68340
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / SRim / STD A/Rim or

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

| | |
|-------------------------------------|--------------------------|
| <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| N/S | O/S |
| <input type="checkbox"/> | <input type="checkbox"/> |

Bal. or Market Value: \$ 93k
 I/C Accident Rpt: Consistent? : Yes or No
 G/A / PR Seen: Consistent? : Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date:
 Person Contacted:
 Vehicle: IN / OUT

Tyre Size: F:
 R: 235/50 R18
 BS / DUN / EXNOVA / GY / FS / LIZA / MIF / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front
 R/Bal: 7 mm
 L/Bal: 7 mm
 D.O.A: 25/8/19
 Survey held at
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
 N/S Frt
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
 7/9/19 LTA S2204 sticker
 d/s \$2100 confirmed with newly.
 (\$18,804.60 Red - 90%)

RECEIVED 10 SEP 2019

Date/Time, File Pass to?
 09/09/19
 1) : Preli. Report
 : Final Report
 Date/Time, File Return to?

Days Of Repair: 3
 Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$
 : Interview (\$
 : Tech. Invs (\$
 : Weekend (\$

| | |
|----------------|-----|
| Survey Fee: | 450 |
| Transportation | 11 |
| Photos | |
| Others | |
| TOTAL | 461 |

Report Format :
 Lump Sum / I.B.I: (\$ 2,100 / L/S)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ruth Chua Gek Tiang

Date: 03 Sep 2019

Preliminary Advice

Insured Vehicle No : SKX6113L
TP Vehicle No : SLD9833R Accident Date : 25/08/2019
Make : MERCEDES-BENZ GLA180 URBAN (R18 Assignment Date : 27/08/2019
LED)
Date of Inspection : 02/09/2019 Est. Duration of Repair : 3 days
Inspection At : S M Spray Painting Pte Ltd (HQ)
25, Kaki Bukit Road 4, #08-30 Synergy@KB
Singapore 417800

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 20,904.60 |
| Revised Amount | :S\$ | 2,664.00 |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 2,664.00 |

Lump Sum Repair :S\$

Total Loss Consideration

| | |
|--------------------|------|
| New for Old Value | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate | :S\$ |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ |

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP

...CLAIM SUBFOLDER...(New Assignment)

| CLAIM SUBFOLDER TRACKING | | | | | | | |
|--------------------------|-------------|---------------|--|---------|---------------|-------------|--|
| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'ed | Status |
| Main | 26 Aug 2019 | | 27 Aug 2019 16:58 Assign | | | | New Assignment Cancel Case |

| | | | | |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|
| Main | Reference | Claim Details | Documents | Show All |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|

| CLAIM SUBFOLDER DETAILS | | | | [Created by insurer] |
|-----------------------------|--|------------------------|---------------------------------|----------------------|
| Insured: | PANG JIAN SONG WILSON, ID: S8511069A, Tel: +6597718227, Email: insoundproductions@gmail.com | | | |
| Main Claimant: | LESTER PHOA, ID: S8308930Z | | | |
| Vehicle Reg. No.: | SLD9833R | Date of Loss: | 25/08/2019 20:00 - :59 | |
| Claim Type: | TP / CMTD1904070 | Policy/Cover Note No.: | D19MTPV01008758 (Comprehensive) | |
| Vehicle Reg. No. (Insured): | SKX6113L | Policy No. (Claimant): | | |
| | | Excess: | | |
| Repairer: | S M Spray Painting Pte Ltd (HQ) 25, Kaki Bukit Road 4, #08-30 Synergy@KB, 417800 Kaki Bukit - Tel: 6384 1755/6384 1766 | | | |
| Handling Insurer: | Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Ruth Chua Gek Tiang - 6329 5153] | | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 05/09/2019] | | | |
| Driver/Custodian (Insured): | PANG JIAN SONG WILSON (34 / Male), NRIC: S8511069A, Tel: +6597718227 Email: insoundproductions@gmail.com | | | |
| Adj Asg. Remarks: | WS: WENDY 6384 1755/1766 - PLS ARR SUV MON, 02/09/19 AFTERNOON | | | |

| ASSOCIATED MAIL RECEIVED | View All | Compose Case Mail |
|----------------------------------|--------------------------|-----------------------------------|
| There are no mail for this case. | | |

| ALL ASSOCIATED TASKS | | | | | | | | | | View All | Search Tasks | Create New Task | Complete |
|----------------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|--------------------------|------------------------------|---------------------------------|--------------------------|
| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? | | | | |
| No results. | | | | | | | | | | | | | |

Exclusive Roadshow Deal - up to \$10,000 off all Toyota Models.
 Bedok Mall, Level 1 Atrium, 28 Aug – 3 Sep 2019



Post an Advertisement
 Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

New 5 Years Renewal Coe Honda Fit 1.3A G



2.88% P.A. \$0 Down, Monthly
 From \$438, Sta "B", 2 Yrs
 Warranty Engine, Gearbox
 GV Credit Pte Ltd StarAd



Browse by Category

Sort by Date Posted

6 vehicles

Mercedes-Benz gla180

Advanced Search

| Make | Model | Price | Depreciation | Reg Date | Eng Cap | Mileage |
|------|-------|-------|--------------|----------|---------|---------|
|------|-------|-------|--------------|----------|---------|---------|

| | | | | | | |
|-------------------------|-----------------------------|-----|-----|-------------|-----|-----|
| Search Selection | Mercedes-Benz gla180 | Any | Any | 2016 | Any | Any |
|-------------------------|-----------------------------|-----|-----|-------------|-----|-----|



Mercedes-Benz GLA-Class GLA180 **\$92,800** **\$12,600 /yr** **25-Jan-2016** **1,595 cc** **99,000 km**

In House Finance Available, C&C Unit, FOC 6 Month Warranty! 1 Owner, Beautiful White GLA. Very Well Maintain, Powerful Engine, Smooth Auto Transmission, Ensuring You A Zippy Daily Drive, Yet Returning Excellent Fuel Efficiency! One Of The Lowest Depreciation GL Speedo Motoring

Posted: 01-Sep-2019 Tags: 2016 Mercedes-Benz GLA180, 2016 mercedes-benz gla180, Mercedes-Benz GLA180, mercedes-benz gla180, Mercedes-Benz, GLA180, gla180, Used Mercedes-Benz



Mercedes-Benz GLA-Class GLA180 **\$94,800** **\$12,500 /yr** **28-Mar-2016** **1,595 cc** **74,300 km**

Graded **B** by **STAR**
 Purchase From Case Trust Accredited Dealer To Have Peace Of Mind! C&C R18 Model Unit, STA Certified Accident Free Quality Pre-Owned With C&C Maintained Serviced Record, Original Paintwork With Clean And Neat Interior, 100% Loan Approval With Our Flexible In House

Posted: 01-Sep-2019 Tags: 2016 Mercedes-Benz GLA180, 2016 mercedes-benz gla180, Mercedes-Benz GLA180, mercedes-benz gla180, Mercedes-Benz, GLA180, gla180, Used Mercedes-Benz



Mercedes-Benz GLA-Class GLA180 **\$94,800** **\$12,420 /yr** **08-Apr-2016** **1,595 cc** **80,000 km**

1 Owner Only! Fully Serviced And Maintained By C&C! 100% Accident Free! STA Evaluation Available! Buy With A Peace Of Mind! Low Depreciation! Very Good Petrol Efficiency! High And Flexible Loan Available! High Trade In For Your Used Car! Call Us Now To Make An. ST Carz Pte Ltd

Posted: 31-Aug-2019 Tags: 2016 Mercedes-Benz GLA180, 2016 mercedes-benz gla180, Mercedes-Benz GLA180, mercedes-benz gla180, Mercedes-Benz, GLA180, gla180, Used Mercedes-Benz



Mercedes-Benz GLA-Class GLA180 **\$94,800** **\$12,480 /yr** **25-Feb-2016** **1,595 cc** **-**

Bank Loan Interest Rate At 1.99%. 1 Owner Unit. Flexible Loan Available. Well Maintained Condition And With Original Paintwork. Excellent Condition. Bank Loan And In House Loan Available.

Posted: 15-Aug-2019 Tags: 2016 Mercedes-Benz GLA180, 2016 mercedes-benz gla180, Mercedes-Benz GLA180, mercedes-benz gla180, Mercedes-Benz, GLA180, gla180, Used Mercedes-Benz

[Car Buying](#) [Car Selling](#) [Car Ownership](#) [Buy It](#)
[Car Aftermarket](#) [On The Move](#) [Lifestyle](#)

[Compare](#) **Mercedes-Benz GLA-Class GLA180** **\$110,000** **\$13,250 /yr** **08-Dec-2016** **1,595 cc** **36,000 km**

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars | |
|-------------------------------------|--------------------------------------|
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 930Z |
| Vehicle Details | |
| Vehicle No.: | SLD9833R |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 03 Sep 2019 |
| Vehicle Make: | MERCEDES BENZ |
| Vehicle Model: | GLA180 (R18 BI) |
| Primary Colour: | White |
| Manufacturing Year: | 2016 |
| Engine No.: | 27091030996287 |
| Chassis No.: | WDC1569422J268340 |
| Maximum Power Output: | 90.0 kW (120 bhp) |
| Open Market Value: | \$27,838.00 |
| Original Registration Date: | 04 Jul 2016 |
| First Registration Date: | 04 Jul 2016 |
| Transfer Count: | 1 |
| Actual ARF Paid: | \$25,974.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 03 Jul 2026 |
| PARF Rebate Amount: | \$19,480.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 03 Jul 2026 |
| COE Category: | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years): | 10 |
| QP Paid: | \$47,889.00 |
| COE Rebate Amount: | \$32,724.00 |
| Total Rebate Amount: | \$52,204.00 |

The information contained herein is correct as at 03 Sep 2019

OK

SM SPRAY PAINTING

ON BEHALF OF OWNER :

Policy Particulars: - THIRD PARTY CLAIM

| | | | |
|-------------------|-----------------------------------|-----------|-----|
| Insured veh. | SLD9833R | Excess. | NIL |
| Policy No. | D19MTPV01000265 | Coverage. | |
| Claiming Against. | SLL3222B | | |
| Insured Under. | SOMPO INSURANCE SINGAPORE PTE LTD | | |

Vehicle Particulars & Condition

| | |
|------------------|----------------------|
| Make & Model | MERCEDES BENZ GLA180 |
| Engine No. | *27091030996287 |
| Chassis No. | WDC1569422J268340 |
| Odometer | |
| Engine CC. | 0 |
| Year Of Reg. | 2016 |
| Colour. | WHITE |
| Parf/COE Rebate. | \$ 52,269.00 |

4/5 \$2100

Not Allowed
 2/9/19
 Weight. Attorney...
 3d.

Conditions Of Tyres

| | Size | Make |
|----------------|------|------|
| R/H Front Tyre | | |
| L/H Front Tyre | | |
| R/H Rear Tyre | | |
| L/H Rear Tyre | | |

Description Of Damages

FRONT / REAR PORTION

General Information

Accident Date. 25/8/2019
 Survey held at

Yew Tee Automobile Tech Pte Ltd
 SYNERGY@KB 25 KAKI BUKIT ROAD 4 #01-61 S417800

Remarks

LKK Auto Consultants hence notify the Repairer of the following:

- After spray painting
- (warranties) during resurvey
- subject to confirmation
- on a "Without Prejudice" basis
- (warranties) is allowed
- Supplementary (warranties) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:

Estimate Days Of Repair

ESTIMATE NORMAL PERIOD FOR REPAIR: _____ Days

SM SPRAY PAINTING

| <u>Qty.</u> | <u>Part Item</u> | <u>Description Of Parts</u> | <u>Pricing</u> |
|-------------|------------------|---|------------------------|
| 1 | | FRONT BUMPER 1372.80 | rs/ea \$ 1,520.00 |
| 1 | | FRONT BUMPER REINFORCEMENT | 17 \$ 459.00 |
| 1 | | BONNET | 17 \$ 1,998.00 |
| 1 | | FRONT GRILLE | 17 \$ 1,210.00 |
| 1 | | FRONT LH FENDER | 17 \$ 850.00 |
| 1 | | SUPPORT PANEL | 17 \$ 785.00 |
| | | | List Items \$ 6,822.00 |
| | | | Less 20% \$ 1,364.40 |
| | | | Sub Total \$ 5,457.60 |
| | | | 10% |
| 1 | | FRONT BUMPER INNER SPONGE | 17 \$ 175.00 |
| 1 | | FRONT BUMPER LOWER SPOILER | 17 \$ 750.00 |
| 1 | | FRONT BUMPER FOG LAMP GARNISH LH | 17 \$ 95.00 |
| 1 | | FRONT HEADLAMP LH | 17 \$ 2,800.00 |
| 1 | | FRONT HEADLAMP PANEL LH | 17 \$ 230.00 |
| 1 | | FRONT HEADLAMP NOZZLE COVER LH | 17 \$ 130.00 |
| 1 | | FRONT HEADLAMP NOZZLE LH | 17 \$ 220.00 |
| 1 | | FRONT LH FENDER INNER SHIELD | 17 \$ 200.00 |
| 1 | | FRONT LH FENDER WHEEL ARCH GARNISH | gmd \$ 270.00 |
| 1 | | FRONT LH SHOCK ABSORBER | 17 \$ 950.00 |
| 1 | | FRONT LH KNUCKLE ARM | 17 \$ 990.00 |
| 1 | | FRONT LH LOWER ARM | 17 \$ 780.00 |
| 1 | | FRONT LH LOWER ARM BALL JOINT | 17 \$ 130.00 |
| 1 | | FRONT LH WHEEL BEARING | 17 \$ 110.00 |
| 1 | | FRONT LH STABILIZER BAR LINK | 17 \$ 180.00 |
| 1 | | FRONT LH THRUST ARM | 17 \$ 300.00 |
| 1 | | FRONT LH WHEEL RIM | 17 \$ 750.00 |
| | | | Nett items \$ 9,060.00 |
| | | | Less 10% \$ 906.00 |
| | | | Sub Total \$ 8,154.00 |
| 1 | | STICKER | nr \$ 1,200.00 |
| 1 | | FRONT TYRE LH | 17 \$ 270.00 |
| 1 | | FRONT BUMPER CLIPS | nr \$ 45.00 |
| 1 | | FENDER INNER SHIELD CLIP | 17 \$ 38.00 |
| 1 | | FRONT BUMPER SENSOR | 17 \$ 380.00 |
| | | | S/N \$ 1,933.00 |

SM SPRAY PAINTING

| <u>Qty.</u> | <u>Description Of Parts</u> | <u>Pricing</u> |
|----------------------|---|--------------------------|
| <u>LABOUR</u> | | |
| | To apply undercoating on the repaired and replaced panel for rust protection. | \$ 17 80.00 X |
| | To disconnect and reconnect, check electrical wiring harness wire, sockets, replace damaged parts. | \$ 80.00 20 |
| | To Carry-Out Body Cavity Preservation. | 17 \$ 60.00 X |
| | To remove and refit front bumper sensors. | \$ 80.00 40 |
| | Computer wheel alignment | 17 \$ 100.00 X |
| | Computer set fault code, programming & coding | 17 \$ 580.00 X |
| | To dismantle and refit front undercarriage. | 17 \$ 180.00 X |
| | To remove & replace the above damaged parts, straighten, knock out, realign & repair including cut & weld body panels. To re-adjust to the original position using power tools. | \$ 2,000.00 300 |
| | To spray painting on the replaced & repair parts, prepare spray such as masking tape the unaffected areas with papers, cleaning & sanding of surfaces, final polishing & waxing are also available. | \$ 2,200.00 400 |
| | | LABOUR \$ 5,360.00 |
| | | 21586.80 |
| | | Sub Total. \$ 20,904.60 |
| | | 7% GST \$ 1,463.32 |
| | | Grand Total \$ 22,367.92 |

If the damage is beyond the market value, kindly counter offer the economy repair value of the vehicle for us to consider.

P- 1642.80
 10%
 P- 1478.52
 S.N. 445.00
 L - 760.00

 2683.52
 20%

 2146.81

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19015140/USF3N2

Date: 12/09/2019

REFERENCE

| | | | |
|-----------------------|-------------------------------------|----------------------|-----------------|
| Handling Insurer: | Sompo Insurance Singapore Pte. Ltd. | Policy No: | D19MTPV01008758 |
| Claimant Vehicle No : | SLD9833R | Insured Vehicle No : | SKX6113L |
| Date of Loss: | 25/08/2019 | Nature of Claim: | TP |
| | | Claim No: | CMTD1904070 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|---|-------------|-------------------|
| Reg No: | SLD9833R | Engine No: | 27091030996287 |
| Make & Model: | MERCEDES-BENZ GLA180 URBAN (R18 LED), 1.6 (A) | Chassis No: | WDC1569422J268340 |
| Reg. Date: | 04/07/2016 (Man. Year: 2016) | Odometer: | 49370 km |
| Colour: | White | | |
| Engine Capacity: | 1595 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (\$\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|-----|--------------------------|-----|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Engine Modification: | No | Pre-accident Condition: | |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 235/50R18 | Rear Tyre Size: | 235/50R18 |
| Front Left Side: | Michelin 7 mm | Rear Left Side: | Michelin 7 mm |
| Front Right Side: | Michelin 7 mm | Rear Right Side: | Michelin 7 mm |

The above values represent the remaining tyre treads depth

COST OF CLAIMS

| | Repairer's | Adjuster's | Difference | Diff % | |
|---|--------------------------------|------------------|------------------|------------------|--------------|
| Parts | 16,226.80 | 1,923.52 | 14,303.28 | 88.15 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | | |
| Labour | 5,360.00 | 760.00 | 4,600.00 | 85.82 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | | |
| Towing | 0.00 | 0.00 | 0.00 | | |
| Calculated Gross Total (\$\$) | 21,586.80 | 2,683.52 | 18,903.28 | 87.57 | |
| Approved Total (Overridden) (\$\$) | | 2,100.00 | | | |
| | (\$\$) | 21,586.80 | 2,100.00 | 19,486.80 | 90.27 |
| | + GST 7.00/7.00% (\$\$) | 1,511.08 | 147.00 | 1,364.08 | 90.27 |
| | Nett Amount (\$\$) | 23,097.88 | 2,247.00 | 20,850.88 | 90.27 |

INSPECTION

| | | |
|---------------------|------------|--|
| Date of Assignment: | 27/08/2019 | |
| Date Inspected: | 02/09/2019 | Inspected At: |
| | | S M Spray Painting Pte Ltd (HQ) 25, Kaki Bukit Road 4, #08-30 Synergy@KB Singapore 417800 |

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

| | | |
|---|--|--|
| Reference | | |
| Part Source: MRM-SG | Version: 1.0 (Last Synchronised: 12 Sep 2019) | |
| Parts: M1-SUV | MERCEDES-BENZ GLA180 URBAN (R18 LED) 1.6 (A) (Catalogue:Merimen Singapore 1.0) | |
| Labour: Repairer's | (Price-denominated Standard List) | |
| Print Code: | (Unsubmitted, no print-code for SLD9833R) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: Items/values not in reference catalogue are prefixed with an asterisk *. | | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-------------------------------------|-----------------|-------------|--------------|
| 1 | 1 | | *FRONT BUMPER | Dented/Deformed | 1,520.00 FN | *1,372.80 FN |
| 2 | 1 | | *FRONT BUMPER REINFORCEMENT | Not Necessary | 459.00 FN | *- FN |
| 3 | 1 | | *BONNET | Not Necessary | 1,998.00 FN | *- FN |
| 4 | 1 | | *FRONT GRILLE | Not Necessary | 1,210.00 FN | *- FN |
| 5 | 1 | | *FRONT LH FENDER | Repair | 850.00 FN | *- FN |
| 6 | 1 | | *SUPPORT PANEL | Not Necessary | 785.00 FN | *- FN |
| 7 | 1 | | *FRONT BUMPER INNER SPONGE | Not Necessary | 175.00 FN | *- FN |
| 8 | 1 | | *FRONT BUMPER LOWER SPOILER | Not Necessary | 750.00 FN | *- FN |
| 9 | 1 | | *FRONT BUMPER FOG LAMP GARNISH LH | Not Necessary | 95.00 FN | *- FN |
| 10 | 1 | | *FRONT HEADLAMP LH | Not Necessary | 2,800.00 FN | *- FN |
| 11 | 1 | | *FRONT HEADLAMP PANEL LH | Not Necessary | 230.00 FN | *- FN |
| 12 | 1 | | *FRONT HEADLAMP NOZZLE COVER LH | Not Necessary | 130.00 FN | *- FN |
| 13 | 1 | | *FRONT HEADLAMP NOZZLE LH | Not Necessary | 220.00 FN | *- FN |
| 14 | 1 | | *FRONT LH FENDER INNER SHIELD | Not Necessary | 200.00 FN | *- FN |
| 15 | 1 | | *FRONT LH FENDER WHEEL ARCH GARNISH | Grazed | 270.00 FN | *270.00 FN |
| 16 | 1 | | *FRONT LH SHOCK ABSORBER | Not Necessary | 950.00 FN | *- FN |
| 17 | 1 | | *FRONT LH KNUCKLE ARM | Not Necessary | 990.00 FN | *- FN |
| 18 | 1 | | *FRONT LH LOWER ARM | Not Necessary | 780.00 FN | *- FN |
| 19 | 1 | | *FRONT LH LOWER ARM BALL JOINT | Not Necessary | 130.00 FN | *- FN |
| 20 | 1 | | *FRONT LH WHEEL BEARING | Not Necessary | 110.00 FN | *- FN |
| 21 | 1 | | *FRONT LH STABILIZER BAR LINK | Not Necessary | 180.00 FN | *- FN |
| 22 | 1 | | *FRONT LH THRUST ARM | Not Necessary | 300.00 FN | *- FN |
| 23 | 1 | | *FRONT LH WHEEL RIM | Not Necessary | 750.00 FN | *- FN |
| 24 | 1 | | *STICKER | Necessary | 1,200.00 FS | *400.00 FS |
| 25 | 1 | | *FRONT TYRE LH | Not Necessary | 270.00 FS | *- FS |
| 26 | 1 | | *FRONT BUMPER CLIPS | Necessary | 45.00 FS | *45.00 FS |
| 27 | 1 | | *FENDER INNER SHIELD CLIP | Not Necessary | 38.00 FS | *- FS |
| 28 | 1 | | *FRONT BUMPER SENSOR | Not Necessary | 380.00 FS | *- FS |

F=Franchise part. S=SpcNett. N=NettItemDisc.

| | | |
|--|------------------|-----------------|
| Sub Total (\$\$) | 17,815.00 | 2,087.80 |
| - Nett Item Discount on N Items 10.00/10.00% (\$\$) | 1,588.20 | 164.28 |
| Total Parts (\$\$) | 16,226.80 | 1,923.52 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|---|----------|-----------------|---------------|
| Labour Items | | | | |
| 1 | TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANEL FOR RUST PROTECTION | New | 80.00 | 0.00 |
| 2 | TO DISCONNECT AND RECONNECT,CHECK ELECTRICAL WIRING HARNESS WIRE,SOCKETS,REPLACE DAMAGED PARTS | New | 80.00 | 20.00 |
| 3 | TO CARRY-OUT BODY CAVITY PRESERVTION | New | 60.00 | 0.00 |
| 4 | TO REMOVE AND REFIT FRONT BUMPER SENSORS | New | 80.00 | 40.00 |
| 5 | COMPUTER WHEEL ALIGNMENT | New | 100.00 | 0.00 |
| 6 | COMPUTER SET FAULT CODE,PROGRAMMING & CODING | New | 580.00 | 0.00 |
| 7 | TO DISMANTLE AND REFIT FRONT UNDERCARRIAGE | New | 180.00 | 0.00 |
| 8 | TO REMOVE & REPLACE THE ABOVE DAMAGED PARTS,STRAIGHTEN,KNOCK OUT,REALIGN & REPAIR INCLUDING CUT & WELD BODY PANELS.TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS | New | 2,000.00 | 300.00 |
| 9 | TO SPRAY PAINTING ON THE REPLACED & REPAIR PARTS,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPERS,CLEANING & SANDING OF SURFACES,FINAL POLISHING & WAXING ARE ALSO AVAILABLE | New | 2,200.00 | 400.00 |
| Gross Labour Cost (S\$) | | | 5,360.00 | 760.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >