



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

EQ INSURANCE COMPANY LTD 5 Maxwell Road #17-00 Tower Block MND Complex, Singapore 069110 ATTN. : MOTOR CLAIMS FAX :		NAME : Mdm Ho Kia Hwa ADDRESS : 240 Jurong East Street 21 #05-366 Singapore 600240 TEL : 96667228		WIP : 61058 EXCESS : DATE: 21-Aug-19	
VEH NO :	SLS8047X	DATE IN :		CONTACT PERSON :	Jess 63957874
CHASSIS NO :	JM6DJ2HAA01200136	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA2	DATE REG.:	6-Oct-17	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	REAR BUMPER	1	MDC3R-50-221BBB	del	\$ 893.40
2	BRACKET CENTER	1	MKD53-50-251	?	\$ 5.40
3	STAY, REAR BUMPER	2	MD09W-50-271A	?	\$ 22.80
4	CAP, REAR BUMPER	1	MD09W-50-705	X	\$ 39.60
5	FASTENER, REAR BUMPER	7	MB45A-56-146A	net	\$ 21.00
6	GROMMET, REAR BUMPER	4	MBHN1-50-0Z1A	net	\$ 10.80
7	GROMMET, REAR BUMPER	2	M9991-00-501	net	\$ 6.00
8	TAPE PROTECTOR, REAR BUMPER	3	MG51D-50-EM1A	net	\$ 25.80
9	LAMP, LICENSE PLATE	2	MD09H-51-270A	?	\$ 111.60
TOTAL PARTS					\$ 1,136.40
LESS 10%					\$ 113.64
TOTAL PARTS COST					\$ 1,022.76
Labour Description					
1	MZ-BR-REAR01	TO REPLACE REAR BUMPER. TO REPAIR REAR END PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT.		660.	\$ 1,980.00
2	MZ-SP-SFRT01	TO RESPRAY REAR BUMPER AND REAR END PANEL.		630	\$ 1,890.00
3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS. (WITH REVERSE SENSOR)		✓ NETT	\$ 660.00
4	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.		X NETT	\$ 330.00
5	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.		ant ✓ NETT	\$ 70.00
6	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.		X	\$ 250.00
7	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		150	\$ 250.00

8	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180-	\$ 350.00
9		TO SUPPLY BODY COATING.	NETT	TBA
10	MZ-BR-SUNDRI	SUNDRIES.	20	NETT \$ 100.00
			TOTAL LABOUR	\$ - \$ 5,880.00
			TOTAL PARTS	\$ - \$ 1,022.76
			TOTAL	\$ - \$ 6,902.76
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ -
			GST 7%	\$ - \$ -
			GRAND TOTAL	\$ - \$ -

REMARKS:
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature

Taufik 97495749
04 days 'WP'
Resurvey before paint
suve@khando.com
24/9/19 21110

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: