

CONNECT 3

566 Woodlands Road (Mandai Estate) Singapore 728697

Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

ROC:53360061L

GST:53360061L

QT19/PC656C/TPC-549

Lonpac Insurance Bhd

100 Beach Road

#19-00 Shaw Tower

Singapore 189702

QUOTATION

Dear Sir,

Cost of Repair to Vehicle PC626C


With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (\$\$)	AMOUNT (\$\$)
1.	Front windscreen	1	3,800.00	3,800.00
2.	Front windscreen inner moulding	1	680.00	680.00
3.	Front LH rear view mirror assy	1	1,350.00	1,350.00
4.	Sealant	8	40.00	320.00
5.	Labour to remove & refit front windscreen	1	1,000.00	1,000.00
6.	Check wiring	1	20.00	20.00
7.	Labour charges	1	600.00	600.00
8.	Spray painting	1	800.00	800.00
SUB-TOTAL				S\$8,570.00

- Price before 7% gst

Thank you.

Yours faithfully,



Winnie Chai

HP: 9850-9666

