

**CAS GARAGE PTE LTD**

(Reg No. 20182506740)

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

**VEHICLE REPAIR ESTIMATE**

Insurance Company: AIG ASIA PACIFIC INSURANCE PTE LTD

Address: NO 78, SHENTON WAY, #07-16  
S(079120)

Aches.

Telephone: 64193000

Fax: 68357416

Email shengyang.lim@aig.com

noormarriesa.abukassim@aig.com

Make/ Model : Elantra  
HYUNDAI ~~AVANTE~~

Date: 28.08.2019

Chassis No : KMHD841CMJU729840

Vehicle No: SMD6534J

Date/Time of Accide 27.08.2019/0830

**Materials Cost/ Spare Parts Cost****TO BE COMPLETED BY SERVICE ADVISOR**

| ITEMS | PARTS DESCRIPTION                            | QTY | LIST PRICE \$ |  | FINAL PRICE \$   |
|-------|----------------------------------------------|-----|---------------|--|------------------|
| 1     | REAR BOOTLID <i>Painted</i>                  | 1   | \$ 1,745.80   |  | \$ ✓ 1,745.80    |
| 2     | REAR BOOTLID INNER LOCK <i>Painted</i>       | 1   | \$ 145.70     |  | \$ ✓ 145.70      |
| 3     | REAR BOOTLID SMARTKEY ANTENNA <i>Painted</i> | 2   | \$ 125.80     |  | \$ ✗ 251.60      |
| 4     | REAR BOOTLID INNER TRIM <i>New</i>           | 1   | \$ 195.80     |  | \$ ✗ 195.80      |
| 5     | REAR BOOTLID LATCH <i>Painted</i>            | 1   | \$ 38.50      |  | \$ ✓ 38.50       |
| 6     | REAR BOOTLID LOGO <i>New</i>                 | 1   | \$ 85.80      |  | \$ ✓ 85.80       |
| 7     | REAR BOOTLID "ELANTRA" EMBLEM <i>New</i>     | 1   | \$ 83.60      |  | \$ ✓ 83.60       |
| 8     | REAR BOOTLID WEATHERSTRIP <i>New</i>         | 1   | \$ 154.80     |  | \$ ✓ 154.80      |
| 9     | REAR BOOTLID REFLECTORS <i>Painted</i>       | 2   | \$ 398.60     |  | \$ ✓ 797.20      |
| 10    | END PANEL <i>Distalbed</i>                   | 1   | \$ 598.80     |  | \$ ✓ 598.80      |
| 11    | END PANEL TOP GARNISH <i>Distalbed</i>       | 1   | \$ 175.90     |  | \$ ✓ 175.90      |
| 12    | TAILAMPS <i>Painted</i>                      | 2   | \$ 498.30     |  | \$ ✓ 996.60      |
| 13    | TAILAMPS PANEL <i>RT Distalbed</i>           | 2   | \$ 345.80     |  | \$ 345.80 691.60 |
| 16    | SPARE TYRE FLOOR PANEL <i>Reqs</i>           | 1   | \$ 745.80     |  | \$ ✓ 745.80      |
| 17    | SPARE TYRE TOP BOARD <i>Distalbed</i>        | 1   | \$ 385.90     |  | \$ ✓ 385.90      |
| 18    | SPARE TYRE TOOL BOX SPONGE <i>New</i>        | 1   | \$ 285.70     |  | \$ ✗ 285.70      |
| 19    | REAR BUMPER <i>Distalbed</i>                 | 1   | \$ 654.30     |  | \$ ✓ 654.30      |
| 20    | REAR BUMPER LOWER <i>Distalbed</i>           | 1   | \$ 359.80     |  | \$ ✓ 359.80      |
| 21    | REAR BUMPER RETAINERS <i>New</i>             | 2   | \$ 85.90      |  | \$ ✓ 171.80      |
| 22    | REAR BUMPER REFLECTOR <i>Painted</i>         | 2   | \$ 98.70      |  | \$ ✓ 197.40      |
| 23    | REAR BUMPER REINFORCEMENT <i>Painted</i>     | 1   | \$ 398.20     |  | \$ ✓ 398.20      |
| 24    | REAR REINFORCEMENT BRACKETS <i>Painted</i>   | 2   | \$ 85.90      |  | \$ ✗ 171.80      |
| 26    | REINFORCEMENT BRACKETS METAL <i>New</i>      | 2   | \$ 294.80     |  | \$ ✗ 589.60      |
| 27    | REAR BUMPER LOWER COVER <i>New</i>           | 2   | \$ 145.90     |  | \$ ✗ 291.80      |
| 28    | REAR FENDER <i>Reqs</i>                      | 2   | \$ 1,845.30   |  | \$ ✗ 3,690.60    |
| 29    | REAR FENDER INNER TRIM <i>New</i>            | 2   | \$ 298.50     |  | \$ ✗ 597.00      |
| 30    | REAR FENDER INNER COWLING <i>New</i>         | 2   | \$ 165.90     |  | \$ ✗ 331.80      |
| 31    | REAR SILENCER BOX <i>Painted</i>             | 1   | \$ 785.60     |  | \$ ✓ 785.60      |

**Total List Price Cost**

PARTS DISCOUNT 20%

\$ 15,618.80  
\$ 12,495.04

9039.10

7231.28

| SPECIAL NETT                                                              | PARTS DESCRIPTION                         | QTY   | PRICE \$  | FINAL PRICE \$       |
|---------------------------------------------------------------------------|-------------------------------------------|-------|-----------|----------------------|
| 1                                                                         | EMERGENCY BREAK DOWN SIGN <i>new</i>      | 1 SET | \$ 180.00 | \$ 180.00            |
| 2                                                                         | REVERSE SENSORS <i>2nd</i>                | 1 SET | \$ 250.00 | \$ <del>250.00</del> |
| 3                                                                         | REVERSE CAMERA <i>2nd</i>                 | 1 SET | \$ 280.00 | \$ <del>280.00</del> |
| 4                                                                         | REAR NUMBER PLATE WITH CASING <i>2nd</i>  | 1 SET | \$ 50.00  | \$ <del>50.00</del>  |
| 5                                                                         | REAR BUMPER CLIPS <i>new</i>              | 1 SET | \$ 30.00  | \$ <del>30.00</del>  |
| 6                                                                         | END PANEL TOP GARNISH CLIPS <i>new</i>    | 1 SET | \$ 30.00  | \$ <del>30.00</del>  |
| 7                                                                         | REAR BUMPER INNER TRIM CLIPS <i>new</i>   | 1 SET | \$ 30.00  | \$ <del>30.00</del>  |
| 8                                                                         | END PANEL SEALANT <i>new</i>              | 2     | \$ 80.00  | \$ <del>80.00</del>  |
| 9                                                                         | SPARE TYRE INSULATOR PAD <i>new</i>       | 1 SET | \$ 180.00 | \$ <del>180.00</del> |
| 10                                                                        | REAR FENDER INNER TRIM CLIPS <i>new</i>   | 2 SET | \$ 60.00  | \$ <del>60.00</del>  |
| 11 <i>Per</i>                                                             | FRONT BUMPER LOWER COVER CLIPS <i>new</i> | 1 SET | \$ 30.00  | \$ <del>30.00</del>  |
| 12 <i>Per</i>                                                             | FRONT FENDER COWLING SET <i>new</i>       | 2 SET | \$ 60.00  | \$ <del>60.00</del>  |
| Total Special Nett Items                                                  |                                           |       |           | \$ 1,260.00          |
| 680                                                                       |                                           |       |           |                      |
| <b>Labour Works/ Panel Beating Related Works</b>                          |                                           |       |           |                      |
| Job Scope                                                                 |                                           |       |           | Quotation            |
| TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGNE ALL PARTS |                                           |       |           | \$ 2,400.00          |
|                                                                           |                                           |       |           | 1200.                |
| <b>Spray Painting</b>                                                     |                                           |       |           |                      |
| Job Scope                                                                 |                                           |       |           | Quotation            |
| TO RESPRAY AFFECTED AREAS                                                 |                                           |       |           | \$ 2,200.00          |
|                                                                           |                                           |       |           | 1200                 |
| <b>Others Cost (Accident Repair Related Expenses)</b>                     |                                           |       |           |                      |
| Job Scope                                                                 |                                           |       |           | Quotation            |
| TO TUFFCOAT AFFECTED AREA                                                 |                                           |       |           | \$ 60 200.00         |
| TO REMOVE/ REFIT REAR SILENCER BOX                                        |                                           |       |           | \$ 80 180.00         |
| TO CONDUCT WIRING CHECK ON THE REAR TAILAMPS                              |                                           |       |           | \$ 30 150.00         |
| TO REMOVE/ REFIT & REPLACE REAR SENSORS AND DISTANCE SETTLING             |                                           |       |           | \$ 50 180.00         |
| TO REMOVE/ REFIT & REPLACE REAR CAMERA                                    |                                           |       |           | \$ 50 200.00         |
| TO REMOVE/ REFIT REAR INTERIOR UPHOLSTERY                                 |                                           |       |           | \$ 80 250.00         |
| TO CONDUCT WATER LEAKAGE TEST                                             |                                           |       |           | \$ X 120.00          |
| TO APPLY UNDERCOATING TO THE AFFECTED AREAS                               |                                           |       |           | \$ 80 250.00         |
| TO REMOVE AND REPLACE BOOTLID MECHANISM                                   |                                           |       |           | \$ 80 150.00         |
| Total Others Cost                                                         |                                           |       |           | \$ 1,680.00          |
| GRAND TOTAL                                                               |                                           |       |           | \$ 20,035.04         |

**CAS GARAGE PTE LTD**  
 UEN 201828067M  
 1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY,  
 SINGAPORE 417883

CAS GARAGE PTE LTD

Person Incharge: Allan  
 Direct Contact: +65 8782 7171  
 Email: allangoh.cas@gmail.com  
 Fax: +65 6509 9501

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Adrian Lim

1/2 29/08/19.

08 Days

total: 10821.28

1/2: 8650