

DATE 28/8/2019 16:07

MAKE :

**MODEL : HYUNDAI SONATA**

Like

AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid Lamp (RH) X old Bump X nn			\$ 230.20
	Rear Bumper - de ✓			\$ 578.40
	Rear Bumper Clip - nec ✓			\$ 22.00
	Rear Bumper Protector (RH) X nn			\$ 38.00
	SUB TOTAL			\$ 868.60
	LESS 20%			\$ 173.72
	DISCOUNTED TOTAL			\$ 694.88
	Rear Bumper Advertisement Logo - nec ✓			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH) - nec ✓	\$ 100.00		\$ 200.00
				\$ 250.00
	Labour Charge			200
	Panel Beating			\$ 350.00
	Spray Painting Charge			\$ 250.00
	Wiring Charge			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 770.00
	ESTIMATE TOTAL			\$ 1,714.88

1 Car / 16/11/19  
 // 29/8/19 1225 hr.  
 2 hrs.  
 U/S  
 After Repair p Ld

I hereby acknowledge and agree to notify the insurer of the following:

- I have agreed parts during survey
- Parts prices are subject to confirmation
- Third party survey is on a "No Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be recovered and is subject to final approval from insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.