

CHNG BROTHERS MOTOR SERVICES

2 Kaki Bukit Avenue 2, #02-32 Kaki Bukit Autohub, Singapore 417921

Tel: +65 67470407 Fax: +65 67426933

E-mail: info@chngbrothers.com

Attn: Admin

62564315

QUOTATION

AIG ASIA PACIFIC INSURANCE PTE. LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Department

Tel: +65 64193000 Fax:

Vic

Your Ref. : SJL5878U
Vehicle No. : SLZ3329D
Make & model : BWM 520i
Chasis No. : WBANT12010CX30348
Engine No. : A7471510N46B20BE
Accident Date : 24/08/2019
Policy No. : 5101321023
Date : 30/08/2019
Page : 1

Thank you for your inquiry. We are pleased to submit our quote as follows:

Item	Description	Qty	U/Price S\$	Amount S\$
1	REAR END PANEL <i>Not Nec</i>	1.0 PCS	619.00	X 619.00
2	BUMPER HOOK COVER <i>new</i>	1.0 PCS	19.60	X 19.60
3	REAR BUMPER <i>Deformed</i>	1.0 PCS	1460.50	✓ 1460.50
4	REAR BUMPER LIP <i>Deformed</i>	1.0 PCS	320.00	✓ 320.00
5	BUMPER SIDE RETAINER (L/H/R) <i>new</i>	1.0 PCS	51.40	✓ 51.40
6	BUMPER SIDE RETAINER (R/H/R) <i>new</i>	1.0 PCS	51.40	✓ 51.40
7	REAR BUMPER REINFORCEMENT <i>Best</i>	1.0 PCS	421.20	✓ 421.20
8	BUMPER BEAM SCREW/INNER CLIPS SET <i>new</i>	1.0 SET	90.00	X 90.00
9	REAR BUMPER TOP RETAINER <i>old</i>	1.0 PCS	74.00	✓ 74.00
10	SUNDRIES <i>new</i>	1.0 SET	120.00	X 120.00
11	LAMP (R/H/R) <i>new</i>	1.0 PCS	630.00	X 630.00
12	REVERSE SENSOR <i>1 piece used</i>	2.0 PCS	291.70	291.70 583.40
13	WIRE HARNESS (REVERSE SENSOR) <i>new</i>	1.0 PCS	425.60	X 425.60
14	Discount 5%			-243.30
15	SubTotal (L)			4622.80
16	PANEL BEAT & REPAIR REAR DAMAGE	1.0 X	250	600.00
17	TO PUTTY AND RE-SPRAY AFFECTED PORTION	1.0 X	400	600.00
18	TO PROVIDE UNDER TURFCOAT	1.0 X	740	X 180.00
19	TO CHECK WIRING SYSTEM, FOCUS LIGHTINGS	1.0 X		30 80.00
20	TO REMOVE AND REFIT COMPONENTS / FACILITATE THE REPAIR	1.0 X		X 250.00
21	TO REMOVE REVERSE SENSOR	1.0 X		60 150.00
22	SubTotal (LABOUR)			1,860.00

SINGAPORE DOLLAR SIX THOUSAND FOUR HUNDRED EIGHTY TWO AND CENTS EIGHTY ONLY.

E. & O.E

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey

Customer's Signature/Co. Stamp

- Third party survey is on a "Without Prejudice" basis

Any claim for faulty workmanship is limited solely to the rectification free of cost of such work, no claim for loss consequential or otherwise being admissible. Any objections to the validity of these charges must be made seven (7) days from the date of this invoice otherwise it is assumed that this bill is accepted as correct.

Acknowledged by Repairer

Signature:

Date:

total: 3206.39

L/S: 2.31C (Nett Value)

08 Days

Total S\$ 6,482.80
Discount S\$ 0.00
Net Total S\$ 6,482.80

Terms: C.O.D

CHNG BROTHERS MOTOR SERVICES