

ASS. REC. BY:

REF: CS/CTI19015284/039302

Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Elaine Cheong of CTI Date/Time: 29/08/2019

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKE 87135 Insured: CB 74218

at Workshop m/s Joo Hak Kee Auto Pte Ltd Tel: 67431913

of BIK 3007 Ubi Road 2 #01-406

Policy No: DMBISN3049941900 Claim No: SNM190204043C02

Sum Insured: Excess:

Make of Veh: D.O.A. 28/08/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 29.8.19 2.46p.m. Person Contacted: Shermin Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	CB 74218: NA/INC19015213/h4 D.O.A. 28/08/2019
	SKE 87135: NA/INC19015213/h4 D.O.A. 28/08/2019

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

C71/

ASSIGNMENT

From:
Estimated Cost:

Date:

Veh No:

SKE87135

Yr Regn:

412

Type: M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CAN

Make:

Honda city

C.C

1497

Colour

s.hw

A/C: Insured / Std / NI / NA

Sp. Reading

108250

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MRH6M25509PO20070

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185-60R15

R:

S/DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

28/8/19

D.O.I.

29/8/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

To Inspect Vehicle No:
at Workshop m/s
of

SKE87135

JMK

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

30k

IDAC Accident Report:

Consistent? : Yes or No

GIA / FR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

LTA 28860

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

net 6140

Date / Time

Action / Instruction

2nd rule Des 9k.

3/9/19

L/S \$2700 confirmed with sherman
(\$1,303.04 Red 33%)

RECEIVED 4 SEP 2019

Date/Time, File Pass to?

04/09/19

1)

Type

Date/Time, File Return to?

2)



Prel. Report



Final Report

Days Of Repair:

5

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

Add Fee:



Site Insp (\$

) 8+RS \$1



Interview (\$

) Photos



Tech. Invs (\$

) Others



Weekend (\$

) TOTAL

Report Format:

Lump Sum / I.B.I. (\$ 2,700/- L/S)

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Aug 2019		29 Aug 2019 14:41 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:									
Main Claimant:		DARRELL CHIN MEE CHOO							
Vehicle Reg. No.:		SKE8713S	Date of Loss: 28/08/2019 16:00 - :59						
Claim Type:		TP / SNM19D204043C02	Policy/Cover Note No.: DMB1SN3049941900						
Vehicle Reg. No. (Insured):		CB7421B	Policy No. (Claimant):						
			Excess: S\$1,500.00						
Repairer:		Joo Hak Kee Auto Pte Ltd (HQ) Blk 3007 Ubi Road 1, #01-406, 408701 Ubi - Tel: 67431913							
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 09/09/2019]							
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[New Cars](#)[Used Cars](#)[Sell My Car](#)[Directory](#)[Products](#)[Insurance](#)[Articles](#)[F](#)



31 Aug - 1 Sep 2019
DOWNTOWN EAST
10am to 8pm

GREAT PRICES. BETTER CARS. COE Renewed Cars



• \$0 Down payment • Low Monthly Installments • 1 Year Warranty • 100% Approvals

C
A U T
DE
fr

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD![Post an Ad](#)[Advertiser Login](#)[Ways of Selling](#)**New 5 Years Renewal Coe Toyota Altis 1.6A**

2.4E 16V P 1.4 2041ccw \$0 Down
Free 1st Year 48K 2nd Year 32K 3rd Year 16K
Engine 2000cc
GV Credit Pte Ltd



Browse by Category

Sort by Date Posted

1 vehicles

city

Advanced Search

Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
Search Selection	city	Any	Any	2013	Any	Any
	Honda City 1.5A VTEC	\$39,800	\$9,100 /yr	27-May-2013	1,497 cc	97,311 km
(2013 Facelift Model!) 1st Owner Unit. Vehicle Fully Done Up In Showroom Condition With Premium Grooming And Brand New Paint Co. Purchase Comes With 6 Months Certified Pre Owned Car Warranty With 24/7 Roadside Assistance. STA/VICOM/AA Evaluation Friendly. FI						
Sincere Motoring Pte Ltd						

Posted: 29-Aug-2019 Tags: 2013 Honda City, 2013 honda city, Honda City, honda city, Honda, City, city, Used Honda

Save this search criteria, to get email alerts whenever a match is found.

Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
-------	-------	--------------	----------	---------	---------	---

For old advertisements, view Expired ads

[Home](#)
[New Cars](#)
[Used Cars](#)
[Sell My Car](#)
[Directory](#)
[Products](#)
[Insurance](#)
[Article](#)
[Forum](#)
[Resour](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage car insurance. Find buy used city, city Singapore, used city Singapore, used city, used vehicles Singapore or even buy used city Singapore. We have new car dealers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job opening properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable. That this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy.

Follow sgCarMart.com
[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 6771

Vehicle Details

Vehicle No.: SKE8713S
Vehicle to be Exported: No
Intended Deregistration Date: 30 Aug 2019
Vehicle Make: HONDA
Vehicle Model: CITY 1.5L I-VTEC MT
Primary Colour: Silver
Manufacturing Year: 2009
Engine No.: L15A71804670
Chassis No.: MRHGM25509P020070
Maximum Power Output: 88.0 kW (118 bhp)
Open Market Value: \$18,487.00
Original Registration Date: 11 Apr 2012
First Registration Date: 11 Apr 2012
Transfer Count: 0
Actual ARF Paid: \$18,487.00 924)

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 10 Apr 2022
PARF Rebate Amount: \$11,092.00

Intended COE Rebate Details

COE Expiry Date: 10 Apr 2022
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$56,501.00
COE Rebate Amount: \$14,768.00
Total Rebate Amount: \$25,860.00

The information contained herein is correct as at 30 Aug 2019

OK

ATTN: MOTOR CLAIMS DEPARTMENT
 OWNER: DARRELL CHIN MEE CHOO
 TP INSURER: NTUC INCOME INSURANCE CO-OPERATIVE LTD
 POLICY NO: 5059040331-06
 REFERENCE: TP CLAIM
 DOA: 28/08/2019

REPAIR ESTIMATE

Est. No. : E19080006
 Date : 29/08/2019
 Vehicle Num. : SKE8713S
 Make/Model : HONDA, CITY
 Chassis/Eng# : MRHGM25509P020070
 Yr. of Manu : 2009

Not Allocated
 LMR
 d/s \$2700
 the job charge
 Sdy.
 29/8/19

No	Description	Qty	U/P	Amt
Section: LIST ITEMS				
1	Rear Bumper	DD 1.00	463.70	463.70 ✓
2	Rear Bumper Side Retainer	RM 2.00	14.80	29.60 ✓
3	Taillamp	CM 2.00	205.70	411.40 ✓
4	Bootlid	DD/Bul 1.00	503.90	503.90 ✓
5	Bootlid Chrome Garnish	CM 1.00	74.40	74.40 ✓
6	Bootlid Hinge	R 2.00	64.30	128.60 X
7	Bootlid Inner Lock	RM 1.00	56.80	56.80 ✓
8	Bootlid Logo Emblem	RM 1.00	17.80	17.80 ✓
9	Bootlid "CITY" Emblem	RM 1.00	16.20	16.20 ✓
10	Bootlid "I-Vtec" Emblem	RM 1.00	22.20	22.20 ✓
11	Rear End Panel	2070.60 202 1656.48 RM 1.00	399.30	399.30 ✓
12	Rear End Panel Top Garnish	RM 1.00	66.60	66.60 ✓
13	Bootlid Rubber	RM 1.00	150.80	150.80 ✓

Amt S\$ 2,341.30

Discount (20.00%) S\$ 468.26

Subtotal S\$ 1,873.04

Section: SPECIAL NETT ITEMS

14	Reverse Sensor	should 1 set	1.00	350.00	350.00 2005.14
----	----------------	--------------	------	--------	----------------

Amt S\$ 350.00

Discount (0.00%) S\$ 0.00

Subtotal S\$ 350.00

Section: LABOUR

15	To Panel Beat on Necessary Damaged Part	1.00	800.00	800.00 700
16	To Sand Down, Putty and Spray Paint on Necessary Damaged Part	1.00	800.00	800.00 750

Continue on next page...



JOO HAK KEE AUTO PTE LTD

裕合记汽车私人有限公司

SINCE 1986

ATTN: MOTOR CLAIMS DEPARTMENT
OWNER: DARRELL CHIN MEE CHOO
TP INSURER: NTUC INCOME INSURANCE CO-OPERATIVE LTD
POLICY NO: 5059040331-06
REFERENCE: TP CLAIM
DOA: 28/08/2019

REPAIR ESTIMATE

Est. No. : E19080006
Date : 29/08/2019
Vehicle Num. : SKE8713S
Make/Model : HONDA,CITY
Chassis/Eng# : MRHGM25509P020070
Yr. of Manu : 2009

No	Description	Qty	U/P	Amt
17	To Dismantle and Replace Reverse Sensor	1.00	120.00	120.00
18	To Dismantle and Replace Bootlid Inner Lock	1.00	60.00	60.00

Amt S\$ 1,780.00

Discount (0.00%) S\$ 0.00

Subtotal S\$ 1,780.00

LKK Auto Cons: ... please notify
the Repairer of ...
• To resurvey be ...
• To display del ...
• Parts prices: ...
• Third party ...
... (s) must be resurveyed and
... approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

9 - 15648

S.N - 200

L - 1560

3416.48

2733



Joo Hak Kee Auto Pte. Ltd.

LIST ITEMS Subtotal S\$ 1,873.04
SPECIAL NETT ITEMS Subtotal S\$ 350.00
LABOUR Subtotal S\$ 1,780.00
Total S\$ 4,003.04

BLK 3007 UBI ROAD 1 #01-406, SINGAPORE 408701
BLK 3014 UBI ROAD 1 #01-324, SINGAPORE 408702

TEL: 6743 1913 FAX: 6743 5234
EMAIL: admin@jhk.com.sg

CO/GST REG NO: 201300082W
WEBSITE: www.jhk.com.sg

bizSAFE₃

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119015284/USF3N2

Date: 06/09/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SN3049941900	
Claimant Vehicle No :	SKE8713S	Insured Vehicle No :	CB7421B	
Date of Loss:	28/08/2019	Nature of Claim:	TP	Claim No: SNM19D204043C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKE8713S	Engine No:	L15A71804670
Make & Model:	HONDA CITY, 1.5 (A)	Chassis No:	MRHGM25509P020070
Reg. Date:	11/04/2012 (Man. Year: 2009)	Odometer:	108250 km
Colour:	Silver		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,223.04	1,856.48	366.56	16.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,780.00	1,560.00	220.00	12.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,003.04	3,416.48	586.56	14.65
Approved Total (Overridden) (\$\$)		2,700.00		
(\$\$)	4,003.04	2,700.00	1,303.04	32.55
+ GST 7.00/7.00% (\$\$)	280.21	189.00	91.21	32.55
Nett Amount (\$\$)	4,283.25	2,889.00	1,394.25	32.55

INSPECTION

Date of Assignment:	29/08/2019	Inspected At:	Joo Hak Kee Auto Pte Ltd (HQ)
Date Inspected:	29/08/2019		Blk 3007 Ubi Road 1, #01-406
			Singapore 408701

Estimated Period of Repair: 5.0 days**Adjuster:** MARCUS CHUA**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 05 Sep 2019)
Parts: 143	HONDA CITY 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKE8713S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	463.70 FL	*463.70 FL
2	2		*REAR BUMPER SIDE RETAINER	Bent	29.60 FL	*29.60 FL
3	2		*TAILLAMP	Cracked	411.40 FL	*411.40 FL
4	1		*BOOTLID	Dented/Buckled	503.90 FL	*503.90 FL
5	1		*BOOTLID CHROME GARNISH	Cracked	74.40 FL	*74.40 FL
6	2		*BOOTLID HINGE	Repair	128.60 FL	*- FL
7	1		*BOOTLID INNER LOCK	Twisted	56.80 FL	*56.80 FL
8	1		*BOOTLID LOGO EMBLEM	Necessary	17.80 FL	*17.80 FL
9	1		*BOOTLID CITY EMBLEM	Necessary	16.20 FL	*16.20 FL
10	1		*BOOTLID I-VTEC EMBLEM	Necessary	22.20 FL	*22.20 FL
11	1		*REAR END PANEL	Badly Dented	399.30 FL	*333.60 FL
12	1		*REAR END PANEL TOP GARNISH	Twisted	66.60 FL	*66.60 FL
13	1		*BOOTLID RUBBER	Twisted	150.80 FL	*74.40 FL
14	1		*SET REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,691.30	2,270.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	468.26	414.12
Total Parts (\$\$)	2,223.04	1,856.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ON NECESSARY DAMAGED PART	New	800.00	700.00
2	TO SAND DOWN,PUTTY AND SPRAY PAINT ON NECESSARY DAMAGED PART	New	800.00	750.00
3	TO DISMANTLE AND REPLACE REVERSE SENSOR	New	120.00	50.00
4	TO DISMANTLE AND REPLACE BOOTLID INNER LOCK	New	60.00	60.00
Gross Labour Cost (S\$)			1,780.00	1,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >