



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: AXA INSURANCE PTE LTD	Document No.	: SQT19004162	Page	1
	8 SHENTON WAY	Date	: 23. Sep 2019		
	#27-01 AXA TOWER	Customer No.	: WZA006		
	SINGAPORE 068811	Svc Advisor	:		
Registration No	: SKQ7665R	Engine No	: L15B73625180		
Chassis No	: MRHFC1660JT000287	Date Time	: 23. Sep 2019 8:59:55 AM		
Model	: CIVIC 1.5 TURBO VTIS YM2018	Surveyor Name	:		
Owner's Name	: SOH JUNQIANG	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 22/8/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:SOH JUNQIANG						
	OWNER INSURER:AVIVA LTD						
	ACC DATE:22/08/2019						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:AXA INSURANCE						
	TP VEH:SDV 8059 X						
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) b1 ✓	1	45.00		45.00	3.15	48.15
71101-TEA-T00ZZ	FACEFR.BUMPER de	1	579.90	25	434.92	30.44	465.36
71102-TBA-A00	GRILLE, FR.BUMPER LOWER X	1	69.70	25	52.27	3.66	55.93
71130-TEA-T00	BEAM COMPFR.BUMPER ?	1	345.90	25	259.42	18.16	277.58
71193-TEA-T01	SPACERR.FR.BUMPER SIDE ne	1	10.40	25	7.80	0.55	8.35
71198-TEA-T01	SPACERL.FR.BUMPER SIDE ne	1	10.40	25	7.80	0.55	8.35
91505-TM8-003	CLIP,BUMPER ne	16	2.30	25	27.60	1.93	29.53
71121-TEA-T02	BASE,FR.GRILLE CHROME ?	1	79.90	25	59.92	4.19	64.11
71124-TEA-T01	EXTENSION ASSYR.FR.GRILLE X	1	85.60	25	64.20	4.49	68.69
71129-TEA-T01	EXTENSION ASSYL.FR.GRILLE X	1	85.60	25	64.20	4.49	68.69
71125-TEA-T01	MOLDINGFR.GRILLE ?	1	100.40	25	75.30	5.27	80.57
75700-TBA-A00	EMBLEM ?	1	15.00	25	11.25	0.79	12.04
90301-ST0-003	NUTPUSH 3MM ?	2	2.10	25	3.15	0.22	3.37
Sum Item					1112.83	77.89	1,190.72
BOSUN	SUNDRIES	1	100.00	30	100.00	7.00	107.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	380.00	280	380.00	26.60	406.60
BKBU01R	REMOVE & RENEW FR BUMPER INCLUDING FITTINGS ON	1	1500.00	560	1500.00	105.00	1605.00

Printed on 23/9/2019 9:05:45 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: AXA INSURANCE PTE LTD	Document No.	: SQT19004162	Page	2
	: 8 SHENTON WAY	Date	: 23. Sep 2019		
	: #27-01 AXA TOWER	Customer No.	: WZA006		
	: SINGAPORE 068811	Svc Advisor	:		
Registration No	: SKQ7665R	Engine No	: L15B73625180		
Chassis No	: MRHFC1660JT000287	Date Time	: 23. Sep 2019 8:59:55 AM		
Model	: CIVIC 1.5 TURBO VTIS YM2018	Surveyor Name	:		
Owner's Name	: SOH JUNQIANG	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 22/8/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BP02R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (2P)	1	1000.00	450	1000.00	70.00	1070.00
Sum Labor					2980.00	208.60	3,188.60

Survey By	<u>Fasur</u>	Total Amount	4,092.83	286.49	4,379.32
Date & Time	<u>23/09/19 @ 1055</u>	Total (Inclusive of GST)			<u>4,379.32</u>
Excess					
Status					
Signature	<u>[Signature]</u>				

3 days
Resy before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Printed on 23/9/2019 9:05:45 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.