

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 2 September 2019

To : LKK

By Fax: 6256-4315

Attn : Bryan Ang

Tel: 97237799

VEHICLE NO : FW 7741G

Honda Wave 125S

ACCIDENT DATE: 19 August 2019

	<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>	
1	Rear Tail Lamp - broken	1	125.00	✓
2	Pillion Bar - cut	1	85.00	✓
3	Rear Reflection - cracked	1	135.00	✓
4	Rear Mudguard - broken	1	195.00	✓
5	Swing Arm - BT	1	320.00	✓
6	Shock Absorber - 2 destroyed	1	390.00	✓
7	Rear Rim - 2 destroyed	1	280.00	✓
8	Exhaust Pipe - Leovince ✓ cut/rst	1	560.00	✓
9	Wheel Hub 2 Dam	1	95.00	✓
10	Rear LH Footrest ✓ cut	1	65.00	✓
11	Footrest Bracket ✓ cut	1	95.00	✓
12	Front Footrest ✓ rst	1	68.00	✓
13	Footrest Rubber ✓ cut	1	65.00	✓
14	Handle Bar NN	1	98.00	X
15	Meter Cover ✓ broken	1	105.00	✓
16	Mirror - broken	1 set	130.00	✓
17	Head Lamp - cut	1	380.00	✓
18	Head Lamp Cover ✓ cut	1	165.00	✓
19	Throttle Grip ✓	1	85.00	✓
20	Front LH Side Panel ✓ cut	1	95.00	✓
21	Fork Tube X NN	1 set	360.00	X
22	Front LH Signal ✓ cut	1	90.00	✓
23	Front Centre Panel ✓ broken	1	95.00	✓

Sub-Total	4,081.00
Less 10%	408.10
Sub-Total	3,672.90

[illegible]

VEHICLE NO : FW 7741G

Honda Wave 125S

Nett Items

- | | | |
|---|--|-------------------------|
| 1 | Rear number plate <i>broken</i> | 15.00 ✓ |
| 2 | Towing Fee <i>Nil</i> | 40.00 X |
| 3 | Remove & replace parts, align & etc | 320.00 150/- |
| 4 | Supply body decal sticker | 120.00 80/- |
| 5 | Remove replace rear rim, swing arm, shock absorber, sprocket chain - wheel tub | 220.00 180/- |

Special Nett Items

- | | | |
|---|----------------------|----------|
| 1 | Meter Assy <i>NN</i> | 380.00 X |
|---|----------------------|----------|

Sub-Total 1,095.00

Nett Total 4,767.90

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion. Thank you

SG 98 MOTOR PTE LTD

29/08/2019 @ 1800m
Nett Amount
2/sum 4 days.
ya
LKK Auto

LKK Auto Consultants hence notify the Repaire of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Acknowledged by Repaire
Signature:
Date: