

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29

Kaki Bukit Autohub, Singapore 417921

Tel No. : 67461515 / 67471787 Fax No. : 67485015

Website : www.successunited.com.sg

Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd

AIG Building

78 Shenton Way, #07-16

Singapore 079120

Attention : Motor Claim Department

Contact : 64191053 Fax No. : 68357416

Estimate : TP19-108

Date : 20/08/2019

Vehicle Num. : SGQ3306B

Make/Model : Toyota Wish-2006

Chassis/Eng# : ZNE100345827/1ZZ2796768

Accident Date : 17/08/2019

Claim No. :

Reference :

Policy No. : (10/01/2020)

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1 pc	Rear Boot Lid <i>Ren</i>		1,517.45 +
2.	1 pc	Rear Boot Lid Weatherstrip <i>3rd plan</i>		571.85 +
3.	1 pc	Rear Boot Lid Mechanism Lock <i>new</i>		651.60 +
4.	1 pc	Rear No. Plate Lamp Garnish <i>new</i>		475.35 +
5.	1 pc	Rear Boot Lid Toyota Logo <i>new</i>		151.54 +
6.	1 pc	Rear Windscreen Moulding <i>new</i>		247.15 +
7.	1 pc	Rear Lamp LH <i>new</i>		581.90 +
8.	2 pcs	Rear Boot Damper L/R <i>new</i>	274.51	549.02 +
9.	1 pc	Rear Bumper Assy <i>new</i>		584.50 +
10.	10 pcs	Rear Bumper Clips <i>new</i>	12.40	124.00 +
11.	2 pcs	Rear Bumper Side Holder L/R <i>new</i>	179.80	359.60 +
12.	2 pcs	Rear Bumper Bracket L/R <i>2H Best</i>	182.54	365.08 +
13.	1 pc	Rear Bumper Reflector Lamp <i>new</i>		175.50 +
14.	1 pc	Rear End Panel <i>Dented</i>		835.13 +
List TotalS\$:				7,189.67
25.00% Discount S\$:				1,797.42
				5,392.25

1514.50
1135.87

590

SPECIAL NETT ITEMS :				
1.	1 pc	Rear Windscreen Sealant <i>new</i>		40.00 +
2.	1 pc	Rear No. Plate w/Frame <i>new</i>		45.00 +
3.	1 set	Reverse Sensor <i>Damaged</i>		280.00 +
Special Nett Total S\$:				365.00

200

LABOUR :

To remove, rearrange electrical wirings, check lighting

80.00 30

To remove, instal rear windscreen

200.00 +

CONTINUE / ...

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29

Kaki Bukit Autohub. Singapore 417921

Tel No. : 67461515 / 67471787 Fax No. : 67485015

Website : www.successunited.com.sg

Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd

AIG Building

78 Shenton Way, #07-16

Singapore 079120

Attention : Motor Claim Department

Contact : 64191053 Fax No. : 68357416

Estimate : TP19-108

Date : 20/08/2019

Vehicle Num. : SGQ3306B

Make/Model : Toyota Wish-2006

Chassis/Eng# : ZNE100345827/1ZZ2796768

Accident Date : 17/08/2019

Claim No. :

Reference :

Policy No. : (10/01/2020)

S/N	Quantity	Particular	Unit Price	Amount S\$
		To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident		1,200.00 600
		To putty and respray painting on affected area.	1230	1,000.00 600
		Labour Total S\$:		2,480.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total S\$: 8,237.25

=====

SUCCESS UNITED PTE LTD

Supplementary: 668.75
Total: 3234.62
L/S: 2.6K
0.5K

Adrian L
L/S 28/08/19.
04-05Kms.

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29
Kaki Bukit Autohub, Singapore 417921
Tel No. : 67461515 / 67471787 Fax No. : 67485015
Website : www.successunited.com.sg
Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way, #07-16
Singapore 079120
Attention : Motor Claim Department
Contact : 64191053 Fax No. : 68357416

Supplementary Estimate : TP19108S

Date : 02/09/2019
Vehicle Num. : SGQ3306B
Make/Model : Toyota Wish-2006
Chassis/Eng# : ZNE100345827/1ZZ2796768
Accident Date : 17/08/2019
Claim No. :
Reference : SGJ3887C
Policy No. : (10/01/2020)

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1 pc	LIST ITEMS : Rear Exhaust Silencer Box Assy <i>Bent.</i>	<i>785</i>	<i>785</i> 1,129.80
		List TotalS\$:	<i>785</i>	1,129.80
		25.00% Discount S\$:	<i>588.75</i>	282.45
				847.35
		LABOUR : To remove, replace rear exhaust silencer & re-align		80.00 ✓
		Labour Total S\$:		80.00

Supplementary : 668.75

Total S\$: 927.35
=====

SUCCESS UNITED PTE LTD