

Merimum

ASSIGNMENT

From:

Date:

29/8/2019

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: 8FQ3134S

at Workshop m/s

premium

of

55 Ubi Road 1

Insured:

Policy No.

2100381328

Claims No.

594373883256

Sup. Insured:

Excess:

800 01/9/19

18K

(Client's Record)

Make of Veh:

10 (am)

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05/8/19

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SFQ3134S

Yr Regn:

2014, July.

Type: ☒ M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A6

C.C.

1984

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

98066

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WAU2224 G3EN085139

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 225/55R17.

R: 225/55R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

29/08/19.

Survey held at

Premium.

Des. of Damages: ☒ Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	OD AIG.
	SFQ 3134S - cs/mcg 17016056/ Aqf362
	2019 - 21/03/2017
29/8/19 @ 10.08am	revert to Victor via Merimum.
	MV : 82K
	PV : 613K
	Nett : 20MK
30/8/19 @ 4.35pm	Victor informed c/a via merimum.
01/9/19 @ 9.37am	Informed Syafiq c/a to ex: 800 by email.

Date/Time, File Pass to?

☐

Preli. Report

1) 18/12 2019

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Wheel and (\$)

Survey Fee:

Transportation:

S + RS \$

Flake

Other:

TOTAL

Report Format:

MER-OD

Lump Sum / L.R. (\$)

13702.40

200

11

211

RECEIVED 19 DEC 2019

017 Arg vehicle: SFQ 31345 DOA: 23/08/2019.

01/11/19 @ 2.49pm confirmed with Mr BOO final fig £ 13102.40, 5 days.
(Red £ 13859.60, 51%)

-Nivitha (LKK Auto)

From: Claims <claims@premiumauto.com.sg>
Sent: Saturday, 24 August 2019 11:28 AM
To: 'Admin A'; 'Admin-D (LKKAuto)'; 'SUR'
Cc: 'Claims'
Subject: OD CLAIM FOR SFQ 3134 S ON 23/8/2019
Attachments: SFQ 3134 S - 23082019.PDF; SAftersales19082411320_0001.jpg; SAftersales19082411320_0002.jpg

Dear All,

Kindly register OD claims for this vehicle. Attached is GIA report for your reference.

We will forward you the estimate once is available.

Please arrange survey on 29/8/2019, 10am. Owner waiting

Best Regards,
Syafiq
Claims Admin Assistant

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 1 November 2019 2:49 PM
To: Boo seng yak; SUR; Carrine Leong; Chang Chee Sing;
jiayee.yap@premiumauto.com.sg
Subject: RE: FINAL REVISION - SFQ3134S - OD AIG - SURVEYED 29 AUG 19

Dear Mr Boo,

WITHOUT PREJUDICE

Confirm final fig \$13,102.40 before excess \$800.00 & GST and 5 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Wednesday, 30 October 2019 5:34 PM
To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; Chang Chee Sing <claims@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg
Subject: FINAL REVISION - SFQ3134S - OD AIG - SURVEYED 29 AUG 19

Hi Adrian and all,

Revised estimate and photographs attached.

Please confirm repair cost of \$13,102.40 @ 5 days of repairs.

Your early closure is well appreciated.

Best regards - jb

Claim Audit

AUDIT TRAIL					By
No.	On	Audit	Remarks		
1	24 Aug 2019 11:18	Cim Veh Model Changed			[I] Merimen Administrator
2	24 Aug 2019 11:18	Cim Created	Reg No: SFQ3134S, Policy No: 2100381328-05, Acct Date: 2019/08/23, Claim Type: SC, Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG), Ins.Status => Notification, Created from SAS:MPA119111508		[I] Merimen Administrator
3	26 Aug 2019 16:03	Cim Registration Modified	Acct Time:18:50:00->18:00:00, Pol No:2100381328-05->2100381328, Init.Est.:>5,000 - 6,000.		[I] Tong, WahXin
4	26 Aug 2019 16:03	Cim Veh Model Changed	(204806) AUDI A6 1.8 TFSI S-tronic (A).		[I] Tong, WahXin
5	30 Aug 2019 08:58	Cim Registration Modified	Setl.Type:3->0, Claim Type:SC->OD.		[I] LEE SU THING
6	30 Aug 2019 08:58	Adj Cim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)		[I] LEE SU THING
7	30 Aug 2019 08:58	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):		[A] LEE SU THING
8	30 Aug 2019 08:58	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/09/10		[A] LEE SU THING
9	30 Aug 2019 08:58	Adj Mandate Set	Approved:8000.00,Reinsp:Adj decides.		[A] LEE SU THING
10	30 Aug 2019 08:58	Cim Registration Modified	Rep:1137->200611.		[A] LEE SU THING
11	30 Aug 2019 08:58	Cim Veh Model Changed	(204806) -> (201410) AUDI A6 2.0 TFSI MU (A).		[A] LEE SU THING
12	30 Aug 2019 08:58	Adj Adjuster Assigned	[None] -> ADRIAN LING		[A] LEE SU THING
13	30 Aug 2019 10:05	Adj Rpt Initiated			[A] SHIAU CHAN
14	30 Aug 2019 10:05	Cim Dtl Modified	JPJ Reg. Date: -> 2014/07/31.		[A] SHIAU CHAN
15	30 Aug 2019 10:05	Cim Details Notified			[A] SHIAU CHAN
16	30 Aug 2019 10:07	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/09/10		[A] SHIAU CHAN
17	30 Aug 2019 10:08	Adj Mandate Request	Cur.Req:10554.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.		[A] SHIAU CHAN
18	30 Aug 2019 16:08	Cim Registration Modified	Excess: -> 800.00, 2F Remarks: -> Not Applicable, GST: -> 7.00.		[I] Nadaraja, Deeban
19	30 Aug 2019 16:08	Label Added	(20226):Coverage Confirmed.		[A] Merimen Administrator
20	30 Aug 2019 16:35	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/09/10, Mandate Remarks: Re-inspection to be done for damage check and supplementary items / labour.		[I] Koh, Victor-CK
21	30 Aug 2019 16:35	Adj Mandate Set	Approved:10554.00:Re-inspection to be done for damage check and supplementary items / labour, Reinsp:Yes.		[I] Koh, Victor-CK
22	31 Oct 2019 15:40	Adj Mandate Request	Cur.Req:13102.40:KINDLY APPROVE REPAIR COST OF \$13,102.40.		[A] SHIAU CHAN
23	01 Nov 2019 14:33	Adj Next Rpt Changed	Cur Rpt:Final Rpt, Cur Due Date:2019/09/10, Mandate Remarks:		[I] Koh, Victor-CK
24	01 Nov 2019 14:33	Adj Mandate Set	Approved:13102.40:		[I] Koh, Victor-CK

Date From Date To Audit Type None Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No.	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2262867	30 Aug 2019 10:05:31	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SFQ3134S		11.77

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Monday, 2 September 2019 9:37 AM
To: Claims; SUR
Subject: RE: OD CLAIM FOR SFQ 3134 S ON 23/8/2019

Dear Syafiq,

As instructed by our client, please proceed to repair the insured vehicle **SFQ 3134S (Excess \$800/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewse@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>
Sent: Tuesday, 27 August 2019 3:09 PM
To: Admin A <admin-a@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Claims' <claims@premiumauto.com.sg>
Subject: RE: OD CLAIM FOR SFQ 3134 S ON 23/8/2019

Dear all,

Attached is the estimate for your kind reference.

Best Regards,

Syafiq

Claims Admin Assistant

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Claim Audit

AUDIT TRAIL

No.	On	Audit	Remarks	By
1	24 Aug 2019 11:18	Cim Veh Model Changed		[] Merimen Administrator
2	24 Aug 2019 11:18	Cim Created	Reg No: SFQ3134S, Policy No: 2100381328-05, Acct Date: 2019/08/23, Claim Type: SC, Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG), Ins.Status => Notification. Created from SAS:MPA119111508	[I] Merimen Administrator
3	26 Aug 2019 16:03	Cim Registration Modified	Acct Time:18:50:00->18:00:00. Pol No:2100381328-05->2100381328, Init.Est.->5,000 - 6,000.	[I] Tong, WahXin
4	26 Aug 2019 16:03	Cim Veh Model Changed	(204806) AUDI A6 1.8 TFSI S-tronic (A).	[I] Tong, WahXin
5	30 Aug 2019 08:58	Cim Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] LEE SU THING
6	30 Aug 2019 08:58	Adj Cim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] LEE SU THING
7	30 Aug 2019 08:58	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] LEE SU THING
8	30 Aug 2019 08:58	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/09/10	[A] LEE SU THING
9	30 Aug 2019 08:58	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] LEE SU THING
10	30 Aug 2019 08:58	Cim Registration Modified	Rep:1137->200611.	[A] LEE SU THING
11	30 Aug 2019 08:58	Cim Veh Model Changed	(204806) -> (201410) AUDI A6 2.0 TFSI MU (A).	[A] LEE SU THING
12	30 Aug 2019 08:58	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] LEE SU THING
13	30 Aug 2019 10:05	Adj Rpt Initiated		[A] SHIAU CHAN
14	30 Aug 2019 10:05	Cim Dtl Modified	JPJ Reg. Date: -> 2014/07/31.	[A] SHIAU CHAN
15	30 Aug 2019 10:05	Cim Details Notified		[A] SHIAU CHAN
16	30 Aug 2019 10:07	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2019/09/10	[A] SHIAU CHAN
17	30 Aug 2019 10:08	Adj Mandate Request	Cur.Req:10554.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
18	30 Aug 2019 16:08	Cim Registration Modified	Excess: -> 800.00, 2F Remarks: -> Not Applicable, GST: -> 7.00.	[I] Nadaraja, Deeban
19	30 Aug 2019 16:08	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
20	30 Aug 2019 16:35	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2019/09/10. Mandate Remarks: Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK
21	30 Aug 2019 16:35	Adj Mandate Set	Approved:10554.00:Re-inspection to be done for damage check and supplementary items / labour. Reinsp:Yes.	[I] Koh, Victor-CK

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2262867	30 Aug 2019 10:05:31	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SFQ3134S		11.77

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 30 Aug 2019

Preliminary Advice

Vehicle No	: SFQ3134S	Accident Date	: 23/08/2019
Make	: AUDI A6	Policy No.	: 2100381328
Assignment Date	: 30/08/2019	Excess	: S\$0.00
Date of Inspection	: 29/08/2019	Est. Duration of Repair	: 4.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	26,485.00
Revised Amount	:S\$	9,147.00
Check Items (Estimated)	:S\$	1,407.00
Total	:S\$	10,554.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	82,000.00
COE / PARF Rebate	:S\$	61,264.00
Salvage Value	:S\$	
Margin for Repair	:S\$	20,736.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	182J

Vehicle Details

Vehicle No.:	SFQ31345
Vehicle to be Exported:	Yes
Intended Deregistration Date:	29 Aug 2019
Vehicle Make:	AUDI
Vehicle Model:	A6 2.0 TFSI MU
Primary Colour:	Black
Manufacturing Year:	2013
Engine No.:	CDN390154
Chassis No.:	WAUZZZ4G3EN085139
Maximum Power Output:	132.0 kW (177 bhp)
Open Market Value:	\$39,172.00
Original Registration Date:	31 Jul 2014
First Registration Date:	31 Jul 2014
Transfer Count:	0
Actual ARF Paid:	\$41,841.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Jul 2024
PARF Rebate Amount:	\$29,288.00

Intended COE Rebate Details

COE Expiry Date:	30 Jul 2024
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$65,002.00
COE Rebate Amount:	\$31,976.00
Total Rebate Amount:	\$61,264.00

The information contained herein is correct as at 29 Aug 2019

OK

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

31 Aug - 1 Sep 2019
DOWNTOWN EAST
10am to 6pm

GREAT PRICES. BETTER CARS. COE Renewed Cars

• \$0 Down payment • Low Monthly Installments • 1 Year Warranty • 100% Approvals

C S M O
AUTOMOBILES

DEALS starting from as low as **\$450 /month**

FOR SALE BY OWNER

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

2016 BMW 116d, PML Serviced, Price \$71.8k Neg.

Owner Going Overseas, Priced To Sell!
Direct Owner StarAd

HIN LUNG AUTO
Ho Bee Garage

One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars

30 years
of car sale

Browse by Category Save Search Print Sort by Date Posted 20 results/page

3 vehicles Search Audi A6 Advanced Search Search View All

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Search Selection	Audi A6	Any	Any	2014	Any	Any	Any	Available
	☐ Audi A6 2.0A TFSI MU Graded B by STA	\$84,800	\$12,680 /yr	30-Sep-2014	1,984 cc	64,000 km	Luxury	Available
Probably The Best One Owner 2014 A6. STA Evaluation Done. Just Servicing With Wear And Tear Repaired With Receipts. Super Smooth, Powerful Yet Quiet Engine. The A6 Equivalent To E200 With A Depreciation Of Only \$12K Per Year. High Residue Value. Comes With Fr...								
	☐ Audi A6 2.0A TFSI MU	\$86,800	\$12,880 /yr	28-Oct-2014	1,984 cc	70,000 km	Luxury	Available
STA Certified 100% Accident-Free, New Road Tax. Ceramic Coated, 6 Months Warranty Engine And Transmission. Highest Trade-In. Standard Bank Loan, Balloon Loan, In-House Loan. 100% Loan Available. Test Drive Today.								
	☐ Audi A6 2.0A TFSI MU	\$87,800	\$12,820 /yr	28-Nov-2014	1,984 cc	-	Luxury	Available
FIRE SALES! Price Reduced By \$3k! 1 Owner Only. Trade-In/Loan/Cash Deal Are Welcomed!								

Save this search criteria, to get email alerts whenever a match is found. Save Search

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart.com is a comprehensive marketplace for buying and selling cars in Singapore. We offer a wide range of cars for sale, from new cars to used cars, and we provide a secure and reliable platform for buyers and sellers. Our website is easy to use and offers a variety of features to help you find the car you are looking for. We also provide a range of services, including car financing, insurance, and maintenance. sgCarMart.com is the go-to website for anyone looking to buy or sell a car in Singapore.

sgCarMart.com is a registered company in Singapore. We are committed to providing a high-quality service to our customers and to ensuring that all transactions are carried out in a secure and reliable manner. We are also committed to providing accurate and up-to-date information to our customers. sgCarMart.com is a member of the Singapore Automobile Association (SAA) and is a member of the Singapore Motor Vehicle Association (SMVA).

Follow sgCarMart.com



About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement

©2004-2019 sgCarMart. All rights reserved.

sgCarMart.com

Compare [3]

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/08/2019 10:56
Date Of Accident	23/08/2019 18:50
Exact Location Of Accident	ALONG ECP AFTER STILL RD ENTRANCE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFQ3134S
Insured/Policyholder	
Name Of Registered Owner	ROBERT CHEW
NRIC No	S1252182J
Email Address	CHROBERTCHEW@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96887802
Alternative Phone No	OFFICE-62418583

Vehicle Particulars

Manufacturer	AUDI
Model	A6 C7 2.0 TFSI MU 4G
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100381328-05
Cover Note Number	

Driver

Name of Driver	ROBERT CHEW
NRIC No	S1252182J
Date Of Birth	19/07/1957
Occupation	INDOOR
Date Of Driving Pass	10/10/1983
Driving Experience	35 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96887802
Fax Number	
Contact Number	OFFICE-62418583
Email Address	CHROBERTCHEW@GMAIL.COM

Address 1B PALM AVENUE
 Postcode 456522
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

TRAFFIC JAM ALONG AYE, MCE, ECP DRIVING OVER AN HOUR ALONG LONG STRETCH OF MASSIVE JAM, SLOW TRAFFIC ALONG THE FINAL STRETCH ON TH WAY CLOSE TO HOME, TAXI IN FRONT SLOWED AND STOPPED COULD NOT STOP MY CAR IN TIME, HITTING TAXI FROM THE BACK

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHD2015D
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders



Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: July Fey
NRIC/ID No: 6207008

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

~~Accident~~ Traffic jam along AGE, MCE, ECP
 Driving over an hour along long
 stretch of massive jam, slow traffic.
 May be the first sketch on the way to
 close to home, taxi in front slowed
 or stopped, and ~~my car~~ could not
 stop stop my car in time, hitting
 taxi from the back

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:



Reporting Centre Personnel's Signature

Name: Tony [unclear]

NRA/Id No: 62042077

Accident Photo



Accident Photo



Accident Photo



Accident Photo



AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : CHEW ROBERT
 Period of Insurance : 31 Jul 2019 To 30 Jul 2020
 Engine No. : CDN390154
 Chassis No. : WAUZZZ4G3EN085139

Vehicle No. : SFO3134S
 Policy No. : 2100381328-05
 Endorsement No. :
 Issued Date : 24 Jun 2019

ABOUT THE COVER

Make/Model : AUDI A6 C7 2.0 TFSI MU
 Engine Capacity/Tonnage : 1,984.00 CC
 Driver Restriction : NA
 Sum Insured : Market Value
 Off Peak Car : No
 First Year of Registration : 2014
 Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1600cc - 2000cc Optional

* Limitations rendered inoperative by Section 6 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

CHEW ROBERT - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408899 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6336 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125219

PREMIUM LEASING - KATL
 281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
 SINGAPORE 159938
 Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

OUR AIG AUTO HOTLINE: +65 6338 6200

IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured in the accident:

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit Writ/Summons/Correspondences from third party(ies) to AIG immediately.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number **(65) 6419-3000** for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within **5** working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the **original** insurance policy and schedule issued by AIG, a copy of the Accident Report from **Audi Customer Service Centre** must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Popular Rent A Car Pte. Ltd.

Activation Hotline: 67428888

501 Guillemard Road Singapore 399840

Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc).

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is **IMPORTANT** and **MUST** be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

12

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP :65331

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1022/2019/NS
Date : 27-Aug-19

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Robert Chew
Address : 1B Palm Avenue
Singapore 456522
Telephone : HP +65 96887802
Type of Claim : Own Damage Claim
Policy No. : 2100381328-05
Vehicle No : **SFQ 3134 S**
Model Code : Audi A6 C7 2.0 TFSI MU 4G
Model / Year : Jul-14
Engine No : CDN 390154
Chassis No : WAUZZZ4G3EN085139
Mileage :
Date In :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 24-Aug-19
Place of Accident : Along ECP After Still Rd Entrance

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFQ 3134 S

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	✓
2	To dismantle and renew front bumper, bonnet and both headlights. To inspect front lock carrier. Re-organise crash management components. Reinstall all parts removed.	\$ 3,200.00	1750 1600
3	To respray front bumper and bonnet.	\$ 2,200.00	1100
4	To carry out diagnostic checks.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 6,072.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFQ 3134 S

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>cracked</i>	\$ 2,443.00	<i>x 1954.40 ✓</i>
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 249.00	<i>x</i>
3	FRONT BUMPER CLOSING ELEMENT	\$ 173.00	<i>x</i>
4	FRONT BUMPER SPOILER <i>new</i>	\$ 227.00	<i>x</i>
5	RADIATOR GRILLE <i>cracked</i>	\$ 1,227.00	<i>✓ 951.60</i>
6	RADIATOR GRILLE COVER <i>Not New</i>	\$ 33.00	<i>? x</i>
7	FRONT BUMPER FOAM FILLER PIECE <i>Not New</i>	\$ 90.00	<i>? x</i>
8	FRONT BUMPER SIDE REINFORCEMENT <i>Not New</i>	\$ 754.00	<i>? x</i>
9	FRONT BUMPER COVER <i>cracked</i>	\$ 112.00	<i>✓ 89.20</i>
10	FRONT BUMPER GUIDE PIECE - LH / RH <i>new 2H</i>	\$ 68.00	<i>+ 27.12 ✓</i>
11	FRONT BUMPER GRILLE - LH / RH <i>new</i>	2 \$ 278.00	<i>x</i>
12	FRONT BUMPER END CAP - LH	\$ 36.00	<i>x</i>
13	HEADLIGHT WASHER SYSTEM COVER CAP - LH / RH <i>new</i>	2 \$ 104.00	<i>x</i>
14	LIFT CYLINDER HOSE <i>new</i>	\$ 36.00	<i>x</i>
15	CAUTION SIGN <i>new</i>	NEC \$ 13.00	<i>✓ 9.76</i>
16	AIRCON STICKER <i>new</i>	NEC \$ 18.00	<i>✓ 14</i>
17	SIGNAL HORN - LH HIGH TONE <i>new</i>	\$ 168.00	<i>x</i>
18	SIGNAL HORN - RH LOW TONE <i>new</i>	\$ 262.00	<i>x</i>
19	SIGNAL HORN SPRING SHACKLE - LH / RH <i>new</i>	2 \$ 83.00	<i>x</i>
20	FRONT PARKING AID SENSOR - INNER <i>Not New</i>	2 \$ 419.00	<i>x</i>
SUB TOTAL SPARE PARTS		\$ 6,793.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFQ 3134 S

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	FRONT PARKING AID SENSOR - OUTER <i>Not Nec</i>	2 S	462.00 +
22	BONNET <i>Dented</i>	S	4,965.00 ✓ <i>3972</i>
23	BONNET ATTACHMENT PARTS <i>Not Nec</i>	S	130.00 ? X
24	BONNET SAFETY CATCH	S	127.00 ✓
25	BONNET LOCK BAR	2 S	90.00 ✓
26	BONNET CATCH HOOK	S	16.00 ✓
27	BONNET LID LOCK	2 S	391.00 +
28	MICRO SWITCH	2 S	133.00 +
29	BOWDEN CABLE - CENTRE	S	53.00 +
30	BONNET LID LOCK CABLE	S	67.00 +
31	MAIN BEAM HEADLIGHT MOUNTING - LH / RH <i>Not Nec</i>	2 S	214.00 +
32	GAS DISCHARGE LAMP HEAD LIGHT - LH / RH <i>RH only</i>	1 S	6,100.00 + <i>2440 ✓</i>
33	HEADLIGHT LIFT CYLINDER - LH / RH <i>RH Dented</i>	2 S	432.00 + <i>172.40 ✓</i>
34	FRONT NO. PLATE <i>Best</i>	S/N S	40.00 ✓
35	SUNDRIES <i>Not Nec</i>	S	400.00 ? X
TOTAL SPARE PARTS		:	\$ 20,413.00
TOTAL LABOUR CHARGES		:	\$ 6,072.00
GRAND TOTAL		:	\$ 26,485.00

All charges are not inclusive of GST.

16864.92

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 29/08/19
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 04 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/1022/2019/NS

24-Sep-19

Glory Tan

1 of 1

SFQ 3134 S

Audi A6 C7 2.0 TFSI MU 4G

Quantity	Description	Unit Price	Amount
----------	-------------	------------	--------

Parts

- | | | | |
|---|--|-----------|----------|
| 1 | Headlight compensating piece <i>OK</i> | \$ 77.00 | ✓ 61.12 |
| 2 | Headlight adjustment element <i>OK</i> | \$ 83.00 | ✓ 65.92 |
| 3 | Front fender brace RHS - Bent. | \$ 75.00 | ✓ 59.63 |
| 4 | Front wheel spoiler RHS <i>Done</i> | \$ 242.00 | ✓ 193.20 |

\$ 477.00

For 24/09/19

TOTAL

\$ 477.00

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFO 3134 S

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Repair car</i>	\$ 2,443.00	*
2	FRONT BUMPER FIXING PARTS <i>3 new</i>	\$ 249.00	*
3	FRONT BUMPER CLOSING ELEMENT	\$ 173.00	*
4	FRONT BUMPER SPOILER <i>new</i>	\$ 227.00	*
5	RADIATOR GRILLE <i>cracked</i>	\$ 1,227.00	✓
6	RADIATOR GRILLE COVER ?	\$ 33.00	?
7	FRONT BUMPER FOAM FILLER PIECE ?	\$ 90.00	?
8	FRONT BUMPER SIDE REINFORCEMENT ?	\$ 754.00	?
9	FRONT BUMPER COVER <i>cracked car</i>	\$ 112.00	✓
10	FRONT BUMPER GUIDE PIECE - LH / RH <i>new</i>	2 \$ 68.00	+
11	FRONT BUMPER GRILLE - LH / RH <i>2 new</i>	2 \$ 278.00	*
12	FRONT BUMPER END CAP - LH	\$ 36.00	*
13	HEADLIGHT WASHER SYSTEM COVER CAP - LH / RH <i>new</i>	2 \$ 104.00	*
14	LIFT CYLINDER HOSE <i>new</i>	\$ 36.00	+
15	CAUTION SIGN <i>2 new</i>	NEC \$ 13.00	✓
16	AIRCON STICKER <i>new</i>	NEC \$ 18.00	✓
17	SIGNAL HORN - LH HIGH TONE <i>2 new</i>	\$ 168.00	+
18	SIGNAL HORN - RH LOW TONE <i>2 new</i>	\$ 262.00	+
19	SIGNAL HORN SPRING SHACKLE - LH / RH <i>new</i>	2 \$ 83.00	+
20	FRONT PARKING AID SENSOR - INNER <i>2 new</i>	2 \$ 419.00	+
SUB TOTAL SPARE PARTS		: \$ 6,793.00	

OK
3/9

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFQ 3134 S

S/N	Parts Description	Damage Parts & Prices		REMARKS
		S/NETT		
21	FRONT PARKING AID SENSOR - OUTER <i>not new</i>	2	\$ 462.00	<i>x</i>
22	BONNET <i>Dented</i>		\$ 4,965.00	<i>✓</i>
23	BONNET ATTACHMENT PARTS <i>?</i>		\$ 130.00	<i>?</i>
24	BONNET SAFETY CATCH <i>?</i>		\$ 127.00	<i>x</i>
25	BONNET LOCK BAR	2	\$ 90.00	<i>x</i>
26	BONNET CATCH HOOK		\$ 16.00	<i>x</i>
27	BONNET LID LOCK <i>New</i>	2	\$ 391.00	<i>x</i>
28	MICRO SWITCH <i>New</i>	2	\$ 133.00	<i>x</i>
29	BOWDEN CABLE - CENTRE		\$ 53.00	<i>x</i>
30	BONNET LID LOCK CABLE		\$ 67.00	<i>x</i>
31	MAIN BEAM HEADLIGHT MOUNTING - LH / RH <i>3</i>	2	\$ 214.00	<i>x</i>
32	GAS DISCHARGE LAMP HEAD LIGHT - LH / RH <i>3</i>	2	\$ 6,100.00	<i>x</i>
33	HEADLIGHT LIFT CYLINDER - LH / RH <i>can</i>	2	\$ 432.00	<i>x</i>
34	FRONT NO. PLATE <i>Best</i>	S/N	\$ 40.00	<i>✓</i>
35	SUNDRIES <i>?</i>		\$ 400.00	<i>?</i>
TOTAL SPARE PARTS		:	\$ 20,413.00	
TOTAL LABOUR CHARGES		:	\$ 6,072.00	
GRAND TOTAL		:	\$ 26,485.00	

All charges are not inclusive of GST.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP :65331

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/1022/2019/NS
Date : 27-Aug-19

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian

5 days - ok - jb - 30 Oct 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Robert Chew
Address : 1B Palm Avenue
Singapore 456522
Telephone : HP +65 96887802
Type of Claim : Own Damage Claim
Policy No. : 2100381328-05
Vehicle No : **SFQ 3134 S**
Model Code : Audi A6 C7 2.0 TFSI MU 4G
Model / Year : Jul-14
Engine No : CDN 390154
Chassis No : WAUZZZ4G3EN085139
Mileage :
Date In :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 24-Aug-19
Place of Accident : Along ECP After Still Rd Entrance

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SFQ 3134 S

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N	\$ 480.00	\$ 480.00
2	To dismantle and renew front bumper, bonnet and both headlights. To inspect front lock carrier. Re-organise crash management components. Reinstall all parts removed. (HL x 1)		\$ 3,200.00	\$ 1,250.00
3	To respray front bumper and bonnet.		\$ 2,200.00	\$ 1,100.00
4	To carry out diagnostic checks.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 6,072.00	\$ 3,022.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFQ 3134 S

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 2,443.00	\$ 1,954.40
2	FRONT BUMPER FIXING PARTS	\$ 249.00	
3	FRONT BUMPER CLOSING ELEMENT	\$ 173.00	
4	FRONT BUMPER SPOILER	\$ 227.00	
5	RADIATOR GRILLE	\$ 1,227.00	\$ 981.60
6	RADIATOR GRILLE COVER	\$ 33.00	
7	FRONT BUMPER FOAM FILLER PIECE	\$ 90.00	
8	FRONT BUMPER SIDE REINFORCEMENT	\$ 754.00	
9	FRONT BUMPER COVER	\$ 112.00	\$ 89.20
10	FRONT BUMPER GUIDE PIECE - LH / RH	2 \$ 68.00	\$ 27.12
11	FRONT BUMPER GRILLE - LH / RH	2 \$ 278.00	
12	FRONT BUMPER END CAP - LH	\$ 36.00	
13	HEADLIGHT WASHER SYSTEM COVER CAP - LH / RH	2 \$ 104.00	
14	LIFT CYLINDER HOSE	\$ 36.00	
15	CAUTION SIGN	NEC \$ 13.00	\$ 9.76
16	AIRCON STICKER	NEC \$ 18.00	\$ 14.00
17	SIGNAL HORN - LH HIGH TONE	\$ 168.00	
18	SIGNAL HORN - RH LOW TONE	\$ 262.00	
19	SIGNAL HORN SPRING SHACKLE - LH / RH	2 \$ 83.00	
20	FRONT PARKING AID SENSOR - INNER	2 \$ 419.00	
SUB TOTAL SPARE PARTS		\$ 6,793.00	\$ 3,076.08

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFQ 3134 S

S/N	Parts Description	c/f	Damage Parts & Prices		REMARKS
			S/NETT	\$	
					3,076.08
21	FRONT PARKING AID SENSOR - OUTER	2	\$	462.00	
22	BONNET		\$	4,965.00	\$ 3,972.00
23	BONNET ATTACHMENT PARTS		\$	130.00	
24	BONNET SAFETY CATCH		\$	127.00	
25	BONNET LOCK BAR	2	\$	90.00	
26	BONNET CATCH HOOK		\$	16.00	
27	BONNET LID LOCK	2	\$	391.00	
28	MICRO SWITCH	2	\$	133.00	
29	BOWDEN CABLE - CENTRE		\$	53.00	
30	BONNET LID LOCK CABLE		\$	67.00	
31	MAIN BEAM HEADLIGHT MOUNTING - LH / RH	2	\$	214.00	
32	GAS DISCHARGE LAMP HEAD LIGHT - LH / RH	2	\$	6,100.00	\$ 2,440.00
33	HEADLIGHT LIFT CYLINDER - LH / RH	2	\$	432.00	\$ 172.40
34	FRONT NO. PLATE	S/N	\$	40.00	\$ 40.00
35	<i>Added parts - see attached</i>		\$	477.00	\$ 379.92
36	SUNDRIES		\$	400.00	
TOTAL SPARE PARTS			\$	20,890.00	\$ 10,080.40
TOTAL LABOUR CHARGES			\$	6,072.00	\$ 3,022.00
GRAND TOTAL			\$	26,962.00	\$ 13,102.40

All charges are not inclusive of GST.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/1022/2019/NS 24-Sep-19 Glory Tan 1 of 1 SFQ 3134 S Audi A6 C7 2.0 TFSI MU 4G
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Headlight compensating piece	\$ 77.00	\$ 61.12
2	Headlight adjustment element	\$ 83.00	\$ 65.92
3	Front fender brace RHS	\$ 75.00	\$ 59.68
4	Front wheel spoiler RHS	\$ 242.00	\$ 193.20
		\$ 477.00	\$ 379.92
	TOTAL	\$ 477.00	\$ 379.92

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SFQ 3134 S

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1022/2019/NK

9 Dec 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SFQ 3134 S, Audi A6 C7 2.0 TFSI.

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

With reference to the above-mentioned vehicle, no. **SFQ 3134 S** claimant,
Mr. Robert Chew, please find the related document per attached.

1. A copy of the Original invoice no. 85014578 – S\$13,163.57.
2. A copy of the Discharge Voucher duly signed by client.

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SFQ 3134 S

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6366 2223
Main Teletax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6366 2223
Main Teletax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Teletax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 12:27

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014578 Date: 07/12/2019 Order: SFQ31348 Term: 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No: SFQ31348 (V 22395)	Regn Date: 31/07/2014	Mileage: 99359	WIP No.: 65331
Model: A6 C7 2.0 TFSI MU 4G207H (MY 1	Chassis: WAUZZZ4G3EN085139	Engine: CDN 390154	Dept: U
You have been assisted by :- UB-Tony Foong (33)			

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE	40.00	1.00	40.00
Q	EXC	M: 8888 Insurance Excess/Liability	-800.00	1.00	-800.00
S	BODYWORK	M: TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNES FOR HEADLIGHT,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	480.00	1.00	480.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER,BONNET AND RHS HEADLIGHT.TO INSPECT FRONT LOCK CARRIER.REORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	1250.00	1.00	1,250.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER AND BONNET	1100.00	1.00	1,100.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A4G0853651 T94	GRILLE(LAST) Less 020%	1.00	1227.00	981.60
X	A4G0941044D	HEADLAMP(LAST) AP Less 020%	1.00	3050.00	2,440.00
X	A4G0853888C	SPOILER AP Less 020%	1.00	241.50	193.20
X	A4G0807081	COVER Less 020%	1.00	111.50	89.20
X	A4G0823029A	HOOD Less 020%	1.00	4965.00	3,972.00
X	A4G0807065A GRU	COVER(LAST) AP Less 020%	1.00	2443.00	1,954.40
X	A4G0821136A	SUPPORT AP Less 020%	1.00	74.60	59.68
X	A8F7806305	SPACER AP Less 020%	2.00	38.20	61.12
X	A4G0807284	GUIDE AP Less 020%	1.00	33.90	27.12
X	A4F0941111	007449/(V) (SK)ADJUST Less 020%	2.00	41.20	65.92
X	A4G0955102B	(SK)CYLINDER AP Less 020%	1.00	215.50	172.40
X	A4G0010515	STICKER Less 020%	1.00	17.50	14.00
X	A8K0010520A	PLATE Less 020%	1.00	12.20	9.76

Parts 10,040.40
Labour 0.00
Sublet 3,062.00
Menus 0.00
Lubricant 0.00

Sub-Total 12,302.40

7% GST 861.17

Grand Total 13,163.57



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SFQ3134S

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1022/2019/TF
27 September 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages


RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A6 C7 2.0 TFSI MU
Vehicle Chassis No. : WAUZZZ4G3EN085139
Vehicle Regn No. : SFQ3134S
Vehicle Mileage : 99359KM
Vehicle Owner : Mr. Robert Chew
Certificate No : 2100381328-05
Own Damage Excess : \$856.00 (Inclusive 7% GST)
Accident Date : 23/08/2019
Place : Along ECP After Still Rd Entrance
Repair Cost : \$ 13,163.57
WIP No. : 65331
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159080
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time :
Date : 27/9

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Aug 2019		30 Aug 2019 08:58 Edit Adj Rpt	S\$13,102.40 Edit Estimates	S\$13,102.40 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	ROBERT CHEW, ID: S1252182J, Tel: +6596887802, Email: CHROBERTCHEW@GMAIL.COM								
Vehicle Reg. No.:	SFQ3134S	Date of Loss:	23/08/2019 18:00 - :59 [60 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 5943738832SG	Policy/Cover Note No.:	2100381328 (Comprehensive)						
		Excess:	S\$800.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Nadaraja, Deeban] Deeban.nadaraja.nadaraja@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 10/09/2019]								
Driver/Custodian:	ROBERT CHEW (62 / Male) , NRIC: S1252182J, Tel: +6596887802 Email: CHROBERTCHEW@GMAIL.COM								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (01/11/2019): Alert - Adj Mandate Approved (S\$13102.40) - SFQ3134S - Claim Handler: Nadaraja, ... - AIG_SG (30/08/2019): Alert - Adj Mandate Approved (S\$10554.00) - SFQ3134S - Claim Handler: Nadaraja, ... - AIG_SG (30/08/2019): SFQ3134S / OD / 23/08/2019 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SFQ31345 (5943738832SG)
 OD
 Aug 23 2019 6:00PM
 [ROBERT CHEW]
 Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Assessment Reports															1 per page		☒			
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print			
1	30/08/19 10:07	Adjuster Immediate Advice													 Load HTM					
Photos/Images															3 per page		☒			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print			
1	30/08/19 10:00	General View													 Load JPG		☒			
2	30/08/19 10:00	Chassis Number													 Load JPG		☒			
3	30/08/19 10:00	General View													 Load JPG		☒			
4	30/08/19 10:00	General View													 Load JPG		☒			
5	30/08/19 10:00	General View													 Load JPG		☒			
6	30/08/19 10:00	General View													 Load JPG		☒			
7	30/08/19 10:00	General View													 Load JPG		☒			
8	30/08/19 10:00	General View													 Load JPG		☒			
9	30/08/19 10:00	General View													 Load JPG		☒			
10	30/08/19 10:00	General View													 Load JPG		☒			
11	30/08/19 10:00	General View													 Load JPG		☒			
12	30/08/19 10:00	General View													 Load JPG		☒			
13	30/08/19 10:00	General View													 Load JPG		☒			
14	30/08/19 10:00	General View													 Load JPG		☒			
15	30/08/19 10:00	General View													 Load JPG		☒			
16	30/08/19 10:00	General View													 Load JPG		☒			
17	30/08/19 10:00	General View													 Load JPG		☒			
18	30/08/19 10:00	General View													 Load JPG		☒			
19	30/08/19 10:00	General View													 Load JPG		☒			
20	30/08/19 10:00	General View													 Load JPG		☒			
21	30/08/19 10:00	General View													 Load JPG		☒			
22	30/08/19 10:00	General View													 Load JPG		☒			
23	30/08/19 10:00	General View													 Load JPG		☒			
24	31/10/19 09:20	Reinspection Photo													 Load JPG		☒			
25	31/10/19 09:20	Reinspection Photo													 Load JPG		☒			
26	31/10/19 09:20	Reinspection Photo													 Load JPG		☒			
27	31/10/19 09:20	Reinspection Photo													 Load JPG		☒			
28	31/10/19 09:20	Reinspection Photo													 Load JPG		☒			
29	31/10/19 09:20	Reinspection Photo													 Load JPG		☒			
30	31/10/19 09:20	Reinspection Photo													 Load JPG		☒			
31	31/10/19 09:20	Reinspection Photo													 Load JPG		☒			
32	31/10/19 09:20	Reinspection Photo													 Load JPG		☒			
33	31/10/19 09:20	Reinspection Photo													 Load JPG		☒			
34	31/10/19 09:20	Reinspection Photo													 Load JPG		☒			
35	31/10/19 09:20	Reinspection Photo													 Load JPG		☒			
36	31/10/19 09:20	Reinspection Photo													 Load JPG		☒			
37	31/10/19 09:20	Reinspection Photo													 Load JPG		☒			
38	31/10/19 09:20	Reinspection Photo													 Load JPG		☒			
39	31/10/19 09:20	Reinspection Photo													 Load JPG		☒			
40	31/10/19 09:20	Reinspection Photo													Load JPG		☒			
41	31/10/19 09:20	Reinspection Photo													Load JPG		☒			

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
42	31/10/19 09:20	Reinspection Photo	 Load JPG	☒
43	31/10/19 09:20	Reinspection Photo	 Load JPG	☒
44	31/10/19 09:20	Reinspection Photo	 Load JPG	☒
45	31/10/19 09:20	Reinspection Photo	 Load JPG	☒
46	31/10/19 09:20	Reinspection Photo	 Load JPG	☒
47	31/10/19 09:20	Reinspection Photo	 Load JPG	☒
48	31/10/19 09:20	Reinspection Photo	 Load JPG	☒
49	31/10/19 09:20	Reinspection Photo	 Load JPG	☒
50	31/10/19 09:20	Reinspection Photo	 Load JPG	☒
51	31/10/19 09:20	Reinspection Photo	 Load JPG	☒
52	31/10/19 09:20	Reinspection Photo	 Load JPG	☒
53	31/10/19 09:20	Reinspection Photo	 Load JPG	☒
54	31/10/19 09:20	Reinspection Photo	 Load JPG	☒
55	31/10/19 09:21	Reinspection Photo	 Load JPG	☒
56	31/10/19 09:21	Reinspection Photo	 Load JPG	☒
57	31/10/19 09:21	Reinspection Photo	 Load JPG	☒
58	31/10/19 09:21	Reinspection Photo	 Load JPG	☒
59	31/10/19 09:21	Reinspection Photo	 Load JPG	☒
60	31/10/19 09:21	Reinspection Photo	 Load JPG	☒
61	31/10/19 09:21	Reinspection Photo	 Load JPG	☒
62	31/10/19 09:21	Reinspection Photo	 Load JPG	☒
63	31/10/19 09:21	Reinspection Photo	 Load JPG	☒
64	31/10/19 09:21	Reinspection Photo	 Load JPG	☒
65	31/10/19 09:21	Reinspection Photo	 Load JPG	☒
66	31/10/19 09:21	Reinspection Photo	 Load JPG	☒
67	31/10/19 09:21	Reinspection Photo	 Load JPG	☒
68	31/10/19 09:21	Reinspection Photo	 Load JPG	☒
69	31/10/19 09:21	Reinspection Photo	 Load JPG	☒
70	31/10/19 09:21	Reinspection Photo	 Load JPG	☒
71	31/10/19 09:21	Reinspection Photo	 Load JPG	☒
72	31/10/19 09:21	Reinspection Photo	 Load JPG	☒
73	31/10/19 09:21	Reinspection Photo	 Load JPG	☒
74	31/10/19 09:21	Reinspection Photo	 Load JPG	☒
75	31/10/19 09:21	Reinspection Photo	 Load JPG	☒
76	31/10/19 09:21	Reinspection Photo	 Load JPG	☒
77	31/10/19 09:21	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/08/19 09:59	Singapore Accident Statement	 Load PDF	
2	30/08/19 09:59	Certificate of Insurance	 Load PDF	
3	30/08/19 09:59	Driver's Driving License	 Load PDF	
4	30/08/19 09:59	ESTIMATE	 Load PDF	
5	31/10/19 15:39	REVISED ESTIMATE	 Load PDF	
6	06/01/20 10:12	Workshop Invoice	 Load PDF	
7	06/01/20 10:12	Discharge Voucher	 Load PDF	
8	06/01/20 10:16	Supplementary	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	04/09/19 02:32	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	24/08/19 11:13	Accident Photo	 Load JPG	☒

Assessment Reports				1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
2	24/08/19 11:13	Accident Photo		Load JPG	☒
3	24/08/19 11:13	Accident Photo		Load JPG	☒
4	24/08/19 11:13	Accident Photo		Load JPG	☒
5	24/08/19 11:13	Accident Photo		Load JPG	☒
6	24/08/19 11:13	Accident Photo		Load JPG	☒
7	24/08/19 11:13	Accident Photo		Load JPG	☒
8	24/08/19 11:13	Accident Photo		Load JPG	☒
9	24/08/19 11:13	Accident Photo		Load JPG	☒
10	24/08/19 11:13	Accident Photo		Load JPG	☒
11	24/08/19 11:13	Accident Photo		Load JPG	☒
12	24/08/19 11:13	Accident Photo		Load JPG	☒
13	24/08/19 11:13	Accident Photo		Load JPG	☒
14	24/08/19 11:13	Accident Photo		Load JPG	☒
15	24/08/19 11:13	Accident Photo		Load JPG	☒
16	24/08/19 11:13	Accident Photo		Load JPG	☒
17	24/08/19 11:13	Accident Photo		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	24/08/19 11:14	Sketch Plan		Load JPG	☒
2	24/08/19 11:14	Sketch Plan #2		Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19015325/AQF3E2

Date: 06/01/2020

REFERENCE

Insured/Claimant: ROBERT CHEW Policy No: 2100381328
Date of Loss: 23/08/2019 Nature of Claim: OD Claim No: 5943738832SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFQ3134S**
Make & Model: AUDI A6, 2.0 TFSI MU (A) Engine No: CDN390154
Reg. Date: 31/07/2014 (Man. Year: 2013) Chassis No: WAUZZZ4G3EN085139
Colour: Black Odometer: 98066 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$82,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17 Rear Tyre Size: 225/55 R17
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,792.92	10,080.40	10,712.52	51.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,072.00	3,022.00	3,050.00	50.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,864.92	13,102.40	13,762.52	51.23
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	26,064.92	12,302.40	13,762.52	52.80
+ GST 7.00/7.00% (S\$)	1,824.54	861.17	963.37	52.80
Nett Amount (S\$)	27,889.46	13,163.57	14,725.89	52.80

INSPECTION

Date of Assignment: 30/08/2019
Date Inspected: 29/08/2019 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Cracked	2,443.00 FS	*1,954.40 FS
2	1	*FRONT BUMPER FIXING PARTS	Not Necessary	249.00 FS	*- FS
3	1	*FRONT BUMPER CLOSING ELEMENT	Not Necessary	173.00 FS	*- FS
4	1	*FRONT BUMPER SPOILER	Not Necessary	227.00 FS	*- FS
5	1	*RADIATOR GRILLE	Cracked	1,227.00 FS	*981.60 FS
6	1	*RADIATOR GRILLE COVER	Not Necessary	33.00 FS	*- FS
7	1	*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	90.00 FS	*- FS
8	1	*FRONT BUMPER SIDE REINFORCEMENT	Not Necessary	754.00 FS	*- FS
9	1	*FRONT BUMPER COVER	Cracked	112.00 FS	*89.20 FS
10	1	*FRONT BUMPER GUIDE PIECE - LH/RH	O/S Necessary	68.00 FS	*27.12 FS
11	2	*FRONT BUMPER GRILLE - LH/RH	Not Necessary	278.00 FS	*- FS
12	1	*FRONT BUMPER END CAP - LH	Not Necessary	36.00 FS	*- FS
13	2	*HEADLIGHT WASHER SYSTEM COVER CAP - LH/RH	Not Necessary	104.00 FS	*- FS
14	1	*LIFT CYLINDER HOSE	Not Necessary	36.00 FS	*- FS
15	1	*CAUTION SIGN	Necessary	13.00 FS	*9.76 FS
16	1	*AIRCON STICKER	Necessary	18.00 FS	*14.00 FS
17	1	*SIGNAL HORN - LH HIGH TONE	Not Necessary	168.00 FS	*- FS
18	2	*SIGNAL HORN SPRING SHACKLE - LH/RH	Not Necessary	83.00 FS	*- FS
19	2	*FRONT PARKING AID SENSOR - INNER	Not Necessary	419.00 FS	*- FS
20	2	*FRONT PARKING AID SENSOR - OUTER	Not Necessary	462.00 FS	*- FS
21	1	*BONNET	Dented	4,965.00 FS	*3,972.00 FS
22	1	*BONNET ATTACHMENT PARTS	Not Necessary	130.00 FS	*- FS
23	1	*BONNET SAFETY CATCH	Not Necessary	127.00 FS	*- FS
24	2	*BONNET LOCK BAR	Not Necessary	90.00 FS	*- FS
25	1	*BONNET CATCH HOOK	Not Necessary	16.00 FS	*- FS
26	2	*BONNET LID LOCK	Not Necessary	391.00 FS	*- FS
27	1	*BOWDEN CABLE - CENTRE	Not Necessary	53.00 FS	*- FS
28	1	*BONNET LID LOCK CABLE	Not Necessary	67.00 FS	*- FS
29	2	*MAIN BEAM HEADLIGHT MOUNTING - LH/RH	Not Necessary	214.00 FS	*- FS
30	1	*GAS DISCHARGE LAMP HEAD LIGHT - LH/RH	O/S Cracked	6,100.00 FS	*2,440.00 FS
31	1	*HEADLIGHT LIFT CYLINDER - LH/RH	O/S Damaged	432.00 FS	*172.40 FS
32	1	*FRONT NO. PLATE	Bent	40.00 FS	*40.00 FS
33	1	*SUNDRIES	Not Necessary	400.00 FS	*- FS
34	1	*HEADLIGHT COMPENSATING PIECE	Cracked	61.12 FS	*61.12 FS
35	1	*HEADLIGHT ADJUSTMENT ELEMENT	Cracked	65.92 FS	*65.92 FS
36	1	*FRONT FENDER BRACE RHS	Bent	59.68 FS	*59.68 FS
37	1	*FRONT WHEEL SPOILER RHS	Damaged	193.20 FS	*193.20 FS
38	1	*SIGNAL HORN - RH LOW TONE	Not Necessary	262.00 FS	*- FS
39	2	*MICRO SWITCH	Not Necessary	133.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 20,792.92 10,080.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHTS. TO INSPECT FRONT LOCK CARRIER, RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	3,200.00	1,250.00
3	TO RESPRAY FRONT BUMPER AND BONNET.	New	2,200.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECKS.	New	192.00	192.00
Gross Labour Cost (\$\$)			6,072.00	3,022.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >