

## STUTTGÅRT AUTO PTE LTD 27A TANJONG PENJURU, SINGAPORE 609042 SUPPLEMENTARY



PORSCHE

China Taiping Insurance (S) Pte Ltd 3 Anson Rd, #16-00 Springleaf Tower,		NAME: Ms Ho Siew Lee		WIP: 49666		49666	
		ADDRESS:	89A Sommerville Estate Road		EXCESS:		
Singapore 079909			Sommerville Park		DATE:	31.08.2019	
ę.			Singapore 2580!	59			
ATTN.:	MOTOR CLAIMS	TEL:					
FAX:							
VEH NO:	SLH44P	DATE IN:		CONTACT PERSON:	EVA	6	3310683
CHASSIS NO: WP1ZZZ95ZFLB67269		MILEAGE :		TYPE OF CLAIM:	OD		
MODEL:	Macan S	DATE REG.:	13.03.2015	POLICY NO.:			
			NATURE OF WO	PRKS		3 1 1 1 1 1 1 1 1 1	
/NO		<u>Pa</u>	irts Description	*			
	QTY				REVISED	REVISED PRICES	
1 TOP PANEL	LOWER SUPPORT LHE 54		1	P95B-807-333- +		\$	44.8
2 BREATHER LINE (RADIATOR) 1 P95B-122-447-E -						\$	61.3
BUMPER WIRING HARNESS 1 P958-971-095-A-						\$	300.7
4 HEADLAMP BRACKET LH 61 P95B-941-451-C-						\$	39.1
5 TJOINT NO	ZZLE CAT		1	P958-955-875	\$ :	\$	26.0
86 BREATHER	LINE EXPANSION TANK	X/	1	P95B-122-447-C -		\$	39.1
	7077554						
				TOTAL PARTS		\$	511.0
LESS 10%						\$	51.1
				TOTAL PARTS COST		\$	459.9
		<u>Labour Descripti</u>	<u>on</u>				
		東. 一種	7	TOTAL LABOUR	\$	\$	
				TOTAL PARTS	\$ -	\$	459.90
		e.		TOTAL	\$ -	\$	459.90
				LESS EXCESS	\$ -	\$	
				TOTAL AFTER EXCESS	\$ -	5/4	
				GST 7%	\$ -	\$	
1. (A) 3. (A)					<del>                                      </del>	-	

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE

BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL

BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

\*DISCLAIMER

- 2 TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A
  QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED
  IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.
- 3 THIS IS ONLY AN ESTIMATE BASED ON PARTS AVAILABILITIES AT CURRENT LOCAL SINGAPORE WAREHOUSE. IF THERE IS A NEED TO INCLUDE AIRFREIGHT PARTS, WE WILL INFORM DULY.

GRAND TOTAL