

Adrian Merimen

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SME2447B
 at Workshop m/s Premium
 of SS Ubi Rd 1
 Insured: _____
 Policy No: 1800108691
 Claims No: _____
 Sum Insured: _____ Excess: \$500
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 250K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 13 hrs days Res: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SME2447B Yr Regn: 2018 / Sept
 Type: M.Capt / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi Q7 cc 1984
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading 12494 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAU2224M8J2050408

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255/55R19

R: 255/55R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 30/08/19

Survey held at: Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

07 A16

SME 2447B - X

30/8 Revet via Merimen

Request Mandate

MV:

PV:

Nett:

RECEIVED 10 MAR 2020

23/1/20 Confirm final fig \$6256-96
sent by email (Ref \$7,157-04
53%)

2/9 Approved Mandate by Victor Koh

2/9 Sent E-Mail inform Premium authorise and excess \$500

3 day

Date/Time, File Pass to?

Date/Time, File Return to?

1) 10/3/20

2) Typist

3) _____

4) _____

5) _____

6) _____

Print Report:

Final Report: PIP \$6256-96

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

— S + RS, — SI

Photos

Others

TOTAL

200

11

211

View Received Message

This mail is associated with :

***SME2447B (4364570311SG)**

OD

Aug 25 2019 11:00AM

[XINSHA HOLDING PTE LTD]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 02/09/2019 16:53 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$7032.00) - SME2447B - Claim Handler: Mithoo Singh, Aashweenjeet Kaur

Approved:7032.00:Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Monday, September 02, 2019 5:58 PM
To: Claims; SUR
Subject: OD CLAIM FOR SME 2447 B ON 25/8/2019

Hi : Syafiq

Dear Sir/ Mdm,

As instructed by our client, please proceed to repair the insured vehicle SME2447B (excess \$500/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonne.wong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [mailto:claims@premiumauto.com.sg]
Sent: Thursday, August 29, 2019 8:56 AM
To: Admin A <admin-a@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Claims' <claims@premiumauto.com.sg>
Subject: OD CLAIM FOR SME 2447 B ON 25/8/2019

Dear All,

Kindly register OD claim for this vehicle. Attached is the GIA report for your reference.

We will forward you the estimate once it is available.

Please arrange survey on 30/8/2019, 11am. Owner waiting.

Best Regards,
Syafiq

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 30 Aug 2019

Preliminary Advice

Vehicle No	: SME2447B	Accident Date	: 25/08/2019
Make	: AUDI Q7	Policy No.	: 1800108691
Assignment Date	: 30/08/2019	Excess	: S\$0.00
Date of Inspection	: 30/08/2019	Est. Duration of Repair	: 3.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages FRONT portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,414.00
Revised Amount	:S\$	7,032.00
Check Items (Estimated)	:S\$	2,137.00
Total	:S\$	9,169.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	250,000.00
COE / PARF Rebate	:S\$	84,070.00
Salvage Value	:S\$	
Margin for Repair	:S\$	165,930.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/08/2019 17:26
Date Of Accident	25/08/2019 11:15
Exact Location Of Accident	HAVELOCK RD TURNING TO CLEMENCEAU AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SME2447B
Insured/Policyholder	
Name Of Registered Owner	XINSHA HOLDING PTE LTD
Co Reg No	201331764G
Email Address	FOOKK@XINSHAHOLDING.COM
Mobile Phone No	(LOCAL) +65-96552323
Alternative Phone No	OFFICE-96552323

Vehicle Particulars

Manufacturer	AUDI
Model	Q7-2.0 TFSI QU (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800108691
Cover Note Number	

Driver

Name of Driver	RUI HONG
NRIC No	S7574505B
Date Of Birth	28/03/1975
Occupation	INDOOR
Date Of Driving Pass	18/02/2009
Driving Experience	10 YEARS AND 6 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96270458
Fax Number	
Contact Number	
Email Address	RUIHONG1@HOTMAIL.COM

Address BLK 6A BOON TIONG ROAD
#15-43
Postcode 164006
Was driver an employee of the Insured's Company YES
If No, Relationship of the Driver with the Insured
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 3
Passenger 1
NAME: : JANICE BONZA
GENDER: : FEMALE
Passenger 2
NAME: : SHU FANG YUI
GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

ON 25 AUG 19, 11:15AM, I WAS TURNING ON THE SIDE ROAD FROM HAVELOCK ROAD TO CLEMENCEAU ROAD. NOTICING THAT THE CAR IN FRONT OF ME MOVED, SO I FOLLOWED. AS A HABIT, I LOOKED FOR THE TRAFFIC TO THE RIGHT AGAIN WHILE STARTED MOVING ON. WHEN I LOOKED BACK TO THE PATH, I NOTICED THE CAR HAD STOPPED. I DID AN EMERGENCY STOP THEN HOWEVER, BUMPED INTO THE CAR IN FRONT OF ME (AS SHOWN IN THE VIDEO).

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJU7025D
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorized Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/IN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 25 Aug 19 11:15 am, I was turning on the side road from Havelock road to Clemenceau road. ^{Notifying that} the car in front of me moved, so I followed. As a habit, I looked for the traffic to the right off's who's started manouver. When I looked back to the path, I noticed the car had stopped. I did an emergency stop then a ~~How~~ Howler, bumped into the car in front of me (as shown in the video).

DECLARATION

I/We declare the following particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]

Reporting Centre Personnel's Signature
Name:
AIC/Fils No:


[Signature]
57574504B



Accident Photo



Accident Photo



Accident Photo



IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MPA 119 112578 Vehicle Registration No : SME 2447B
Name (as shown in NRIC) : SME 2447B NRIC/FIN/Passport No : 2013217646
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : _____ Singapore ()
Contact (Tel) : _____ Mobile No. : 9655 2323
Email Address : _____
Date of Accident : 25/08/19 Time of Accident : 1115 hrs.
Place of Accident : Havelock rd turning to Clementine Ave.
Insurance Company : AIU

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

from reporting only to own damage claim

Policyholder / Driver's Signature
Date: Ken

28/8/19

Reporting Centre Personnel's Signature
Name: Esman
NRIC/FIN No.: S6803526C
Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 10321

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1033/2019/NS
Date	:	29-Aug-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Xinsha Holding Pte Ltd
Address	:	Blk 6A Boon Tiong Road Singapore 164006
Telephone	:	(HP)+65 96552323
Type of Claim	:	Own Damage Claims
Policy No.	:	1800108691
Vehicle No	:	SME 2447 B
Model Code	:	Audi Q7 2.0 TFSI QU
Model / Year	:	24/9/2018
Engine No	:	CYR 066147
Chassis No	:	WAUZZZ4M8JD050408
Mileage	:	
Date In	:	
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	25-Aug-19
Place of Accident	:	Havelock Rd Turning To Clemenceau Ave

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SME 2447 B

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	✓ \$480-00
2	To dismantle and renew front bumper assy. Re-organise crash management components. Reinstall all parts removed.	\$ 1,350.00	600 \$600-00
3	To respray front bumper.	\$ 1,350.00	600 \$600-00
4	To carry out diagnostic check.	S/N \$ 192.00	✓ \$192-00
TOTAL LABOUR CHARGES		: <u>\$ 3,372.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 2447 B

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>red</i>	S 2,242.00	✓ \$1793-60
2	FRONT BUMPER FIXING PARTS <i>new</i>	S 403.00	+
3	FRONT BUMPER AIR GUIDE - LH / RH <i>2H new</i>	2 S 120.00	+
4	FRONT BUMPER END CAP - LH / RH <i>new</i>	2 S 64.00	+
6	FRONT BUMPER CLOSING ELEMENT-UPPER CENTRE <i>2H</i>	S 252.00	+
7	FRONT BUMPER GRILLE-LOWER CENTRE <i>could be</i>	S 187.00	✓ \$149-60
8	FRONT BUMPER UNDERRUN BAR <i>new</i>	S 735.00	+
9	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	S 191.00	+
10	FRONT BUMPER SPOILER-LH <i>new could be</i>	S 126.00	✓ \$100-80
11	FRONT BUMPER SPOILER-LH OUTER <i>new</i>	S 40.00	+
12	RADIATOR GRILLE <i>could be</i>	S 2,269.00	✓ \$1815-20
13	RADIATOR GRILLE COVER <i>new</i>	S 62.00	+
14	RADIATOR GRILLE INNER COVER <i>new</i>	S 56.00	+
15	FRONT BUMPER AIR GUIDE GRILLE-LH <i>new</i>	S 271.00	+
16	FRONT BUMPER AIR GUIDE GRILLE CAP- LH <i>new</i>	S 30.00	+
17	AIR GUIDE GRILLE SPOILER - LH FRONT INNER <i>new</i>	S 55.00	+
18	FRONT BUMPER FOAM FILLER PIECE <i>new</i>	S 156.00	+
19	FRONT BUMPER CARRIER <i>new</i>	S 791.00	+
20	FRONT BUMPER CARRIER SUPPORT-LH/RH <i>new</i>	2 S 66.00	+
SUB-TOTAL SPARE PARTS		: \$ 8,116.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 2447 B

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/Nett		
21	FRONT BUMPER GUIDE SECTION- LH <i>new</i>	\$	40.00 <i>+</i>	
22	FRONT BUMPER COVER <i>new</i>	\$	119.00 <i>+</i>	
23	CAUTION SIGN <i>new</i>	NEC \$	13.00 <i>+</i>	
24	FANFARE BRACKET - LH LOW TONE <i>new</i>	\$	206.00 <i>+</i>	
25	FRONT PARKING AID SENSOR - INNER OUTER <i>new</i>	2 \$	462.00 <i>+</i>	
26	FRONT PARKING AID SENSOR SEAL RING	4 \$	12.00 <i>+</i>	
27	RADIATOR AIR GUIDE - LH	\$	25.00 <i>+</i>	
28	RADIATOR AIR GUIDE - LOWER <i>new</i>	\$	37.00 <i>+</i>	
29	FRONT WHEEL COVER - LH / RH <i>new</i>	2 \$	604.00 <i>—</i>	<i>\$482-40</i>
30	WHEEL COVER CLIP <i>new</i>	NEC \$	5.00 <i>—</i>	<i>\$3-36</i>
31	GROMMET <i>new</i>	NEC \$	63.00 <i>+</i>	
32	FRONT NO. PLATE <i>Bent</i>	S/N \$	40.00 <i>—</i>	<i>\$40-00</i>
33	SUNDRIES <i>Not Nec</i>	\$	300.00 <i>+</i>	
TOTAL SPARE PARTS		:	\$ 10,042.00	
TOTAL LABOUR CHARGES			\$ 3,372.00	
GRAND TOTAL			\$ 13,414.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

:

Adrian Lim

Surveyed Date

:

30/08/19.

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

:

Not Authorised, 03 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

:

This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	764G
Vehicle Details	
Vehicle No.:	SME2447B
Vehicle to be Exported:	Yes
Intended Deregistration Date:	30 Aug 2019
Vehicle Make:	AUDI
Vehicle Model:	Q7 2.0 TFSI QU (252 BHP)
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	CYR066147
Chassis No.:	WAUZZZ4M8JD050408
Maximum Power Output:	185.0 kW (248 bhp)
Open Market Value:	\$59,278.00
Original Registration Date:	24 Sep 2018
First Registration Date:	24 Sep 2018
Transfer Count:	0
Actual ARF Paid:	\$78,701.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Sep 2028
PARF Rebate Amount:	\$59,025.00
Intended COE Rebate Details	
COE Expiry Date:	23 Sep 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$31,307.00
COE Rebate Amount:	\$25,045.00
Total Rebate Amount:	\$84,070.00

The information contained herein is correct as at 30 Aug 2019

OK

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 10321

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/1033/2019/NS
Date	:	29-Aug-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian,

3 days - ok - Jy - 31 Oct 2019

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Xinsha Holding Pte Ltd
Address	:	Blk 6A Boon Tiong Road Singapore 164006
Telephone	:	(HP)+65 96552323
Type of Claim	:	Own Damage Claims
Policy No.	:	1800108691
Vehicle No	:	SME 2447 B
Model Code	:	Audi Q7 2.0 TFSI QU
Model / Year	:	24/9/2018
Engine No	:	CYR 066147
Chassis No	:	WAUZZZ4M8JD050408
Mileage	:	
Date In	:	
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	25-Aug-19
Place of Accident	:	Havelock Rd Turning To Clemenceau Ave

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SME 2447 B

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	\$ 480.00
2	To dismantle and renew front bumper assy. Re-organise crash management components. Reinstall all parts removed.	\$ 1,350.00	\$ 600.00
3	To respray front bumper.	\$ 1,350.00	\$ 600.00
4	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 3,372.00	\$ 1,872.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 2447 B

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remark
1	FRONT BUMPER	\$ 2,242.00	\$ 1,793.60
2	FRONT BUMPER FIXING PARTS	\$ 403.00	
3	FRONT BUMPER AIR GUIDE - LH / RH	2 \$ 120.00	
4	FRONT BUMPER END CAP - LH / RH	2 \$ 64.00	
6	FRONT BUMPER CLOSING ELEMENT-UPPER CENTRE	\$ 252.00	
7	FRONT BUMPER GRILLE-LOWER CENTRE	\$ 187.00	\$ 149.60
8	FRONT BUMPER UNDERRUN BAR	\$ 735.00	
9	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$ 191.00	
10	FRONT BUMPER SPOILER-LH	\$ 126.00	\$ 100.80
11	FRONT BUMPER SPOILER-LH OUTER	\$ 40.00	
12	RADIATOR GRILLE	\$ 2,269.00	\$ 1,815.20
13	RADIATOR GRILLE COVER	\$ 62.00	
14	RADIATOR GRILLE INNER COVER	\$ 56.00	
15	FRONT BUMPER AIR GUDIE GRILLE-LH	\$ 271.00	
16	FRONT BUMPER AIR GUIDE GRILLE CAP- LH	\$ 30.00	
17	AIR GUIDE GRILLE SPOILER - LH FRONT INNER	\$ 55.00	
18	FRONT BUMPER FOAM FILLER PIECE	\$ 156.00	
19	FRONT BUMPER CARRIER	\$ 791.00	
20	FRONT BUMPER CARRIER SUPPORT-LH/RH	2 \$ 66.00	
SUB-TOTAL SPARE PARTS		\$ 8,116.00	\$ 3,859.20

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 2447 B

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		<u>S/Nett</u>	<u>Remark</u>
			\$ 3,859.20
21	FRONT BUMPER GUIDE SECTON- LH	\$ 40.00	
22	FRONT BUMPER COVER	\$ 119.00	
23	CAUTION SIGN	NEC \$ 13.00	
24	FANFARE BRACKET - LH LOW TONE	\$ 206.00	
25	FRONT PARKING AID SENSOR - INNER OUTER	2 \$ 462.00	
26	FRONT PARKING AID SENSOR SEAL RING	4 \$ 12.00	
27	RADIATOR AIR GUIDE - LH	\$ 25.00	
28	RADIATOR AIR GUIDE - LOWER	\$ 37.00	
29	FRONT WHEEL COVER - LH / RH	2 \$ 604.00	\$ 482.40
30	WHEEL COVER CLIP	NEC \$ 5.00	\$ 3.36
31	GROMMET	NEC \$ 63.00	
32	FRONT NO. PLATE	S/N \$ 40.00	\$ 40.00
33	SUNDRIES	\$ 300.00	
TOTAL SPARE PARTS		\$ 10,042.00	\$ 4,384.96
TOTAL LABOUR CHARGES		\$ 3,372.00	\$ 1,872.00
GRAND TOTAL		\$ 13,414.00	\$ 6,256.96

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SME 2447 B

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/1033/2019/NH

20th February 2020

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SME 2447 B, Audi Q7 2.0 TFSI qu.

With reference to the above-mentioned vehicle, no. **SME 2447 B**, claimant, **Xinsha Holding Pte Ltd**, please find the related document per attached.

1. A copy of the Original invoice no. 85014863 – S\$ 6,159.95.
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SME 2447 B

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6386 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 8841 1183

Customer Service
Service Appointment 6365 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 14:56

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014863 Date: 19/02/2020 Order: SME2447B Term: 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No: SME2447B (V 38440) Regn Date: 24/09/2018 Mileage: 14492 WIP No.: 10321

Model: Q7 2.0 TFSI QU (252 bhp) 4MB0I Chassis: WAUZZZ4M8JD050408 Engine: CYR 066147 Dept: U

You have been assisted by :- UB-Tony Foong (33)

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE	40.00	1.00	40.00
Q	EXC	M: 8888 Insurance Excess/Liability	-500.00	1.00	-500.00
S	BODYWORK	M: TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	480.00	1.00	480.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER ASSY. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	600.00	1.00	600.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER	600.00	1.00	600.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A4M0807065B GRU	COVER Less 020%	1.00	2242.00	1,793.60
X	A4M0807647B 4W3	GRILLE(LAST) AP Less 020%	1.00	187.00	149.60
X	A4M0807061D 4W3	FR.SPOILER(LAST) AP Less 020%	1.00	126.00	100.80
X	A4M0853651J MX3	(A) (SK)GRILLE 3/9/19 Less 020%	1.00	2269.00	1,815.20
X	A4M0853717 4W3	(A) (SK)COVER 3/9/19 Less 020%	1.00	301.50	241.20
X	A4M0853718 4W3	COVER(LAST) Less 020%	1.00	301.50	241.20
X	A4M0854451	CLIP Less 020%	6.00	0.70	3.36

Parts 4,344.96
Labour 0.00
Sublet 1,912.00
Menus 0.00
Lubricant 0.00

Sub-Total 5,756.96

7% GST 402.99

Grand Total 6,159.95



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SME 2447 B

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/1033/2019/EH
11 October 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi Q7 2.0 TFSI QU
Vehicle Chassis No. : WAUZZZ4M8JD050408
Vehicle Regn No. : SME 2447 B
Vehicle Mileage : 14010 KM
Vehicle Owner : Xinsha Holding Pte. Ltd.
Certificate No : 1800108691
Own Damage Excess : S\$ 535.00 (Inclusive 7% GST)
Accident Date : 25 August 2019
Place : Havelock Rd Turning To Clemenceau Ave
Repair Cost : \$ 6159.95
WIP No. : 10321
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time : 1720 hrs
Date : 11/10



DISCHARGE VOUCHER- AIG - SME 2447 B

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Sep 2019		30 Aug 2019 14:56 Edit Adj Rpt	S\$6,256.96 Edit Estimates	S\$6,256.96 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	XINSHA HOLDING PTE LTD, Co. Reg. No.: 201331764G, Tel: +6596270458								
Vehicle Reg. No.:	SME2447B	Date of Loss:	25/08/2019 11:00 - :59 [11 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 4364570311SG	Policy/Cover Note No.:	1800108691 (Comprehensive)						
		Excess:	S\$500.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Mithoo Singh, Aashweenjeet Kaur] Aashweenjeetkaur.Mithoosingh@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 10/09/2019]								
Driver/Custodian:	RUI HONG (44 / Female) , NRIC: S7574505B, Tel: +6596270458 Email: RUIHONG1@HOTMAIL.COM								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (02/09/2019): Alert - Adj Mandate Approved (S\$7032.00) - SME2447B - Claim Handler: Mithoo Sing... - AIG_SG (02/09/2019): SME2447B / OD / 25/08/2019 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SME2447B (4364570311SG)
OD
Aug 25 2019 11:00AM
[XINSHA HOLDING PTE LTD]
Premium Automobiles Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	26/08/19 17:41	Video - Accident [Linked Accident Report Documents]	Load MP4	
Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/08/19 18:14	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/08/19 17:43	General View	Load JPG	☒
2	30/08/19 17:43	General View	Load JPG	☒
3	30/08/19 17:43	General View	Load JPG	☒
4	30/08/19 17:43	General View	Load JPG	☒
5	30/08/19 17:43	General View	Load JPG	☒
6	30/08/19 17:43	General View	Load JPG	☒
7	30/08/19 17:43	General View	Load JPG	☒
8	30/08/19 17:43	General View	Load JPG	☒
9	30/08/19 17:43	General View	Load JPG	☒
10	30/08/19 17:43	General View	Load JPG	☒
11	30/08/19 17:43	General View	Load JPG	☒
12	30/08/19 17:43	General View	Load JPG	☒
13	30/08/19 17:43	General View	Load JPG	☒
14	30/08/19 17:43	General View	Load JPG	☒
15	30/08/19 17:43	General View	Load JPG	☒
16	30/08/19 17:43	General View	Load JPG	☒
17	30/08/19 17:43	General View	Load JPG	☒
18	30/08/19 17:43	General View	Load JPG	☒
19	30/08/19 17:43	General View	Load JPG	☒
20	30/08/19 17:43	General View	Load JPG	☒
21	30/08/19 17:43	General View	Load JPG	☒
22	30/08/19 17:43	General View	Load JPG	☒
23	30/08/19 17:43	General View	Load JPG	☒
24	30/08/19 17:43	General View	Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/08/19 17:41	ESTIMATE	Load PDF	
2	30/08/19 17:41	ADDENDUM REPORT	Load PDF	
3	30/08/19 17:41	Certificate of Insurance	Load PDF	
4	30/08/19 17:41	Driving License and nric	Load PDF	
5	30/08/19 17:41	Singapore Accident Statement	Load PDF	
6	10/03/20 17:39	Discharge Voucher	Load PDF	

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
7	10/03/20 17:39	Workshop Invoice		Load PDF

Linked Accident Report Documents

Video			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	26/08/19 17:41	Video - Accident		Load MP4

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	29/08/19 08:48	Addendum Sheet		Load JPG
2	29/08/19 08:50	Accident Statement		Load HTM
3	04/09/19 02:41	Accident Statement		Load HTM

Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	26/08/19 17:37	Accident Photo		Load JPG
2	26/08/19 17:37	Accident Photo		Load JPG
3	26/08/19 17:37	Accident Photo		Load JPG
4	26/08/19 17:37	Accident Photo		Load JPG
5	26/08/19 17:37	Accident Photo		Load JPG
6	26/08/19 17:37	Accident Photo		Load JPG
7	26/08/19 17:37	Accident Photo		Load JPG
8	26/08/19 17:37	Accident Photo		Load JPG
9	26/08/19 17:37	Accident Photo		Load JPG
10	26/08/19 17:37	Accident Photo		Load JPG
11	26/08/19 17:37	Accident Photo		Load JPG
12	26/08/19 17:37	Accident Photo		Load JPG

Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	26/08/19 17:39	Sketch Plan		Load JPG
2	26/08/19 17:39	Sketch Plan #2		Load JPG

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19015372/AYF3E2

Date: 10/03/2020

REFERENCE

Insured/Claimant: XINSHA HOLDING PTE LTD
Date of Loss: 25/08/2019Policy No: 1800108691
Nature of Claim: OD

Claim No: 4364570311SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME2447B	Engine No:	CYR066147
Make & Model:	AUDI Q7, 2.0 TFSI QU (A)	Chassis No:	WAUZZZ4M8JD050408
Reg. Date:	24/09/2018 (Man. Year: 2018)	Odometer:	12494 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$250,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/55 R19	Rear Tyre Size:	255/55 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,042.00	4,384.96	5,657.04	56.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,372.00	1,872.00	1,500.00	44.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	13,414.00	6,256.96	7,157.04	53.36
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	12,914.00	5,756.96	7,157.04	55.42
+ GST 7.00/7.00% (S\$)	903.98	402.99	500.99	55.42
Nett Amount (S\$)	13,817.98	6,159.95	7,658.03	55.42

INSPECTION

Date of Assignment: 30/08/2019

Date Inspected: 30/08/2019 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Deformed	2,242.00 FS	*1,793.60 FS
2	1	*FRONT BUMPER FIXING PARTS	Not Necessary	403.00 FS	*- FS
3	2	*FRONT BUMPER AIR GUIDE - LH / RH	Not Necessary	120.00 FS	*- FS
4	2	*FRONT BUMPER END CAP - LH / RH	Not Necessary	64.00 FS	*- FS
5	1	*FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE	Not Necessary	252.00 FS	*- FS
6	1	*FRONT BUMPER GRILLE - LOWER CENTRE	Cracked	187.00 FS	*149.60 FS
7	1	*FRONT BUMPER UNDERRUN BAR	Not Necessary	735.00 FS	*- FS
8	1	*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	191.00 FS	*- FS
9	1	*FRONT BUMPER SPOILER - LH	Cracked	126.00 FS	*100.80 FS
10	1	*FRONT BUMPER SPOILER - LH OUTER	Not Necessary	40.00 FS	*- FS
11	1	*RADIATOR GRILLE	Cracked	2,269.00 FS	*1,815.20 FS
12	1	*RADIATOR GRILLE COVER	Not Necessary	62.00 FS	*- FS
13	1	*RADIATOR GRILLE INNER COVER	Not Necessary	56.00 FS	*- FS
14	1	*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	271.00 FS	*- FS
15	1	*FRONT BUMPER AIR GUIDE GRILLE CAP - LH	Not Necessary	30.00 FS	*- FS
16	1	*AIR GUIDE GRILLE SPOILER - LH FRONT INNER	Not Necessary	55.00 FS	*- FS
17	1	*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	156.00 FS	*- FS
18	1	*FRONT BUMPER CARRIER	Not Necessary	791.00 FS	*- FS
19	2	*FRONT BUMPER CARRIER SUPPORT - LH / RH	Not Necessary	66.00 FS	*- FS
20	1	*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	40.00 FS	*- FS
21	1	*FRONT BUMPER COVER	Not Necessary	119.00 FS	*- FS
22	1	*CAUTION SIGN	Not Necessary	13.00 FS	*- FS
23	1	*FANFARE BRACKET - LH LOW TONE	Not Necessary	206.00 FS	*- FS
24	2	*FRONT PARKING AID SENSOR - INNER OUTER	Not Necessary	462.00 FS	*- FS
25	4	*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	12.00 FS	*- FS
26	1	*RADIATOR AIR GUIDE - LH	Not Necessary	25.00 FS	*- FS
27	1	*RADIATOR AIR GUIDE - LOWER	Not Necessary	37.00 FS	*- FS
28	2	*FRONT WHEEL COVER - LH / RH	Necessary	604.00 FS	*482.40 FS
29	1	*WHEEL COVER CLIP	Necessary	5.00 FS	*3.36 FS
30	1	*GROMMET	Not Necessary	63.00 FS	*- FS
31	1	*FRONT NO. PLATE	Bent	40.00 FS	*40.00 FS
32	1	*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 10,042.00 4,384.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER ASSY. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,350.00	600.00
3	TO RESPRAY FRONT BUMPER	New	1,350.00	600.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			3,372.00	1,872.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >