LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.

AIG Building

78 Shenton Way #08-16 Singapore 079120

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

30 Aug 2019 Attn: Date:

Preliminary Advice

Vehicle No : SMG6109R Accident Date : 21/08/2019 : AUDI Q5 Policy No. Make : 1800152058 Assignment Date : 30/08/2019 **Excess** : S\$0.00 Date of Inspection : 30/08/2019 Est. Duration of Repair : 4.00

: PREMIUM AUTOMOBILES PTE LTD (UBI) Inspection At

55 UBI ROAD 1 SINGAPORE 408699

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	14,898.00
Revised Amount	:S\$	10,558.00
Check Items (Estimated)	:S\$	960.00
Total	:S\$	11,518.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 180,000.00 COE / PARF Rebate :S\$ 67,851.00

Salvage Value :S\$

Margin for Repair :S\$ 112,149.00

Remarks

(X	()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
()	Other comments :