

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 1713U

DATE : 29.08.2019

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover ✓			\$ 1,052.20
	Front Bumper Bracket (LH) ?			\$ 24.60
	Headlamp Support Panel Assy ✕			\$ 907.40
	Headlamp (LH) ✓			\$ 1,388.00
	Front Fender (LH) ✓			\$ 566.30
	Front Fender Shield (LH) ✕			\$ 174.90
	Front Door (LH) ✓			\$ 2,256.40
	Front Door Mirror Assy (LH) ✓			\$ 670.00
	Rear Door (LH) ✓			\$ 2,201.10
	Front Pillar Upper Cover/Garnish ✕ ✓			\$ 83.50
	Front Wheel Hub Cap (LH) ✓			\$ 107.10
	SUB TOTAL			\$ 9,431.50
	LESS 20%			\$ 1,886.30
	DISCOUNTED TOTAL			\$ 7,545.20
	Front Fender Advertisement Logo (LH) ✓			\$ 100.00 Nett
	Front Door Comfort Logo (LH) ✓			\$ 75.00 Nett
	Front Door Advertisement Logo (LH) ✓			\$ 100.00 Nett
	Rear Door Advertisement Logo (LH) ✓			\$ 100.00 Nett
	Rear Door Comfortdelgro & Apps Sticker (LH) ✓			\$ 80.00 Nett
				\$ 455.00
	Labour Charge			600
	Panel Beating			\$ 1,400.00
	Spray Painting Charge			\$ 1,200.00 850
	Wiring Charge			\$ 50.00 20
	Tuff Kote			\$ 100.00 50
	Towing Charge			\$ 60.00 100
	Transfer of Door		\$ 120.00	\$ 240.00
	FRT Wheel Alignment			\$ 120.00 ✕
	Remove/Refix Aircon & Refill Gas After Repair photo			\$ 150.00 ✕
	TOTAL LABOUR			\$ 3,310.00
	ESTIMATE TOTAL			\$ 11,310.20
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Kalvin LKK
29/8/19 1445h
4 Days
45