

ABWIN SERVICE PTE LTD

8 KAKI BUKIT AVENUE 4 - GATE 2
 #07-48 PREMIER @ KAKI BUKIT SINGAPORE 415875
 Tel: 67139400 Fax: 67139415
 Email: servicecentre@abwin.com.sg Website: www.abwinm9.com
 Company Reg. No: 201318685G GST Reg. No: 201318685G



*Not Allowed
 make
 a/s#
 4 days
 Take photo Attorney. 3/9/19*

ESTIMATED COST: HQQ000094

TO : AIG ASIA PACIFIC INSURANCE PTE. LTD.
ATTN : MOTOR CLAIM DEPARTMENT

DATE : 03-SEP-2019
 MAKE : DAIHATSU
 MODEL : MATERIA 1.5L AUTO ABS
 AIRBAG 2WD
 CHASSIS NO : JDAM402S001015057
 ENGINE NO : 2382686
 SERVICE ADVISOR : SHARIFAH
 PAGE : 1 OF 2

SKB8596D**SOH SEN KIAN**

BLK 972 HOUGANG STREET

91

#14-196

SINGAPORE 530972

CONTACT NO : 98233924

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
-----	-------------	---------------------	--------------------

LIST ITEM

1	FRONT DOOR LH <i>2 X</i>	0.00	
1	REAR DOOR LH <i>2 x 100</i>	0.00	
1	ROCKER PANEL GARNISH LH <i>2 x 100</i>	0.00	
1	REAR FENDER LH <i>2 X</i>	0.00	
Sub Total		0.00	0.00

SPECIAL NETT

1	FRONT DOOR LH SEALANT <i>11 X</i>	50.00	
1	REAR DOOR LH SEALANT <i>11 X</i>	50.00	
10	ROCKER PANEL GARNISH LH CLIPS <i>100</i>	50.00	
1	REAR FENDER LH SEALANT <i>11</i>	50.00	
1	REAR WHEEL RIM LH <i>cut 1/2</i>	480.00	<i>300</i>
1	REAR TYRE LH <i>PU</i>	250.00	<i>X</i>
Sub Total		930.00	0.00

LABOUR

1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	800.00	<i>500</i>
1	TO SPRAY PAINT ON AFFECTED AREAS	1,000.00	<i>800</i>
1	TO CHECK WIRING	120.00	<i>20</i>
1	TO APPLY UNDERCOATING FOR RUST PROOFING	150.00	<i>30</i>
1	TO CONDUCT COMPUTERISED WHEEL ALIGNMENT	120.00	<i>60</i>
1	TO DISMANTLE, REPLACE AND/OR REPAIR FRONT DOOR LH COMPONENTS <i>11</i>	150.00	<i>X</i>
1	TO DISMANTLE, REPLACE AND/OR REPAIR REAR DOOR LH COMPONENTS	150.00	<i>60</i>
Sub Total		2,490.00	0.00

ABWIN SERVICE PTE LTD

8 KAKI BUKIT AVENUE 4 - GATE 2
#07-48 PREMIER @ KAKI BUKIT SINGAPORE 415875
Tel: 67139400 Fax: 67139415
Email: servicecentre@abwin.com.sg Website: www.abwinm9.com
Company Reg. No: 201318685G GST Reg. No: 201318685G

**ESTIMATED COST: HQQ000094**

TO : AIG ASIA PACIFIC INSURANCE PTE. LTD.
ATTN : MOTOR CLAIM DEPARTMENT

SKB8596D
SOH SEN KIAN
BLK 972 HOUGANG STREET
91
#14-196
SINGAPORE 530972
CONTACT NO : 98233924

DATE : 03-SEP-2019
MAKE : DAIHATSU
MODEL : MATERIA 1.5L AUTO ABS
AIRBAG 2WD
CHASSIS NO : JDAM402S001015057
ENGINE NO : 2382686
SERVICE ADVISOR : SHARIFAH
PAGE : 2 OF 2

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
-----	-------------	---------------------	--------------------

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No ill modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SUB-TOTAL	3,420.00	0.00
GST - 7 %	239.40	0.00
TOTAL	3,659.40	0.00

ABWIN SERVICE PTE LTD

SHARIFAH

Prepared By

