

AUTOFRANCE

(A Division of Vantage Automotive Limited)

Business Registration No. 52907220C GST Registration No. M2-0000551-1

305 Alexandra Road

159942, Singapore

Tel : 6376 2288

Fax : 6477 7373



PEUGEOT

GST Registration No. M2-0000551-1

E S T I M A T E

Estimate No. : BP 4323	Page No. : 1 of 2
Date Estimated : 29/08/2019	
Prepared By : Andy Ooi Lee Keong	

<p>- ESTIMATE REPAIR FOR -</p> <p>Lee Dong Chan 355 BUKIT TIMAH ROAD #08-04</p> <p>Singapore 259724</p>	<p>- ACCOUNT - 77</p> <p>Axa Insurance Pte Ltd No. 8 Shenton Way #24-01 Axa Tower Singapore 068811</p>
--	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKT4002H	VF38E5GZTFL011178	04/06/2015	508SW1.6 Allure	10

DESCRIPTION	VALUE
TO CONDUCT TP CLAIM AGAINST AXA INSURANCE-SKU8468R DOA. 28/08/2019	0.00
SUNDRIES	50. 150.00
LABOUR TO REMOVE, REPLACE, REPAIR AND REALIGN REAR BUMPER TAILGATE PANEL AND ALL AFFECTED AREAS ⁵⁰⁰	1000 1,500.00
LABOUR TO PUTTY AND RESPRAY REAR BUMPER, TAILGATE PANEL AND ALL AFFECTED AREAS ^{500.}	1000 1,500.00
TO CONDUCT ECU PROGRAMMING CHECK AND CLEAR FAULT CODES RESTORE ALL PROGRAMME MODULE (NETT)	560. 600.00
TO REMOVE AND REINSTALL REAR BUMPER SENSORS, CONDUCT DISTANCE SETTINGS (NETT)	✓ 120.00
Total Labour 1:	3,870.00

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
1611343680	TAILGATE	1	2,886.00	10.00	Rx 2,597.40
1611916580	REAR BUMPER	1	956.00	10.00	de 860.40
1611901380	BRACKET SET	1	130.00	10.00	net 117.00
745387	REFLECTOR RH	1	61.00	10.00	? 54.90
742162	BUMPER BRACKET	1	80.00	10.00	net 72.00
7422W6	BUMPER ABSORBER	1	152.00	10.00	? 136.80
1608321780	SENSOR-OBSTACLE DETECTION FRT/REAR	4	99.00	10.00	? 356.40
1608472280	SENSOR-OBSTACLE DETECTION FRT/REAR	2	180.00	10.00	? 324.00
7422W9	BUMPER BRACKET	1	502.00	10.00	? 451.80
8666CX	BADGE	1	32.00	10.00	net 28.80
9809004580	BADGE 508 SW	1	55.00	10.00	net 49.50
00007810AH	RR BADGE LION	1	46.00	10.00	net 41.40
Total Parts :					5,090.40

AUTOFRANCE

(A Division of Vantage Automotive Limited)

Business Registration No. 52907220C GST Registration No. M2-0000551-1

305 Alexandra Road

159942, Singapore

Tel : 6376 2288

Fax : 6477 7373



PEUGEOT

GST Registration No. M2-0000551-1

E S T I M A T E

Estimate No. : **BP 4323**
Date Estimated : **29/08/2019**
Prepared By : **Andy Ooi Lee Keong**

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKT4002H	VF38E5GZTFL011178	04/06/2015	508SW1.6 Allure	10

Taufik 97495749
WP'
4/9/19 @ 1145
Resurvey before paint
3 days
sure/khantowm.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Customer Name & Signature / Company Stamp	Date	Labour 1	: 3,870.00
		Parts	: 5,090.40
		Labour 2	: 0.00
		Excess	: 0.00
		Total GST @ 7%	: 627.23
		Grand Total	: 9,587.63

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval. This estimate is valid for a period of 30 days only.