

# AUTOFRANCE

(A Division of Vantage Automotive Limited)  
 Business Registration No. 52907220C GST Registration No. M2-0000551-1  
 305 Alexandra Road  
 159942, Singapore  
 Tel : 6376 2288  
 Fax : 6477 7373



GST Registration No. M2-0000551-1

## ESTIMATE

Estimate No. : <b>BP 4323</b>	Page No. : 1 of 2
Date Estimated : 29/08/2019	
Prepared By : <b>Andy Ooi Lee Keong</b>	

<b>- ESTIMATE REPAIR FOR -</b>	<b>- ACCOUNT - 77</b>
Lee Dong Chan 355 BUKIT TIMAH ROAD #08-04  Singapore 259724	Axa Insurance Pte Ltd No. 8 Shenton Way #24-01 Axa Tower Singapore 068811

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKT4002H	VF38E5GZTFL011178	04/06/2015	508SW1.6 Allure	10

DESCRIPTION	VALUE
TO CONDUCT TP CLAIM AGAINST AXA INSURANCE-SKU8468R DOA. 28/08/2019	0.00
SUNDRIES	50. 150.00
LABOUR TO REMOVE, REPLACE, REPAIR AND REALIGN REAR BUMPER TAILGATE PANEL AND ALL AFFECTED AREAS <sup>500</sup>	1000 1,500.00
LABOUR TO PUTTY AND RESPRAY REAR BUMPER, TAILGATE PANEL AND ALL AFFECTED AREAS <sup>500.</sup>	1000 1,500.00
TO CONDUCT ECU PROGRAMMING CHECK AND CLEAR FAULT CODES RESTORE ALL PROGRAMME MODULE (NETT)	<del>400</del> 600.00
TO REMOVE AND REINSTALL REAR BUMPER SENSORS, CONDUCT DISTANCE SETTINGS (NETT)	✓ 120.00
<b>Total Labour 1:</b>	<b>3,870.00</b>

PART NUMBER	DESCRIPTION	QTY	PRICE	DISC	VALUE
1611343680	TAILGATE	1	2,886.00	10.00	Rp 2,597.40
1611916580	REAR BUMPER	1	956.00	10.00	de 860.40
1611901380	BRACKET SET	1	130.00	10.00	net 117.00
745387	REFLECTOR RH	1	61.00	10.00	? 54.90
742162	BUMPER BRACKET	1	80.00	10.00	net 72.00
7422W6	BUMPER ABSORBER	1	152.00	10.00	? 136.80
1608321780	SENSOR-OBSTACLE DETECTION FRT/REAR	4	99.00	10.00	? 356.40
1608472280	SENSOR-OBSTACLE DETECTION FRT/REAR	2	180.00	10.00	? 324.00
7422W9	BUMPER BRACKET	1	502.00	10.00	? 451.80
8666CX	BADGE	1	32.00	10.00	net 28.80
9809004580	BADGE 508 SW	1	55.00	10.00	net 49.50
00007810AH	RR BADGE LION	1	46.00	10.00	net 41.40
<b>Total Parts :</b>					<b>5,090.40</b>

# AUTOFRANCE

(A Division of Vantage Automotive Limited)

Business Registration No. 52907220C GST Registration No. M2-0000551-1

305 Alexandra Road

159942, Singapore

Tel : 6376 2288

Fax : 6477 7373



PEUGEOT

GST Registration No. M2-0000551-1

## E S T I M A T E

Estimate No. : **BP 4323**  
Date Estimated : **29/08/2019**  
Prepared By : **Andy Ooi Lee Keong**

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKT4002H	VF38E5GZTFL011178	04/06/2015	508SW1.6 Allure	10

Taufik 97445749  
WP  
4/9/19 @ 1145  
Resumy before paint  
30 days  
siv@hhands.com

Labour 1	:	3,870.00
Parts	:	5,090.40
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	627.23
Grand Total	:	<b>9,587.63</b>

Customer Name & Signature / Company Stamp

Date

The above estimates are base on visual inspection and it is possible that further materials and labour may be required upon dismantling. Should this occur, we will submit supplementary quotation for further approval. This estimate is valid for a period of 30 days only.

**AUTOFRANCE**

(A Division of Vantage Automotive Limited)  
Co. Regs. No. S2907220C GST Regs. No. M2-0000551-1

305 Alexandra Road  
Vantage Automotive Centre  
Singapore 159942  
Service Booking: 6477 7377  
Parts: 6477 7420  
Vantage 24-Hour Assiat: 6473 8588  
Fax: 6477 7300



**FINALIZATION REPORT**  
**SERVICE TAX INVOICE**  
RE-PRINT

REPAIR ORDER NO. <b>bp 115165</b>	Date IN <b>01/10/2019</b> Payment Term <b>30 Days From Invoice</b> Customer Service Advisor <b>Simon Koh Eng Aun</b>	Invoice Number  Invoice Date  Invoice By <b>Simon Koh Eng Aun</b>	Page No. <b>1 of 1</b>
--------------------------------------	---	--	------------------------

CUSTOMER INFORMATION	INVOICE TO <b>77</b>
<b>Lee Dong Chan</b> 355 BUKIT TIMAH ROAD #08-04  Singapore 259724	<b>Axa Insurance Pte Ltd</b> No. 8 Shenton Way #24-01 Axa Tower Singapore 068811

REGISTRATION No. <b>SKT4002H</b>	CHASSIS No. <b>VF38E5GZTFL011178</b>	STOCK No. <b>208526</b>	REGISTRATION DATE <b>04/06/2015</b>	MODEL <b>508SW1.6 Allure</b>	MILEAGE <b>75071</b>
-------------------------------------	---	----------------------------	--	---------------------------------	-------------------------

CODE	DESCRIPTION	UNITS	DISC %	NETT
	TO CONDUCT TP CLAIM AGAINST AXA INSURANCE-SKU8468R DOA. 28/08/2019	0	0.00	0.00
	SUNDRIES	1	0.00	50.00
	LABOUR TO REMOVE, REPLACE, REPAIR AND REALIGN REAR BUMPER TAILGATE PANEL AND ALL AFFECTED AREAS	1	0.00	1,000.00
	LABOUR TO PUTTY AND RESPRAY REAR BUMPER, TAILGATE PANEL AND ALL AFFECTED AREAS	1	0.00	1,000.00
	TO CONDUCT ECU PROGRAMMING CHECK AND CLEAR FAULT CODES RESTORE ALL PROGRAMME MODULE (NETT)	2	0.00	600.00
	TO REMOVE AND REINSTALL REAR BUMPER SENSORS, CONDUCT DISTANCE SETTINGS (NETT)	1	0.00	120.00
<b>Sub-Total :</b>				<b>2,770.00</b>

CODE	DESCRIPTION	UNITS	DISC %	NETT
0000742162	BUMPER BRACKET RH	1	10.00	72.00
00007810AH	RR BADGE LION	1	10.00	41.40
00008666CX	PEUGEOT EMBLEM	1	10.00	28.80
1611901380	BRACKET SET	1	10.00	117.00
1611916580	REAR BUMPER	1	10.00	860.40
9809004580	BADGE 508 SW	1	10.00	49.50
<b>Sub-Total :</b>				<b>1,169.10</b>

Attending CSO : Simon Koh  
Should you require further explanation, please reach me at

Service Packages	<b>0.00</b>	Total Labour/Parts/Service Package Charges	<b>S\$ 3,939.10</b>
Labour Charges	<b>2,770.00</b>	Less Insurance Excess	<b>S\$ 0.00</b>
Parts Charges	<b>1,169.10</b>	GST @ 7%	<b>S\$ 275.74</b>
Lubricant/Misc	<b>0.00</b>	Invoice Total Amounts	<b>S\$ 4,214.84</b>
		Less Deposit/Voucher	<b>S\$ 0.00</b>

<b>Computer generated invoice. No signature is required.</b>	<b>Amount Payable</b>	<b>S\$ 4,214.84</b>
--	-----------------------	---------------------

All amounts are in Singapore Dollars.  
Work was carried out subject to the Company's Terms and Conditions of Service.  
No complaints will be entertained unless reported within seven (7) days of the date of this invoice.  
For credit purchases, interest @1% per month will be debited on overdue amounts.