

ASS. REC. BY:

REF: CS/FCI 19015472/ESF312

Special Instruction:

Surveyor Steve

ASSIGNMENT (Office)

From (Person):

Karent

of

FCI

Date/Time:

2.9.19 2.36pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGU 863H

Insured:

SHD F306G

at Workshop m/s:

Hwa Pong Auto

Tel:

96835655

of

Blk 70 Woodlands Industrial Park E

Policy No:

Claim No:

D19005644 MF5H

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28.8.2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

2.9.19 2.45pm

Person Contacted:

Francis

Vehicle (IN) OUT

Date/Time

Action/Instruction (✓) Estimate

SGU 863H - NSI / NC 19015257 / K19f3 DOA - 28/08/2019

SHD F306G - NSI / NC 19015237 / K19f3 DOA - 28/08/2019

03/09/19

@ 14:24 pm checked with Francis (Cyprian),
maybe total loss & will update us again.

03/09/19

@ 15:00 pm running pending estimate from repairer to

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Mv 19.000

Pr 13.366

NV 5.634

18/9/19 Discuss with Action \$5500 report limit

30/10/19 Finalize claim \$5500 15 repair days

(\$ 14,878.08 Red - 73%)

RECEIVED 30 OCT 2019

Date/Time, File Pass 107

30/10/19

1) Type: 4

Date/Time, File Return 107



: Prel. Report



: Final Report

Days Of Repair:

15

Resurvey No. of Trip:

2

Add Foo:



: Site Insp (\$



: Interview (\$



: Tech. Insp (\$



: Weekend (\$

Survey Fee:

Transportation:

3 + RS. 3

Photos 150

Others 173

TOTAL

10x5-

170+150

50

50+50

173

643

Report Format:

Lump Sum / L.B.I. (\$

\$ 5,500/- 45)

Veh No: SG4 863H

Yr Regn: 2/5/07

Type: M Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Tractor or

Make: Mazda 2

Colour: White

Sp. Rending: N/A

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Locked / Burnt or

Brake: In order / Jammed / Locked / Burnt or

Modl: Nil / S/R / STD A/R / or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Fnt / Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal.

L/Bal.

D.O.I.

Hwa Peng

2/9/19

30/10/2019

MOTOR SURVEY ASSIGNMENT

Date	30-08-2019	Our Ref No. D19005644MFSH
Accident Date	28-08-2019	Claim Type. Third Party
Insured Vehicle	SHD7306G	Third Party Vehicle. SGU863H
Survey Location	Blk 70 Woodlands Industrial Park E	
Contact Person.	MR FRANCIS	
Contact No.	96885655/ 96885655	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HWA PENG AUTO SERVICE (1996)	Attention. NIL
Cc : TP Solicitor	CHEONGHOH LAW CORPORATION	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Re: SURVEY ASSESSMENT - D19005644MFSH/1

Shirley Hiew (LKK Auto)

Tue 3/9/2019 3:00 PM

To: 'Karen Tan' <karentan@msfirstcapital.com.sg>; 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>

Cc: SUR <sur@lkkauto.com>; assignments <assignments@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>

Dear Karen,

Please be informed that we have inspected the vehicle SGU 863H on 02/09/2019.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte LtdPhone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>**Sent:** Monday, 2 September 2019 2:48 PM**To:** 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>**Cc:** 'Karen Tan' <karentan@msfirstcapital.com.sg>**Subject:** RE: SURVEY ASSESSMENT - D19005644MFSH/1

Dear Sir/Madam,

Thank you for your assignment.

Best Regards,

Summer Lee | Admin**LKK Auto Consultants Pte Ltd**Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>**Sent:** Monday, 2 September, 2019 2:36 PM**To:** ASSIGNMENTS@LKKAUTO.COM**Cc:** CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Karen Tan <karentan@msfirstcapital.com.sg>**Subject:** PRI: SURVEY ASSESSMENT - D19005644MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)


Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Classic Promo! Best Deal! Fast Selling! Hurry Down Now!



Flexible Loans, Trade In Are
Welcome, 100% Deposit Refund
For Unapproved Loans
Classic Credit [Viewing](#)

- Free VICOM evaluation
- Free grooming and 6 months maintenance
- In-house workshop ensures quality service
- Member of SVTA and hire purchase association
- 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

[Browse by Category](#)
[Sort by Date Posted](#)
[20 results/page](#)

3 vehicles

Mazda 2

[Advanced Search](#)

Search Selection

Mazda 2

Any

Any

> 10 year(s)
old

Any

Any

Any

Available



Mazda 2 HB 1.5A SP (COE till 10/2021)

\$14,900

\$6,930 /yr

27-Oct-2006

1,498 cc

123,678 km

Hatchback

Available

1 Owner Since Day One! Family Passed Down Car. Original Paintwork And Raw Beauty. Mint Interior And Exterior. Super Bright Headlights. Loan/Insurance/Trade In Can Be Arranged. Please Fix Appointment To View Car.

DIRECT OWN

Posted: 25-Aug-2019 Tags: 2006 Mazda 2, 2006 mazda 2, Mazda 2, mazda 2, Mazda, 2, Used Mazda



Mazda 2 HB 1.5A R (New 5-yr COE)

\$30,800

\$6,150 /yr

03-Aug-2009

1,498 cc

64,464 km

Hatchback

Available

Full Agent Service! 1 Owner And Low Mileage! Immaculate And Best Condition, Definitely Worth For Another 5 Years Drive. Accident Free And For Your Ease Of Mind, STA Or Your Prefer Workshop's Evaluation Are Welcome. High Loan Available, Various In House Loan With L...

Posted: 31-Aug-2019 Tags: 2009 Mazda 2, 2009 mazda 2, Mazda 2, mazda 2, Mazda, 2, Used Mazda



Mazda 2 HB 1.5A R (OPC) (New 5-yr COE)

\$32,800

\$6,550 /yr

27-Aug-2009

1,498 cc

34,646 km

Hatchback

Available

Super Low Mileage Car! Carefully Maintained By 1 Meticulous Owner And Accident Free. Always Parked Under Shelter And Serviced On Time. Car In Pristine Condition And Clean Interior. Leather Seats Was Maintained By Specialist Previously. Price Include Conversion To N...

Posted: 01-Sep-2019 Tags: 2009 Mazda 2, 2009 mazda 2, Mazda 2, mazda 2, Mazda, 2, Used Mazda

Save this search criteria, to get email alerts whenever a match is found.

Model

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view [Expired ads](#)

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rate insurance. Find buy used Mazda 2, Mazda 2 Singapore, used Mazda 2 Singapore, used Mazda 2, used vehicles Singapore or even buy used Mazda 2 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job opportunities for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[Compare](#)


[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	832M
Vehicle Details	
Vehicle No.:	SGU863H
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Sep 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA2 SP
Primary Colour:	White
Manufacturing Year:	2006
Engine No.:	ZY378358
Chassis No.:	JM0DY10Y270212708
Maximum Power Output:	82.0 kW (109 bhp)
Open Market Value:	\$12,016.00
Original Registration Date:	02 May 2007
First Registration Date:	02 May 2007
Transfer Count:	2
Actual ARF Paid:	\$13,218.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Apr 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$25,115.00
COE Rebate Amount:	\$13,366.00
Total Rebate Amount:	\$13,366.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 02 Sep 2019

OK



華平汽車服務

HWA PENG AUTO SERVICE (1996)

70 Woodlands Industrial Park E9 Singapore 757836

TEL: 6365 6100 FAX: 6365 6101

Spray Painting • Panel Beating • Body Repair • Engine Tuning • Towing Service • Insurance Claim • L.T.A. Inspection Service
Co. Reg 52823719E

ESTIMATE REPORT


C/o 70 Woodlands Industrial Park E9
Singapore 757836

Vehicle Number : SGU863H
Make And Model : Mazda 2
Date of Accident : 28 August 2019

S/No	Parts	QTY	Unit Price	List Price
1	Front bumper / TN	1		\$ 892.00 589/
2	Front bumper retainer LH & RH / BR	2	\$ 36.20	\$ 72.40 /
3	Front fender RH / OO	1		\$ 341.00 /
4	Rocker panel RH / OO	1		\$ 811.00 /
5	Rocker panel garnish LH & RH / BR	2	\$ 138.00	\$ 276.00 /
6	Center pillar RH / OO	1		\$ 925.00 /
7	Front door RH / OO	1		\$ 1,025.00 679/
8	Front door hinge top & bottom RH / BT	2	\$ 105.00	\$ 210.00 100/
9	Front door lock RH / BT	1		\$ 251.00 150/
10	Front door handle RH X N/A	1		\$ 150.00 X
11	Front door window regulator RH / BR	1		\$ 142.00 /
12	Front door window regulator motor RH / Jammed	1		\$ 168.00 /
13	Front door inner trimboard RH / CR4	1		\$ 863.00 325/
14	Rear door RH / OO	1		\$ 1,018.00 589/
15	Rear door hinge top & bottom RH / BT	2		\$ 210.00 100/
16	Rear door lock RH / BT	1		\$ 242.00 150/
17	Rear door handle RH / BR	1		\$ 132.00 /
18	Rear door window regulator RH / BR	1		\$ 136.00 /
19	Rear door window regulator motor RH / Jammed	1		\$ 168.00 /
20	Rear door inner trimboard RH / CR4	1		\$ 816.00 300/
21	Rear fender RH / OO	1		\$ 1,012.00 /
22	Rear bumper / BR	1		\$ 821.00 650/
23	Rear bumper side retainer LH & RH / BR	2	\$ 37.60	\$ 75.20 /
24	Rear axle / BT	1		\$ 1,041.50 /
25	Rear shock absorber LH & RH / BT	2	\$ 243.00	\$ 486.00 /
26	Rear shock absorber coil spring LH & RH (RH) MIS /	2	\$ 261.00	\$ 522.00 180/
27	Rear wheel bearing hub with bearing LH & RH / Jammed	2	\$ 385.00	\$ 770.00 370/
28	Rear floor panel X N/A	1	\$ 927.00	\$ 927.00 X
29	Rear exhaust muffler X N/A	1		\$ 582.00 X
				\$ 15,085.10
				Less 20% \$ 3,017.02
				Total \$ 12,068.08

9961.10
- 20%
7968.88

To be continued page 2



華平汽車服務 HWA PENG AUTO SERVICE (1996)

70 Woodlands Industrial Park E9 Singapore 757836

TEL: 6365 6100 FAX: 6365 6101

Spray Painting • Panel Beating • Body Repair • Engine Tuning • Towing Service • Insurance Claim • L.T.A. Inspection Service
Co. Reg 52823719E

Page 2

S/No	Parts	QTY	Unit Price	List Price
Special Nett Item				
30	Front bumper clips / NK		\$	60.00 30/
31	Front door trimboard clips / NK		\$	60.00 30/
32	Rocker panel garnish clips LH & RH / NK		\$	120.00 20/
33	Rear door trimboard clips / NK		\$	60.00 30/
34	Rear bumper clips / NK		\$	60.00 30/
35	Rear bumper lower spoiler X NN		\$	500.00 X
36	Rim (AX) 2 pc (Rear RH & LH) BR /		\$	1,000.00 500/
			Total	\$ 1,860.00

Labour & Misc Charges

To dismantle, replace & panel beating affected parts.	\$	2,500.00	1800/
To spray paint on affected areas.	\$	2,400.00	1800/
To apply anti-rust on affected areas.	\$	300.00	50/
To remove/refit front & rear door mechanism & components.	\$	200.00	100/
To remove/refit rear upholstery, rear seat, roof lining etc.	\$	200.00	80/
To remove & replace rear exhaust muffler.	\$	150.00	X
To remove & replace rear undercarriage.	\$	450.00	200/
To perform computerized wheel alignment.	\$	120.00	60/
To remove/refit reverse sensors.	\$	80.00	20/
To check wiring.	\$	50.00	30/
		4140	
</			

Store (LKK) wit Arin dl 2/9/19
15 days
L/S
Ry AL SPY

Grand Total : \$ 20,378.08

P- 7968.88

N- 640

L- 4140

12,748.88

L/S - 10,199.10

= 10,200.00

Repair limit - \$5500

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19015472/Esf3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 31-10-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 7306G	Veh. Inspected	SGU 863H
Policy No.		Coverage (\$)	0.00
Claim No.	D19005644MFSH	Excess (\$)	0.00
Assign From	KARENT	Assign Date	02/09/2019
2. Vehicle Particulars & Condition			
Make & Model	MAZDA 2	c.c	1498
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	JM0DY10Y270212708	Colour	WHITE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/65 R14	FALKEN	5 mm
L/H Front Tyre	185/65 R14	FALKEN	5 mm
R/H Rear Tyre	185/65 R14	FALKEN	5 mm
L/H Rear Tyre	185/65 R14	FALKEN	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND UNDERCARRIAGE. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	28/08/2019	Inspection Date	02/09/2019
Survey held at	HWA PENG AUTO SERVICE (1996) 70 WOODLAND INDUSTRIAL PARK E SINGAPORE 757836		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		15 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGU 863H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	TORN	892.00	589.00
2	FRONT BUMPER RETAINER LH & RH @\$36.20	BROKEN	72.40	72.40
1	FRONT FENDER RH	DENTED	341.00	341.00
1	ROCKER PANEL RH	DENTED	811.00	811.00
2	ROCKER PANEL GARNISH LH & RH @\$138.00	BROKEN	276.00	276.00
1	CENTER PILLAR RH	DENTED	925.00	925.00
1	FRONT DOOR RH	DENTED	1,025.00	679.00
2	FRONT DOOR HINGE TOP & BOTTOM RH @\$105.00	BENT	210.00	100.00
1	FRONT DOOR LOCK RH	BENT	251.00	150.00
1	FRONT DOOR HANDLE RH	NOT NECESSARY	150.00	-
1	FRONT DOOR WINDOW REGULATOR RH	BROKEN	142.00	142.00
1	FRONT DOOR WINDOW REGULATOR MOTOR RH	JAMMED	168.00	168.00
1	FRONT DOOR INNER TRIMBOARD RH	CRUSHED	863.00	325.00
1	REAR DOOR RH	DENTED	1,018.00	582.00
2	REAR DOOR HINGE TOP & BOTTOM RH	BENT	210.00	100.00
1	REAR DOOR LOCK RH	BENT	242.00	150.00
1	REAR DOOR HANDLE RH	BROKEN	132.00	132.00
1	REAR DOOR WINDOW REGULATOR RH	BROKEN	136.00	136.00
1	REAR DOOR WINDOW REGULATOR MOTOR RH	JAMMED	168.00	168.00
1	REAR DOOR INNER TRIMBOARD RH	CRUSHED	816.00	300.00
1	REAR FENDER RH	DENTED	1,012.00	1,012.00
1	REAR BUMPER	BROKEN	821.00	650.00
2	REAR BUMPER SIDE RETAINER LH & RH @\$37.60	BROKEN	75.20	75.20
1	REAR AXLE	BENT	1,041.50	1,041.50
2	REAR SHOCK ABSORBER LH & RH @\$243.00	BENT	486.00	486.00
2	REAR SHOCK ABSORBER COIL SPRING LH & RH @\$261.00	O/S MISSING	522.00	180.00
2	REAR WHEEL BEARING HUB WITH BEARING LH & RH @\$385.00	JAMMED	770.00	370.00
1	REAR FLOOR PANEL	NOT NECESSARY	927.00	-
1	REAR EXHAUST MUFFLER	NOT NECESSARY	582.00	-

Report Ref No. CS/FCI19015472/Esf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 20% DISCOUNT		-3,017.02	-1,992.22
			12,068.08	7,968.88
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT BUMPER CLIPS (SN)	NECESSARY	60.00	30.00
1	FRONT DOOR TRIMBOARD CLIPS (SN)	NECESSARY	60.00	30.00
2	ROCKER PANEL GARNISH CLIPS LH & RH (SN)	NECESSARY	120.00	20.00
1	REAR DOOR TRIMBOARD CLIPS (SN)	NECESSARY	60.00	30.00
1	REAR BUMPER CLIPS (SN)	NECESSARY	60.00	30.00
1	REAR BUMPER LOWER SPOILER (SN)	NOT NECESSARY	500.00	-
4	RIM (SN)	(REAR RH / LH) BROKEN (2 PCS ONLY)	1,000.00	500.00
			1,860.00	640.00
	<u>LABOUR</u>			
	TO DISMANTLE,REPLACE & PANEL BEATING AFFECTED PARTS.		2,500.00	1,800.00
	TO SPRAY PAINT ON AFFECTED AREAS.		2,400.00	1,800.00
	TO APPLY ANTI-RUST ON AFFECTED AREAS.		300.00	50.00
	TO REMOVE/REFIT FRONT & REAR DOOR MECHANISM & COMPONENTS.		200.00	100.00
	TO REMOVE/REFIT REAR UPHOLSTERY,REAR SEAT,ROOF LINING ETC.		200.00	80.00
	TO REMOVE & REPLACE REAR EXHAUST MUFFLER.	NOT NECESSARY	150.00	-
	TO REMOVE & REPLACE REAR UNDERCARRIAGE.		450.00	200.00
	TO PERFORM COMPUTERIZED WHEEL ALIGNMENT.		120.00	60.00
	TO REMOVE/REFIT REVERSE SRNSORS.		80.00	20.00
	TO CHECK WIRING.		50.00	30.00
	-		-	-
	-		-	-
	-		-	-
			6,450.00	4,140.00
GRAND TOTAL			20,378.08	12,748.88

Report Ref No. CS/FCI19015472/Est3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,500.00
---	--	--	----------

Report Ref No. CS/FCI19015472/Esf3n2

MARKET VALUE: \$19,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$13,366.00=NETT VALUE: \$5,634.00

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.